

EXHIBIT C

Guy B. Wallace, State Bar No. 176151
gwallace@schneiderwallace.com
Sarah Colby, State Bar No. 194475
scolby@schneiderwallace.com
SCHNEIDER WALLACE
COTTRELL KONECKY
WOTKYNS LLP
2000 Powell Street, Suite 1400
Emeryville, CA 94608
Telephone: (415) 421-7100
Facsimile: (415) 421-7105

Adam B. Wolf, State Bar No. 215914
awolf@prwlegal.com
Catherine Cabalo, State Bar No. 248198
ccabalo@prwlegal.com
PEIFFER ROSCA WOLF
ABDULLAH CARR & KANE
4 Embarcadero Center, 14th Floor
San Francisco, CA 94111
Telephone: (415) 766-3592
Facsimile: (415) 402-0058

Linda M. Dardarian, State Bar No. 131001
ldardarian@gbdhlegal.com
Andrew P. Lee, State Bar No. 245903
alee@gbdhlegal.com
GOLDSTEIN BORGEN DARDARIAN & HO
300 Lakeside Drive, Suite 1000
Oakland, CA 94612
Telephone: (510) 763-9800
Facsimile: (510) 835-1417

Attorneys for Plaintiffs and the Proposed Classes

UNITED STATES DISTRICT COURT

NORTHERN DISTRICT OF CALIFORNIA-SAN JOSE DIVISION

ABDUL NEVAREZ; PRISCILLA NEVAREZ,
and SEBASTIAN DEFRANCESCO, on behalf of
themselves and all others similarly situated;

Plaintiffs,

vs.

FORTY NINERS FOOTBALL COMPANY, LLC,
a Delaware limited liability company, *et al.*,

Defendants.

Case No. 5:16-cv-07013-LHK (SVK)

CLASS ACTION

**DECLARATION OF JEFFREY SCOTT
MASTIN IN SUPPORT OF PLAINTIFFS'
MOTION FOR CLASS CERTIFICATION**

Date: June 14, 2018
Time: 1:30 p.m.
Crtrm: 8
Before: Hon. Lucy H. Koh
Trial Date: April 22, 2019

1 I, Jeffrey Scott Mastin, declare as follows:

2 1. This Declaration is submitted in support of Plaintiffs' Motion for Class Certification in
3 *Nevarez et al., v. Forty Niners Football Co., LLC, et al.*, Case No. 5:16-cv-07013-LHK (SVK), in the
4 U.S. District Court, Northern District of California. I make this Declaration of my own personal
5 knowledge of the facts stated below, and if called as a witness in this case, I could and would testify as
6 stated herein.

7 **QUALIFICATIONS AND BACKGROUND**

8 2. I am a specialist in accessibility for persons with physical disabilities. I received my
9 five-year architectural degree from California Polytechnic State University, San Luis Obispo in 1987.
10 I became a licensed architect in California in 1995 and have been licensed continuously since. I have
11 twenty-four years' experience in Architecture including fourteen years as Project Architect and three
12 years as Construction Manager. I have been a specialist in disability accessibility since 1999.

13 3. I was asked to serve as Subject Matter Expert for the Division of the State Architect
14 ("DSA") in 2015. I have served under contract since 2015 in that capacity, specifically developing
15 and vetting materials for the California Certified Access Specialist Exam.

16 4. I am currently an independent accessibility consultant and President of Facility Access
17 Consulting, Inc. From 2005 through 2008, I was a partner in the architectural firm of Architerra, LLP
18 and one of the firm's resident experts on physical accessibility regulations. I also performed
19 numerous accessibility construction plan reviews for the DSA during this time. I was contracted by
20 that office to review, comment and approve various public agency submittals for compliance with
21 accessibility regulations. Prior to this, beginning in 1995, I was a project architect for three successive
22 architectural firms for large accessibility and architectural projects.

23 5. As a project architect, I have designed a wide variety of projects including civic,
24 institutional, educational, commercial, and health care facilities, as well as a large-scale state housing
25 project for the developmentally disabled. My primary responsibility was to direct or perform all
26 aspects of design and construction document production. This included design, code compliance, cost
27 estimating, materials and systems selection, graphical and technical communication, agency approvals
28

1 and construction field verification.

2 6. A relevant responsibility for a project architect is the investigation and documentation of
3 existing conditions when designing alterations, additions or renovations to existing facilities. Over
4 half of my work as Project Architect involved existing facilities. I am very experienced with
5 inspecting and documenting existing facilities and evaluating their potential for renovation or
6 upgrade. This documentation includes precise measurement and an intimate knowledge of
7 construction materials and systems for a variety of project types and scales.

8 7. I have provided and managed numerous large-scale accessibility site assessments for
9 state and private clients involving tens of millions of square feet of structures and thousands of acres
10 of associated sites. The public projects included the majority of all facilities operated by the Counties
11 of Orange and Alameda in California and five developmental center housing campuses for the State of
12 California. The private projects included over one thousand retail and food service facilities for
13 Fortune 500 companies nationwide. I have also served as a litigation access specialist for both
14 defendants and plaintiffs involving dozens of public agencies and private entities. I have further
15 provided training to dozens of accessibility experts working in forty-five states, including Hawaii. I
16 am familiar with the techniques that people with disabilities employ for mobility, including the
17 mechanics of various mobility aids. I have used this knowledge to work with facility owners to
18 identify and prioritize barriers to accessibility according to the degree of non-compliance and greatest
19 potential for injury.

20 8. I am very familiar with the requirements of federal disability access design standards,
21 including the 2010 Americans with Disabilities Act Standards for Accessible Design (“ADAS”), the
22 Americans with Disabilities Act Accessibility Guidelines (“ADAAG”) and the Uniform Federal
23 Accessibility Standards (“UFAS”). I am also very familiar with the requirements of California
24 accessibility design standards as codified within the California Building Code (“CBC”), often known
25 as Title 24 of the California Code of Regulations (“Title 24”). I have extensive experience measuring
26 and inspecting individual elements of newly constructed, altered and existing facilities to determine
27 the extent to which they comply with these accessibility standards. This includes substantial
28

1 experience in inspecting and assessing various elements of the pedestrian right of way, including
2 sidewalks, curb ramps and cross walks.

3 9. I am a California Certified Access Specialist in good standing (CAsp #88). The
4 certification, administered by the California Division of the State Architect, signifies that I am
5 qualified to evaluate plans, investigate facilities, conduct research, perform inspections, and prepare
6 reports to determine compliance with applicable state and federal accessibility provisions, including
7 statutes, regulations and standards. In addition, an important component of CAsp certification is the
8 duty to evaluate and propose suitable barrier removal measures with a reasonable schedule for
9 accomplishing such measures.

10 10. The opinions I express in connection with this litigation are based upon various
11 professional trainings and seminars I have attended, upon articles, reports, codes, acts, regulations,
12 interpretations and publications that I have studied, my professional experience interpreting and
13 applying the requirements of access regulation in professional practice, and in my experience in
14 working with public entities and business owners to educate them on their obligations for providing
15 accessible facilities.

16 11. Attached to this Declaration as Exhibit A is a true and correct copy of my curriculum
17 vitae.

18 **SCOPE OF WORK AND TESTIMONY IN THIS MATTER**

19 12. Counsel for Plaintiffs retained Gary Waters of Pacific Access Consulting, William
20 “Scott” McBrayer of Construction Quality Group, and Facility Access Consulting, Inc. to survey
21 Levi’s Stadium in Santa Clara, California (“the Stadium”). I conducted the survey on behalf of
22 Facility Access Consulting, Inc. We were asked to determine the extent to which the Stadium and its
23 physical elements comply with the standards set forth in the 2010 ADA Accessibility Standards
24 (“2010 ADAS”), the 1991 ADA Accessibility Guidelines (“1991 ADAAG”), and the 2010 version of
25 Title 24 of the California Building Code (“CBC”), and to assess the sufficiency of the policies,
26 procedures, and practices of Defendants—the City of Santa Clara (“the City”), the Santa Clara
27 Stadium Authority (“the Stadium Authority”), Forty Niners Football Co. LLC, Forty Niners SC
28

Stadium Co. LLC, and Forty Niners Stadium Management Co. LLC—with respect to disability access for persons with mobility disabilities.

13. I inspected the following elements of the Stadium:

- a. Parking lots serving the Stadium
- b. Exemplar accessible shuttle vehicle
- c. Pedestrian right of way between parking lots and the Stadium
- d. Restrooms
- e. Outside seating and sight lines for luxury suites throughout the Stadium, including:
 - i. Level 500 Black Oak Resort Casino Suites
 - ii. Level 500 Citrix Owners Suites
 - iii. Level 500 SAP Tower Suites
 - iv. Level 600 SAP Tower Suites
 - v. Level 700 SAP Tower Suites

14. With respect to parking lots, I was initially asked to inspect all of the parking lots that might be available to Stadium patrons on game days or event day, as identified in the following: (a) the Stadium’s Transportation Management Operations Plan (“TMOP”) (Bates-stamped documents SC 04130 – 04455), a true and correct copy of what I reviewed is attached to this Declaration as Exhibit B; and (b) the Notice of Site Inspections Pursuant to FRCP 34, dated September 29, 2017, a true and correct copy of what I reviewed is attached to this Declaration as Exhibit C. The parking lots that I ultimately inspected include the following:

Red Lot 1¹

¹ Certain online maps of the parking lots adjacent to the west side of the Stadium refer to “Red Lot 1,” “Red Lot VIP,” and “Green Lot 1.” I refer to all three of these lots together as “Red Lot 1” for the purposes of describing my findings in my report and this Declaration.

Yellow Lot 1 Parking

Structure

Yellow Lot 2

Yellow Lot 3

Blue Lot 1

Green Lot 3

Green Lot 2

Red Lot 3

Red Lot 4

Red Lot 5

Red Lot 7

Green Lots 4 & 5

15. With regard to the pedestrian rights of way or paths of travel from each of the parking lots made available to patrons of the Stadium to the entrances to the Stadium, my survey included the sidewalks, curb ramps and crosswalks along the following streets, as identified in Exhibit C to my Declaration. Additionally, I inspected a segment of pedestrian right of way not included in the inspection notice. I inspected the following:

- a. Great American Parkway from Old Mountain View-Alviso Road to Mission College Boulevard.
- b. Tasman Drive from Calabazas Creek to Lafayette Street.
- c. Mission College Boulevard from Great America Parkway to the driveway separating Mission College Lot B and C.
- d. Patrick Henry Drive from Bunker Hill Lane to Great America Parkway.
- e. Democracy Way from Patrick Henry Drive to Old Ironside Drive.
- f. Marie DeBartolo Way from Tasman Drive to end.
- g. Stars and Stripes Drive from Tasman Drive toward the Yellow Lots to end.

h. Centennial Boulevard from Stars and Stripes Drive to Tasman Drive.

i. Bunker Hill Lane from Patrick Henry Drive to Great America Parkway.

16. My inspection of portions of the Stadium itself was part of a larger effort involving several other access specialists engaged by the attorneys for Plaintiffs in this case.

BASES OF EXPERT TESTIMONY

A. Published Materials

17. The opinions I express in connection with this litigation are based upon various professional trainings and seminars that I have either presented or attended, upon articles, reports, codes and publications that I have studied, my professional experience interpreting and applying the requirements of the ADA (including the standards of the 2010 ADAS, the 1991 ADAAG, and UFAS) and the CBC in practice, and my experience in working with public entities and owners to educate them on their obligations under the ADA, the 2010 ADAS, the 1991 ADAAG, and the CBC with regard to providing accessible facilities.

B. Review of Relevant Case Documents and Testimony

18. The opinions I express in this Declaration are based on review and analysis of various documents, including the architectural plans for Levi's Stadium; the Design-Build Agreement between Santa Clara Stadium Authority, Forty Niners Stadium LLC, and Turner/Devcon, a Joint Venture ("the Design-Build Agreement"); and relevant portions of the transcript of the deposition testimony of Dennis Ng. Additionally, I have reviewed the site inspection reports prepared by Gary Waters and William "Scott" McBrayer, the other disability access experts retained by Plaintiffs' counsel to inspect the Stadium in this case. The analysis and conclusions contained in this report reflect my preliminary findings and conclusions, and these are subject to revision and supplementation, as further information becomes available through the discovery process in this case. My work is continuing. I may supplement, revise or change the opinions contained within this Declaration as I review additional documents produced and additional deposition testimony in this litigation and should I conduct any further site inspections of the Stadium and its facilities.

C. Federal Disability Access Design Standards

19. With the passage of the ADA, the Department of Justice issued the ADAAG standards. Since January 26, 1992, public entities have been obligated to perform new construction and alterations in compliance with either ADAAG or UFAS. On September 15, 2010, the Department of Justice published updated accessible design standards, the 2010 ADA Standards for Accessible Design (2010 ADAS). For new construction and alterations commenced between September 15, 2010 and March 15, 2012, public entities had to choose and ensure compliance with one of the following three federal standards: the 2010 ADAS, ADAAG, or UFAS. Physical construction or alterations commenced by public entities on or after March 15, 2012 must comply with the 2010 ADAS.

20. It is considered the appropriate standard of professional care by California architects to ensure that new construction and alterations be performed in compliance with both the CBC and the applicable federal access standard, whichever is more restrictive. The goal in following the more restrictive standard is to ensure the greatest degree of compliance with applicable codes and regulations and consequently, to ensure the greatest usability for persons with disabilities, including persons with mobility disabilities. I have utilized the most restrictive requirements of the applicable federal access standard (2010 ADAS or 1991 ADAAG) and the CBC as the appropriate disability access standard for our work with public entities in California. It is widely accepted among California architects who work with public entities that compliance with the standards of both the applicable federal access standard and the CBC, whichever is more restrictive, is necessary to ensure that persons with mobility disabilities are able to use the public facilities safely and independently.

D. Other Sources Reviewed

21. I have reviewed the Design-Build Agreement and, as noted above, relevant portions of the deposition testimony of Dennis Ng, who was designated by the City and the Stadium Authority as one of its witnesses pursuant to Federal Code of Civil Procedure 30(b)(6).

22. Based on my review of those materials and my knowledge of Titles II and III of the ADA and its implementing regulations, specifically 28 C.F.R. § 35.151(c) and § 36.401, *et seq.*, it is

1 my professional opinion that the federal access design standard that applied to the design and
2 construction of Levi's Stadium is the 2010 ADAS. The Stadium is owned and was developed by the
3 Stadium Authority, a part of the City, and therefore a public entity subject to ADA Title II. The
4 Stadium, and the stores and restaurants therein, also operate as places of public accommodation
5 under ADA Title III. Under Titles II and III of the ADA, new construction by public entities
6 commenced after September 15, 2010 and before March 15, 2012 must comply with the 2010 ADAS,
7 the 1991 ADAAG, or the UFAS. New construction by public and private entities commenced after
8 March 15, 2012 must comply with the 2010 ADAS. Based on my review of the case documents and
9 deposition testimony, it is clear that construction of the Stadium began after March 15, 2012, thereby
10 triggering a duty to comply with the 2010 ADAS. I understand that the Defendants may argue that
11 Stadium construction commenced between September 15, 2010 and March 15, 2012, thereby
12 permitting the election of the 2010 ADAS, ADAAG or the UFAS. This is incorrect. To determine
13 the required federal design standard, one must look at the commencement of construction. Site clean
14 up to prepare for construction took place after March 15, 2012. Temporary power was put in after
15 March 15, 2012 in preparation for construction. The permit for the shell and core of the Stadium, and
16 the beginning of the construction of the shell and core, all took place well after March 15, 2012.
17 Thus, the 2010 ADAS applies.

18 23. To the extent the City or the Stadium Authority elected a federal accessibility standard
19 under any mistaken conclusion that construction on the Stadium commenced prior to March 15,
20 2012, it would have elected either the 1991 ADAAG or the 2010 UFAS. The Design-Build
21 Agreement erroneously specifies Title III of the ADA, which applies to facilities owned and built by
22 private entities, not public entities such as the City or the Stadium Authority. Nonetheless, Title III
23 permits a choice between the 1991 ADAAG and the 2010 ADAS, but not UFAS, for new
24 construction projects by private entities constructed between September 15, 2010 and March 15,
25 2012. For this reason, I analyzed compliance with both the 2010 ADAS and the 1991 ADAAG in
26 my inspection of the Stadium.

27 //

METHODOLOGY

24. In conducting my surveys, I follow the methods outlined in the Department of Justice's ADA Best Practices Tool Kit, Introduction to Appendices 1 and 2. The equipment I use includes a two-foot digital smart level, a metal tape measurer, a door pressure gauge, and a camera. I record the information in note form. Typically, I will begin a survey by familiarizing myself with the facility. I will note whether required elements are provided or not and record dimensions, slopes and cross slopes as appropriate. In conducting the survey, I will identify if the required accessible features are provided and if they meet the most restrictive requirements of the 1991 ADAAG or the 2010 ADAS, depending on the date of construction, and the applicable version of the CBC (the 2010 CBC in this case). This typically involves taking dimensions, slopes and cross slopes, as applicable, and photographs.

25. In conducting the survey, I considered and applied dimensional tolerances except where the requirement is stated as a range with specific minimum and maximum end points. In that case, the range itself is a sufficient tolerance. Moreover, when a standard includes only a maximum, it is considered best practice in the industry to design and construct well below that maximum to ensure compliance with the standard. The same is true for a standard that includes a minimum; it is considered best practice to design and construct well above that minimum to ensure compliance. Using the Dimensional Tolerances for New and Existing Construction approved by the San Francisco Building Inspection Commission on September 16, 1998, attached as Exhibit D to this declaration, I did not record any conditions that would fall within the tolerances listed therein, including the following:

- a. Concrete paving. Standard: Plus or minus 1/4" over 10' for drives, parking surfaces, sidewalks and other side paving.
- b. Concrete slabs for flatness and straightness. Standard: Bull-float slab is plus or minus 1/2" over 10'.
- c. Flatness of counter tops. Standard: 1/4" per 8'.
- d. Clear opening at doors. Standard: plus or minus 3/8".

- e. Plumbing fixture installation. Standard: plus or minus 1/2" measured from the finished wall or floor.
- f. Handrail dimensions. Nominal handrails not to vary more than 3/16" in diameter from code dimension; height plus or minus 3/16" measured from finished floor.
- g. Threshold. Standard: 1/8" variation in threshold height is permitted above the finished floor surface.
- h. Knee clearance under wall mounted plumbing fixtures, including lavatories, drinking fountains, urinals and toilets. Standard: Mounting height above finished floor equals plus or minus 3/8". Within a 30" wide area, centered on the accessible basin or fixture, there may be a variation of 1/4" in height between the lower edge of the counter and the finished floor.
- i. Switches, receptacles, pull stations, controls and similar devices. Standard: Plus or minus 1/2" vertically.
- j. Door operating pressure. Standard: Plus or minus 1/2 pound.
- k. Operating pressures for faucets, flush valves and miscellaneous hardware. Standard: Plus or minus 1/2 pound.

FINDINGS

Parking

Conclusions

26. The parking available for persons with mobility disabilities attending events at the Stadium is not accessible. The Stadium's plan for providing the required number of accessible parking is flawed and the result does not conform to standards. The parking lot closest to Stadium entrances, Red Lot 1, which would allow persons with mobility disabilities to access the Stadium without traveling in the public right of way, does not provide the required number of accessible and van accessible parking spaces. Exhibit B. The Stadium's TMOP incorrectly concludes that the lot

1 provides an adequate number of accessible parking spaces. *Id.* It does not. In addition, the spaces that
2 are provided do not all conform to accessibility standards.

3 27. The Stadium relies on remote parking lots for patrons attending events. The Stadium's
4 TMOP suggests that additional accessible parking can be utilized in these remote lots. Reliance on
5 remote lots by itself for accessible parking is not effective because the public right of way system of
6 sidewalks, curb ramps and other elements is not accessible. I inspected extensive sections of key
7 components associated with these routes of travel and have determined that it is not possible for a
8 patron parking in any remote lot to access a Stadium entrance by way of the public right of way
9 system using an accessible route.

10 28. The Stadium's TMOP purportedly relies upon a shuttle service to transport patrons with
11 disabilities between two designated lots and the Stadium entrance. I inspected a shuttle represented to
12 be typical of the shuttles in use and determined that reliance on these shuttles as a substitute for
13 providing adequate accessible parking near the Stadium entrance is not effective. The shuttle I
14 inspected is equipped to carry 20 passengers but is incapable of transporting more than one person
15 using a wheelchair at a time. It appears to be designed for the purpose of carrying a group
16 representing a cross section of the general public allowing for only the occasional individual with a
17 disability. It is unsuited for transporting a specialized group of persons with disabilities, and would be
18 wholly ineffective if employed for that purpose.

19 29. In addition, I inspected the two lots that the Stadium indicated are served by the shuttle.
20 I found that the many of the designated accessible parking spaces in these lots do not conform to
21 standards. In the case of Blue Lot 1 I found that the route between each of the designated accessible
22 spaces and the shuttle stop had significant barriers to accessibility for individuals with mobility
23 disabilities.

24 30. I inspected other remote parking lots that I understand are not served by the shuttle.
25 Besides the aforementioned lack of accessible routes between these lots and Stadium entrances, these
26 lots are not accessible for additional reasons. Two of the lots do not contain any designated
27 accessible spaces (Yellow Lots 2 and 3). Although most of the remote lots contain such spaces, the
28

locations address building entrances for which the lots are designed, and not necessarily for accessing the public right of way. As a result, a patron with a mobility disability attending an event must choose a route that is generally not intended to be accessible. That person must usually travel along drive aisles within these lots, sharing these routes with vehicles, in order to reach the public right of way, instead of utilizing a parking space that is proximate to the connection to the public right of way.

Observations and Findings

31. The Stadium relies upon remote parking lots to serve patrons attending events using their own vehicles. I understand through review of discovery documents that the total of all parking spaces available to patrons that are controlled by the City is 6,694 (Yellow Lots 1, 2, & 3, Red Lot 1, and Green Lot 1). I further understand that the total number of spaces made available to patrons that are ticketed is 10,664 (Red Lots 3, 4, 5, & 7, Green Lots 2, 3, 4 & 5, and Blue Lot 1), for a total of 17,358 spaces. These figures are derived from Exhibit B at SC 04249.

32. The 2010 ADAS specify the minimum number of required accessible standards based on the total number of spaces provided in the parking facility, as set forth in the following chart:

Total Number of Parking Spaces Provided in Parking Facility	Minimum Number of Required Accessible Parking Spaces
1-25	1
26-50	2
51-75	3
76-100	4
101-150	5

201-300	7
301-400	8
401-500	9
501-1000	2 percent of total
1001 and over	2 percent of total
1001 and over	20, plus 1 for each 100 or fraction thereof, over 1000

33. I understand through my review of discovery documents that the Stadium's plan for providing the required number of accessible parking spaces is faulty, does not conform to standards, and may result in an insufficient number of accessible parking spaces available for patrons who need them. Section 5.3.4 "ADA Access" of the Stadium's TMOP calculates that "the total of 200 ADA parking would be sufficient to meet ADA parking requirements" (Exhibit B at SC 04237). The plan explains that the 200 would be provided at Red Lot 1. *Id.* My calculations applying applicable standards to the parking numbers represented in the TMOP indicate that 273 spaces would be required, including 53 that are van accessible. The Stadium plan would only provide 73% of the number actually required by standards. Moreover, according to my inspection of Red Lot 1, there are only 198 designated accessible spaces provided and far too few of them are van accessible. There are only 15 van accessible spaces among the 198 where 53 would be required by standards according to the plan represented by the TMOP. *Id.* The lot provides only 29% of the van accessible spaces that are required as represented by the plan.

34. The required accessible parking for lots either owned by the City or that are ticketed are separately tabulated and attached to this Declaration as Exhibit E “REQUIRED ACCESSIBLE PARKING.”

35. Accessible spaces are required to be provided in proportion to total parking spaces provided in the applicable parking lot and are calculated according to the table identified above. The percentage of required accessible parking decreases as the size of the lot increases. Rather than aggregating all parking spaces among several lots into one and then applying the table to find the required number, standards explicitly require accessible parking to be calculated on lot-by-lot basis, not aggregated together into one virtual lot. Standards do allow and even encourage relocating all of the accessible spaces that are so derived to other locations that are closer to entrances, or that would otherwise increase accessibility; however, the required number is based on the requirements for the individual lots. It is necessary to calculate the required accessible spaces by lot in order to derive the required number.

36. The Stadium’s remote parking lots are connected to the Stadium by way of the public right of way (“PROW”) system of sidewalks and street crossings. Attached to this Declaration as Exhibit F is a true and correct copy of my “Parking and Public Right of Way Graphic Matrix.” Connections between each lot and the PROW are shown on Exhibit F. Exhibit F graphically indicates pedestrian access connection routes to the PROW and also vehicular drive aisles that may be used as such.

37. Attached to this Declaration as Exhibit G is a true and correct copy of my “Parking Lots Detailed Findings Report with Photographs,” which includes detailed findings by element. Please refer to Exhibit G for more information regarding the barriers described. The following items provide a summary of barriers in each lot.

Red Parking Lot 1

38. Red Lot 1 is located at the West side of the Stadium. I understand that it is owned by the City. It is the closest parking to Stadium entrance gates A, B and C, and comprises 198 DAS. Please refer to Exhibit G Seq. #s (DAS). These DAS are convertible between standard parking spaces

and designated accessible spaces by way of articulating signs. Each such space is equipped with a sign that identifies it as a standard space stating:

**STANDARD
(NON-ACCESSIBLE)
PARKING STALL**

THIS SIGN PLACARD
REPLACES THE
SURFACE PAINT
DESIGNATION

Each such sign has a bottom half that folds up, covering the above language and replacing it with a symbol of an occupant in a wheelchair in white on a blue background and other text associated with accessible parking spaces appearing in white on a blue background.

39. Accessible parking spaces are required to be identified with a sign displaying an ISA (a specific symbol representing a wheelchair and occupant) and the words “VAN ACCESSIBLE” if it is a wider space suitable for a van using a side-deploying wheelchair lift. California law also requires the text “\$250.00 MINIMUM FINE.” Such spaces are required to be clearly delineated and marked to discourage parking in the access aisle, which is the portion at the side of the vehicle facilitating transfer to, or the loading/offloading of a mobility device. California law requires specific surface identification including a large ISA symbol, specific color and manner of markings delineating the stall and access aisle and the words “NO PARKING” in 12” high letters in the access aisle. These various identification methods are intended to alert a person who requires such a stall as to its presence, to discourage unauthorized use and to allow parking enforcement to quickly identify any unauthorized use so that the space can become available to those who require it.

40. In this case the surface markings clearly identify the spaces as accessible stalls. If the sign is configured to identify the space as a standard non-accessible space, only the sign informs the user of this condition. The portion of the sign that is hinged to flip upwards to display the signage indicating that the space is accessible is held in place with a bolt. The absence of the bolt causes the sign to fall back down into the position indicating it as a standard parking space by default. Each sign I observed in Red Lot 1 was in the “standard” configuration at the time of my inspection. I examined

several of the signs and found that the bolts were not tightened, only turned a revolution or two into the recessed threads. When the sign is in the “accessible” configuration and the bolt is not threaded far enough and falls out, the sign would revert by default to the “standard” configuration due to the force of gravity. It would be difficult or impossible for parking enforcement to positively determine the state of the sign when a person utilizes the space. Therefore if a person wishes to make unauthorized use of such a space identified as accessible with impunity, it is possible for that person to simply loosen the bolt and let the sign fall back to its “standard” position.

41. For purposes of identification in this report, Red Lot 1 spaces are described using an arbitrary reference. Parking rows are arranged running east to west. There are 12 such rows arranged north to south that contain accessible parking spaces. The northern 4 rows serve Stadium Gate A, the middle four rows serve Gate B and the southern 4 rows apparently serve Gate C. For the purposes of identification this report refers to spaces in each row numbered from west to east starting with “1” at the west end and ascending to the east, and refers to rows containing accessible spaces from north to south with letters, starting with “A” at the northernmost row and ending with L at the southernmost row. Please refer to Exhibit G Seq. #s 1001-1020.

- There are too few van accessible spaces in the lot (15 provided, 33 required based on the individual lot and 53 required based on the Stadium’s TMOP plan for accessible parking).
- The convertible signs are not effective in reserving the spaces for persons with disabilities because they can be converted by the user, and if the single fastening device fails or loosens on a sign, the sign reverts by default to indicate a standard parking space.
- The accessible signs do not provide the ISA symbol. They instead display a stylized figure that may not be as effective. The ISA is a specific symbol described graphically and precisely by standards.
- The accessible signs are not reflectorized, as required by California standards, making it more difficult to discern and locate by drivers who may be searching for accessible

parking in general, or those accessible to vans, when ambient lighting is poor.

- Five spaces are missing signs (A7, A11, A15, A16, J13).
- Four spaces have excessive surface slopes (E1, F1, G1, H1).
- The access aisle serving space H3 and H4 has a large noncompliant pothole, affecting use of both spaces.
- Five spaces have one or two approx. 1” diameter holes in the space/access aisle, apparently for the installation of equipment or displays (I1, I3, I4, I5, I6).
- Detectable warnings (i.e., truncated domes) obstruct the access aisles serving eight spaces (E13, E14, F13, F14, G13, G14, H13, H14). The detectable warnings obstruct the surface of the access aisle, which is required to be smooth and without level change, and are unnecessary at these locations. The detectable warnings obstruct all four access aisles as well as obstructing the routes of travel between each of the eight DAS and the Stadium Gate.
- There is no access aisle provided at space I19.
- The painted surface markings are faded/worn to the extent that they cannot be discerned at many spaces. In addition, the entire “L” row (i.e., the southernmost row) has new markings painted over old markings -but in different locations, making it difficult to discern the extent and location of any particular space.
- There are many standard spaces that are closer to the entrance at Gate C than are the 85 DAS apparently serving that entrance. In addition, there are many standard spaces that are closer to any Stadium entrance than these 85 DAS.
- The accessible route of travel between the 56 DAS serving Gate B and the security devices has excessive running slope for approximately 40 feet. In addition, there is a section of excessive running slope just east of the security device area.

Yellow Parking Lot 1 – Parking Structure

42. Yellow Lot 1 is a five-story parking structure located across Tasman Drive, a divided road, at the north side of the Stadium. I understand it is owned by the City. Elevators are

located at three of the four corners of the rectangular structure with DAS located associated with elevators at the southwest corner (12 DAS at designated area 1A) and southeast corner (12 DAS at designated area 1D), and 5 grade level DAS located at the northeast corner (designated area LD).

Please refer to Exhibit G, Seq. #s 1101-1124.

- A concrete bollard obstructs the access aisle at the northeast DAS at LD.
- The van DAS at L, at the electric vehicle charging station (EVCS) is signed for charging electric vehicles, however, the charging cable will not reach a vehicle parked in the van accessible space. The cable only extends approx. 12” into the far SE corner of the access aisle for that parking space. In addition, the route between this parking space and the charging station is too narrow to allow a person to access the charging station. If the charging cable did reach far enough, it would obstruct the accessible route between two DAS to the PROW at Stars and Stripes Drive.
- There are excessive surface slopes in seven DAS at area 1A (the northern and southern double DAS, and the second and third double DAS as counted from north).
- A column obstructs the access aisle of the van DAS near the southwest corner at area 1A.
- A concrete waste receptacle obstructs the access aisle of the single DAS at the east side of the elevator at area 1A.
- The accessible route of travel between 11 of the DAS located along the west side of the structure at area 1A is located at the exterior and is exposed to weather, whereas the route for the general public is interior and protected from weather.
- There are standard parking spaces that are closer to any entrance to the parking structure than are ten of the 12 DAS at area 1A.
- There are excessive surface slopes in eight DAS at area 1D (the southern double DAS and the second, third and fourth double DAS as counted from the north).
- A column obstructs the access aisle of the van DAS near the southeast corner at area 1D.

- The accessible route of travel between 11 of the DAS located along the east side of the structure at area 1D is located at the exterior and is exposed to weather, whereas the route for the general public is interior and protected from weather.
- There are standard parking spaces that are closer to any entrance to the parking structure than are the 12 DAS at area 1D.
- The help button on each of the three emergency call boxes serving the DAS at all three areas is located too high above the surface of the floor.

Yellow Parking Lot 2

43. Located at the north side of the Stadium, across Tasman Dr., a divided road. I understand it is owned by the City. There are no designated accessible parking spaces in the lot. Discovery documents indicate that the lot provides 304 parking spaces. Please refer to Exhibit G, Seq. #s 1301-1307.

- There are no DAS provided (none provided, eight required).
- There are no van DAS provided (none provided, two required).
- There are no accessible routes of travel between any area of the lot and the PROW. All but three routes that appear to be utilized by the general public are dirt surfaces and require travel up/down steep hillsides. Two of the three non-dirt routes are vehicular entrances that have inaccessible loose rock, gravel and sand surfaces as well as gaps and vertical edges. The third, a paved route to the PROW located at the northeast corner is a ramp without the required handrails and level landings, and requires travel over inaccessible surfaces (loose rocks, sand and gravel).

Yellow Parking Lot 3

44. This lot is located at the north side of the Stadium, across Tasman Drive, a divided road. I understand it is owned by the City. There are no designated accessible parking spaces in the lot. Discovery documents indicate that there are 428 parking spaces. Please refer to Exhibit G, Seq. #s 1401-1406.

- There are no DAS provided (none provided, nine required).

- There are no van DAS provided (none provided, two required).
- There are no accessible routes of travel between any area of the lot and the PROW. All but two routes which appear to be utilized by the general public are dirt surfaces and some require travel up/down steep hillsides. The two non-dirt routes are vehicular entrances that have inaccessible loose rock, gravel and sand surfaces as well as gaps and vertical edges. The single route that appears to be intended as the main pedestrian route to the PROW is located at the west side and is a dirt surface, with loose rocks, gravel and sand, and has high vertical edges and excessive running slope.

Blue Parking Lot 1

45. Blue lot 1 is not located near the Stadium. I understand that it is a Stadium ticketed facility. It is located approximately 2,900 feet away from the Stadium as measured along pedestrian sidewalks. It is a large area bounded by Democracy Way, Patrick Henry Drive and Old Ironsides Drive. I understand that a shuttle operates between this lot and the Stadium. While DAS are located in three areas of the lot, I observed what appears to be a shuttle stop serving only one of the three areas. Discovery documents indicate that the lot comprises 508 spaces.

46. There are 19 DAS located at the north side of the lot which appear to be served by a shuttle. I refer to these as the north group of DAS. There are 26 DAS located at the northeast corner of the lot. I refer to these as the northeast group of DAS. There are 14 DAS located at the east side of the lot near the north end. I refer to these as the east group of DAS. Please refer to Exhibit G, Seq. #s 1501-1521.

47. General:

- There are not enough DAS provided (59 provided, 61 required).
- There are not enough van DAS provided (nine provided, ten required).

48. North group of 19 DAS:

- There are many standard parking spaces that are located closer to any entrance of the parking lot than are many of the 19 DAS.
- Eight of the eleven access aisles serving the north DAS are too narrow.

- The west two DAS at the north group of DAS are obstructed by the shelter structure.
- The accessible route of travel between some of the eastern DAS in the north group of DAS is partially covered by a deep layer of leaves and debris.
- The ramp at the west end of the accessible route of travel serving the north group of DAS has excessive cross slope on the ramp and excessive slope on the top landing, and handrails are not provided.
- The accessible route of travel between the north group of DAS and the seven portable toilets serving them has multiple raised vertical edges.
- The two handwashing stations at the seven portable toilets serving the north group of DAS are not accessible because water flow is provided by foot pedals.
- The hand sanitizer within the single accessible portable toilet serving the north group of DAS is located too high.

49. Northeast group of 26 DAS:

- There are many standard parking spaces that are located closer to any entrance of the parking lot than are many of the 26 DAS.
- The northeast DAS of the northeast group of DAS is not provided with a wide enough access aisle.
- The access aisle at the DAS located at the north end of the northeast group of DAS is obstructed by area lighting standard and equipment.
- The accessible route of travel between any DAS in the northeast group and the PROW is partially covered by a deep layer of leaves and debris, and trees and shrubs obstruct the required width for much of its length.
- The two handwashing stations at the seven portable toilets serving the northeast group of DAS are not accessible because water flow is provided by foot pedals.
- The hand sanitizer within the single accessible portable toilet serving the northeast group of DAS is located too high.

- The short asphalt connection between the northeast group of DAS and the PROW has excessive cross slope and a convoluted asphalt surface.

50. East group of 14 DAS:

- There are many standard parking spaces that are located closer to any entrance of the parking lot than are many of the 14 DAS.
- There are excessive slopes in the southern eight DAS of the east group of DAS.
- The surface markings at the north DAS of the east group of DAS are worn and not discernable.
- The accessible route of travel between any DAS in the east group and the PROW is partially covered by a deep layer of leaves and debris, and trees and shrubs obstruct the entire width for much of its length.
- The asphalt ramp between the east group of DAS and the PROW has excessive running slope, is a convoluted non-planar surface, and lacks required handrails.
- The two handwashing stations at the seven portable toilets serving the east group of DAS are not accessible because water flow is provided by foot pedals.
- The hand sanitizer within the single accessible portable toilet serving the east group of DAS is located too high.

Green Parking Lot 3

51. Green Lot 3 not located near the Stadium. I understand that it is a Stadium ticketed facility. The lot is bounded by Old Glory Lane, Democracy Way, Patrick Henry Drive and Great America Parkway. Distances to the Stadium from parking in this lot vary greatly depending on the particular location of DAS within the lot, from approximately 3,500 to 4,600 feet away as measured along pedestrian sidewalks.

52. The lot is designed so that the DAS are proximate to and serve the various entrances for four buildings. The locations of the DAS are not designed to serve the PROW and accessible routes of travel are not provided between any DAS and the PROW. Discovery documents indicate that the lot provides 1,183 spaces, however this appears to be incorrect. Earlier superseded discovery

documents put the total number at 732 spaces. I understand through discovery documents that no shuttle operates between this lot and the Stadium. Please refer to Exhibit G, Seq. #s 1601-1609.

- There are many other standard non-accessible spaces that are closer to all entrances to the parking lot than are any of the DAS.
- All accessible routes of travel between any DAS and the PROW requires travel within the vehicular traffic lanes of the parking lot, often along and in the same or opposite direction of travel as vehicles, and requires the user to pass behind parked vehicles.
- There is no signage indicating the intended accessible routes of travel among DAS and the PROW, if such routes exist.

Green Parking Lot 2

53. Green Lot 2 is not located near the Stadium. I understand that it is a Stadium ticketed facility. The lot is bounded by Old Glory Lane, Old Ironsides Drive, Tasman Drive and Great America Parkway. Distances to the Stadium from parking in this lot vary depending on the particular location of DAS within the lot, from approximately 2,600 to 3,200 feet away as measured along pedestrian sidewalks.

54. The lot is designed so that the DAS are proximate to and serve the various entrances for three buildings. A parking structure is located between the buildings. The locations of the DAS are not designed to serve the PROW and accessible routes of travel are not provided between any DAS and the PROW. Discovery documents indicate that the lot provides 426 spaces, however this appears to be incorrect. The parking structure and surface parking appear to provide many more spaces than stated. I did not count the actual spaces. I understand through discovery documents that no shuttle operates between this lot and the Stadium. Please refer to Exhibit G, Seq. #s 1701-1718.

- There are many other standard non-accessible spaces that are closer to all entrances to the parking lot than are any of the DAS.
- There is no signage indicating the intended accessible routes of travel among DAS and the PROW, if such routes exist.

- The four curb ramps making up the walkway along the front of the eight DAS at the west side of the Citrix building have excessive cross slopes, either on the ramp surfaces or the bottom landings, or both.
- The accessible route of travel between the group of eight DAS at the west side of the Citrix building and the PROW at Great America Parkway is not accessible because of excessive cross slopes and inaccessible curb ramps:
 - The walkway between the group of eight DAS and the southwest corner of the building has excessive cross slope for approximately 120 feet long.
 - The curb ramp at the southwest corner of the building, which because of the configuration, must be used by a person using the sidewalk regardless of destination, has excessive cross slopes at the ramp and bottom landing.
 - The curb ramp at the west side of the service drive at the south side of the Citrix building has excessive cross slope.
 - The crossing of the service drive at the south side of the Citrix building has excessive cross slope for approximately 20 feet long.
 - The curb ramp at the east side of the service drive at the south side of the Citrix building has excessive running slope.
- The accessible route of travel between the group of seven DAS at the south side of the north Citrix building and the PROW at Tasman Drive is not accessible because of excessive cross slopes and inaccessible curb ramps:
 - The walkway along the front of the seven DAS has excessive cross slope for approximately 80' long.
 - The curb ramp at the southwest corner of the building has excessive cross slope on the ramp surface.
 - The curb ramp at the south side of the service drive at the west side of the building has excessive cross and running slope.
 - The route of travel across the service drive at the west side of the building

has excessive cross slope.

- The route of travel between the service drive at the west side of the building and Tasman Drive has excessive cross slope for a length of approximately 100 feet.

Red Parking Lot 3

55. Red Lot 3 is not located near the Stadium. I understand that it is a Stadium ticketed facility. The lot is bounded by Bunker Hill Lane, Great America Parkway, by an office facility to the west and San Thomas Aquino Creek to the north. The distance to the nearest entrance to the Stadium is approximately 3,200 feet away as measured along pedestrian sidewalks.

56. There are 22 DAS provided in the lot. The parking lot is designed such that the DAS are proximate to and serve the various entrances for three buildings. The locations of the DAS are not generally designed to serve the PROW and accessible routes of travel are generally not provided between any DAS and the PROW. The exception to this is a group of four DAS at the east side of the east building, which are connected directly to a drive aisle crossing and access path to the PROW at Great America Parkway. Discovery documents indicate that the lot comprises 538 spaces. I understand through discovery documents that no shuttle operates between this lot and the Stadium. Please refer to Exhibit G, Seq. #s 1801-1811.

- There are excessive slopes in the four DAS at the east side of the east building.
- There are many other standard non-accessible spaces that are closer to all entrances to the parking lot, than are any of the DAS.
- There is no signage indicating the intended accessible routes of travel among DAS and the PROW, if such routes exist.
- All accessible routes of travel between any DAS and the PROW require travel within the vehicular traffic lanes of the parking lot, often along and in the same or opposite direction of travel as vehicles. The routes for 18 of the 22 DAS require the user to pass behind parked vehicles.

- The markings at the double DAS located at the south side of the southwest building are faded and/or worn and difficult to discern.
- The markings at the three DAS located at the south side of the east building are faded and/or worn and difficult to discern. In addition, there are excessive surface slopes in the spaces and access aisles.

Red Parking Lot 4

57. Red Lot 4 is not located near the Stadium. I understand that it is a Stadium ticketed facility. The facility is bounded by Patrick Henry Drive, Bunker Hill Lane, Old Ironsides Drive and Tasman Drive. The distance to the nearest entrance to the Stadium varies according to which DAS is used, from approximately 3,200 feet to 4,500 feet as measured along pedestrian sidewalks. Discovery documents indicate that the lot provides 782 spaces and that the entire lot is included. This is incorrect. On-site tenant security informed me that the southern half of the site, including the parking spaces located there, are not available to Stadium patrons during events. I counted 825 provided spaces in the portion of the lot that I understood to be available to patrons of the Stadium.

58. The parking lot is designed such that the DAS are proximate to and serve the various entrances for three buildings. A parking structure is located north of the buildings but contains no DAS. The locations of the DAS are not designed to serve the PROW and accessible routes of travel are not provided between any DAS and the PROW. I understand through discovery documents that no shuttle operates between this lot and the Stadium. Please refer to Exhibit G, Seq. #s 1901-1909.

- There are not enough accessible spaces provided (14 provided, 17 required).
- The double DAS located at the north side of Building 3 is obstructed by portable toilets, and has excessive slopes in stalls and access aisle. In addition, there are unnecessary detectable warnings provided in the access aisle that obstruct the use of the access aisle and the accessible route of travel away from the DAS, because they consist of raised bumps on the surface that is required to be smooth and level.
- The double DAS located at the north side of Building 2 has excessive slopes in stalls and access aisle. In addition, there are unnecessary detectable warnings provided in

the access aisle that obstruct the use of the access aisle and the accessible route of travel away from the DAS, because they consist of raised bumps on the surface that is required to be smooth and level.

- The single DAS at the west side of Building 1 has excessive slopes in the access aisle.
- There are many other standard non-accessible spaces that are closer to all entrances to the parking lot, than are any of the DAS.
- There is no signage indicating the intended accessible routes of travel among DAS and the PROW, if such routes exist.
- All accessible routes of travel between any DAS and the PROW require travel within the vehicular traffic lanes of the parking lot, often along and in the same or opposite direction of travel as vehicles, and require the user to pass behind parked vehicles.

Red Parking Lot 5

59. Red Lot 5 is not located near the Stadium. I understand that it is a Stadium ticketed facility. The facility is bounded by Patrick Henry Drive, Tasman Drive, and retail facilities to the north and west. The distance to the nearest entrance to the Stadium varies according to which DAS is used, from approximately 4,100 feet to 5,400 feet as measured along pedestrian sidewalks. Discovery documents indicate that the lot provides 445 spaces; however, but I observed approximately 600 spaces.

60. The parking lot is designed such that the DAS are proximate to and serve the various entrances for two buildings. The locations of the DAS are generally not designed to serve the PROW and accessible routes of travel are generally not provided between any DAS and the PROW. The exception to this is the four DAS located at the east side of the south building, which are directly connected to a drive aisle crossing and path connecting to the PROW at Patrick Henry Drive. I understand through discovery documents that no shuttle operates between this lot and the Stadium. Please refer to Exhibit G, Seq. #s 2001-2011.

- The double DAS located at the north side of the north building has excessive slopes in the east stall.
- The double DAS located at the east side of the north building has excessive slopes in the south stall.
- There is no accessible route of travel directly between the north building area and the PROW primarily because there is no sidewalk provided along the PROW. Users of DAS at the north area must first utilize a route of travel to reach the southern area. The curb ramp along this route has excessive running slopes, excessive gutter slope and excessive side flare slopes.
- The double DAS located at the south side of the east entrance to the south building has excessive slopes in the north stall.
- There are many other standard non-accessible spaces that are closer to all entrances to the parking lot, than are any of the DAS.
- There is no signage indicating the intended accessible routes of travel among DAS and the PROW, if such routes exist.
- All accessible routes of travel between 12 of the 16 DAS provided and the PROW require travel within the vehicular traffic lanes of the parking lot, often along and in the same or opposite direction of travel as vehicles, and require the user to pass behind parked vehicles.

Red Parking Lot 7

61. Red Lot 7 is not located near the Stadium. I understand that it is a Stadium ticketed facility. It is bordered by Great America Parkway, retail facility to the north and a golf course to the east and south. The nearest Stadium entrance is approximately 5,000 feet away as measured along pedestrian sidewalks. Discovery documents indicate conflicting space totals: indicating that there are either 592 or 600 spaces provided.

62. The parking lot is designed such that the DAS are proximate to and serve the various entrances for one building. The area in front of the second building served by the parking lots,

located at the northeast corner of the lot, was under construction at the time of the inspection. No DAS were observed in this construction area, nor was there any indication that DAS existed there in the past. Five DAS are provided serving the south entrance of the northwest building. The locations of the DAS are generally not designed to serve the PROW, but are nevertheless connected to the PROW by a circuitous route of pedestrian sidewalks that connect the building entrance to the PROW. I understand through discovery documents that a shuttle operates between this lot and the Stadium. Please refer to Exhibit G, Seq. #s 2100-3102.

- There are not enough DAS provided (five provided, twelve required).
- Many other standard non-accessible stalls are closer to parking lot entrances than are any DAS.

Green Parking Lots 4 and 5

63. Green Lots 4 and 5 are not located near the Stadium. I understand that they are Stadium ticketed facilities. They are bordered by Mission College Boulevard to the north and east and Mission Community College to the south and west, a facility that these lots normally serve. The nearest Stadium entrance is approximately 7,200 feet away as measured along pedestrian sidewalks. Discovery documents indicate that there are 2,133 spaces provided.

64. The parking lot is designed such that the DAS are proximate to and serve the campus to the south. The locations of the DAS are generally not designed to serve the PROW, but are nevertheless connected to the PROW by a circuitous route of pedestrian sidewalks that connect the lots to the PROW, which I determined are not accessible. I understand through discovery documents that no shuttle operates between this lot and the Stadium. Mission College denied access to the lot for inspection.

Pedestrian Right of Way from Parking Lots to the Stadium

Summary of Observations

65. Because the Stadium and most of the pedestrian right of way leading to the Stadium were constructed or altered after March 15, 2012, I applied the 2010 ADAS and the 2010 CBC in

1 conducting my inspections and evaluations. For comparison purposes, I also considered and noted
2 any inconsistencies with the 1991 ADAAG.

3 66. All routes between any parking lot inspected and Stadium entrances require
4 navigating multiple inaccessible elements in succession, such as sidewalks, curb ramps, street
5 crossings, and crosswalk buttons, regardless of the particular route chosen, no matter how direct or
6 circuitous the chosen route is.

7 67. The vast majority of elements associated with the public right of way in the area
8 surrounding the Stadium are inaccessible. This is shown in Exhibit F, which illustrates graphically
9 the accessibility and inaccessibility of elements in the public right of way as they are functionally
10 related to one another. Because there are many particular combinations of route segments a person
11 could choose in accessing the Stadium from a remote parking lot, it is not practical to analyze each
12 and every possible choice, nor is it necessary in this case.

13 68. Exhibit F indicates elements that must be encountered along particular routes, linked
14 together in sequence, diverging where decision points are available. Accessible elements are
15 indicated in green and inaccessible elements in red. Analysis of any path from one point to another
16 can be graphically understood. Exhibit F demonstrates that all routes necessarily comprise a
17 significant number of inaccessible elements (red items).

18 69. The lack of accessible routes between any remote parking lot and any Stadium
19 entrance significantly and negatively affects patrons with mobility disabilities. An individual with a
20 mobility disability can find no accessible routes connecting to Stadium entrances. Moreover,
21 discovery documents describing construction history indicate that a great many of the elements
22 identified as inaccessible associated with Great America Parkway, Tasman Drive, Patrick Henry
23 Drive and Old Ironsides Driven are recently constructed and are required to conform to current ADA
24 and CBC standards. These discovery documents indicate that construction activity in certain streets,
25 such as Great America Parkway, would have required curb ramps that conform to 2010 ADAS.

26 **Inspection Findings**

27 70. I inspected ten public right of way segments associated with pedestrian travel among
28

1 parking lots used by patrons to access the Stadium and its entrances. The number, relationship and
 2 distribution of elements a pedestrian could encounter along each segment can be best understood by
 3 referencing Exhibit F, where these PROW segments, their relationship to one another and whether
 4 they are accessible or inaccessible are graphically displayed. Each element indicated in Exhibit F is
 5 represented by a number. That number corresponds to a Sequence number in the detailed reports that
 6 constitute Exhibit H, which is attached to this Declaration as a true and correct copy of my “Public
 7 Right of Way Detailed Findings Report with Photographs.” More detailed information regarding the
 8 nature and degree of barriers associated with these elements is referenced in Exhibit H.

9 **71. Driveways and Curb Ramps.** I reviewed the City’s design standards for driveways
 10 and curb ramps (Bates SC 04584, 04586, 04587, 04590, and 04591), and a true and correct copy of
 11 what I reviewed is attached to this Declaration as Exhibit I.

- 12 • These design standards do not comply with 2010 ADAS or 1991 ADAAG. Curb
 13 ramp designs (ST-14, 15 and 16) direct the contractor to construct a 1/2" lip at the
 14 line of inflection forming the transition between the bottom of the curb ramp and the
 15 gutter – referred to as a “lip detail” -- indicating a sloping transition that is 1" in
 16 length and 1/2" in height. *Id.* There is no indication for gutter slope limits on these
 17 details. *Id.* The 1991 ADAAG, the 2010 ADAS, and DOT guidance all specify
 18 flush transitions and a 5% gutter.
- 19 • It is possible that there is a gutter detail or general specification that may define
 20 gutter slope limits, however, to ensure correct construction the gutter slope
 21 specification is specific to the curb ramp. As such, the information properly belongs
 22 on the curb ramp detail and should be positively referenced on that detail, not hidden
 23 somewhere unlikely to be referenced by the builder.
- 24 • The October 12, 2006 Supplement to the 2001 CBC removed the requirement for a
 25 beveled lip at curb ramps, but prior to that, on January 26, 2005, the DSA issued
 26 interpretation allowing flush transition in general.

27 //

72. **Great America Parkway from Old Mountain View-Alviso Road to Mission College Boulevard.**

- Great America Parkway is the major arterial in the north-south direction serving the Stadium, with pedestrian sidewalks provided along both sides of the street. Great America Parkway can be used by pedestrians traveling to and from the north and south to access Tasman Drive, which connects directly to the Stadium. The vast majority of sidewalks, curb ramps and other elements required to be accessible along Great America Parkway are not accessible, even though many show evidence of being recently constructed and/or are located along areas where streets appear to be recently re-paved and alteration obligations under the ADA and CBC would have required providing accessible elements attending the repaving activity. I understand through my review of discovery documents, including the deposition of Dennis Ng, that these elements were recently constructed and that would require conformance with the 2010 ADAS. All pedestrians traveling between the Stadium and any parking lot except Red Lot 1 and Yellow Lots 1, 2 and 3, must utilize some inaccessible elements associated with Great America Parkway. A summary of typical barriers is presented below. Please refer to Exhibit H, Seq. #s 1-89 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.
- Many curb ramps are too steep, have excessive gutter slopes, and have raised edges or wide gaps at the bottom where transitions are required to be flush. In addition, some curb ramps have sides that are too steep, are not located correctly relative to marked crossings, or are placed too closely together.
- Many of the pedestrian crossing buttons are not accessible because they are located on steep slopes. Some mid-crossing crosswalk buttons are located atop a raised island without a curb ramp and too far away to reach, potentially stranding a user who cannot actuate the crossing signal located in the middle of the street. Whereas

the general public can step up the curb to the relative protection of the island, actuate the signal, and wait outside of traffic lanes, a person who cannot ascend curbs must wait in the roadway traffic lanes for the signal to change. In some of these cases the crosswalk is partially or wholly interrupted by the island so that if the user cannot step up to the curb or utilize a narrow route, he must divert into the traffic lanes of the street in order to pass the median.

- The sidewalks are characterized by long sections of steep cross slopes and raised vertical edges. In addition, both crossings of Tasman Drive have high raised mounds on each side of the four rails used for public light train transportation, where the sides of such rails are required to be at the same level as the asphalt. This is a particularly difficult barrier because the elevation difference occurs in conjunction with unusually wide gaps which are allowed at such locations.
- Some sidewalks are constructed to meander in elevation, sloping up an artificial hill and down the other side. The hills are unnecessary because the street and properties along them are level. The artificial hills create excessive running slope and in some cases, excessive unprotected drop-offs at the side of the sidewalk.

73. **Tasman Drive from Calabasas Creek to Lafayette Street.**

- Tasman is the major arterial in the east-west direction serving the Stadium, with pedestrian sidewalks provided along both sides of the street. Tasman Drive connects directly to the Stadium. The vast majority of sidewalks, curb ramps and other elements required to be accessible along Tasman Drive are not accessible, even though many show evidence of being recently constructed and/or are located along areas where streets appear to be recently re-paved and the ADA and CBC's alteration obligations would have required providing accessible elements attending the repaving activity. I understand through my review of discovery documents, including the deposition of Dennis Ng, that these elements were recently constructed and would have been required to conform to the 2010 ADAS. All pedestrians

traveling between the Stadium and any parking lot except Red Lot 1 utilize some inaccessible elements associated with Tasman Drive. A summary of typical barriers is presented below. Please refer to Exhibit H, Seq. #s 201-246 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.

- Many curb ramps are too steep, have excessive gutter slopes, and have raised edges or wide gaps at the bottom where transitions are required to be flush. In addition, some curb ramps have sides that are too steep and have raised vertical edges or gaps on the ramp and landing surfaces.
- Many of the pedestrian crossing buttons are not accessible because they are located on steep slopes.
- The sidewalks are characterized by long sections of steep cross slopes and raised vertical edges.

74. Mission College Boulevard from Great America Parkway to the driveway separating Mission College Lot B and C.

- Mission College Boulevard connects routes for pedestrians who park in Green Lots 4 and 5 with Great America Parkway and ultimately Tasman Drive, which in turn, connects to the Stadium. The vast majority of sidewalks and curb ramps required to be accessible along Tasman Drive are not accessible. All pedestrians who park in Green Lots 4 or 5 must utilize some inaccessible elements associated with Mission College Boulevard when traveling to and from the Stadium. A summary of selected barriers is presented below. Please refer to Exhibit H, Seq. #s 301-315 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.
- All curb ramps associated with Mission College Boulevard are not accessible to individuals with mobility disabilities. They are inaccessible for various reasons including due to excessive running slope, excessive slope at the gutter, sides that are

too steep, and one that is not located correctly within crosswalk markings.

- The sidewalks are characterized by long sections of steep cross slopes, excessive running slopes and raised vertical edges.

75. **Patrick Henry Drive from Bunker Hill Lane to Great America Parkway.**

- Patrick Henry Drive connects routes for pedestrians who park in Red Lot 5 and may be used by those who park in Red Lot 4 and Blue Lot 1. Patrick Henry drive connects pedestrians in these lots with Tasman Drive, which in turn, connects to the Stadium, or Great America Parkway, which connects to Tasman Drive. The street incorporates a 90-degree turn so that it runs in both the north-south direction and in the east-west direction. Sidewalks are not provided the entire length along both sides of Patrick Henry Drive. East and north side sidewalk portions are not provided south of Democracy way, affecting users of Blue Lot 1 who choose to use the west side connections of Blue Lot 1 to Patrick Henry Drive. Sidewalks are not provided at either side of the street beginning at Bunker Hill Lane at the north end of the inspected portion of Patrick Henry Drive, affecting users who park at the north side of Red Lot 5.
- The vast majority of sidewalks and curb ramps along Patrick Henry Drive are not accessible. All pedestrians who park in Red Lot 5 must utilize some inaccessible elements associated with Patrick Henry Drive. A summary of selected barriers is presented below. Please refer to Exhibit H, Seq. # s 401-426 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.
- All but two curb ramps associated with Patrick Henry Drive are not accessible. They are inaccessible for various reasons including due to excessive running slope, excessive slope at the gutter, have raised edges or wide gaps at the bottom where transitions are required to be flush, have sides that are too steep, and are not located correctly within crosswalk markings. One curb ramp serves a crossing to Blue Lot 1,

however there is no curb ramp at the other side of the crossing.

- The sidewalks are characterized by long sections of steep running and cross slopes and raised vertical edges. Some portions of the sidewalks are constructed to meander in elevation, sloping up an artificial hill and down the other side. The hills are unnecessary because the street and properties along them are level. The artificial hills create excessive running slope and in some cases, excessive unprotected drop-offs at the side of the sidewalk.

76. **Democracy Way from Patrick Henry Drive to Old Ironside Drive.**

- Democracy Way is a relatively short street along the North side of Blue Lot 1, collecting many pedestrians who park in Blue Lot 1. Pedestrians utilizing Democracy Way would travel east to Old Ironsides Drive, and then north to Tasman Drive, which is connected directly to the Stadium entrance. The vast majority of sidewalks and curb ramps along Democracy Way are not accessible, even though some show evidence of having been recently constructed. I understand through my review of discovery documents, including the deposition of Dennis Ng, that some elements I noted as inaccessible were recently constructed and would have been required to conform to the 2010 ADAS. Please refer to Exhibit H, Seq. #s 601-637 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.
- The few curb ramps associated with Democracy Way are not accessible for various reasons including due to excessive running slope, excessive slope at the gutter, have raised edges or wide gaps at the bottom where transitions are required to be flush, have sides that are too steep, and one is positioned incorrectly in relation to crosswalk markings.
- The sidewalks are characterized by long sections of steep running and cross slopes and raised vertical edges. Some portions of the sidewalks are constructed to meander in elevation, sloping up an artificial and hill and down the other side. The hills are

unnecessary because the street and properties along them are level. The artificial hills create excessive running slope and in some cases, excessive unprotected drop-offs at the side of the sidewalk.

77. **Old Ironsides Drive from Bunker Hill Lane to Patrick Henry Drive.**

- Old Ironsides Drive is the closest street to most of the designated accessible parking in Blue Lot 1 and would be the natural choice of route for pedestrians utilizing 40 of the 59 designated accessible parking spaces, namely, those located at the northeast corner and north end of the east side where the accessible route of travel is painted on the surface of the asphalt directing users to Old Ironsides. In addition, these spaces also are not proximate to the shuttle stop located in Blue Lot. Pedestrians parking in Green Lot 2 and 3 and Red Lot 4 may also choose to use Old Ironsides Drive to access Tasman Drive, which is directly connected to Stadium entrances. The vast majority of sidewalks, curb ramps and other elements associate with Old Ironsides Drive are inaccessible, even though some show evidence of having been recently constructed. I understand through my review of discovery documents, including the deposition of Dennis Ng, that some elements I noted as inaccessible were recently constructed and would have been required to conform to the 2010 ADAS.
- All but one curb ramp associated with Old Ironsides Drive is not accessible. They are inaccessible for various reasons including due to excessive running slope, excessive slope at the gutter, have raised edges or wide gaps at the bottom where transitions are required to be flush, have sides that are too steep, and are not located correctly within crosswalk markings. Please refer to Exhibit H, Seq. #s.601-637 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.
- The sidewalks are characterized by long sections of steep running and cross slopes and raised vertical edges. Some portions of the sidewalks are constructed to meander

in elevation, sloping up an artificial and hill and down the other side. The hills are unnecessary because the street and properties along them are level. The artificial hills create excessive running slope and in some cases, excessive unprotected drop-offs at the side of the sidewalk.

78. **Marie DeBartolo Way from Tasman Drive to end.**

- Marie DeBartolo Way is a short roadway serving the east side of the Stadium. The street is not a necessary component in accessing the Stadium from any of the inspected parking lots because the entrances are located on the West side of the Stadium. There are only 5 elements associated with the street segment, but they have accessibility barriers including a curb ramp with an excessive side slope (Seq. #703), a second curb ramp with excessive running slope and gutter slope at the SW corner of Tasman Drive (Seq. # 227), and the south crosswalk of Tasman Drive, which has an excessive cross slope (Seq. # 228). All of these inaccessible elements show evidence of being recently constructed and are located along areas where streets appear to be recently re-paved and the ADA and CBC's alteration obligations would have required providing accessible elements attending the repaving activity. Please refer to Exhibit H for referenced Seq. #s indicating detailed findings, and Exhibit F for a graphical representation of these elements and their relationship to one another.

79. **Stars and Stripes Drive from Tasman Drive toward the Yellow Lots to end.**

- Stars and Stripes Drive collects patrons parking in the designated accessible parking spaces located at the northeast corner of Yellow Lot 1 (parking structure) and those patrons choosing to exit Yellow Lots 2 and 3 via the vehicular entrances at the north sides. Stars and Stripes Drive is also the only non-stair route between the Ace train stations located approximately 1,000 feet east of the Stadium under the Tasman over-crossing of Stars and Stripes Drive. There are also two designated accessible parking spaces located at this station. There are no accessible elements associated with Stars and Stripes Drive. Each sidewalk segment and curb ramp inspected, as

well as the designated accessible parking spaces located at the Ace station is inaccessible for various reasons.

- The parking spaces and access aisles have excessive slope.
- The curb ramps are inaccessible for a variety of reasons including due to excessive running slope, excessive gutter slope, steep side flares, and raised vertical edges at the bottom transition where it is required to be flush.
- The sidewalk segments are characterized by long stretches of excessive cross slope, excessive running slope, portions that are not a firm stable surface and one segment with high vertical edges. In addition, the required minimum width of several segments of sidewalk were potentially obstructed by vehicles in perpendicular and diagonal parking spaces along the street that are not provided with wheel stops to prevent pulling in too far and entering the sidewalk space.
- In addition, there are 81 such on-street marked parking spaces and none of them are designated as accessible.
- Please refer to Exhibit H, Seq. #s 801-813 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.

80. **Centennial Boulevard from Stars and Stripes Drive to Tasman Drive.**

- Centennial Boulevard is a short street connecting Stars and stripes Drive to Tasman Drive. All patrons parking in either Yellow Lot 2 or 3 must utilize either Stars and Strips Drive or Centennial Boulevard in order to access Tasman Drive, which in turn, connects to the Stadium. The pedestrian pathways that are apparently intended to serve as pedestrian routes connecting Yellow Lots 2 and 3 to the PROW are located on Centennial Boulevard (the potential pedestrian routes to Stars and Stripes Drive are vehicular drive entrances). Regardless of whether a patron parking in Yellow Lots 2 or 3 choose to access Stars and Stripes Drive or Centennial Boulevard, nearly every element that must be encountered using either choice is

inaccessible.

- Each sidewalk segment associated with Centennial Boulevard is inaccessible for various reasons including excessive cross slopes, raised vertical edges, and plants obstruct the required width at one segment. These barriers are made more difficult to overcome because in some cases they occur in conjunction with excessive running slope. The excessive running slope generally equals the running slope of the road.
- Please refer to Exhibit H, Seq. #s 901-904 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.

81. **Bunker Hill Lane from Patrick Henry Drive to Great America Parkway.**

- Bunker Hill Lane is a short street that can be utilized by patrons parking in Red Lot 3, 4 or 5 to connect to Great America Parkway, and in turn travel to Tasman Drive. The street is not provided with complete sidewalks on both sides. The sidewalk runs along only the south side of the street between Patrick Henry Drive and Old Ironsides Drive, which is a portion of the route that patrons parking in Red Lot 5 and 4 may choose to utilize, and then switches to only the north side of the street from this point east to Great America Parkway. Each element I inspected on Bunker Hill Lane is inaccessible to individuals with mobility disabilities. In addition, pedestrians heading east from Red Lot 4 or 5 to reach Great America Parkway must cross the street at Old Ironsides; however, there is no curb ramp with which to access the sidewalk at the north side of the street after doing so.
- The sidewalk segment west of Old Ironsides Drive is inaccessible due to excessive running slope. The sidewalk segment east of Old Ironsides Drive is inaccessible due to excessive running and cross slopes, a raised vertical edge and a large pothole.
- Please refer to Exhibit H, Seq. #s 1201-1204 for detailed findings by element and Exhibit F for a graphical representation of elements and their relationship to one another.

Accessible Shuttle Vehicles

82. I inspected one shuttle vehicle represented to be typical of shuttle vehicles in use. (VIN 1FDFE4FS4FDA03363, Ford Motor Co. equipped with Ford Shuttle Bus Prep Package). The shuttle I inspected is configured to carry 20 passengers. The vehicle provides a wheelchair lift and four seats that can be folded up to convert the seating capacity to 16 standard seated passengers and one seated in a wheelchair. At the time of the inspection, the shuttle displayed no markings associating it with either the Stadium or the City. It appeared to be a private shuttle suited for generic applications that serve groups comprising the general public, such as for the purpose of transporting passengers between a hotel and an airport, where the normal demographic imparts only occasional need for transport of persons using large mobility devices, and usually not more than one such individual per trip. It is not designed for, nor would it be effective at transporting a group of individuals with mobility disabilities, considering the typical distribution of mobility devices associated with such a specialized group, usually with more than one person using a large mobility device such as a wheelchair or scooter. For example, it would not be an effective mode of transport for such a group between remote parking lots and a Stadium entrance because many such vehicle trips would be necessary, either by way of engaging additional vehicles or by increasing the frequency of trips using fewer vehicles. Such specialized shuttles should have the ability to carry more than a single wheelchair at a time, ideally accommodating the expected number of large mobility devices in each group that is likely to gather in the time it takes for the next shuttle to arrive.

83. The shuttle vehicle I inspected could be modified to be more effective in this way. For example, additional spaces for mobility devices could be made available by allowing more standard seats to fold out of the way, and by installing additional safety restraint devices in these additional locations. The City or the Stadium could purchase their own shuttles for this purpose, as many public entities do, if leasing arrangements would otherwise stand in the way of making the modifications required for effectiveness.

Luxury Suites

84. I inspected all 168 luxury suites that were made available by Stadium representatives,

1 but only inspected a limited scope of elements within them. I understand that other experts serving
2 Plaintiffs' counsel inspected elements in all the suites that are outside the area of my specialized
3 scope on this project. I inspected doors, exterior spectator accessible seating and interior seating at
4 the window counter.

5 85. Most suites are similarly configured and equipped, with few that are larger or different.
6 Wheelchair spectator seating in each suite is essentially identical, only differing among suites by very
7 minor differences in as-built dimensions. All single suites provide a single exterior accessible seat --
8 larger suites provide two.

9 86. The Stadium has elected to provide a fixed seat that occupies each wheelchair accessible
10 seating location. During my inspection all but one accessible spectator seat was occupied by a
11 removable seat. I believe the heterodox vacancy to be a responsive to a request during the inspection.
12 This practice is allowed by regulations if the seat is removable. However, regulations state that the
13 seat may be brought in when it is determined that accessible seating is not required for an event. 28
14 CFR § 35.151 (g)(3) states in pertinent part:

15 "When wheelchair spaces and companion seats are not required to accommodate
16 persons eligible for those spaces and seats, individual, removable seats may be placed
17 in those spaces and seats"

18 87. In other words, the accessible seat is always available by default and the removable seat
19 is brought in when it is determined that it is appropriate for each event. It is the difference between a
20 passive and an active provision. The standards intend to ensure that the accessible seat is available by
21 default, only becoming unavailable (i.e., by placement of a removable seat) through a deliberate
22 action. The Stadium appears to practice just the opposite -- the accessible seat is always unavailable
23 and requires a deliberate action by staff in order to make it available.

24 88. The Stadium's apparent policy, procedure and practice of proving accessible seating in
25 this manner does not conform to regulations, in my opinion. It inherently induces a necessary delay
26 in the provision of accessible seating each and every time it is required. Because of the Stadium's
27 apparent practice, whether or not the removable seat is readily removable becomes important. I have
28

not conducted any research or testing to determine if the standard seat is readily removable. It is bolted down to the concrete surface and requires a wrench to remove. For this reason it would require Stadium personnel to remove the seat. A properly equipped technician should be able to remove the bolts for such a seat within a few minutes. In addition, each seat is equipped with wheels that could reduce the amount of time required to remove the chair once it is unfastened. However, the length of time required between a patron requesting removal of the seat and the arrival of a properly equipped technician to do so is very important to the determination of “readily removable,” and this is unknown. It is impractical to have the seat removed prior to an event in many cases because the owner of a suite may not have prior knowledge of the requirements of visitors to the suite during any particular event.

89. In addition to the excessive door force found in every luxury suite, every spectator wheelchair seat did not conform to standards in several ways. Each is of insufficient size, obstructs the exiting and general circulation routes for the remainder of spectators in the row, and is not provided with a companion seat in the correct location. I inspected the window counter dining seats and determined that they are not accessible because they are too high. I understand that the dining tables provided in all suites with the possible exception of two, are also too high to be accessible.

90. In addition to the apparent practice of providing removable seats, I identified other aspects that do not conform to accessibility standards applicable at the time of construction. Some aspects, such as excessive door force for example, can be attributed to a lack of maintenance. To be clear, standards and regulations explicitly apply to maintenance and require that accessible elements be maintained. Some aspects attributed to maintenance can have severe negative impacts on persons with disabilities. For example, every luxury suite door requires excessive force to operate. Although this can be caused by a lack of maintenance, its effect is realized through significant difficulty and potential injury for persons with mobility disabilities, for those who cannot physically apply sufficient force to operate the door or those who attempt to operate the door and are injured doing so. However, the vast majority of noncompliant aspects noted appear to be the result of incorrect design and/or construction and non-conformance with the accessibility standards that would have been

1 applicable to the design and construction of the facility.

2 91. New and existing facilities are treated differently in ADA regulations. New construction
3 carries the highest standard of care, with deviations from standards allowed only in those extremely
4 rare cases when doing so would be structural impracticable, such as “when the unique characteristics
5 of terrain prevent the incorporation of accessibility features “ (28 CFR § 35.151a(2)(i)). Barring the
6 relatively few cases where construction tolerances apply, there is no deviation from standards
7 allowed for new construction, to any degree. The Ninth Circuit Court of Appeals has made it clear
8 that even minor deviations with standards are violations resulting in the very discrimination that the
9 ADA intends to prevent (*Long v. Coast Resorts, Inc.*, attached as Exhibit J), states:

10 “In contrast to grandfathered facilities, the ADA requires that newly constructed
11 facilities be ‘readily accessible and usable by individuals with disabilities.’ 42 U.S.C. §
12 12183(a)(1). We need not decide whether the ADA forecloses the possibility that a
13 court might exercise its equitable discretion in fashioning relief for violations of §
14 12183(a), *see e.g., Tenn. Valley Auth. v. Hill*, 437 U.S. 153, 174 (1978), because there
15 is no room for discretion here even if it exists. This violation resulted in the very
16 discrimination the statute seeks to prevent: it denied individuals with disabilities access
17 to public accommodations.”

18 92. The deviations from standards I found negatively affect persons with mobility
19 disabilities. All deviations exclude a certain number of such persons that were intended to be
20 included by the DOJ when adopting the standards. Attached to this Declaration as Exhibit K is a true
21 and correct copy of my photographs referenced in my reports and findings.

22 93. **Luxury Suite Door Operating Force.** All 168 luxury suites I inspected have suite
23 entrance doors and doors to the exterior seating areas that require excessive force to operate (more
24 than 5 lbs. force). [28 CFR 35.130(a), ADAS 404.2.9 Item 1, CBC 11B-404.2.9].

25 94. **Luxury Suite Accessible Seating Size.** All 168 luxury suites I inspected have
26 accessible wheelchair seating areas at the exterior seating area that are not wide enough
27 (approximately 33” rather than 36” minimum). [ADAS 802.1.2, CBC 11B-802.1.2] Reference
28

1 example photograph JM_4118 of Exhibit K.

2 95. **Luxury Suite Accessible Seating and Circulation Routes.** All 168 luxury suites I
3 inspected have accessible wheelchair seating areas at the exterior seating area that obstruct general
4 circulation routes (platforms where wheelchair seating is located that is 61” to 63” long, where
5 standards require minimum 60” for the side access wheelchair seating area plus minimum 12” for the
6 aisle exiting width (72” minimum). The wheelchair locations are at the end of the row of seats.
7 Spectators in this row must cross the wheelchair accessible space in order to exit the row for any
8 reason [ADAS 802.1.5, CBC 11B-802.1.5]. Please reference example photograph JM_4120 of
9 Exhibit K.

10 96. **Luxury Suite Accessible Seating Shoulder Alignment of Companion Seat.** All 168
11 luxury suites I inspected have accessible wheelchair seating areas at the exterior seating area with
12 companion seats that do not provide shoulder alignment with the wheelchair space (the backrest of
13 the companion seat is located approximately 22.25” from the rear of the wheelchair space rather than
14 12”). [ADAS 802.3.1, CBC 11B-802.3.1]. Please reference example photographs JM_3427, 3428 &
15 3435 of Exhibit K.

16 97. **Window Dining and Work Surface.** All 168 luxury suites I inspected have at least
17 one section of counter at the window so that a spectator can utilize the counter for food and/or drink
18 while viewing the field of play while located within the interior of the suite. The counter is positioned
19 too high to serve as an accessible dining surface. Note, although two types of dining surfaces are
20 provided, both types are too high (Approximately 42” AFF rather than 34” maximum). [ADAS
21 902.3, CBC 11B-902.3]. Please reference example photograph JM_4516 of Exhibit K.

22 **Restrooms**

23 **Conclusions**

24 98. Many aspects of the restrooms I inspected do not conform to accessibility standards
25 applicable at the time of construction. Some aspects, such as excessive door force for example, can
26 be attributed to a lack of maintenance. ADA and CBC standards and regulations explicitly apply to
27 maintenance and require that accessible elements be maintained. Some aspects attributed to
28

1 maintenance can have severe negative impacts on persons with disabilities. For example, nearly
 2 every restroom entrance door requires excessive force to operate. Although this can be caused by a
 3 lack of maintenance, its effect is significant difficulty and potential injury for persons with mobility
 4 disabilities, for those who cannot physically apply sufficient force to operate the door or those who
 5 attempt to operate the door and are injured doing so. However, the vast majority of noncompliant
 6 aspects I noted with the Stadium's restrooms appear to be the result of incorrect design and/or
 7 construction and non-conformance with the accessibility standards that would have been applicable
 8 to the design and construction of the facility. The DOJ places an elevated standard of care for new
 9 construction, as opposed to the practice of removing barriers or providing program access within
 10 existing facilities. The Department has made it clear that deviations from new construction standards,
 11 regardless of the degree, when complying with requirements for new construction in the ADA,
 12 results in the "very discrimination the statute seeks to prevent: it denied individuals with disabilities
 13 access to public accommodations." (please refer to the previous section in this report regarding new
 14 construction deviations at Luxury Suites and Exhibit J "*Long v. Coast Resorts*").

15 99. The deviations from standards I found negatively affect persons with mobility
 16 disabilities. Many deviations are of a nature associated with an elevated incidence of injury for such
 17 persons, and all deviations exclude a certain number of such persons that were intended to be
 18 included by the DOJ when adopting the standards.

19 **Observations and Findings**

20 100. I inspected 90 restrooms in total in public areas, including 34 multiple accommodation
 21 Men's restrooms, 36 multiple accommodation Women's restrooms and 20 single accommodation All
 22 Gender restrooms. Many multiple accommodation restrooms are large and have more than a single
 23 entrance/exit door, accessible toilet compartment and semi-ambulatory toilet compartment. Attached
 24 to this Declaration as Exhibit L is a true and correct copy of my Restroom Barriers Matrix, a table
 25 with each restroom identified along the left side column and different types of barriers listed across
 26 the top row. Findings by restroom are found in Exhibit L, and example photographs are listed where
 27 necessary and may be referenced in Exhibit K.

101. **Restroom door force.**

- Out of 117 restroom entrance doors I inspected, 109 require excessive force to operate (average 8.7 lbs., up to 14 lbs., where 5 lbs. maximum is required).
- Door closers normally contribute the majority of the resistance to operation. A door closer is a mechanical device designed to close a door slowly but firmly enough to latch, when door hardware includes latches. It accomplishes this by using spring tension modulated by hydraulic fluid. As the user opens the door, hydraulic fluid passes from one reservoir to another. As the spring pushes the door closed again, the hydraulic fluid passes back to the previous reservoir through a series of valves that control the speed. Door closers have screw adjustments for controlling the speed of closure and usually for spring force. Door closers are made to be adjusted periodically. A properly functioning door closer controlling a properly functioning door can almost always be adjusted allowing operation by a user applying no more than 5 lbs. force.
- There are specialized cases where a door is required to close as part of a building's fire protection system (*i.e.*, a fire door) and is accompanied by unusual air pressure differentials that require greater force to positively latch the door. In these specific cases additional door force is allowed by standards, but this exception only applies to fire doors and is limited in extent to the minimum force actually required by the fire authority. None of the doors identified in this report as requiring excessive pressure to operate are fire doors.
- Lack of adjustment is not the only cause of doors that require excessive force to operate. Parts are subject to wear to the point that they do not operate as designed. Worn hinges, broken or leaking closer valves, and a number of other issues can be the cause for excessive door operation pressures. In these cases, the components can be easily replaced, allowing the door to operate without excessive force.
- The ADA and CBC require that accessible elements be maintained. Facilities can easily test and adjust door operating force and inspection for worn components by conducting

periodic inspections. In a facility such as the Stadium, where use by the public is event-based, with tens of thousands of members of the general public using the facility according to a predictable schedule, it would be simple to inspect and adjust door pressures in preparation for each such event. [28 CFR § 35.130(a), 2010 ADAS 404.2.9 Item 1, CBC 11B-404.2.9 Item 1 and 5].

102. Restroom Door Operation.

- Six restroom entrance doors I inspected do not open the required minimum of 90 degrees. This can be caused by incorrectly located door stops or incorrect closer adjustment, and can be remedied simply or avoided altogether [ADAS 404.2.3, CBC 11B-404.2.3]. Please reference example photograph JM_2436 of Exhibit K.

103. Restroom Door Maneuvering Clearance.

- Six restroom entrance doors I inspected do not provide required maneuvering clearance because of the placement of waste receptacles and large trash/recycling units. Standards and regulations prohibit a reduction in required accessibility, such as placing objects so that they obstruct required accessible clearances. In addition, distinct standards and regulations require the maintenance of accessible elements, including keeping the required clearances unobstructed. [28 CFR § 35.133, ADAS 404.2.4 *et seq*, CBC 11B-404.2.4 *et seq*.] Please reference example photographs JM_0291 & 0292 of Exhibit K.

104. Restroom Door Threshold Transition.

- Six restroom entrance doors I inspected have wide gaps at the threshold transitions (from 3/4" to 1 1/2" wide, averaging over 1 3/8" wide where 1/2" wide maximum is allowed). [1991 ADAS 2010 ADAS 2010 CBC]. Please reference example photographs JM_0118 and JM_0119 of Exhibit K.

105. Restroom Door ISA Signage.

- Seven restroom entrance doors I inspected are missing the required International Symbol of Accessibility (ISA) signage. Regulations and standards require that locations of accessible elements, such as restrooms, be identified so that they can be located by

those who require them. [28 CFR § 35.163(a)]. Please reference example photograph JM_0496 of Exhibit K.

106. **Restroom ISA Signage.**

- None of the 54 restrooms I inspected that provided overhead corridor signage directing patrons to the restroom provide ISA signage on the overhead restroom signage that would be visible from the vantage point of a person traveling along the corridors. [28 CFR § 35.163(a)] Reference example photograph JM_0495 of Exhibit K.

107. **Accessible Wheelchair Toilet Compartment Door Hardware.**

- At least one accessible wheelchair toilet compartment is required in each multi-accommodation restroom. Such a compartment is larger so that persons with mobility disabilities can maneuver to enter, use and exit the compartment and is equipped with grab bars and demonstrates other characteristics prescribed by standards to facilitate use by persons with mobility disabilities.
- In 55 accessible toilet compartments I inspected the compartment doors do not automatically close, as is required, and further, 37 of these 55 doors require the use of two hands simultaneously in order to latch the door in its closed position. ADA and CBC standards require accessible toilet compartment doors to automatically close and that hardware be operable with one hand without requiring tight grasping, pinching, twisting of the wrist, or force exceeding 5 lbs.
- The compartments are equipped with an “occupied” designator that actuates on spring pressure when the compartment door is physically pulled, or pushed closed by the user. Because the door only closes to the point that the spring begins to resist door movement, at this point requiring the user to pull or push the door against the resistance of the spring to its closed position, these doors do not close automatically as required by ADA and CBC standards.
- In addition, in the case of outward swinging compartment doors, it is not possible to both pull the door closed against the spring pressure and slide the latch closed in this

way using only one hand. This is because the slide latch control cannot be used to pull the door closed without the ability to pinch or tightly grasp the hardware. If instead the handle is used to pull the door closed against the pressure of the spring, the door is immediately pushed open by the spring before the user can reposition their hand from the handle to the slide latch in order to secure the door. [ADAS 309.4, 604.8.1.2, CBC 11B-309.4, 604.8.1.2]. Please reference example photographs JM-0031 & JM_0036 through 0038 of Exhibit K.

108. Accessible Wheelchair Toilet Compartment Door Hardware.

- The latches at 15 of the accessible toilet compartments I inspected require excessive force to operate (exceeding the required maximum of 5 lbs. force). All of these instances are a result of misaligned slide-type latches that by nature of design require significant force to overcome relatively small misalignments. The latches and doors can be periodically adjusted so that they conform to ADA and CBC standards, however the potential condition can be avoided altogether by utilizing a different type of latch, such as one utilizing a rotating lever handle, which allows for greater leverage and correspondingly greater latitude for misalignment. [ADAS 309.4, 604.8.1.2, CBC 11B-309.4, 604.8.1.2].

109. Accessible Ambulatory Toilet Compartment Door Hardware.

- In large multiple accommodation restrooms at least one toilet compartment is required, in addition to the accessible toilet compartment, that is designed for persons with mobility disabilities who are ambulatory or semi-ambulatory. Such compartments are slightly larger than standard compartments and have grab bars and demonstrate other specific aspects that facilitate use by such persons.
- All 47 ambulatory toilet compartments I inspected do not automatically close and further, require the use of two hands simultaneously in order to latch the door in its closed position. ADA and CBC standards require ambulatory accessible toilet compartment doors to automatically close and that hardware be operable with one hand

without requiring tight grasping, pinching, twisting of the wrist, or force exceeding 5 lbs.

- The compartments are equipped with an “occupied” designator that operates on spring pressure when the compartment door is physically pulled, or pushed closed. Because the doors only close to the point that the spring begins to resist door movement, requiring the user to pull or push the door to its closed position, these doors do not close automatically as required by ADA and CBC standards.
- In addition, in the case of outward swinging compartment doors, it is not possible to both pull the door closed against the spring pressure and slide the latch closed in this way using only one hand. This is because the slide latch control cannot be used to pull the door closed without the ability to pinch or tightly grasp the hardware. If instead the handle is used to pull the door closed against the pressure of the spring, the door is immediately pushed open by the spring before the user can reposition their hand from the handle to the slide latch in order to secure the door. [ADAS 309.4, 604.8.2.2, CBC 11B-309.4, 604.8.2.2] Please reference example photographs JM-0031 & JM_0036 through 0038 of Exhibit K.

110. Accessible Ambulatory Toilet Compartment Door Hardware.

- The latches at 12 ambulatory accessible toilet compartments I inspected require excessive force to operate (exceeding the required maximum of 5 lbs. force). All of these instances are a result of misaligned slide-type latches that by nature of design require significant force to overcome relatively small misalignments. The latches and doors can be periodically adjusted so that they conform to ADA and CBC standards, however the condition can be avoided by utilizing a different type of latch, such as those utilizing a rotating lever handle, which allows for greater leverage and corresponding greater latitude for misalignment. [ADAS 309.4, CBC 11B-309.4].

111. Slopes in the Maneuvering Clearance at Accessible Toilets.

- The clear maneuvering space associated with an accessible toilet is required to be level

because persons with mobility devices must be able to maneuver and transfer from their mobility device to the toilet seat without the mobility device rolling away or shifting suddenly, for example, when all four wheels of a wheelchair are not in contact with the floor. Inaccessible conditions associated with areas where such persons must transfer from their mobility devices to another surface, such as to a vehicle seat or toilet, are associated with an increased incidence of injury.

- The maneuvering clear space associated with 23 toilets I inspected have excessive floor slope within the areas that are required to be clear and level to accommodate safe transfer of a person from the seat of their mobility device to the toilet seat (from 2.5% to 7.7%, averaging 5.2% among toilet locations) where maximum slope of 2.1% is required). [ADAS 305.2, CBC 11B-305.2]. Please reference example photographs JM_2011 through 2013 of Exhibit K.

112. Accessible Toilet Seat Height.

- Accessible toilet seats are required to be within a specific height range in order to accommodate safe transfer from a wheelchair or other seated mobility device and for persons who are otherwise ambulatory but who cannot bend down to a low seat. As mentioned above, inaccessible conditions associated with transfer are associated with an increased incidence of injury.
- Four of the accessible toilets I inspected have seats that are too low (lower than the 17" minimum required by the ADA and CBC). This condition negatively affects both persons transferring from a mobility device equipped with a higher seat and those persons who cannot bend down to sit, or rise from a low seat. [ADAS 604.4, CBC 11B-604.4] Reference example photographs JM_2090 & 2091 of Exhibit K.

113. Accessible Toilet Position Relative to Side Wall.

- Accessible toilets are required by the ADA and CBC to be located within a specific distance range from the side wall where the grab bar is located so that a person who requires grab bars to transfer to the toilet can do so safely.

- Nine of the accessible toilets I inspected are located too far from the side wall where the grab bar is located (farther than the 18” maximum required). [ADAS 604.2, CBC 11B-604.2]. Please reference example photographs JM_2006 & 2007 of Exhibit K.

114. Toilet Paper Dispenser Location.

- Many persons with disabilities have limited reach range from a seated position, impaired trunk control necessary for correcting imbalance and/or have an impaired sense of balance. A person attempting to reach farther than this limit can cause such a person to suffer a stress injury or can cause him to contort to an unsteady position, with the potential to fall off of the seat. This is of particular concern for those individuals with an impaired sense of balance, or who cannot react quickly enough to correct an imbalance when detected. ADA and CBC standards require that toilet paper dispensers be located within a specific range relative to the front of the toilet in order to ensure that it can be used by such persons. Multiple dispensers are not required by standards but when multiple dispensers are provided, each dispenser must be located within the prescribed range.
- Fifty-eight of the accessible toilets I inspected have incorrectly located toilet paper dispenser(s) (less than or greater than the required 7” to 9” in front of the front of the toilet). [ADAS 604.7, CBC 11B-604.7]. Please reference example photographs JM_2508, 2509, 2537 & 2538 of Exhibit K.

115. Baby Changing Table Located Incorrectly.

- I inspected 70 wheelchair accessible toilet compartments. Twenty-eight of those contain a baby changing table that is located in such a way that when deployed, prevents the toilet compartment door from opening wide enough for wheelchair passage. This means that if the changing table is in the deployed position within the compartment, a person who requires the compartment door to open fully in order to enter, such as a person using a wheelchair, will not be able to enter the compartment. The person will not be able to raise the table because he cannot enter the compartment to do so. Under

these circumstances the accessible toilet compartment would not be available for the use for an individual with a mobility disability. [ADAS 404.2, 604.8.1.2, CBC 11B- 404.2, 604.8.1.2]. Please reference example photographs JM_3408 & 3409 of Exhibit K.

116. Obstructed Accessible Portion of Lavatory Mirror.

- ADA and CBC standards require that the reflective portion of mirrors in lavatories be placed low enough so that they are usable for a person seated at wheelchair height. In six restrooms I inspected, the lavatory mirrors have a LCD screen that is low enough to allow use of the mirror for the general public but its low position obstructs the mirror portion at the prescribed heights for wheelchair accessibility, preventing its effective use by many persons with disabilities, such as persons seated in wheelchairs or of short stature. [28 CFR 35.130(a) & (b)(1)(ii), ADAS 603.3, CBC 11B-603.3]. Please reference example photographs JM_2407 & 2408 of Exhibit K.

117. Urinal Flush Valve Height.

- ADA and CBC standards prescribe a maximum height of controls for urinal flush valves so that persons with mobility disabilities can reach them. The urinal flush valves at the Stadium are the automatic sensor type; however, they are equipped with a manual flush actuator for use when the sensor does not operate correctly.
- All of the 32 restrooms I inspected that are equipped with urinals have flush valve controls that are located too high (approximately 48" AFF rather than 44" AFF maximum). [ADAS 308.3.2, CBC 11B-605.4]. Please reference example photographs JM_2539 & 2540 of Exhibit K.

118. Knee Clearance at Baby Changing Tables.

- ADA and CBC standards require knee and toe clearances at baby changing tables so that persons seated in wheelchairs can utilize the work surface while facing forward.
- Fourteen of the restrooms I inspected have baby changing tables mounted too low so that they do not provide adequate knee clearance (less than the minimum 27" height required). [ADAS 306.3.3, 902.2, CBC 11B-306.3.3 Ex. 2, 902.2]. Please reference

example photographs JM_3141 & 3142 of Exhibit K.

119. Drinking Fountain Knee Clearance.

- ADA and CBC standards require both high drinking fountains, for persons who have difficulty bending or stooping; and low drinking fountains, for persons using mobility devices. ADA and CBC standards also require knee and toe clearance at low position drinking fountains so that a person seated in a wheelchair, for example, can address the fountain facing forward.
- 10 of the low drinking fountains I inspected that are required to be accessible to persons using wheelchairs lack sufficient knee clearance (less than the 27” minimum required). These are located at or near rooms 3.96.03, 03.43.02, 03.57.02, 04.43.01, 05.76.06, 05.22.02, 04.02.01, 05.55.03, 06.55.03, and 07.53.03. [ADAS 306.3.3, 602.2, CBC 11B-306.3.3, 602.2]. Please reference example photographs JM_0255 & 0258 of Exhibit K.

120. Drinking Fountain Stream Height.

- ADA and CBC standards require drinking fountain stream height to be high enough to insert a cup for drinking. This is primarily so that a person who cannot position their mouth to the stream can instead use an intermediary cup for drinking.
- Two drinking fountains I inspected do not provide a high enough stream of water to facilitate drinking from a cup (less than the 4” height required). These are located at or near rooms 05.22.02 and 4.02.01. [ADAS 602.6, CBC 11B-602.6]. Please reference example photographs JM_2475 & 2477 of Exhibit K.

121. Provision of Ambulatory Toilet Compartment.

- Restroom 07.20.01 does not provide an accessible ambulatory toilet compartment, although it is required to provide one (20 sanitary fixtures are provided in the restroom with no ambulatory toilet compartment provided. At least one ambulatory toilet compartment is required when there are more than 5 such fixtures provided in a restroom). [ADAS 213.3.1, CBC 11B-213.3.1].

122. **Urinal Height.**

- The accessible urinal at Restroom 03.74.02 is mounted too high (17.5” AFF to rim rather than 17” AFF maximum. [ADAS 605.2, CBC 11B-605.2]. Please reference photograph JM_0132 of Exhibit K.

123. **Restroom Dispenser Clearance.**

- ADA and CBC standards require additional width in alcoves where persons with mobility disabilities must reach controls. The women’s product dispenser in Women’s restrooms 04.57.01 and 04.44.01 is located in such an alcove but is not provided with adequate accessible clearances (in this case, a clear space that is less than 36” wide when the depth of the alcove exceeds 24”). [ADAS 305.7.1, CBC 11B-305.7.1]. Please reference example photographs JM_2066 through 2068 & 2070 of Exhibit K.

124. **Toilet Maneuvering Clearance.**

- Four accessible toilet compartments are not wide enough because baby changing tables are mounted within the compartment on the side wall (from 57.25” to 58” clear rather than 60” minimum clear at Men’s restroom at NRG Terrace, Men’s and Women’s at Mellon Club West, and restroom 03.43.02). [ADAS 305.2, CBC 11B-305.2]. Please reference example photograph JM_5861 of Exhibit K.

125. **Lavatory Clearance**

- In an all-gender restroom located in the United Club (Level 300, location 03.47.04), the lavatory knee and toe clearance is obstructed by permanently-mounted pull-out steps. The restroom is identified by an accessible symbol and the lavatory is required to be accessible. The steps obstruct the accessible knee and toe clearance at the lavatory as well as the required clearance at the toilet. [ADAS 306.2, 306.3 and 604.8.1.1, CBC 11B-306.2, 306.3, and 604.8.1.1]. Please reference example photographs JM_2020 through JM_2024 of Exhibit K.

//

//

Other Stadium Areas

NRG Solar Terrace

- **Integration of Patrons at Lowered Wheelchair Height Bar Seating.** There are two exterior bars with dual video monitors, each with both standing height seating and lowered bar for wheelchair height seating. However, the wheelchair height seating is segregated to the side and with only oblique views to either video monitor, whereas the general public utilizing the standing bar may interact among themselves and are directly in front of at least one of the video monitors. [28 CFR 35.130(a) & (b)(1)(ii) & (b)(1)(iv)]. Please reference photographs JM_5840, 5844, 5845, 5850 & 5851 of Exhibit K.
- **Dining Tables.** None of the tables on the Terrace provide an accessible dining surface because they are too high (approximately 42” AFF rather than 34” maximum) and required knee and toe clearance is obstructed by the table base. [ADAS 902.3, CBC 11B-902.3]. Please reference photographs JM_5847 & 5848 of Exhibit K.

BNY Mellon Club West

126. Access to Club Level.

- The accessible access routes to the Club level are not aligned with the routes for the general public, as is required by ADA and CBC standards. In addition, the accessible routes cannot be readily discerned, are not equivalent in quality, and are not as safe as the routes for the general public.
- The general public accesses the Club level via a stair or escalator in a formal open grand two-story space that leads directly to the reception counter. The only elevators serving the Club, located some distance to the South and North from this space, are accessed via a route completely hidden by heavy opaque black curtains, and require traveling along “back of house” corridors frequented by vehicular traffic.
- ADA and CBC standards require identification of at least one accessible route to an elevator, and signage directing to at least one accessible elevator is required at the area

of the stair and escalator. The elevator routes to the Club are not identified in any way. In addition, the Club reception area with heavy black curtains at each side interrupts the main service corridor that circumnavigates the Stadium at the 100 level. The facility provides a bypass tunnel at the Club Lobby that allows service activities and vehicles to operate without passing through the Club Lobby. The bypass tunnel does not extend far enough to the North and/or the South in order to bypass the accessible routes to either elevator, which are located farther to the North and South than the curtains at either side of the Club Lobby. A person utilizing the accessible route must pass through either black curtain, North or South, and continue along the service corridor frequented by vehicular traffic. Moreover, there are no surface markings segregating vehicular traffic from pedestrian routes. As such, a person using an accessible route to travel to and from the Club is exposed to the potential hazard of injury due to vehicular traffic. [28 CFR 35.130(a), (b)(1)(ii) & (b)(1)(iv), ADAS 206.3, CBC 11B-206.3]. Please reference photographs JM_5824 through 5831 of Exhibit K.

127. **Reception Counter.** The reception counter is too high (42" AFF rather than 36" AFF maximum). [ADAS 904.4.1, CBC 11B-904.4.1]. Please reference photographs JM_5821 through 5823 of Exhibit K.

128. **Exterior Patio at Fifty Yard Line Field Level.** The exterior patio is not accessible to individuals with mobility disabilities due to the following aspects:

- Item 4.04 a: The three pairs of glass doors leading to the exterior area require excessive force to operate (8 lbs. force rather than 5 lbs. force maximum). [28 CFR § 35.130(a), CBC 11B-404.2.9 Item 1 and 5]. Please reference photograph JM_5803 of Exhibit K.
- Item 4.04 b: Four dining tables are provided. Accordingly, at least one needs to be accessible to individuals with mobility disabilities. However each is too high to be accessible (42" AFF to table top, rather than 34" maximum). In addition, the required toe space at each table is obstructed by the table base. Finally, the tables are not located so as to provide a level accessible clear space (2.9% slope rather than 2.1% maximum)

[ADAS 902.2 & 902.3, CBC 11B-902.2 & 902.3.] Please refer to photographs JM_5805 through 5812 of Exhibit K.

- Item 4.04 c: The area of the exterior patio offering full view of the field of play slopes too steeply to offer an accessible clear space for viewing (2.9% slope rather than 2.1% maximum). There is a level portion of the patio offering accessible clear space; however, this area offers a lesser view of the field of play. A person viewing the field from the sloping portion of the exterior patio is able to view 100% of the field of play, whereas a person viewing from the level portion can only view approximately 70% of the field of play. [28 CFR 35.130(a), (b)(1)(ii) & (b)(1)(iv), ADAS 305.2, CBC 11B-305.2.]. Please refer to photographs JM_5813 through 5820 of Exhibit K.

Other Areas

129. Interior Ramps at Level 400 Yahoo! Club Connecting Upper and Lower Levels.

- South side of Club – the ramp is missing edge protection at the top approximate 2’ long portion and bottom approximate 8’ long portion, and a portion of the ramp running slope measures up to 8.6%. [ADAS 405.2 & 405.9, CBC 11B-405.2 & 405.9]. Please reference photographs JM_3163 through 3166 of Exhibit K.
- North side of club – The ramp is missing edge protection at the top approximate 2’ long portion and bottom approximate 8’ long portion, and a portion of the ramp running slope measures up to 8.5%. [ADAS 405.2 & 405.9, CBC 11B-405.2 & 405.9]. Please reference photograph JM_3167 through 3170 of Exhibit K.

130. General Portable Companion Seating Equivalency. The facility utilizes portable companion seats. ADA and CBC standards require that portable companion seats be of the same quality and have similar amenities as the permanent seats utilized for the general public. Almost all of the portable seats I observed lacked folding armrests with cup holders, although these are provided on permanent seats. [ADAS 802.3.2, CBC 11B-802.3.2]. Please reference example photographs: JM_2276 & 2277 of Exhibit K.

//

131. **United Club Accessible Table Knee Clearance.** The accessible tables provided at the United Club do not provide required knee clearance (26.5” high rather than 27” minimum). [ADAS 902.2, CBC 11B-902.2]. Please reference photographs JM_3159 through 3161 of Exhibit K.

132. **United Club Cup Dispenser Reach Range.** There are multiple countertop cup dispensers. Each has four openings for cups arranged vertically. The top two are beyond accessible reach range (up to 62” AFF rather than 48” AFF maximum). In addition, the operating mechanisms on the ice tea dispensers are beyond accessible reach range (49 1/2” AFF rather than 48” AFF maximum). [ADAS 308.2.1 & 308.3.1, CBC 11B-308.2.1 & 308.3.1]. Please reference photographs JM_0447 through 0450, 0453 & 0454 of Exhibit K.

133. **United Club Recycle Containers Reach Range.** There are multiple waste receptacles with two openings: one for recycling and the other for trash. The recycling opening is beyond accessible reach range. (12.5” lateral reach over obstruction that is 43” high, rather than 10” maximum lateral reach over an obstruction, or 24” maximum lateral reach over an obstruction that is 34” high maximum). [ADAS 308.3.2, CBC 11B-308.3.2]. Please reference photographs JM_0456, 0457, 0459 & 0460 of Exhibit K.

Luxury Suite Accessible Sightlines

134. This report evaluates the viewing conditions of the field of play from 168 luxury suites located on several levels and distributed around the perimeter of the field. Within each suite, this report evaluates angles for spectators both seated in designated accessible suite seating positions and when seated at the window dining counters. The Stadium appears to be laid out with the seats staggered in each successive row, allowing spectators to view the field of play between the heads and above the shoulders of spectators seated in the row in front of them (rather than having seats aligned in successive rows, requiring spectators to view the field of play above the heads of spectators in front of them).

135. The 2010 ADA Standards require lines of sight at wheelchair spaces for this staggered seat arrangement. Section 802.2.2.2, “Lines of Sight Between Heads” states:

Where standing spectators are provided lines of sight over the shoulders and between

the heads of spectators standing in the first row in front of their seats, spectators seated in wheelchair spaces shall be afforded lines of sight over the shoulders and between the heads of standing spectators in the first row in front of wheelchair spaces.

This provision applies to the designated accessible wheelchair seat(s) and is intended to express the overarching provision for “equality of benefit” found in the regulations effectuating the ADA, as the provision applies to meaningful spectator viewing; essentially, the provision seeks to ensure meaningful views in these settings without requiring that the spectator with a disability have the ability to stand.

136. In addition to the designated wheelchair seating locations, each of the 168 luxury suites I inspected contains at least one “window counter” - a counter dining surface located at the window for the purpose of viewing the field of play while dining. This position offers a distinct spectator benefit and although no specific standards require accessible sight lines from these positions, they are covered by the regulations effectuating the ADA for general prohibitions against discrimination and those ensuring accessibility of new construction found at 28 CFR § 35, as follows:

- 35.130 General prohibitions against discrimination. (b)(1) A public entity, in providing any aid, benefit, or service, may not, directly or through contractual, licensing, or other arrangements, on the basis of disability (ii) Afford a qualified individual with a disability an opportunity to participate in or benefit from the aid, benefit, or service that is not equal to that afforded others;
- 35.151 New construction and alterations. (a) Design and construction. (1) Each facility or part of a facility constructed by, on behalf of, or for the use of a public entity shall be designed and constructed in such manner that the facility or part of the facility is readily accessible to and usable by individuals with disabilities, if the construction was commenced after January 26, 1992.

137. Although no specific standards apply, the United States Department of Justice (DOJ) and the Ninth Circuit Court of Appeals have made it clear that public entities must ensure that newly constructed facilities and elements are accessible even in the absence of specific standards. (*Fortyune*

1 v. *City of Lomita*, attached as Exhibit M).

2 138. The *Fortyune* decision is consistent with assistance materials offered by the DOJ. The
3 DOJ issues a Technical Assistance Manual (“TA Manual”) to assist individuals and entities to
4 understand their obligations under the ADA. In a 1994 supplement to the TA Manual, the DOJ
5 offered the following guidance on complying with 28 C.F.R. § 35.151 when applicable federal
6 standards did not contain specifications for a type of feature or facility:

7 In such cases the technical requirements of the chosen standard should be applied to the
8 extent possible. If no standard exists for particular features, those features need not
9 comply with a particular design standard. However, the facility must still be designed
10 and operated to meet other title II requirements, including program accessibility.”

11 139. Therefore I evaluated the “window counter” seating locations with regard to
12 accessibility, specifically, whether any portion of these counters provided a view of the field for
13 persons with disabilities.

14 140. In evaluating sight lines for these two elements in this report, I used two
15 anthropometrical units: standing shoulder height and eye height of an individual seated in a
16 wheelchair. Shoulder height is defined as “The vertical distance from the floor to the tip (acromion)
17 of the shoulder, when standing.”

18 141. For the purposes of evaluating spectator view angles in this matter, I utilized the
19 commonly accepted wheelchair eye height ranges as well as the specific measurements for eye height
20 and shoulder height set forth in “Exhibit B” of the Consent Order in *USA v. Ellerbe Becket*, March 4,
21 1998 (Exhibit N of this report). The Order defines specific relationships to be used by the defendant
22 when designing accessible seating in stadiums. “Exhibit B” states:

23 The average anthropometric dimensions employed shall be: (1) average eye height for a
24 person sitting in a wheelchair is 47.45"; (2) horizontal distance from the eye of an
25 average person sitting in a wheelchair to the edge of the tier on which the wheelchair
26 rests is 30"; (3) average head height of a standing spectator is 67.65"; (4) average eye
27 height of a standing spectator is 63.45"; and (5) average shoulder height of a standing
28

1 spectator is 55.65".

2 142. For the purpose of evaluating the sightlines at the Stadium, shoulder heights are used
3 because the seats are staggered from row to row affording views between the heads and above the
4 shoulders of spectators in front.

5 143. The metrics set forth in the above-cited Order do not represent the range of individual
6 shoulder and eye heights that can be expected among spectators, but rather rely upon simplified
7 single measurements apparently corresponding to the mean. As a result, relying on such simplified
8 average dimensions will necessarily exclude a certain number of spectators with disabilities from
9 viewing the field of play as the standards intended.

10 144. Anthropometrics commonly used for eye heights of individuals seated in wheelchairs
11 and shoulder heights of standing individuals vary among sources but always include a range.
12 Designers typically practice inclusive design by accommodating the full range, or the majority of the
13 range, represented by individuals, for example, by using the range representing 90% of individuals
14 (*i.e.*, from the 5th percentile to 95th percentile). Shoulder heights from the International Encyclopedia
15 of Ergonomics and Human Factors, Second Edition, range from 48.86" (5th percentile female) to
16 60.86" (95th percentile male) with the male mean (*i.e.*, average) at 56.81" and the female mean at
17 52.52".

18 145. Because the eye and shoulder heights given in the Order represent average values, by
19 definition, the designer relying upon it can expect to exclude a significant number of spectators
20 seated in wheelchairs from being afforded the views prescribed by standards. For example, the Order
21 sets the shoulder height higher than the average female and lower than the average male, generally
22 affording view angles for at least 50% of spectators in the former case -when seated behind standing
23 females; and for less than 50% of individuals in the latter case -when seated behind males. As such,
24 mere conformance with the measurements set forth in the Order is not expected to afford the intended
25 level of access, and therefore should not be considered a measure of success in fulfilling the
26 obligation. As such, nonconformance with these measurements signifies a definitive lack of intended
27 access.

146. In order to accurately represent the view angles afforded spectators seated in wheelchairs in the luxury suites, it was necessary to inspect each and every such suite, as the viewing angles vary based on elevation and position relative to the field. This variance reaches favorable and unfavorable extremes at certain points relative to the field. As such, the full the range of available views can be represented by the photographs of sightlines in the relatively few suites where such extremes occur.

147. I photographed views from wheelchair seating locations at these suites where the shoulder height of standing spectators in the row immediately in front is 55.65", as viewed from the vantage point of a person seated in a wheelchair with an eye height of 47.45". Both of these heights correspond to heights set forth by the Order. In addition, I recorded photographically the views from an eye height of 43" and of 52", which correspond to the range of heights found to be common among guidance materials. Finally, for reference, I recorded photographically the views from the vantage point of a standing spectator in the same location.

148. Luxury Suite Accessible Seating View of Field.

- The general seating at the exterior luxury suite seating provides views of the field between heads and over the shoulders of spectators. As such, ADA and CBC standards require the same view of the field from the accessible wheelchair seating area when spectators are standing. Of the 168 luxury suites I inspected, 165 do not provide accessible sightlines of the field of play when spectators are standing. A spectator seated in the accessible seating area in one of these 165 suites, who cannot stand, can view from 0% to approximately 15% of the field of play under such circumstances, depending on the particular suite, whereas a spectator who can stand can view 100% of the field of play under the same circumstances. [ADAS 802.2.2.2, CBC 11B- 802.2.2.2]. Attached to this Declaration as Exhibit O are true and correct copies of my sightline photographs that depict views over the shoulder of standing spectators from the wheelchair seat in a typical suite. Attached to this Declaration as Exhibit P are true and correct copies of my photographs that depict similar views in a

suite with the most favorable sightlines.

149. Luxury Suite View of Field from Window Dining Counter.

- All 168 luxury suites I inspected have at least one section of counter at the window so that a spectator can utilize the counter for food and/or drink while viewing the field of play while located within the interior of the suite. The windows in front of counters can be retracted entirely out of the way. However, regardless of window position, no window counter position in any suite provides a wheelchair user, or a person with similar eye level, a view of any part of the field when spectators are seated in the first row of seating in front of the counter. A person who is standing may view 100% of the field of view from the counter under the same conditions. [28 CFR§ 35.130(a) & (b)(1)(i) & (b)(1)(ii)]. Attached to this Declaration as Exhibit Q are true and correct copies of my sightline photographs depicting views from the window counter over the shoulders of seated spectators with windows closed. Attached to this Declaration as Exhibit R are true and correct copies of my sightline photographs that depict similar views with the windows open.

150. I was asked to inspect specific portions of the facility and elements associated with accessing the facility including parking, the accessible shuttle service and the public right of way system of sidewalks curb ramps and street crossings necessary to access Stadium entrances; as well as elements required to be accessible that are located inside the stadium, such as restrooms and portions of luxury suites. My inspections were comprehensive and thorough. I covered 13 City owned and ticketed parking lots offering over 17,000 parking spaces for Stadium patrons and an exemplary accessible shuttle vehicle used to transport persons with disabilities , and I inspected over ten miles of actual length of sidewalks and street crossings, comprising over 100 curb ramps.

151. Inside the stadium I inspected 90 public restrooms and 168 Luxury Suites, as well as other portions of the facility such as aspects of the large BNY Mellon Club West, located at field level at the 50 yard line, the large United and Yahoo club suites located at the 300 and 400 levels and the NRG solar terrace. I understand that other experts have inspected distinct specific portions of the

1 Stadium, and when taken together, the corporate scope of our respective inspections in the public
2 areas of the Stadium are comprehensive.

3 152. In my expert opinion, the vast majority of persons with disabilities attempting to
4 travel to the Stadium by vehicle or as pedestrians will encounter significant barriers to access. I found
5 that parking is inadequate and not accessible, the accessible shuttle appears to be an ineffective
6 method of accessing the Stadium and there are no accessible routes in the public right of way
7 between any remote parking lot and Stadium entrances.

8 153. I found significant and pervasive barriers to accessibility in areas that I inspected
9 associated with use of elements located inside the Stadium. I found that there are barriers to
10 accessibility associated with every restroom I inspected, and with the entry and use of every luxury
11 suite I inspected. In addition, many of the elements I inspected in the large suites (BNY Mellon,
12 United and Yahoo suites) and the NRG Terrace are not accessible.

13 154. The barriers I identified for persons accessing and using the Stadium exclude
14 persons with mobility disabilities who are intended to be included by the enforcing agencies who
15 adopt standards for accessibility to ensure that facilities and programs are accessible to and usable by
16 persons with disabilities. Others with mobility disabilities may nevertheless attempt to use the
17 facilities out of necessity, but in doing so may encounter difficulty and fatigue, endure delays and
18 complications, and are often subjected to an elevated and unreasonable risk of injury. Many of the
19 barriers I identified are of the types that are associated with an increased potential for injury for such
20 persons.

21 155. Many of the barriers I identified both inside and outside the stadium are not merely
22 the result of a lack of maintenance, rather, they do not conform to standards that were in effect at the
23 time of their design and construction and were therefore apparently caused by faulty design and/or
24 construction. For example, I reviewed standard drawings purportedly employed by the City of Santa
25 Clara to direct the design and construction of curb ramps that if used, would actually direct a builder
26 following the standard drawings to construct noncompliant curb ramps. Indeed, many of the barriers I
27 found associated with recently constructed curb ramps in areas I inspected demonstrate these design
28

1 deficiencies, abundantly realized in concrete in areas of the public right of way.

2 156. In addition, I reviewed the plans for the construction of the Stadium and noted that
3 construction details directed the builder to build elements that did not conform to applicable
4 standards. For example, construction documents indicating the position of accessories at toilets that
5 are required to be accessible indicate outdated and incorrect dimensions. I found that the majority of
6 these accessories I inspected are indeed located incorrectly. The drawings indicating the size and
7 configuration of accessible wheelchair spectator seating is likewise outdated and incorrect, and does
8 not conform to applicable standards.

9 157. I found that the accessible spectator seating in each of the 168 luxury suites do not
10 conform to standards in several respects. They are not wide enough, are positioned incorrectly and
11 are not provided with a companion seat in the correct location. In addition, sightlines of the field of
12 play from the designated accessible spectator seats in fully 165 of the 168 suites inspected do not
13 conform to standards. Where the general public enjoys full views of the field of play under all
14 conditions, including when spectators in front of their seats are standing, those viewing the field from
15 the accessible seating locations who cannot rise from their seats have only a limited view of the field
16 of play when spectators are standing. Standards explicitly require equity in sightlines in these specific
17 conditions.

18
19 I declare under the penalty of perjury under the laws of the United States that the foregoing
20 is true and correct. Executed on April 6, 2018 in Provincia de Manabi, Ecuador

21
22 

23 Jeffrey Scott Mastin
24
25
26
27
28

EXHIBIT A

Jeff Mastin

Accessibility Expert

Facility Access Consulting, Inc., Carlsbad, California

jmastin@fac-ca.com • 949-439-5095

Experienced and highly knowledgeable expert on federal and various state accessibility regulation and interpretation. Highly regarded as an expert for both Plaintiff and Defendant, dedicated to unbiased interpretation of accessibility standards.

Credentials/Education

- Architect, California License C-25681
- California Certified Access Specialist (CASP) #088
- Bachelor of Science, Architecture - California Polytechnic State University, San Luis Obispo
- Division of the State Architect (DSA) Subject Matter Expert (SME) for the California State Certified Accessibility Specialist (CASP) exam.

Employment History

- Current Principal/President, Facility Access Consulting, Inc., 2004-present
- Partner, Architerra Architects, 2006-2009
- Project Architect, Carter & Burgess 1998-2006
- Project Architect/Project Manager, Pitman Group Architects, 1994-1998
- Construction Manager, Pacific Newspaper Services, 1991-1994
- Architect Intern, Andrews Rothenburger Architects 1987-1991

General Experience

- Twenty-three (23) years in architectural design
- Twenty-four (24) years leading teams
- Eighteen (18) years specializing in disabled accessibility
- Three (3) years in construction management
- Current Principal/President, Facility Access Consulting, Inc.

Accessibility Expert Witness Services

Qualified in federal and California courts to provide expert opinion in areas including architecture, construction, disability access, program access, the preparation and implementation of an ADA transition plan, policies procedures and practices regarding disability access barriers, and barrier removal.

Served as expert witness for either plaintiff or defense counsel, in excess of one hundred cases. Subject facilities include a wide variety of privately and publicly funded public accommodations such as:

- Assembly, including stadiums;
- Civic facilities, including courthouses, health services, libraries, parks and recreation, etc.;
- Public pedestrian rights of way
- Education, including K-12, Community College, and University,
- Entertainment, including theaters and movie studios;
- Hospitality;
- Housing, public and private;
- Medical, including hospitals and health care facilities;
- Retail;
- Transportation facilities, including rolling stock.

Selection of Accessibility Experience

- Indian Wells Tennis Garden** 2015-2017
 Provided access compliance assessment and recommendations for remediation for the 54 acre tennis campus including two stadiums, and extensive temporary facilities provided for the annual BNP Paribas Open, with a two week attendance of over 400,000.
- Panda Express** 2014-present
 Provided access compliance assessment and recommendations for remediation for 100 food service facilities in California. Served as expert witness in litigation matters.
- University of California Irvine Medical Center** 2008 -present
 Provided/providing access compliance assessment and recommendations for remediation for the medical campus and off-campus facilities. Provided/providing plan review and plan check, accessibility consulting, and employee training. Plan review services include the 500,000 sf Douglas Hospital. Campus assessment includes 25 buildings comprising 1.4 million sf., the 39 acre site, and parking facilities. Training includes various staff seminars and regular meetings to advise staff.
- Westfield, LLP** 2010-present
 Provided access compliance assessments for multiple retail mall facilities in California, Oregon, New Jersey, New York and Washington, which included recommendations and detailed design. Provided services in support of settlement negotiations for several properties that were the subjects of litigation. Provided/providing plan review. Currently assisting design staff with accessible design.
- University of California San Diego** 2015-present
 Served on design team as accessibility consultant for Blake and Warren student hall renovations.
- Due Diligence Services** 2015-present
 Routinely serve on Due Diligence teams as an accessibility expert, evaluating potential property acquisitions. Clients include the University of California San Diego and private developers.
- Accessibility Expert for Court Appointed Monitor** 2010-2015
 Provided accessibility services in support of the Monitor in Pierce v County of Orange. Assisted in ensuring compliance with the Court-ordered plan of remediation at five Orange County Jail facilities. Worked with all parties to develop innovative solutions that satisfied security/safety concerns, yet were aligned with intent of the Order.
- Division of the State Architect (DSA), Accessibility Consultant** 2010-2011
 Served as field accessibility consultant and architect for fast track modernization barrier removal at 12 K-12 facilities. Identified barriers, designed remediation and closed out contractor work.
- Macy's Nationwide, Accessibility Survey** 2008-2009
 Developed state-specific criteria for use in facility evaluations. Trained and supported dozens of surveyors performing access compliance inspections for over 700 facilities nationwide. Assisted in developing tablet-based survey tools. Directed and was responsible for quality assurance and recommending remediation for each of over 700 assessments.
- San Francisco Unified School District** 2007-2009
 Provided various accessibility surveys, assessments, plan reviews, scope analysis and code interpretation regarding existing and proposed SFUSD facilities for Plaintiff's counsel under a class action stipulated judgment.
- Division of the State Architect (DSA), Contract Plan Reviewer** 2005-2009
 Provided access compliance plan reviews on a regular basis for public school projects as a contract consultant to DSA. Included working with applicants through back-check and approval.

- Hotel Portofino, Redondo Beach, CA, Accessibility Expert** 2008 to present
Initially served as accessibility expert during litigation. Later provided access compliance assessment and recommendations for remediation for the facility, including on-site marina and conference centers. Provided expert witness services in accessibility, architecture and construction.
- Santa Rosa Junior College, ADA Title II Assessment** 2007-2008
Principal/Project Manager for survey of Santa Rosa, California campus. Provided recommendations and costs for remediation. Conducted seminar and training for administrators and staff in how to better meet their obligations. Developed an SQL database system for managing the detailed information.
- Los Angeles Unified School District, Accessibility Consultant** 2007-2008
Provided accessibility consulting for the District during performance of a Modified Consent Decree, including interpreting standards on behalf of LAUSD at meetings with the Court-appointed Monitor.
- City College of San Francisco, Accessibility Path of Travel Assessment** 2006-2008
Surveyed and provided recommendations for campus-wide circulation system strategy to be implemented under a consent decree. Developed and presented options that ensured adequate accessibility while minimizing waste (service provided as consultant to Architerra, LLP, Court appointed expert, agreed to by both parties).
- YUM! Brands Nationwide, Accessibility Survey and Assessment** 2005-2006
Provided access compliance assessments and recommendations for remediation for 107 food service facilities nationwide.
- Staples Statewide, Accessibility Survey and Assessment** 2006
Provided access compliance assessments and recommendations for remediation for 55 retail stores and associated facilities in California.
- Orange County Justice Centers, Project Manager/Designer** 2003-2005
Project Manager/Designer for the renovation of three Orange County, CA courthouses to remove ADA barriers to public access. Balanced user requirements for function and County concerns for cost and schedule. Developed innovative solutions to remove barriers in fifty courtrooms while preserving the unique character of each facility and successfully working within the unique and sensitive political landscape inherent to the justice center environment.
- The Depot at Santa Ana, Assessment and Recommendation Study** 2005
Prepared assessment and recommendation study for the 40,000 sf multi-use transportation station. Researched and identified the deficiencies of the facility in implementing Client program. Provided recommendations and concept plan. Provided comprehensive accessibility assessment with remediation recommendations and costs.
- State of California Developmental Centers, ADA Surveys** 2001-2004
Project Architect and on-site manager for accessibility assessment for 3 facilities (Sonoma, Fairview and Lanterman). Scope of work at each campus consisted of approximately 80 buildings comprising 1,000,000 s.f. and 500 acres. Trained and field-managed survey teams. Included recommendations for barrier removal and assistance with formal transition plan.
- County of Alameda, CA, ADA Title II Compliance Survey Project Architect** 2003
Project Architect providing services to survey and recommend remediation with associated costs for 37 County facilities totaling two million square feet. Trained and field-managed survey teams and worked closely with the County of Alameda to assure quality control and non-disruption of services.
- County of Orange, CA, ADA Title II Compliance Survey Project Architect** 1999-2000
Project Architect for the survey of 144 County facilities totaling 11,000,000 sf. and 38 harbors, beaches and parks totaling 79,000 acres. Trained and field-managed survey teams and worked closely with the County of Orange to assure quality control. Included recommendations for barrier removal and assistance with formal transition plan.

Selection of Architectural Projects


- Porterville Developmental Center 96-Bed Forensic Expansion** 2004-2005
Project Architect for the 80 million dollar project that included 6 skilled nursing forensic residence buildings with surrounding secure perimeter and new Protective Services building. The project also included 173 acre site infrastructure for 14 future buildings. The extensive site improvements included roads, utilities and full emergency back-up power as well as systems for well water production and distribution, and physical and electronic security.
- State of California Lanterman Developmental Center, Project Architect** 1999-2000
Project Architect for security and ADA compliance improvements to the existing campus. Balanced security and accessibility requirements for design of the campus Police Services Facility, two school buildings, and the retrofit of five existing residence buildings.
- Riverside Community Hospital** 2002-2003
Assistant Project Architect for new parking structure, 8,000 s.f. G.I. expansion, 14,000 s.f. remodel and 21,000 s.f. E.R. renovation. Designed improvements to allow all hospital functions to remain operational during construction.
- New Corporate Facility, Mag Instrument** 1999-2003
Project Architect for the 50 million dollar 700,000 s.f. facility. The project included corporate offices, machine room, cafeteria, aluminum anodizing plant, assembly, warehouse, and shipping areas. The 300,000sf machine room featured an innovative sub-floor oil collection flume working in conjunction with an oil-removing air handling system.
- Camarillo Ranch Business Park Master Plan** 1997
Project Architect for the 45 acre speculative development that included subdivision, road and utility infrastructure and preservation of the historic Camarillo Ranch Home.
- Sisters of Notre Dame Academy, Los Angeles** 1996
Project Architect for renovation to the circa 1920 historic elementary school.
- Medical Materials Corporation** 1995-1996
Project Architect for the 35,000 s.f. high-tech manufacturing facility improvement and expansion. Worked closely with Client to design manufacturing processes and material handling to minimize and control hazardous occupancy requirements. Project included emergency systems for explosion relief and temperature control of heat-reactive materials.
- Los Angeles Times Orange County Facility Press Bay Expansion** 1991-1994
Project Engineer directly responsible for construction of the ten million dollar process systems installation, air handling and central plant expansion to accommodate the press bay expansion. Applied innovative construction staging, and engineered interim processes that utilized existing infrastructure that saved hundreds of thousands of dollars. Interacted with trade unions in utilizing skills of construction personnel. This position was primarily a construction management position with extensive design-build services.

EXHIBIT B

August 16, 2017

San Francisco 49ers

Transportation Management and Operations Plan for the Levi's® Stadium in Santa Clara





This page intentionally left blank.

Table of Contents

1.0 Purpose	1
2.0 Objectives	3
2.1 Administrative Objectives	3
2.1.1 Flexibility and Scalability	3
2.1.2 Procedures for Review and Update	3
2.1.3 Input from Interested Parties	3
2.1.4 Collection and Evaluation of Annual Data	4
2.2 Performance Objectives	5
2.2.1 Limit Duration of Traffic Congestion	6
2.2.2 Avoid Intrusions into Residential Neighborhoods	6
2.2.3 Avoid Intrusions into Surrounding Businesses	7
2.2.4 Facilitate Transit Ridership and Minimize Impacts to Existing Transit Service	9
2.2.5 Facilitate Arrivals by Bicycle	11
2.2.6 Ensure Safety	11
2.2.7 Provide Access to Neighboring Properties	11
2.2.8 Provide Adequate Parking	12
2.2.9 Effective Community Outreach and Education	12
2.2.10 Non-Permitted Parking	12
3.0 Working Groups	17
3.1 Transportation Operations Group (TOG)	17
3.1.1 Community Liaison	17
3.1.1 Stadium Manager	188
4.0 Annual Schedule and Event Type	21
4.1 Annual Events Calendar	21
4.2 Stadium Authority Meeting Schedule	22
4.3 Working Group Meeting Schedule	22
4.4 Matrix of Control by Event Size	22
4.4.1 Parking Supply	23
4.4.2 Vehicle Access	24
4.4.3 Transit Access	27
4.4.4 Bicycle Access	27
4.4.5 Pedestrian Access	28
4.4.6 Emergency Vehicle Access	28
5.0 Components	29
5.1 Vehicle Access	29
5.1.1 Vehicle Ingress	29
5.1.2 Vehicle Egress	46
5.2 Transit Access	53
5.2.1 VTA Light Rail	53
5.2.2 VTA Local Bus	77
5.2.3 Other Public Bus	80
5.2.4 Charter Bus	80
5.2.5 Caltrain	82
5.2.6 Capitol Corridor	83



5.2.7	ACE	86
5.3	Pedestrian Access	87
5.3.1	Roadway Closures / Pedestrian Only Areas	87
5.3.2	Access to Transit	88
5.3.3	Access to Parking	94
5.3.4	ADA Access	98
5.4	Bicycle Access	101
5.4.1	Access Routes	101
5.4.2	Bicycle Parking	102
5.5	Parking	106
5.5.1	Employee Parking	106
5.5.2	Patron Parking	107
5.6	Taxi and Pedicab Access	120
5.7	Emergency Vehicle Access Plan	124
5.7.1	Ambulance	124
5.7.2	Police	124
5.7.3	Fire	126
5.7.4	Stadium Traffic Operations Center	126
5.8	TMOP Contingency Planning	127
5.8.1	Transit Access	127
5.8.2	Vehicular Access and Parking	127
6.0	Weekday Considerations	131
6.1	Advanced Communication	131
6.1.1	Patrons	131
6.1.2	Area Businesses	131
6.1.3	Changeable Message Signs	132
6.2	Vehicle Access	132
6.3	Transit Access	134
6.4	Parking	134
6.5	Residential/Business Notifications and Communications	135
7.0	Integration/Coordination with Nearby Facilities	137
7.1	Great America Theme Park	137
7.1.1	Great America Theme Park Parking During Events	137
7.1.2	Great America Theme Park Vehicle Access during Events	139
7.2	Techmart and Convention Center Vehicle Access during Events	143
7.3	Santa Clara Youth Soccer Park Vehicle Access during Events	147
7.4	Santa Clara Golf & Tennis Club Vehicle Access during Events	149
7.5	David's Restaurant and Banquet Facility Vehicle Access during Events	151
7.6	Our Lady of Peace Church and Shrine	153
7.7	Great America Commuter Rail Station	154
8.0	Main Lot Modifications	157
9.0	Development of Operating Budget	157

List of Tables

Table 2-1: Summary of Data to be Collected	4
Table 2-2: Anticipated Arrival and Departure Patterns	5
Table 2-3: Transit Providers, and Data to be Collected	9
Table 4-1: Potential Stadium Events	21
Table 4-2: Anticipated Transit and Automobile Use for Events of Different Size	23
Table 5.1-1: Signal Phasing Modifications – Vehicle Ingress	40
Table 5.1-2: Encroachment Permit Needs	42
Table 5.1-3: Signal Phasing Modifications – Vehicle Egress	52
Table 5.5-1: Employee Event day Parking Demand	106
Table 5.5-2: Stadium Parking Program	110

List of Figures

Figure 2-1: Event Day Neighborhood Roadway Restrictions	8
Figure 2-2: Transit Providers	10
Figure 2-3: Neighboring Commercial Properties	13
Figure 2-4: Gameday Parking Facilities	14
Figure 3-1: Stadium TMOP Operations Flow Chart	Error! Bookmark not defined.
Figure 4-1: TMOP Area of Influence by Event Size	25
Figure 4-2: Intersection Adjustments by Event Size	26
Figure 5.1-1a: Vehicular Paths of Travel – Ingress	31
Figure 5.1-2: Detailed Gameday Signage	33
Figure 5.1-3: Advance Event Message Signs	34
Figure 5.1-4: Proposed Inbound Lane Configurations and Control	38
Figure 5.1-5: Pedestrian Crossings at Monitored Intersections	39
Figure 5.1-6: Traffic Signal Improvement Locations	43
Figure 5.1-7: Paratransit and Pick-up / Drop-off Routes, and Supplemental	47
Figure 5.1-8: Proposed Outbound Lane Configurations and Control	49
Figure 5.2-1a: VTA Light Rail Schematic East of Great America Station	58
Figure 5.2-2a: VTA Satellite Lots	63
Figure 5.2-3a: Post-Event Arrivals at VTA Great America Station (Westbound Egress)	70
Figure 5.2-4a: Great America Light Rail Station Platform Configuration	72
Figure 5.2-5: At-Grade Crossing of Tasman Drive	75
Figure 5.2-6: VTA Bus Routes	79
Figure 5.2-7: Charter Bus Staging Area on Event Day	81
Figure 5.2-8: Great America Commuter Rail Station Platform Configuration	85
Figure 5.3-9: Directional Signage and Access to Transit	89
Figure 5.3-10: Great America Light Rail Station Platform Queuing Area	90
Figure 5.3-11: VTA Supplemental Bus Route Staging Area on Event Days	91
Figure 5.3-12: Charter Bus Staging Area on Event Day	93
Figure 5.3-13: Pedestrian Access to Parking Facilities on Event Days	95
Figure 5.3-14: Stadium Security Perimeter	96
Figure 5.3-15: Paratransit and Pick-up / Drop-off Routes, and Supplemental ADA Shuttle Routes	100
Figure 5.4-1: Bicycle Routes	103
Figure 5.4-2: Bicycle Diversions on Event Day	104
Figure 5.4-3: Bicycle Parking Facilities	105
Figure 5.5-1: Gameday Parking Facilities	109
Figure 5.5-2a: Vehicular Paths of Travel – Ingress	113
Figure 5.5-3: Areas of Parking Prohibitions	115
Figure 5.5-4: Red Lot 1 ADA Parking	117



Figure 5.5-5: Tailgating Regulations.....	119
Figure 5.6-1: Taxi Staging Area on Event Days	121
Figure 5.7-1: Emergency Vehicle Access.....	125
Figure 6-1: Proposed Outbound Lane Configurations and Control	133
Figure 7-1: Great America Theme Park Parking Supply on Event Day	138
Figure 7-2a: Access to Great America Theme Park on Event Day – Inbound.....	141
Figure 7-3: Advanced Signage	144
Figure 7-4: Access to Techmart, Convention Center, and the Hyatt Hotel on Event Days	146
Figure 7-5: Access to Santa Clara Youth Soccer Park on Event Days.....	148
Figure 7-6: Access to Santa Clara Tennis Club on Event Day	150
Figure 7-7: Access to David's Restaurant on Event Day	152

This page intentionally left blank.



1.0 Purpose

The purpose of this Transportation Management and Operations Plan (TMOP) is to provide a flexible framework and plan for the provision of safe and efficient multi-modal access, and adequate parking, for Levi's® Stadium in Santa Clara, California. The stadium includes approximately 70,000 seats, with the potential for expansion to approximately 75,000 seats for the purpose of periodically hosting special events, such as the NFL Super Bowl. Per *The 49ers Stadium Project EIR* (City of Santa Clara, 2009), for capacity events such as typical San Francisco 49er games, 50,500 attendees are expected to arrive by automobile (as shown in Table 15, page 176 of the EIR, volume 1), with an average vehicle occupancy of 2.7 persons per vehicle (corresponding to 18,865 vehicles in total). 18,000 attendees will arrive by transit, including 5,000 by charter bus, 4,500 by Santa Clara Valley Transit Authority (VTA) light rail, 4,500 by local and regional bus services, and 4,000 by heavy rail (of which 3,000 would arrive via a transfer from Caltrain to VTA light rail). It should be noted that ridership projections from EIR are to be updated as new ticket sales progress, and VTA uses that information to update its travel demand modeling. VTA will provide annual updated ridership projections.

Through research collected, assumptions made prior to the opening of Levi's Stadium have had the opportunity to be vetted for accuracy. Those changed assumptions include an observed average ridership of 3.2 riders per vehicle for NFL events and 3.0 for non-NFL events, 14,000 cars parked during typical NFL events and from 5,000 to 11,000 cars parked for large Non-NFL events. It is important to note that these numbers represent data collected only in Levi's Stadium controlled parking lots. There are several other parking lots (totaling approximately 1,200 stalls) which have been separately permitted by the City of Santa Clara. While event-specific parking data for these lots is not received directly by the Stadium Management Company and is not included in the Stadium Manager's lot-by-lot event parking records, the presumed use of these lots for event parking is incorporated into the traffic and parking planning for each event. In addition, VTA's Light Rail operation typically sees an average of 8,300 riders for NFL event and 6,600 for Non-NFL events. VTA's bus operation typically provides transportation to between 500 and 1,500 passengers depending on the event. Overall, the mode split for all forms of non-automobile transportation has ranged from as low as 7% to as high as 25%..

The TMOP includes administrative and performance objectives by which the success of the plan's implementation goals can be measured. TMOP administrative objectives are intended to ensure that the plan is flexible and scalable, that procedures for review and update are clearly defined and that feedback from the public as well as other involved public and private organizations are considered. TMOP performance objectives include minimizing the duration of traffic congestion throughout the Stadium area, providing adequate parking facilities, facilitating trips by non-automobile uses, encouraging transit use, preventing intrusion into neighborhoods while maintaining access to neighboring business properties, and ensuring safe travel for all event patrons and local traffic.

As part of this document, working groups comprised of both public and private organizations are identified to ensure the effective implementation of traffic, transit, and parking plans. One working group will focus on day-to-day operations, while the other will function in an advisory capacity. Participants in each working group are based upon jurisdictional authority and/or expertise that support the functions of that particular group.

The TMOP includes an Annual Events Calendar for the Stadium, scheduled meetings for the Stadium Authority and working groups, and outlines the extent to which the TMOP should be implemented for events of different sizes. Based on the number of attendees expected for each event, the number of parking facilities used, the amount of lane reconfiguration and signal modification required, and the amount of transit service provided can be adjusted.

The TMOP outlines all elements necessary to facilitate safe and efficient access to and from the Stadium by way of all modes of transportation. With regard to vehicle ingress and egress, the type and location of signage is defined, the locations for all intersection treatments and roadway closures are identified, responsibility for implementation of various TMOP elements is defined, and the requisite number of hours to apply the TMOP is identified. Plans to allow access to neighboring business properties, and to restrict access into local neighborhoods are outlined. The types of transit service provided to the Stadium on event days are outlined, and methods to provide safe, orderly, and efficient access to transit facilities during the heavy egress load are described. New transit facilities to be built specifically for Stadium use are detailed. Designated pedestrian and bicycle facilities are described, and wayfinding signage to the stadium and to transit is outlined. Parking facilities for employees and patrons are identified, and plans for the use of other nearby parking facilities are outlined. The TMOP also outlines plans for emergency vehicle access, identifying the fastest routes to and from the Stadium during events.

The TMOP identifies a methodology for implementing elements of the TMOP on weekday evenings, in addition to weekends. Plans for advanced notification and outreach are outlined, and methods for maximizing traffic flow towards the Stadium during business hours are described. As businesses in the area will continue to function during the Stadium's ingress period for weekday events, methods for effective communications between these businesses (and area residents) and the Stadium's working groups are outlined.

Integration and coordination with nearby facilities are a priority of the TMOP. Specific access plans, advanced signage, and means of communication are identified for businesses that will operate during Stadium events, including the Great America Theme Park, Santa Clara Convention Center, Techmart, Santa Clara Youth Soccer Park, Santa Clara Golf and Tennis Club, and David's Restaurant and Banquet Facility.

Implementation of the measures identified in the TMOP will require resources. The TMOP identifies on-going budgeting requirements of TMOP monitoring and upkeep (including funding responsibilities), and budgeting requirements of TMOP implementation by event size and type (including funding responsibilities).

Finally, the TMOP is intended to be an evolving, living document, to be updated as necessary to better serve the surrounding community and the users and managers of the facility.



2.0 Objectives

While overall transportation and parking objectives remain unchanged, event traffic and parking plans are customized on an event-by-event basis depending on input from all parties and the unique needs of each event. This customization, based on direct input from all transportation management participants, and has resulted in a definite improvement in parking and transportation operations for each subsequent event.

The TMOP includes administrative and performance objectives by which the success of the plan's implementation goals can be measured. These objectives are intended to ensure the plan is flexible and scalable, with provisions for obtaining input, collecting data, and allowing for future modifications to improve performance.

2.1 Administrative Objectives

2.1.1 Flexibility and Scalability

To ensure the effectiveness of the TMOP in various scenarios, the TMOP is both flexible and scalable. Annual reviews and updates, when necessary, are conducted to better serve the public. Further, the TMOP has the ability to be modified within the year to respond to on-going concerns and issues based on feedback received and observations made, on an event-by-event basis. The TMOP is also scalable, allowing size-appropriate measures to be deployed for sold out NFL events of approximately 68,500 attendees as well as smaller events.

2.1.2 Procedures for Review and Update

The TMOP functions as an actively maintained procedures manual, that is continuously updated to better serve the transportation and parking needs of the facility, as conditions change in the surrounding area of the stadium, and as better means for providing effective transportation solutions are identified. On an annual basis, after the end of the NFL season (anticipated as the first quarter of the calendar year), the written TMOP will be reviewed and updated as necessary, through recommendations of the working groups, that are ratified by the Director of Community Development (Please refer to Section 3.0 below for a description of the working groups). Some elements of the TMOP will be reviewed at various points during the season in order to make any adjustments that may be necessary immediately (e.g., issues related to neighborhood intrusion). The Transportation Operations Group (described in section 3.0) will be responsible for maintaining the TMOP document. These changes will also be included in an annual report prepared by the Stadium Manager, for review by the Director of Community Development.

2.1.3 Input from Interested Parties

Stadium Working Groups, as described in section 3.0 of the TMOP, are responsible for the implementation of the TMOP, collection of data to assess the plan's effectiveness, and obtaining input from interested agencies and the public. Specifically, the Transportation Operations Group makes observations on event days, considers feedback from the Community Liaison (the point of contact for community members), and considers feedback from the Stadium Stakeholders Group, which is comprised of professionals from public agencies and private organizations. All recommended changes reviewed and approved by the Director of Community Development will be presented at Stadium Authority Meetings.

2.1.4 Collection and Evaluation of Annual Data

To assess the TMOP's effectiveness, and evaluate future improvement measures, travel behavior data will be periodically collected. Specifically, data is to be collected annually on a sample basis for the first five years after Stadium operations commence, followed by collections every five years moving forward. It is expected that after five years of operation, the majority of operational improvements will have been identified and implemented, and users of the area surrounding the Stadium will understand event day operations. As such, the collection of additional annual data would not be beneficial.

Data will be collected during a regular-season Sunday afternoon game, and during a regular-season weekday evening game should one occur (i.e., Monday Night Football, Thursday Night Football), both at least one month after the start of the regular season. A summary of topics to be examined, and details regarding the data to be collected is provided in **Table 2-1**.

Table 2-1: Summary of Data to be Collected

Item for Evaluation	What Data is to be Collected?	Responsible Party for Collection and Compilation of Data	When shall Data be Collected?	Where Data shall be Collected?	How Data shall be Summarized?
Duration of Congestion	Field observations and aerial photographs (one Sunday and one evening game)	Transportation Consultant under Stadium Manager Direction	End of a Sunday afternoon game, End of a weekday evening game	Main Parking Lot, key traffic congestion points	Graphically; to identify bottleneck locations
Intrusion into Santa Clara, San Jose and Sunnyvale Residential Neighborhoods	Aerial photographs of on-street parking (one Sunday and one evening game)	Transportation Consultant under Stadium Manager Direction	Aerial photography taken at 15-minute intervals from 9:00 AM to 6:00 PM; during a Sunday afternoon game and a weekday evening game	Aerial photographs of surrounding residential neighborhoods	Tabular; to identify the extent of intrusion into neighborhoods
Transit Ridership	Boarding/alighting data from transit providers	VTA, ACE, Capitol Corridor, Caltrain	Collected before season (once on a Sunday, once on a Monday), and every game; summarized at the end of season	On transit providers' trains / buses, at transit stops	Tabular
Parking	Aerial photographs of Stadium parking facilities, parking counts	Transportation Consultant under Stadium Manager Direction	Aerial photography taken at 15-minute intervals from 9:00 AM to 6:00 PM; during a Sunday afternoon game and a weekday evening game	All Stadium parking facilities	Tabular
Modal Split	Arrival data from all modes of travel	Traffic Consultant, VTA, ACE, Capitol Corridor, Caltrain	Throughout season, prior to the start of a season	Aerial photographs, transit data, bicycle parking counts	Tabular
Access to Neighboring Properties	Aerial photographs of neighboring properties parking facilities, field observations	Transportation Consultant under Stadium Manager Direction	Aerial photography taken at 15-minute intervals from 9:00 AM to 6:00 PM; during a Sunday afternoon game and a weekday evening game	Aerial photographs of neighboring properties parking facilities	Tabular; to identify the extent to which neighboring uses are utilized

Source: AECOM, 2014.




2.2 Performance Objectives

Performance objectives of the TMOP are based on expected arrival and departure totals as provided in *The 49ers Stadium Project EIR* (City of Santa Clara, 2009). Anticipated arrival and departure totals for vehicle trips are summarized in **Table 2-2**. The values provided are based on factors including transit availability, average vehicle occupancy rates, available roadway capacity, historical Candlestick Park information, and anticipated modal split information. As shown in *The 49ers Stadium Project EIR*, 74 percent of patrons are expected to arrive by automobile, 7 percent are expected to arrive by charter bus, and 19 percent are expected to arrive by public transportation. This data is to be updated once per season.

Table 2-2: Anticipated Arrival and Departure Patterns

Time Frame	Auto Trips		Charter Buses		Total Vehicle Trips
	Percent	Trips	Percent	Trips	
General Arrival Pattern					
> 5 Hours	6	1,122	0	0	1,122
4-5 Hours	8	1,496	0	0	1,496
3-4 Hours	14	2,619	2	2	2,621
2-3 Hours	14	2,619	5	6	2,624
1-2 Hours	19	3,554	28	32	3,586
< Hour	39	7,295	65	74	7,369
Total	100	18,704	100	114	18,818
General Departure Pattern					
During Game	10	1,870	10	11	1,882
> 1 Hour	64	11,971	80	91	12,062
1-2 Hours	26	4,863	10	11	4,874
Total	100	18,704	100	114	18,818

Source: City of Santa Clara, *The 49ers Stadium Project EIR*, 2009.



2.2.1 Limit Duration of Traffic Congestion

Providing a transportation plan that minimizes the duration of traffic congestion is a key program objective. As specified in section 2.1.4, the duration of congestion will be annually measured as part of the program's assessment program. Per the *Transportation Management Plan for a New San Francisco 49ers Stadium in Santa Clara, CA* (AECOM, 2009), the period of arrival for football games can be as long as five hours prior to the start of a game. However, the period of departure will typically occur near the completion of a game, and conclude less than two hours afterward. Thus, efforts to limit the duration of traffic congestion are focused on post-game traffic departure.

The duration of traffic congestion will be measured by way of field observations at key traffic locations. The locations to be examined will include but not limited to the Stadium Main Parking Lot, the SR 237 eastbound and westbound ramps at Great America Parkway, the Great America Parkway / Mission College Boulevard intersection, and the Lawrence Expressway / Tasman Drive intersection. At the Stadium Main Parking Lot, the duration of congestion shall be identified as the time at which the lot begins to empty, to the time at which queuing at lot exit points ceases. At each other location, the duration of congestion shall be identified as the time at which the Stadium Main Parking Lot begins to empty, to the time at which the intersection's standard signal phasing would be sufficient to manage traffic. The time at which intersection's standard signal phasing would be sufficient to manage traffic is to be determined by the judgment of assigned traffic monitoring officers. When queuing for outbound vehicles is observed to clear the intersection each traffic cycle, the officer will report to the Stadium's Traffic Operations Center. Once all officers have reported that queuing no longer results in vehicles waiting multiple cycles to clear an intersection, all signals will be returned to their standard signal phasing via the Stadium's Traffic Operations Center. As noted in section 2.1.4, this data will be collected during a regular-season Sunday game, and during a regular-season weekday evening game (i.e., Monday Night Football, Thursday Night Football), both at least one month after the start of the regular season.

2.2.2 Avoid Intrusions into Residential Neighborhoods

As reducing noise, air quality, and traffic impacts to the surrounding residential neighborhoods is of utmost importance, the potential for intrusion of traffic and pedestrians into residential areas shall be examined. As noted in the *Transportation Management Plan for a New San Francisco 49ers Stadium in Santa Clara, CA* (AECOM, 2009), to prohibit Stadium patrons from intruding on residential areas, such as the Adobe Wells Mobile Home Park, Agnews and the Rivermark neighborhoods, Stadium access as well as Stadium parking in those neighborhoods will be restricted on the following roadways:

Event-related vehicle access restriction and on-street parking restriction:

- Calle De Primavera;
- Fairway Glen Drive;
- Hogan Drive;
- Eisenhower Drive;
- Hope Drive;
- Agnew Road;
- Bassett Street;
- Davis Street;
- Cheeney Street;
- Fillmore Street;
- Lakeshore Drive;
- Lake Santa Clara Drive;
- Reamwood Avenue;
- Birchwood Drive;
- Adobe Wells Mobile Home Park Access;
- Palamos Avenue;
- Sandia Avenue;
- Bridgewood Way;
- Wildwood Avenue;
- Stars and Stripes Drive;
- Centennial Boulevard;
- Renaissance Drive; and
- Democracy Way.



On-street parking restriction only:


- Lick Mill Boulevard;
- Lafayette Street;
- Freedom Circle;
- Mission College Boulevard;
- Hitchborn Drive;
- Our Lady's Way;
- Patrick Henry Drive;
- Old Ironsides Drive;
- Old Glory Lane;
- Betsy Ross Drive;
- Bunker Hill Lane;
- Stars and Stripes Drive;
- Democracy Way;
- Calle Del Sol;
- Calle De Luna; and
- Calle Del Mundo.

An illustration of the event day restrictions of roadways providing access to residential neighborhoods is provided in **Figure 2-1**. Intrusion into residential areas is to be measured through an examination of on-street parking conditions beyond these roadways. When requested by the Transportation Operations Group (TOG), aerial photographs will be taken at 15-minute intervals from 9:00 AM to 6:00 PM on a regular-season Sunday game day, assuming a 1:00-1:30 PM start time. The TOG is responsible for evaluating the aerial photographs and determining the extent to which intrusion occurs. Based on findings, adjustments to the TMOP will be proposed.

2.2.3 Avoid Intrusions into Surrounding Businesses

To be completed based on outcome of TMOP meeting.

Figure 2-1: Event Day Neighborhood Roadway Restrictions





2.2.4 Facilitate Transit Ridership and Minimize Impacts to Existing Transit Service

A major goal of the TMOP is to facilitate and encourage the use of transit on event days, as the use of transit will provide multiple benefits to the area, including the minimization of the period of transportation congestion. In addition to encouraging transit use, impacts to existing transit service should be minimized in order to limit the impact to existing transit passengers.

Transit operating agencies shall provide, to the extent possible, transit service (route, capacity, frequency) and ridership data for each regular-season game. The TOG shall request hourly passenger boarding and alighting by station from transit operators. A summary of each transit agency, and the anticipated data to be collected, is provided in **Table 2-3**. Each transit provider has been met with to identify needs with respect to data collection efforts, and to develop a strategy to collect as much data as is appropriate. **Figure 2-2** illustrates the transit providers' routes in the vicinity of the Stadium.

Table 2-3: Transit Providers, and Data to be Collected


Transit Provider	Transit Service Type	Boarding / Alighting by Station	Capacity / Utilization	Headways
Santa Clara Valley Transportation Authority (VTA)	Light Rail	x	x	x
	Bus	x	x	x
Caltrain	Heavy Rail	x	x	--
Altamont Corridor Express (ACE)	Heavy Rail	x	x	--
Capitol Corridor	Heavy Rail	x	x	--
Charter Bus	Bus	--	x	--

Source: AECOM, 2014.

The Transportation Operations Group (TOG), described in greater detail in Section 3, is responsible for summarizing transit ridership, and qualitatively assessing transit operations. Event day conditions shall be compared with non-event day conditions (as determined through non-event day data collections) to determine the impact of event patrons on transit operations. The transit analysis shall consider impacts due to changes in transit service levels and ridership.

Lowering headways and increasing service frequency, when feasible, would enable operating agencies to increase the number of patrons delivered to the Stadium. The addition of special transit service (e.g., special bus service, expanded VTA LRT Sunday service with limited-stop routes) to accommodate event patrons, and the coordination of transit service between the Stadium and rail facilities, would improve service to events and potentially minimize impacts to existing transit service. Additionally, for events with above 20,000 attendees, the section of Tasman Drive immediately adjacent to the Stadium, between Centennial Boulevard and the Great America Theme Park driveway / Convention Center driveway (herein referred to as "Convention Center Circle"), may be closed to all vehicular traffic. Such a closure would allow for a pedestrian zone for Stadium patrons arriving from or departing to VTA light rail; improving VTA light rail boarding and alighting efficiency at the Great America VTA Station.

Figure 2-2: Transit Providers





2.2.5 Facilitate Arrivals by Bicycle

Facilitating and encouraging arrival to events by bicycling is also a major goal of the TMOP.

The extent to which bicycle access is facilitated is to be measured through an evaluation of the usage levels of the Stadium bicycle parking facilities, and nearby bike trails as well. Specifically, bicycle parking counts shall be collected for event days and non-event days for comparison. Aerial photographs are to be taken at 15-minute intervals pre-game, mid-game, and post-game during a regular-season Sunday game, and during a regular-season weekday evening game (i.e., Monday Night Football, Thursday Night Football), both at least one month after the start of the regular season to identify any effects of the Stadium on nearby bicycle facilities. The Transportation Operations Group (TOG) is responsible for evaluating the aerial photographs and determining the adequacy of the available bicycle parking supply. Based on findings, adjustments to the TMOP will be proposed.

2.2.6 Ensure Safety

The safety of patrons using all modes of transportation, as well as the safety of residents throughout the area is a crucial program objective. The ways in which general safety levels will be affected (positively and negatively) shall be addressed, and the means by which they are to be quantified shall be discussed in this section of the TMOP.

The Stadium area shall be assigned a unique identification number that will be applied to all crime and incident reports prepared by the Santa Clara, San Jose and Sunnyvale Police Departments. The Santa Clara Police Department is responsible for analyzing crime and incident data and evaluating the safety of Stadium patrons and residents throughout the area on Stadium event days compared to non-event days, and for providing updated information to the Transportation Operations Group. Based on the findings, adjustments to the TMOP and Public Safety Plan will be proposed.

2.2.7 Provide Access to Neighboring Properties

An objective of the TMOP is to ensure access to owners, employees, business patrons, and other users of neighboring properties. Major nearby land uses which may be in normal operation on event days include, but are not limited to, the following:

- Great America Theme Park;
- Convention Center;
- Techmart;
- David's Restaurant and Banquet Facility;
- Our Lady of the Peace Church and Shrine;
- AMC Mercado 20;
- Mission College;
- Santa Clara Golf & Tennis Club;
- Santa Clara Youth Soccer Park;
- Hyatt Regency;
- Hilton Santa Clara;
- Avatar Hotel and Bennigans Restaurant;
- Santa Clara Marriott; and
- Owners/Managers of area Retail Commercial Centers.

The location of each neighboring property is illustrated in **Figure 2-3**. The extent to which the TMOP allows efficient access to these properties is to be measured through an evaluation of each property's parking facilities. Aerial photographs are to be taken at 15-minute intervals pre-game, mid-game, and post-game during a regular-season Sunday game, and during a regular-season weekday evening game (i.e., Monday Night Football, Thursday Night Football), both at least one month after the start of the regular season. The Stadium Manager shall also collect and provide data and observations in the form of a written report during these data collection periods. The Stadium

Manager will retain a transportation consultant to evaluate the aerial photographs and determine whether game day access to the properties is adequate. Based on findings, adjustments to the TMOP will be proposed.

2.2.8 Provide Adequate Parking

The provision of adequate parking levels within a reasonable walking distance to the stadium is important to minimize the number of conflict points between patrons walking to/from the stadium and automobiles. Aerial photographs are to be taken at 15-minute intervals pre-game, mid-game, and post-game during a regular-season Sunday game, and during a regular-season weekday evening game prior to darkness (i.e., Monday Night Football, Thursday Night Football), both at least one month after the start of the regular season. The Transportation Operations Group is responsible for evaluating the aerial photographs, determining the occupancy levels of each lot, and determining the overall adequacy of the available parking supply. Based on findings, adjustments to the TMOP will be proposed. An illustration of the likely parking facilities for Stadium events is provided in **Figure 2-4**.

2.2.9 Effective Community Outreach and Education

The Stadium Manager, along with the City of Santa Clara, will define measures of effectiveness for outreach and education plans, and identify the extent to which the plans meets each measure of effectiveness. Community outreach and education measures will include:

- Education upon ticket purchase and/or with tickets;
- Brochures and mailers to area residents and local businesses;
- Press releases and media alerts;
- Telephone hotline;
- Web-based dissemination via social media and cell phone application;
- Information posted on VTA light rail trains and buses; and
- Stadium Stakeholders Group meetings.

2.2.10 Non-Permitted Parking

As noted in section 2.2.2, parking in non-permitted areas (on-street in residential neighborhoods, or in no-event off-street parking lots) is to be evaluated using aerial photographs taken at 15-minute intervals from 9:00 AM to 6:00 PM on a regular-season Sunday game day, assuming a 1:00-1:30 PM start time. The Transportation Operations Group is responsible for evaluating the aerial photographs and determining the extent to which non-permitted parking occurs. It is expected that enforcement of the Stadium's prescribed parking plan would be carried out by the appropriate jurisdiction's law enforcement.

Figure 2-3: Neighboring Commercial Properties



Figure 2-4: Gameday Parking Facilities





This page intentionally left blank.



3.0 Working Groups

Two working groups are identified to ensure the effective implementation of traffic, transit, and parking plans. The make-up and emphasis of each working group is slightly different, but together they provide support for the Stadium Authority and Stadium Manager, and the entity charged with daily operations of the Stadium facility.

The first working group, the Transportation Operations Group (TOG), focuses on day-to-day operations including pre-season planning, individual event planning, and event follow-up assessments. The second working group, the Stadium Stakeholders Group (SSG), functions primarily in an advisory capacity, acting in more of an information gathering and sharing role, taking public input through the Community Liaison and providing recommendations to the TOG. Participants in each group are based upon jurisdictional authority and/or expertise that support the functions of the particular group.

3.1 Transportation Operations Group (TOG)

The TOG is responsible for setting up and revising traffic, transit, and parking plans, assessing the performance of these plans, and responding to recommendations from the SSG. The TOG is to participate in meetings prior to and following each event with 20,000 or more attendees held at the Stadium, and meetings convened for events with fewer than 20,000 attendees on a case-by-case basis. The TOG is responsible for taking input, observations, and recommendations into consideration, and moves them forward to assess operational feasibility. The TOG will include (but is not limited to) the following members:

- San Francisco 49ers Stadium Operations Staff
- Valley Transportation Authority (VTA) Staff
- City of Santa Clara Staff (including Public Safety Staff)
- Caltrain Staff
- Altamont Corridor Express (ACE) Staff
- Capitol Corridor Staff
- Participating law enforcement agencies (led by City of Santa Clara Police Department)
- Community Liaison

3.1.1 Community Liaison

A Community Liaison position or office will be established by the TOG to function as a single point of contact for residents and businesses. The Community Liaison position or office will be staffed by the Stadium Manager. The Community Liaison is responsible for relaying community input, and obtaining information on transportation and parking issues related specifically to Stadium operations. Residents and businesses can contact the Community Liaison via e-mail at neighbors@levisstadium.com.

The Community Liaison serves as the first line of communication for community members and Stadium patrons. For larger issues that cannot be dealt with by the Community Liaison, community members and Stadium patrons shall present issues at SSG meetings for resolution, and/or forward significant issues to the Stadium Manager for their review and resolution.

3.1.2 Stadium Manager

The Stadium Manager will coordinate with area residents and area businesses, maintain permits and agreements with all parties involved, and facilitate Stadium-related data collection efforts. Specifically, the Stadium Manager will hold all parking permits, and will hire a parking operator to manage all event day parking operation.



This page intentionally left blank.



4.0 Annual Schedule and Event Type

The TMOP includes an Annual Events Calendar for the stadium, as well as scheduled meetings for the Stadium Authority, and working groups.

4.1 Annual Events Calendar

The anticipated Annual Events Calendar is to be compiled by the Stadium Manager, and shall identify and describe all anticipated stadium activity, ensuring that each event receives an appropriate amount of attention with regard to traffic, transit, and parking provision. The information to be provided in the schedule for event purposes shall include:

- 4.1.1 Number of Events
- 4.1.2 Event Type
- 4.1.3 Number of Attendees
- 4.1.4 Day, Time and Duration of Event
- 4.1.5 Special Considerations

The anticipated Annual Events Calendar will be updated throughout the course of the year. All updates require approval by the Director of Community Development or City Manager, whichever is appropriate given the size of the event. Schedule updates will be conveyed to the community via the Stadium web site and other appropriate outreach methods to ensure affected parties are made aware of changes in the Annual Events Calendar that may affect them.

Typically, an NFL season will run from August through December, with 10 scheduled home games (two preseason games and eight regular season games). Additionally, up to two home playoff games may be scheduled in January. In addition, the Stadium would host non-NFL events and other community events. **Table 4-1** lists potential events that may be held at the Stadium annually.

Table 4-1: Potential Stadium Events

Event Type	Estimated Attendance	No. of Events per Year	No. of Days per Event	Estimated Parking Demand per Day
San Francisco 49ers Games	68,500	10-12	1	18,865
X-Games	50,000	1	4	4,500
Moto-Cross	42,500	1	1	13,005
International Soccer	68,500	2	1	12,240
Concerts	45,000	1	1	11,475
College Football	37,500	1	1	11,475
Festivals/Antique Shows	25,000	8	1	9,000
College Bowl Game	25,000	1	1	7,650
Car Shows (parking lot event)	12,000	2	4	1,200
Small Events	50 to 500+	250	1	varies

Source: *The 49ers Santa Clara Stadium Project EIR*, City of Santa Clara, 2005; AECOM, 2014.

4.2 Stadium Authority Meeting Schedule

The Annual Events Calendar shall identify all Stadium Authority meetings, which are to be held concurrently with the regularly scheduled Santa Clara City Council meetings. The Santa Clara City Council meets twice a month, typically on the second and fourth Tuesday of each month. At its meetings (which are to be recorded with agendas and minutes), the Stadium Authority will receive and evaluate reports and recommendations from the TOG and SSG, provide feedback, and take any necessary actions.

4.3 Working Group Meeting Schedule

Stadium Stakeholders Group meetings shall occur quarterly. At their scheduled meetings, the SSG shall obtain input, evaluate Stadium operations, identify areas of concern, and advise the Transportation Operations Group. The TOG is to participate in meetings prior-to and following each event with 20,000 or more attendees held at the Stadium, and events with fewer than 20,000 attendees on a case-by-case basis. At their scheduled meetings, the TOG shall assess the performance of the TMOP, evaluate input, observations, and recommendations provided by the SSG, and revise the TMOP as necessary. Significant TOG findings and recommendations shall be reported at Stadium Authority meetings.

4.4 Matrix of Control by Event Size

Travel characteristics to the Stadium will vary depending on the size and type of event occurring. For smaller events, a lower transit modal split, and a lower average vehicle occupancy is expected. Thus, for smaller events, elements of the TMOP may be scaled down to minimize the effect of Stadium operations on the surrounding transportation network. Estimated levels of transit ridership and automobile use for events of varying size are summarized in **Table 4-2**.

**Table 4-2: Anticipated Transit and Automobile Use for Events of Different Size**

Event Size	Event Type	Expected Transit Ridership ⁽¹⁾						Charter Bus	Expected Vehicle Trips ⁽¹⁾		
		Light Rail	Bus	Caltrain	Capitol Corridor	ACE	Mode Share		Patrons	AVO ⁽²⁾	Total Cars
68,500 ⁽³⁾	Football Game	4,500	4,500	3,000	500	700	19%	5,000	50,300	3.4	18,865
55,000 ⁽³⁾	X-Games Moto-Cross Internat'l Soccer Concert (Large) College Football	3,600	800	2,400	400	0	13%	500	47,300	3.3	18,000
35,000 ⁽³⁾	Festivals Antique Show Concert (Medium)	1,800	550	1,200	200	0	11%	0	31,250	2.39	13,000
20,000 ⁽⁴⁾	Car Show Concert (Small)	700	325	450	75	0	8%	0	18,455	2.15	8,500
10,000 ⁽⁴⁾	Small Events	200	100	100	25	0	4%	0	9,575	2.05	4,700

Source: AECOM, 2014.

Notes: ⁽¹⁾ Ridership, vehicle arrivals, and total parked cars represent the maximum expected value for a given range of attendees.⁽²⁾ Average Vehicle Occupancy (AVO) is scaled based on the size of a given event.⁽³⁾ Tasman Drive may be closed for events of this size.⁽⁴⁾ Tasman Drive may not be closed for events of this size.

4.4.1 Parking Supply

As shown in **Table 4-2**, the number of parking spaces required to accommodate events of different sizes varies from a maximum of 18,865 spaces to under 5,000 spaces (not including employee parking). The number of parking spaces required to accommodate events in Levi's Stadium affiliated parking lots is adjusted based upon data collection through the events hosted thus far at Levi's Stadium. For example, the average vehicle occupancy has been shown to be greater than the 2.7 anticipated for NFL events, thus fewer parking spaces are expected in demand. Another example includes concert events with audiences that indicate significant drop-off/pick-up of event patrons, such as parents dropping off their children. These dropped-off patrons do not occupy parking stalls but special provisions are made for post-event automobile access to designated pick-up locations. In general, we have learned that, for a number of reasons, the full activation of all of 18,000+ spaces within Levi's Stadium contracted parking lots is not necessary to host the largest events scheduled. The extent to which the TMOP should be scaled with respect to parking is summarized below:

- **68,500 Attendees:** For "capacity" events, all points of the TMOP shall be fully applied.
- **55,000 Attendees:** Due to the anticipated reduction in average vehicle occupancy, and lower transit mode share, events such as large concerts and international soccer matches with 55,000 attendees will only generate approximately 865 fewer vehicle trips than a capacity event. As such, all parking elements of the TMOP should be fully applied, with the exclusion of some parking facilities furthest from the Stadium. Any event day signage related to these facilities shall not be included.

- 35,000 Attendees: Events with 35,000 attendees will generate approximately 6,000 fewer vehicle trips than a capacity event. As such, all parking elements of the TMOP should be fully applied, with the exclusion of parking facilities furthest from the Stadium. Signage related to these facilities shall not be included.
- 20,000 Attendees: Events with 20,000 attendees will generate approximately 10,000 fewer vehicle trips than a capacity event. As such, all event parking can be accommodated within the City-controlled parking facilities adjacent to the Stadium, as well as other partnering parking facilities nearest to the Stadium. Any event signage south of Patrick Henry Drive shall direct motorists to these facilities.
- 10,000 Attendees: Events with 10,000 attendees will generate approximately 14,000 fewer vehicle trips than a capacity event. As such, all event parking can be accommodated entirely within the Great America Main Parking Lot. Signage provided in the Stadium area should direct motorists to the nearest Great America Main Parking Lot driveway.

The parking supply required to accommodate each event size is shown in **Figure 4-1**. Further, **Figure 4-1** illustrates the Stadium's "area of influence" by event size.

4.4.2 Vehicle Access

Per **Table 4-2**, the number of vehicle trips generated by patrons for events of different sizes varies from a maximum of 18,865 vehicles to under 5,000 vehicles. Based on the expected number of patrons for a given event, the minimum number of parking facilities contracted to provide parking on event days will be utilized. The extent to which the TMOP should be scaled with respect to vehicle access is summarized below:

- 68,500 Attendees: For "capacity" events, all points of the TMOP shall be fully applied.
- 55,000 Attendees: All parking elements of the TMOP shall be fully applied, with permitted off-site lots. However, as the roadways used to access these excluded facilities may be used to access other parking facilities that will otherwise be included, all traffic-related elements of the TMOP shall be fully applied.
- 35,000 Attendees: Elements of the TMOP shall be applied, with permitted off-site lots. Lane reconfigurations and signal modifications at intersections near these excluded facilities shall be revised to focus traffic flow to other parking facilities.
- 20,000 Attendees: Event parking shall be accommodated within the City-controlled parking facilities adjacent to the Stadium, and within permitted off-site lots. Lane reconfigurations throughout the Stadium area would no longer be required, though some signal timing modifications would be warranted to focus flow towards parking facilities. Officer presence at intersections would only be required at intersections adjacent to parking facilities.
- 10,000 Attendees: Event parking shall be accommodated entirely within the Stadium Great America Main Parking Lot. This level of vehicle trip generation would not necessitate lane reconfigurations or signal modifications. Officer presence at intersections would not be required.

Intersection adjustments by event size are shown in **Figure 4-2**.

Figure 4-1: TMOP Area of Influence by Event Size





Figure 4-2: Intersection Adjustments by Event Size





As noted in section 2.2.2, vehicle traffic, as well as on-street parking, will be restricted on several roadways for a portion of each event day to minimize the potential for intrusion into residential areas. Specifically, event parking would be restricted at the following locations:

Event-related vehicle access restriction and on-street parking restriction:

- Calle De Primavera;
- Fairway Glen Drive;
- Hogan Drive;
- Eisenhower Drive;
- Hope Drive;
- Agnew Road;
- Bassett Street;
- Davis Street;
- Cheeney Street;
- Fillmore Street;
- Lakeshore Drive;
- Lake Santa Clara Drive;
- Reamwood Avenue;
- Birchwood Drive;
- Adobe Wells Mobile Home Park Access;
- Palamos Avenue;
- Sandia Avenue;
- Bridgewood Way;
- Wildwood Avenue;
- Stars and Stripes Drive;
- Centennial Boulevard;
- Renaissance Drive; and
- Democracy Way.

On-street parking restriction only:

- Lick Mill Boulevard;
- Lafayette Street;
- Freedom Circle;
- Mission College Boulevard;
- Hitchborn Drive;
- Our Lady's Way;
- Patrick Henry Drive;
- Old Ironsides Drive;
- Old Glory Lane;
- Betsy Ross Drive;
- Bunker Hill Lane;
- Stars and Stripes Drive;
- Democracy Way;
- Calle Del Sol;
- Calle De Luna; and
- Calle Del Mundo.

However, since parking for events with 20,000 attendees and fewer can be accommodated within the immediate vicinity of the Stadium, it is unlikely that intrusion into residential areas would occur for events of this size. As such, the listed restrictions would not be necessary for events with 20,000 attendees or fewer.

4.4.3 Transit Access

Per **Table 4-2**, the transit mode share is expected to decrease with smaller events. For non-football events, ACE is not assumed to provide service beyond its current service schedule. However, ACE could choose to provide event "specials" to some large events. A small amount of Charter Bus use may be expected for events with 55,000 attendees, but none is expected for smaller events. With lower ridership levels on VTA bus and Capitol Corridor at smaller events, queuing is expected to be proportionally smaller. Similarly, fewer VTA buses will be staged along Old Ironsides Drive during events. VTA light rail queuing will also be smaller for events with lower attendance levels. Thus, for events with 20,000 attendees or lower, the closure of Tasman Drive between the Convention Center and Centennial Boulevard would not be required. It should be noted that Tasman Drive could be open or closed for events with more than 20,000 attendees, allowing the Stadium Manager the flexibility to keep Tasman Drive open when needed.

4.4.4 Bicycle Access

Bicycle access to the Stadium with the implementation of the TMOP shall remain the same, regardless of the size of event occurring. However, for events with 20,000 attendees or lower, only the bicycle parking lot at the northeast corner of the Great America Main Parking lot would be required, containing 328 bicycle parking spaces. For events exceeding 20,000 attendees, a bicycle valet service shall be provided that includes a dedicated, bicycle storage area

with valet service for visitors. The bicycle storage locations are currently activated outside of the west canopies at Red Lot 1 outside of Intel Gate A, and in Green 1 outside of Dignity Health Gate C.

4.4.5 Pedestrian Access

As noted in section 4.4.2, for events with 20,000 attendees or lower, TMOP lane reconfigurations as outlined in section 5.1 would not be required. Officer control at intersections would only be required at intersections adjacent to parking facilities for events with 20,000 attendees, and officer control at intersections would not be required for events with 10,000 attendees. Further, per section 4.4.3, for events with 20,000 attendees or lower, the closure of Tasman Drive between the Convention Center and Centennial Boulevard would not be required. As such, for smaller events, pedestrians would access the Stadium using standard intersection crossing periods. However, it should be noted that for all events that do implement the closure of Tasman Drive (i.e., events with more than 20,000 attendees), the mid-block Tasman Drive pedestrian crossing may be opened, and vice-versa, when Tasman Drive is open (i.e., events with fewer than 20,000 attendees) the crossing may be closed.

4.4.6 Emergency Vehicle Access

Emergency vehicles would be permitted to use the restricted section of Tasman Drive, although they would be required to travel at slow speeds to ensure pedestrian safety. Access to all sides of the stadium would be provided via the Stadium's Main Lot (Red Lot 1 and Green Lot 1), Tasman Drive, and Centennial Boulevard. Traffic control officers would be directed to prioritize emergency vehicle access through officer-controlled intersections during gameday events.

As noted in section 4.4.2, for events with 20,000 attendees or lower, TMOP lane reconfigurations would not be implemented. Further, per section 4.4.3, for events with 20,000 attendees or lower, the closure of Tasman Drive between the Convention Center and Centennial Boulevard would not be required. As such, for smaller events, emergency vehicles would be able to access to the Stadium from all directions.



5.0 Components

The TMOP identifies all necessary components for providing efficient access to and from the stadium site by way of all modes of transportation. This section provides details on how access for each mode will be provided.

5.1 Vehicle Access

Vehicle access to and from the Stadium will be optimized to maximize inbound capacity during the pre-event period and outbound during the post-event period through a comprehensive program of lane adjustments, traffic signal timing / phasing modifications, and street restrictions supplemented with signage and deployment of officers to monitor intersection operation. Vehicle access has been designed to maximize traffic flow in and out of the Stadium area, thereby minimizing the overall period of congestion for all users while retaining local traffic needs and minimizing conflict points between Stadium and non-Stadium traffic. In addition, for events with above 20,000 attendees, the section of Tasman Drive immediately adjacent to the Stadium, between Convention Center Circle east to Centennial Boulevard, may be closed to all vehicular traffic providing a pedestrian zone for Stadium patrons arriving from or departing to VTA light rail or walking to and from off-site parking facilities. Further, during vehicle ingress, the north side of Tasman Drive between Great America Parkway and Convention Center Circle (i.e., westbound Tasman Drive) will be closed to all non-emergency vehicular traffic, extending the pedestrian zone for Stadium patrons walking from off-site parking facilities west of the Stadium. During vehicle egress, the south side of Tasman Drive between Great America Parkway and Convention Center Circle (i.e., eastbound Tasman Drive) will be closed to all non-emergency vehicular traffic, extending the pedestrian zone for Stadium patrons walking to off-site parking facilities west of the Stadium.

Access routes to and from Stadium parking facilities are illustrated in **Figures 5.1-1a** and **5.1-1b** for ingress and egress, respectively.

5.1.1 Vehicle Ingress

In the hours prior to the start of any Stadium event, the surrounding transportation network is to be adjusted to allow for efficient ingress into designated parking facilities. The details associated with the traffic plan for vehicle ingress includes:

Hours of Implementation

Based on historical behavior at Candlestick Point and Levi's Stadium, fans typically arrive at parking facilities over five hours prior to the start of a regular-season Sunday afternoon game. Thus, for regular-season Sunday afternoon games, the vehicle ingress portion of the TMOP should be implemented five hours prior to the start of a game. However, as part of the Stadium's Conditions of Approval, tailgating activities shall not occur prior to 9:00 AM on game days in the Great America Theme Park parking lot, or Stadium parking areas within the Stadium security perimeter (i.e., Lots 1, 2, 3, 4, 7, 10, 11, and 12). These parking areas will be barricaded and staffed until 9:00 AM to preclude event attendees from arriving before 9:00 AM. Thus, access to these specific locations will be prohibited prior to 9:00 AM for regular-season Sunday afternoon games. However, it should be noted that this policy is subject to change based on the discretion of the Santa Clara Chief of Police, or his/her designee.

For events of smaller size, the hours of implementation of the TMOP should be scaled appropriately per the findings of section 4.0. For weekday evening events, the hours of implementation of the TMOP should be in accordance with the findings of section 6.0.

Directional Signage

The vehicle ingress plan associated with the TMOP shall include signage to direct patrons to the Stadium parking facilities. It is anticipated that over 60 percent of Stadium patrons will have assigned parking lots to park in, and in some cases, assigned spaces within assigned parking lots to park in. The remaining 40 percent of Stadium patrons without assigned parking lots will park in general admission parking lots. Directional signage shall be placed throughout the Stadium area to clearly identify routes to specific assigned parking lots, as well as general admission cash-only lots. The location of each sign throughout the Stadium area is illustrated in **Figure 5.1-2**.

Changeable Message Signs

As arrival to some of the Stadium's parking facilities can be expected to begin over five hours prior to the start of a regular-season Sunday afternoon game, changeable message signs must be in place and functioning no less than six hours prior to a start of a game. For events of smaller size, the schedule for deployment of changeable message signs should be scaled appropriately per the findings of section 4.0.

Each sign shall notify motorists of Stadium activity, and suggest alternate routes for other land uses. The location of each sign is provided in **Figure 5.1-3**. Further, it should be noted that four days in advance of an event, additional changeable message signs are to be placed at key locations (e.g., nearby freeway ramps and key roadways) to warn drivers to expect traffic congestion due to Stadium-related traffic. Signs will indicate the day and time of the game, warn drivers that substantial congestion is expected, and recommend alternative routes using other freeway ramps or streets to avoid Stadium-related traffic.



Figure 5.1-1a: Vehicular Paths of Travel – Ingress



Figure 5.1-1b: Vehicular Paths of Travel – Egress



Figure 5.1-2: Detailed Gameday Signage





Figure 5.1-3: Advance Event Message Signs





Road Restrictions and On-Street Parking Restrictions

As discussed in section 2.2.2, some roadways shall be closed to all motorists, and others shall be restricted to motorists who are local residents. Many of the road restrictions will include residential streets – ensuring that Stadium traffic does not negatively affect local residents. These roadways include:

Event-related vehicle access restriction and on-street parking restriction:

- Calle De Primavera;
- Fairway Glen Drive;
- Hogan Drive;
- Eisenhower Drive;
- Hope Drive;
- Agnew Road;
- Bassett Street;
- Davis Street;
- Cheeney Street;
- Fillmore Street;
- Lakeshore Drive;
- Lake Santa Clara Drive;
- Reamwood Avenue;
- Birchwood Drive;
- Adobe Wells Mobile Home Park Access;
- Palamos Avenue;
- Sandia Avenue;
- Bridgewood Way;
- Wildwood Avenue;
- Stars and Stripes Drive;
- Centennial Boulevard;
- Renaissance Drive; and
- Democracy Way.

On-street parking restriction only:

- Lick Mill Boulevard;
- Lafayette Street;
- Freedom Circle;
- Mission College Boulevard;
- Hitchborn Drive;
- Our Lady's Way;
- Patrick Henry Drive;
- Old Ironsides Drive;
- Old Glory Lane;
- Betsy Ross Drive;
- Bunker Hill Lane;
- Stars and Stripes Drive;
- Democracy Way;
- Calle Del Sol;
- Calle De Luna; and
- Calle Del Mundo.

As arrival to some of the Stadium's parking facilities can be expected to begin over five hours prior to the start of a regular-season Sunday afternoon game, roadway restrictions must be implemented no less than six hours prior to a start of a game. For events of smaller size, the schedule for road restrictions and on-street parking restrictions should be scaled appropriately per the findings of section 4.0.

A hierarchy of solutions are to be implemented, based on the extent to which neighborhood intrusion occurs:

1. Initially, cones and "ROAD CLOSED TO STADIUM TRAFFIC" signs shall be placed at the appropriate residential streets.
2. Should unacceptable levels of neighborhood intrusion occur, curbside signage shall be provided noting that on-street parking is prohibited for Stadium traffic, in addition to the placement of cones and "ROAD CLOSED TO STADIUM TRAFFIC" signs.
3. Should unacceptable levels of neighborhood intrusion continue to occur, officers will be assigned to neighborhood entrances to monitor all vehicle entry to residential streets, in addition to the placement of cones, "ROAD CLOSED TO STADIUM TRAFFIC" signs, and curbside signage.
4. Finally, should unacceptable levels of neighborhood intrusion continue to occur, a Residential Permit Parking program may be instituted if requested by the impacted neighborhoods, and should the affected city concur. In addition to the placement of cones, "ROAD CLOSED TO STADIUM TRAFFIC" signs, curbside signage,

and the assignment of officers to monitor vehicle entry, signage noting that the area is designated for Residential Permit Parking only shall be installed.

Additionally, certain roadways will be marked for restricted parking and/or tow away zones. These roadways shall include Patrick Henry Drive, Old Ironsides Road, Bunker Hill Lane, and Democracy Way, which will be designated for Charter Bus staging, and Lafayette Street, which is to be used by residents only. Implementation of these parking restrictions should be done by way of signage along the curb, stating that parking is prohibited on specific Stadium operation dates.

Officer Monitored Intersections

A number of intersections in the vicinity of the Stadium that will include lane adjustments as part of the TMOP traffic ingress plan will include officers to monitor traffic flow. Officers would not manually direct traffic flow; traffic signals at each intersection will continue to operate with signal timing optimized for movements carrying Stadium traffic. However, it should be noted that traffic control priority will be for light rail, and no manual operations of traffic signals are planned.

The duty of each officer stationed at an intersection is to ensure that motorists and pedestrians continue to observe their designated signal crossing times, as well as ensure that prohibited movements do not occur (e.g., turns into residential neighborhoods). Each intersection, and the proposed number of officers assigned to manage the event day traffic flow, are listed below:

- Great America Parkway / SR-237 Ramps (requires two officers);
- Great America Parkway / Great America Way (no officers required);
- Great America Parkway / Old Mountain View–Alviso Road (requires one officer);
- Great America Parkway / Bunker Hill Lane (requires one officer);
- Great America Parkway / Tasman Drive (requires three officers);
- Great America Parkway / Stadium North Driveway (requires one officer, post-event only);
- Great America Parkway / Old Glory Lane (requires three officers);
- Great America Parkway / Patrick Henry Drive (requires two officers);
- Great America Parkway / Mission College Boulevard (requires three officers);
- Great America Parkway / Our Lady Way (no officers required);
- Great America Parkway / U.S. 101 Northbound Ramps (one officer required);
- Great America Parkway / U.S. 101 Southbound Ramps (one officer required);
- Lawrence Expressway / Tasman Drive (requires two officers);
- Lawrence Expressway / Sandia Avenue (requires two officers);
- Patrick Henry Drive / Tasman Drive (requires two officers);
- Old Ironsides Drive / Tasman Drive (requires two officers);
- Convention Circle / Tasman Drive (requires one officer);
- Tasman Drive at-grade crossing (requires two officers);
- Centennial Boulevard / Tasman Drive (requires two officers);
- Calle Del Sol / Tasman Drive (requires two officers);
- Calle Del Sol / Calle De Luna (requires one officer);
- Lafayette Street / Calle De Luna (requires one officer);
- Lick Mill Boulevard / Tasman Drive (requires one officer);
- North 1st Street / Tasman Drive (requires two officers);



- Lafayette Street / Hogan Drive (no officers required);
- Marriott Parking Access / Mission College Boulevard (requires one officer);
- Freedom Circle / Agnew Road / Mission College Boulevard (requires one officer); and,
- Montague Expressway / Mission College Boulevard (requires two officers).

The locations of officer-monitored intersections are illustrated in **Figure 5.1-4**.

Lane Delineation (coning)

A number of intersections in the vicinity of the Stadium will require lane adjustments, including the restriction of some turning movements and lane restrictions. These adjustments will allow for the most efficient flow of vehicles into the Stadium area, while minimizing conflicts with pedestrians.


The majority of these lane adjustments will be implemented using cones and temporary barricades, which minimizes the required setup and takedown time and allow for easy modifications as needed to permit access for special vehicles and non-Stadium traffic. At officer-monitored intersections, the deployment of traffic monitoring personnel will supplement coning in the enforcement of the designated lane changes. The lane adjustments to be implemented during the vehicle ingress period are illustrated in **Figure 5.1-4**.

Traffic Signal Timing/Phasing Modifications

A number of intersections will require adjustments to traffic control devices during event periods. In particular, it will be necessary to adjust signal timing at intersections near the Stadium (including some of the intersections with lane adjustments and / or officer monitoring) during the vehicle ingress period to accommodate heavy inbound traffic flows towards the Stadium. A special event-day signal plan containing all the necessary timing and phasing adjustments will be developed for use during events and will be implemented either in the field by officers, from the Stadium's Traffic Operations Center, or from the Traffic Operations Center at the Santa Clara City Hall. However, as noted, traffic control priority will be for light rail, and no manual operations of traffic signals are planned.

While some intersections would see major changes in timing and phasing for traffic, light rail phasing at all intersections along Tasman Drive will be retained (with some modifications, if required) to facilitate light rail operations through the Stadium area. Some pedestrian phases at specific intersections along major event-day traffic routes will be temporarily deactivated to eliminate potential vehicular-pedestrian conflicts, which could both present safety issues for pedestrians and substantially affect traffic flow to and from the Stadium. The locations of allowable pedestrian crossings during events are illustrated in **Figure 5.1-5**. These signal modifications will be supplemented by the presence of the officers deployed throughout the Stadium area, who will be directed to facilitate pedestrian and bicycle access in coordination with VTA's light rail operations as needed to ensure the safety of all roadway users, whether Stadium-related or not. In particular, it may be occasionally necessary to prematurely terminate conflicting traffic phases at some intersections to facilitate the movement of pedestrians and light rail trains into and out of the area. Officers stationed at these intersections would serve to reinforce these signal timing changes by flushing out vehicles stranded in the intersection and keeping light rail tracks and crosswalks clear and unobstructed. **Table 5.1-1** summarizes the intersection vehicle turning movements and signal phases that will remain active during the vehicle ingress period.

Figure 5.1-4: Proposed Inbound Lane Configurations and Control



Digitized by Google




Table 5.1-1: Signal Phasing Modifications – Vehicle Ingress

Intersection	Active Traffic Phases / Movements								Active Pedestrian Phases			
	NBL	NBTR	SBL	SBTR	EBL	EBTR	WBL	WBTR	North (E-W)	South (E-W)	East (N-S)	West (N-S)
Great America Parkway / SR-237 Westbound Ramps				X			X	X				X
Great America Parkway / SR-237 Eastbound Ramps		X	X	X		X						X
Great America Parkway / Great America Way		X	X	X		X		X			X	X
Great America Parkway / Old Mountain View–Alviso Road		X	X	X		X						X
Great America Parkway / Bunker Hill Lane			X	X				X		X	X	X
Great America Parkway / Tasman Drive			X						X			
Great America Parkway / Old Glory Lane		X							X			X
Great America Parkway / Patrick Henry Drive	X	X				X	X				X	X
Great America Parkway / Mission College Boulevard	X	X		X		X					X	X
Patrick Henry Drive / Tasman Drive				X		X		X	X	X	X	
Old Ironsides Drive / Tasman Drive				X		X			X	X	X	
Convention Circle / Tasman Drive						X			X	X	X	
Centennial Boulevard / Tasman Drive								X	X	X		X
Calle Del Sol / Tasman Drive				X	X			X	X			
Calle Del Sol / Calle De Luna	X	X				X		X				
Lafayette Street / Calle De Luna	X	X		X			X	X	X		X	
Lick Mill Boulevard / Tasman Drive		X		X			X	X	X	X		
North 1 st Street / Tasman Drive	X	X	X	X	X	X	X	X	X	X	X	X
Marriott Parking Access / Mission College Boulevard		X				X	X		X	X	X	X
Freedom Circle / Agnew Road / Mission College Boulevard		X	X		X		X	X	X	X	X	X
Mission College Boulevard / Montague Expressway	X	X	X	X	X	X	X	X	X	X	X	X
Lawrence Expressway / Tasman Drive	X	X	X	X	X	X	X	X	X	X	X	X
Lawrence Expressway / Sandia Avenue	X	X	X	X	X	X	X	X	X	X	X	X

Source: AECOM, 2014.

Notes: X = Active Phase / Movement

■ = Non-existent movement or crossing



Traffic Control Center Coordination

A traffic control center within Levi's® Stadium is used to manually manage traffic signal operations to better accommodate traffic needs. Manual management of signal operations is possible at intersections with updated signal controller cabinets, surveillance cameras, traffic signal fiberoptic interconnection conduits and cables, and associated communications upgrades. Per the CEQA Findings and Statement of Overriding Considerations associated with the 49ers Santa Clara Stadium Project, the following intersections were identified as requiring upgrades:

- Great America Parkway / Great America Way;
- Great America Parkway / Alviso Road;
- Great America Parkway / Bunker Hill Lane;
- Great America Parkway / Tasman Drive;
- Great America Parkway / Old Glory Lane;
- Great America Parkway / Patrick Henry Drive;
- Great America Parkway / Mission College Boulevard;
- Lawrence Expressway / Tasman Drive;
- Lafayette Street / Great America Way;
- North First Street / Montague Expressway;
- Zanker Road / Montague Expressway;
- O'Toole Avenue / Montague Expressway;
- Trade Zone Boulevard / Montague Expressway;
- North First Street / SR 237;
- Great America Parkway / SR 237;
- I-880 NB / Tasman Drive; and
- Abbott Avenue / Calaveras Boulevard.

Additionally, per the Stadium Development Permit, traffic signal controller cabinets, surveillance cameras, traffic signal fiberoptic interconnection conduits and cables, and associated communications upgrades shall be installed at locations identified in this TMOP within the area bounded by SR 237 to the north, U.S. 101 to the south, Calabazas Creek to the west, and the Guadalupe River to the east. Specifically, upgrades were made at the following locations:

- Patrick Henry Drive / Tasman Drive;
- Old Ironsides Drive / Tasman Drive;
- Convention Center Circle / Tasman Drive;
- Centennial Boulevard / Tasman Drive;
- Calle Del Sol / Tasman Drive;
- Lick Mill Boulevard / Tasman Drive;
- Freedom Circle (West) / Mission College Boulevard;
- Freedom Circle (East) / Agnew Road / Mission College Boulevard;

The location of all intersection receiving upgraded traffic signal controller cabinets, surveillance cameras, traffic signal fiberoptic interconnection conduits and cables, and associated communications upgrades is shown in **Figure 5.1-6**.

Encroachment Permits


Encroachment permits are required to place equipment and modify access/controls within other jurisdictions' rights of way. These jurisdictions (aside from the City of Santa Clara) include the City of San Jose, City of Sunnyvale, VTA, and Caltrans. Encroachment permits, including the relevant jurisdictions, are summarized in **Table 5.1-2**.

Table 5.1-2: Encroachment Permit Needs

Location	Item	Jurisdiction
SR 237 at Great America Parkway	Changeable Message Signs (2)	Caltrans
U.S. 101 at Great America Parkway	Changeable Message Signs (1)	Caltrans
U.S. 101 at Lawrence Expressway	Changeable Message Signs (1)	Caltrans
U.S. 101 at Montague Expressway	Changeable Message Signs (1)	Caltrans
I-880 / U.S. 101 Interchange	Changeable Message Signs (2)	Caltrans
I-880 / SR 237 Interchange	Changeable Message Signs (2)	Caltrans
U.S. 101 / SR 237 Interchange	Changeable Message Signs (2)	Caltrans
SR 237 at Lawrence Expressway	Changeable Message Signs (1)	Caltrans
SR 237 at North 1 st Street	Changeable Message Signs (1)	Caltrans
Reamwood Avenue / Tasman Drive	Roadway restriction, Traffic Monitoring Officer (1)	City of Sunnyvale
Adobe Wells Entrance / Tasman Drive	Roadway restriction	City of Sunnyvale
Birchwood Drive / Tasman Drive	Roadway restriction, Traffic Monitoring Officer (1)	City of Sunnyvale
Lawrence Expressway / Tasman Drive	Traffic Monitoring Officer (1)	Santa Clara County
Lawrence Expressway / Tasman Drive	Changeable Message Signs (3)	Santa Clara County
Lawrence Expressway / Sandia Avenue	Traffic Monitoring Officer (1)	Santa Clara County
Tasman Drive, Lawrence Expressway to North 1 st Street	Signal Coordination	Santa Clara County
North 1 st Street / Tasman Drive	Traffic Monitoring Officer (1)	City of San Jose
Tasman Drive, adjacent to Stadium	New at-grade crossing	VTA
Great America VTA Station	Mid-Block Crossing Gate Operator	VTA

It should be added that all non-VTA personnel stationed, or working in the vicinity of VTA light rail tracks will have received VTA safety training. This training will come as part of a Rail Access Permit issued to the 49ers.

Figure 5.1-6: Traffic Signal Improvement Locations



Jurisdictional Permissions

To implement the proposed intersection adjustments on event days, the City of Santa Clara Traffic Engineer will obtain permissions based on the jurisdiction a specific intersection falls under. Intersections that require adjustment per TMOP are sorted by jurisdiction below:

Caltrans, Santa Clara County, City of San Jose:

- Changeable Message Signs:
 - S.R. 237 approaching U.S. 101 eastbound;
 - S.R. 237 approaching Lawrence Expressway eastbound;
 - S.R. 237 approaching Great America Parkway eastbound;
 - S.R. 237 approaching Great America Parkway westbound;
 - S.R. 237 approaching I-880 westbound;
 - U.S. 101 approaching S.R. 237 eastbound;
 - U.S. 101 approaching Lawrence Expressway eastbound;
 - U.S. 101 approaching Great America Parkway westbound;
 - U.S. 101 approaching Montague Expressway westbound;
 - U.S. 101 approaching I-880 westbound;
 - I-880 approaching U.S. 101 northbound;
 - I-880 approaching S.R. 237 southbound
 - Lawrence Expressway / Tasman Drive;
 - North 1st Street / Tasman Drive; and
 - Montague Expressway / Mission College Boulevard.
- Cones, temporary barricades, signal adjustments, directional signage:
 - Reamwood Avenue at Tasman Drive;
 - Adobe Wells Mobile Home Park Access at Tasman Drive;
 - Birchwood Drive at Tasman Drive;
 - Wildwood Avenue at Mission College Boulevard;
 - Lawrence Expressway / Tasman Drive;
 - Lawrence Expressway / Sandia Avenue;
 - Lawrence Expressway / Sandia Avenue; and
 - Montague Expressway / Mission College Boulevard.

City of Santa Clara:

- Cones, temporary barricades, signal adjustments, directional signage:
 - Great America Parkway / SR-237 Ramps;
 - Great America Parkway / Great America Way;
 - Great America Parkway / Old Mountain View Alviso Road;
 - Great America Parkway / Bunker Hill Lane;
 - Great America Parkway / Tasman Drive;
 - Great America Parkway / Stadium North Driveway;
 - Great America Parkway / Old Glory Lane;
 - Great America Parkway / Patrick Henry Drive;
 - Great America Parkway / Mission College Boulevard;
 - Great America Parkway / Our Lady Way;



- Patrick Henry Drive / Tasman Drive;
- Old Ironsides Drive / Tasman Drive;
- Convention Circle / Tasman Drive;
- Centennial Boulevard / Tasman Drive;
- Calle Del Sol / Tasman Drive;
- Calle Del Sol / Calle De Luna;
- Lafayette Street / Calle De Luna;
- Lick Mill Boulevard / Tasman Drive;
- North 1st Street / Tasman Drive;
- Marriott Parking Access / Mission College Boulevard;
- Freedom Circle / Agnew Road / Mission College Boulevard;
- Roadway Restriction to Event Traffic:
 - Calle De Primavera at Lafayette Street;
 - Fairway Glen Drive at Lafayette Street;
 - Hogan Drive at Lafayette Street;
 - Eisenhower Drive at Lafayette Street;
 - Hope Drive at Lafayette Street;
 - Basset Street at Agnew Road;
 - Davis Street at Agnew Road;
 - Cheeney Street at Agnew Road;
 - Fillmore Street at Agnew Road;
 - Hunter Place at Agnew Road;
 - Lakeshore Drive at Agnew Road;
 - Lake Santa Clara Drive at Agnew Road; and
 - Agnew Road at Lafayette Street.

Access to Area Properties (employees, neighborhoods, golf course, etc)

In order to provide access to owners, employees, business patrons, and other users of neighboring properties during event periods, in locations where lane configurations have been adjusted and roadways have been closed, employees and patrons of local businesses, as well as local residents, will continue to have access to their properties. Ingress and egress of non-Stadium traffic will be facilitated by the presence of officers and stadium staff stationed at key intersections surrounding the Stadium. Officers will be directed to prioritize this non-Stadium traffic to minimize the impacts of Stadium events (and associated roadway restrictions and traffic congestion) on neighboring stakeholders.

Parking Locations

Arrival at some of the Stadium's parking facilities can be expected to begin as early as 9:00 am for a regular-season Sunday afternoon game. As such, all Stadium parking facilities must be clearly marked prior to 9:00 am. For events of smaller size, the schedule for deployment of parking lot signage should be scaled appropriately per the findings of section 4.0. However, it should be noted that this policy is subject to change based on the discretion of the Santa Clara Chief of Police, or his/her designee.

Stadium staff will be present at these locations throughout the duration of the pre-event, event, and post-event periods to provide Stadium patrons with directional guidance and to assist patrons with disabilities in securing shuttle access to the Stadium.

Non-TMOP Parking Facilities

Measures to protect property owners from parking intrusion by Stadium patrons are described in Section 5.5.1.

Passenger Drop-Off / Pick-Up Area

The defined location for passenger drop-off and pick-up can vary for events. The largest variance comes between NFL and Non-NFL events at Levi's Stadium. For 49ers home games, two locations have been identified for use. Patrons looking to drop-off and pick-up on the west side of Levi's Stadium can do so at Betsy Ross Drive and Bunker Hill Lane. Patrons accessing the east side of Levi's Stadium can utilize the Calle De Luna for drop-off and pick-up.

During Non-NFL events, the locations utilized during 49ers home games will be activated. However, depending on the nature of the event, additional locations may be activated. For example, during concerts that are expected to attract many young patrons that will be dropped off and picked up, contracted parking lots would be converted into larger drop-off and pick-up locations. The size and scope would be scaled appropriately depending on the demand. In instances such as this, additional communication takes place via website, email blasts, and flyers handed out upon dropping off for pick up directions.

Outreach and Education

Season ticket holders and general admission patrons/parkers will be able to access transportation, transit, and parking information via a number of different methods. To ensure that these patrons, as well as area residents, businesses, and transit users are informed of event day occurrences and operations, the Stadium Manager shall disseminate educational travel information to all parties. Public awareness and communications strategies for implementation include:


- Education upon ticket purchase and/or with tickets;
- Brochures and mailers to area residents and local businesses;
- Press releases and media alerts;
- Telephone hotline;
- Web-based dissemination via social media and cell phone application;
- Information posted on VTA light rail trains and buses; and
- Stadium Stakeholders Group meetings.

5.1.2 Vehicle Egress

Prior to the end of any given Stadium event, the traffic plan for vehicular ingress will be modified to optimize traffic flow away from the area. The details associated with the traffic plan for vehicle egress includes:



Figure 5.1-7: Paratransit and Pick-up / Drop-off Routes, and Supplemental



Hours of Implementation

Post-game traffic changes will be in effect up to three hours following game end to facilitate vehicle egress for Stadium patrons. Similar to vehicle ingress, the hours of implementation of the TMOP's traffic changes related to vehicle egress will be scaled appropriately for events of smaller size (as described in Section 4.0) or weekday evening events (Section 6.0).

Directional Signage

Specific egress routes will be designated for each event-day parking facility in order to optimize the distribution of post-event traffic in all four directions and into the roadway network serving the Stadium, generally following the same route as the ingress route. Similarly to the ingress period, directional signage will be placed to assist motorists exiting the area during the Stadium egress period.

Changeable Message Signs

The changeable message signs described in Section 5.1.1 will remain in effect through the post-event period to minimize entry in to the Stadium area by non-Stadium traffic and optimize traffic flow away from the Stadium. The signs are relocated and messaging adjusted to reflected desired traffic patterns and information.

Road Restrictions and On-Street Parking Restrictions

The street restrictions and on-street parking restrictions described in Section 5.1.1 will remain in effect through the post-event period to contain and direct Stadium traffic.

Officer Monitored Intersections

Officers assigned to the intersections listed in Section 5.1.1 will remain at their post through the post-event period to optimize Stadium vehicle egress, until such a time that traffic congestion returns to ambient levels.

Lane Delineation (coning)

The lane adjustments to be implemented during the vehicle egress period are illustrated in **Figure 5.1-8**.

At approximately halftime during a Stadium gameday (or the equivalent half-way mark for other Stadium events), traffic monitoring personnel deployed at intersections will begin implementing the required lane adjustments for the vehicle egress period, starting with the areas furthest from the Stadium. Any changes to lane adjustments at intersections without officer monitoring are expected to be executed by traffic monitoring personnel stationed at the next closest intersection.

Traffic Signal Timing/Phasing Modifications

At approximately halftime during a Stadium gameday (or the equivalent half-way mark for other Stadium events), a specialized signal plan for vehicle egress will enter into effect. Similar to the vehicle ingress signal plan, the vehicle egress signal plan will implement a series of timing and phasing modifications at Stadium area intersections to facilitate traffic flow away from the Stadium along the designated egress routes.

Digitized by Google



Table 5.1-3 summarizes the intersection vehicle turning movements and signal phases that will remain active during the vehicle egress period. As with vehicle ingress, pedestrian phasing at all intersections and light rail phasing at all intersections along Tasman Drive will be retained to facilitate pedestrian access and light rail operations.

Traffic Control Center Coordination

Remote traffic signal coordination as described in Section 5.1.1 will apply during the Stadium vehicle egress period.

Encroachment Permits

Encroachment permits as described in Section 5.1.1 will apply during the Stadium vehicle egress period.

Responsibilities

The responsibilities associated with intersection adjustments would remain the same for the vehicle egress period as for the vehicle ingress period.

Access to Area Properties (employees, neighborhoods, golf course, etc)

Access to neighboring properties would be retained and secured similar to the vehicle ingress period.

Parking Locations

Any directional signage to help Stadium patrons find their vehicles will remain in place for the duration of the event (and after its conclusion), and Stadium staff will continue to be present at these locations to facilitate patron needs. Following the end of the vehicle egress period, Stadium staff will remove any temporary Stadium-related signage. For events of smaller size, the schedule for parking lot use and Stadium staff deployment at these locations should be scaled appropriately per the findings of section 4.0.

Non-TMOP Parking Facilities

Measures to protect property owners from parking intrusion by Stadium patrons are described in Section 5.5.1.

Passenger Drop Off/Pick Up Area

The consolidated passenger pick-up and drop-off area for private vehicles and ADA paratransit vehicles, as described in Section 5.1.1 for vehicle ingress, would remain in effect through the duration of the event and post-event periods.

Counterflow Operations

Event egress counter-flow operations on Great America Parkway have been put in place for large scale events at Levi's Stadium. While the event is still in process (e.g. during NFL half-time), contracted labor and equipment is set up for egress operations at the direction of Levi's Stadium Management, SCPD and the command post.

During peak egress times, typically right at the end of the event, traffic directions are reversed in two northbound lanes on Great America Parkway between Old Glory Lane and Mission College Blvd. The number 1 and 2 lanes are reversed during this operation. During this period, the normal background traffic flowing northbound on Great America Parkway is restricted to either a left turn or a U-turn at Mission College Blvd. During the counter-flow operation,



employee shuttles and emergency vehicles are only allowed access northbound on Great America Parkway north of Mission College Blvd via controlled movements with security and public safety personnel at the affected intersections. Several issues must be taken into consideration during the counter-flow operations on this stretch of Great America Parkway. First, employees typically park in Purple Lot 3, which exits onto Great America Parkway from the east at Patrick Henry Drive. Security and public safety personnel must carefully control the interaction to allow this traffic to enter the counter-flow lanes. Secondly, pedestrians must be controlled at all sidewalks and intersections, which is typically done by security personnel with the assistance of public safety officers. Priority is given to vehicular traffic, especially at intersections further away from the stadium. It must also be considered during events in which shared use takes place of the Great America Theme Park parking lot how to allow access for their patrons, depending on the time of the operation. Traffic is also allowed for theme park visitors to pick up their guests of the park.

Counter-flow operations also take place on northbound Great America Parkway between Bunker Hill Lane and State Highway 237. During peak egress times at the end of an event, traffic directions are reversed in two southbound lanes on Great America Parkway from Highway 237 to Bunker Hill Lane. Security personnel are posted at all driveways exiting into the counter-flow lanes, prohibiting incorrect directional turns from those driveways. With this operation activated, cars from Red Lot 1 are afforded the opportunity to choose between exiting onto 237W or 237E at Bunker Hill Lane, by choosing the counter-flow or regular flow lanes. Guests exiting from Red Lot 3, Red Lot 4, Red Lot 5 and potentially Green Lot 2 and portions of Blue Lot 1, are afforded the opportunity to exit onto 237E by traveling on Old Mountain View/Alvisio Road or continuing in the counter-flow lanes to 237W. Guests exiting Red Lot 6 are afforded the opportunity to exit to 237E by remaining in the regular flow lanes on Great America Parkway northbound, or to Hwy 101 via Great America Way to southbound Lafayette Street to Montague Expressway. Electronic Portable Changeable Message Signs (PCMS) are placed at various points of choice to inform guests of their options.

Counter-flow operations will take place on Tasman westbound between Patrick Henry Drive and Lawrence Expressway, reversing traffic in the eastbound number one lane to flow westbound between the two streets. The number two lane will remain eastbound, allowing access for local Adobe Wells residents and guests during operation implementation. This plan allows a dedicated in and out access point for the residents, granting them a smoother and lesser impact during exit operations.

Outreach and Education

Outreach and education as described in Section 5.1.1 will apply during the Stadium vehicle egress period.

Table 5.1-3: Signal Phasing Modifications – Vehicle Egress

Intersection	Active Traffic Phases / Movements								Active Pedestrian Phases			
	NBL	NBTR	SBL	SBTR	EBL	EBTR	WBL	WBTR	North (E-W)	South (E-W)	East (N-S)	West (N-S)
Great America Parkway / SR-237 Westbound Ramps	X	X		X								X
Great America Parkway / SR-237 Eastbound Ramps		X			X							X
Great America Parkway / Great America Way		X			X		X				X	X
Great America Parkway / Old Mountain View–Alviso Road		X										X
Great America Parkway / Bunker Hill Lane		X					X			X	X	X
Great America Parkway / Tasman Drive	X						X		X			
Great America Parkway / Old Glory Lane							X		X			X
Great America Parkway / Patrick Henry Drive		X		X		X	X				X	X
Great America Parkway / Mission College Boulevard	X	X		X		X					X	X
Patrick Henry Drive / Tasman Drive	X						X		X	X	X	
Old Ironsides Drive / Tasman Drive		X					X		X	X	X	
Convention Circle / Tasman Drive	X								X	X	X	
Centennial Boulevard / Tasman Drive			X						X	X		X
Calle Del Sol / Tasman Drive			X		X		X		X			
Calle Del Sol / Calle De Luna	X	X				X		X				
Lafayette Street / Calle De Luna	X	X		X			X	X	X		X	
Lick Mill Boulevard / Tasman Drive		X		X		X	X	X	X	X		
North 1 st Street / Tasman Drive	X	X	X	X	X	X	X	X	X	X	X	X
Marriott Parking Access / Mission College Boulevard		X	X			X			X	X	X	X
Freedom Circle / Agnew Road / Mission College Boulevard		X	X			X			X	X	X	X
Mission College Boulevard / Montague Expressway	X	X	X	X	X	X	X	X	X	X	X	X
Lawrence Expressway / Tasman Drive	X	X	X	X	X	X	X	X	X	X	X	X
Lawrence Expressway / Sandia Avenue	X	X	X	X	X	X	X	X	X	X	X	X

Notes: X = Active Phase / Movement

■ = Non-existent movement or crossing



5.2 Transit Access

Transit access to the site is efficient and direct. Both heavy and light rail service already have stations within a few minute walk from the site. VTA Light Rail stops just north of the Stadium site. One of the Union Pacific Railroad's main lines lies directly east of the site, allowing train service from Sacramento/Oakland, Stockton/Tracy, and Gilroy/San Jose/San Francisco. Though Caltrain does not pass directly by the site, there are options described below for a convenient transfer. Special bus service operated by local transit agencies is anticipated to continue in a similar fashion to that now provided for events at Candlestick Point, and adequate bus parking and loading areas are available on the streets near the site. A system of exclusive pedestrian walkways can be developed using portions of existing streets and parking lots that would be closed to vehicles on event days. Such a system would minimize pedestrian/vehicle crossings after an event, and enhance the fan experience by making access to transit quicker and more convenient.

5.2.1 VTA Light Rail

It is important to note that the details of VTA light rail and bus operations before and after various events at the Stadium have been coordinated and developed in concert with VTA staff. This section of the TMOP seeks to outline what those operational details might be, and describes a number of potential solutions.

VTA provides light rail service to the Stadium. VTA currently operates two light rail lines (Winchester to Mountain View and Santa Teresa to Alum Rock) that jointly serve the system spine on North First Street and then branch off east and west of that spine. The closest existing light rail loading/unloading area is the Great America Station, which is located immediately northwest of the Stadium entrance on Tasman Drive, and is regularly served by the Winchester to Mountain View light rail line. The current Sunday LRT (Light Rail Train) service, with two car trains every 30 minutes, could carry approximately 2,000 riders. The service would be relatively slow for Stadium patrons if all local stops were made. Adequately serving the projected event-day demand will require significantly more light rail service than is currently operated on Sunday by VTA.

The details associated with transit access with regard to VTA light rail are as follows:

Ridership

The VTA light rail system is 42 miles long, and provides good geographic coverage. Stadium patrons in the areas of Milpitas, Berryessa, East San Jose, Downtown San Jose, Willow Glen, South San Jose, and Campbell are all within a short distance of a light rail station. Patrons from other areas can easily drive to the light rail stations with parking lots. Ridership levels are expected to increase substantially on event days, with an estimated 4,500 Stadium patrons using the service (as estimated in the EIR). Approximately 4,500 patrons were estimated to use local bus service (2,500 SamTrans, 1,500 VTA local bus, and 500 east bay public bus) to reach the Stadium. It is possible that VTA will encourage these patrons to use light rail instead of buses to reach the Stadium. Therefore, a conservative assumption is that 3,000 of the bus riders will come via light rail instead. Of the potential 7,500 total LRT riders, two-thirds (5,000) are expected to arrive from the southeast and one-third (2,500) from the northwest. Additionally, it is expected that 90 percent (2,700) of the 3,000 Caltrain riders are coming from the north and are likely to transfer to light rail in Mountain View. Therefore, the total demand for light rail could be 10,200 patrons – 5,000 from the southeast and 5,200 from the northwest.

Service Levels

Working with VTA, appropriate service levels for events will be determined. This section presents an initial workable scenario for providing an adequate opening day service.

Headways

VTA Light Rail service in the Stadium area currently operates at 15-minute headways (i.e., frequency of service). VTA Light Rail has a one-mile-long single-track segment at Mountain View, which would constrain headways serving the Mountain View end of the line on event days. Headways could be potentially shortened for brief periods before and after events by adding an on-the-ground supervisor/dispatcher at the Mountain View end and skipping the intermediate station at Evelyn. VTA currently has single-track operations between downtown Mountain View and across Central Expressway to Whisman Station. Analysis indicates that increasing capacity at the end of VTA's LRT line in Mountain View is key to serving Stadium event transit demand mid-line at the Great America Station and to serving the future BART connection in Milpitas. As VTA now operates on an easement from Caltrain, LRT improvements will require additional right-of-way and likely realignment of Caltrain tracks. Due to the complexity of the project, and the incremental utility of additional double-track, VTA is implementing the double-track improvement in two phases. Phase I proposes extending the existing LRT storage track east of the Mountain View Station approximately 1,400 feet east, to connect with the existing single track near the Highway 85 overpass, and adding a special event platform across from Caltrain. This gives VTA some operational flexibility, fits within the railroad corridor without effecting Caltrain operations, and can be done relatively quickly and inexpensively. VTA and Caltrain staffs are in agreement on the Phase I improvement. What is more critical to successful LRT service is the Phase II improvement, double-tracking light rail from Highway 85 to Whisman Station. VTA, Caltrain, and High Speed Rail staffs are currently in discussions to advance the Phase II improvement. Implementation of VTA's planned new Northern Express line, which will provide LRT service from Mountain View to Alum Rock, is not possible until completion of the Phase II Double Track, anticipated by end of 2016.

Since there are two tracks east of the Evelyn Station, shorter headways could be operated east from the Bayshore/NASA station (though the double track starts between the Evelyn and Whisman stations, the first crossover that would allow turning trains back is between the Middlefield and Bayshore/NASA stations). A possible maximum service plan would be six minute headways to Mountain View and six minutes to Bayshore/NASA, for a combined three minute headway east of Bayshore/NASA. These headways could potentially serve 6,000 to 10,000 riders in the peak hour. However, through conversations with VTA, it is expected that a minimum of a 7.5 minute frequency could be provided. To operate highly frequent service, special automatic or manual overrides of traffic signals may be necessary, but traffic volumes are low on Sunday afternoons along the route, an area that is mostly made up of research parks.

Train Size

The Winchester to Mountain View line, as illustrated in **Figure 5.2-1**, is currently restricted to two-car train operation due to the size of the stations on the Vasona segment of that line (downtown San Jose to Winchester). The Tasman West segment (First Street to Mountain View) of the Winchester to Mountain View line, including the Great America station that would serve the proposed Stadium, has three-car stations. Several operating constraints on the Winchester to Mountain View line affect the potential frequency of service. On the Tasman West segment, there the single-track section near the Caltrain station in Mountain View, mentioned above. On the Vasona segment, there are several single-track segments.



Current plans show Winchester trains continuing to Mountain View as they do today. VTA hopes to eventually double track the short segment in Mountain View and begin operating a line between Alum Rock and Mountain View. This analysis does not assume that the double tracking has been completed. However, it is assumed that VTA could operate frequent service to Mountain View for short periods to meet Stadium demands until Phase 2 is implemented.

Event-Day Service

VTA has identified three basic types of events that are likely to occur.

- **All Day Events** where people are expected to arrive and leave over extended periods;
- **Timed Events** where people are expected to arrive in a short period of time, and leave immediately after the event; and
- **Hybrid Events** where people might arrive over an extended period of time but leave at a specified time, or vice versa.

Event Planning and Analysis

Each event will be evaluated to see what the projected light rail ridership and extra service needs would be. This would be done on a continuing basis as information about event schedules are received by VTA. A post event review will also be completed in order to address issues for future events.

All Day Events

These are the all day events where the people are expected to arrive and leave at various times during the event. This might include events like art & wine festivals, craft fairs, etc. In this case, depending on the size of the event, VTA would make no changes to existing service, run additional cars on existing trains, or supplement service with additional trains to boost the frequency. The exact level of service and number of trains and operators required would depend on the event. These events would often be handled by adding cars to existing trains.

Timed Events

This would include 49ers games and events such as concerts or other major sporting events. Smaller events of this type may only require additional cars on scheduled trains, with one or two added trains to handle the anticipated load at the end of the event.

For larger events such as 49ers games, VTA would prepare an augmented schedule for that day. The schedule would preserve the existing service as much as possible. The pre-event service would involve adding cars to the appropriate trains, including trains that do not serve Great America in order to handle loads resulting from people transferring. There would be added trips from Alum Rock and Santa Teresa, locations not normally served by the trains going to Mountain View. There would also be service added between Mountain View and Great America to handle extra passengers from Caltrain. These extra pre-event trains would start approximately 3 hours before the event start time. The exact number and times of extra trains would be determined by the size and timing of the event. Weekday pre-event service would rely very heavily on existing service with maximum car deployments. A limited number of extra trains may be added from each end of the line.

During the event VTA would move and stage the extra trains to be as close to the stadium as possible for the post-event service. A new double crossover will be constructed on Tasman Drive just west of Patrick Henry Drive, and a

storage track is being planned for Tasman Drive between Old Ironsides and Patrick Henry. It is anticipated that these projects will be completed in late August of 2014. The proposed storage areas are illustrated in **Figures 5.2-1a** and **5.2-1b**. The new storage track will be able to accommodate three 3-car trains and these trains would travel eastbound. Also, eastbound trains could stage on the regular service track, but this would require single tracking portions of the system between Mountain View and Old Ironsides and adversely affect regular service. Three 3-car trains can be staged at Baypointe on the center track for trains heading towards Mountain View. Trains could also be stored at the Light Rail operating division on Younger St. and/or Alum Rock, but these locations are 20-30 minutes away from Great America and these extra trains would have to be inserted between regular trains in order to arrive at the stadium at the right time.

For post-event, as many as 7-8 trains could be sent from Great America towards Mountain View (two would have 2 cars while the rest would have 3 with a total capacity of around 3,000-3,500 riders). The first 3-4 trains could depart approximately every 5 minutes. The next 3-4 trains would likely depart approximately every 10 minutes (due to single track limitations in Mountain View). After that the limit would most likely be 4 per hour (half of these would be three car trains with a total capacity 1,600 per hour). This would be examined more closely once the game day loads settle down. Some of the initial extra trains may be able to cycle back and load in the opposite direction if needed.

Figure 5.2-1: Transit Service in the Stadium Vicinity



Figure 5.2-1a: VTA Light Rail Schematic East of Great America Station







Figure 5.2-1b: VTA Light Rail Schematic West of Great America Station



Trains leaving the stadium towards Alum Rock and Santa Teresa could depart approximately every 5 minutes depending on load times. This would mean 8-10 three-car trains could leave the station heading towards Santa Teresa or Alum Rock (with a capacity of 3800-4800 riders). Passengers going east will have to be segregated by destination in order to facilitate loading the trains to make sure people are not confused. Some of the initial extra trains may be able to cycle back and load in the opposite direction if needed.

In addition, an extra train or two may have to be staged at Younger St. to fill in for regular Winchester trains coming from Mountain View that are seriously delayed by post-game loading.

Current plans call for all trains to serve all stations. In most cases the close headways and signal restrictions will require this to happen.

Based on the current fleet, there would be a limit of around 13-14 added trains if all were 3-car consists. Current regular service would require 37 cars (18 two car and 1 one car). The 13-14 added trains would require another 45 cars for a total of 82, leaving 17 spares for maintenance. It is very unlikely more than 80 cars would be available on a regular basis, limiting the capacity to 12-13 extra trains.

VTA buses could be used to augment light rail service to busier locations, if needed. Exact locations for the pick-up and drop off for these buses are to be determined. Possibilities include using Stars & Stripes or the bus stops on Great America at Old Glory and Tasman.

Hybrid Events

These events would treat either the pre-event or post-event service similar to an All Day Event while treating the post event or pre-event service like a timed event. The operating plan would be a mix of the All Day Event plan and a Timed Event Plan.

Passenger Loading/Queuing Areas

A passenger loading/queuing area will be provided north of the stadium on Tasman Drive for major events. The street will be closed to vehicular traffic in this area. This area will allow for easy, direct access to and from the stadium for light rail users. During the post-event exodus, passengers heading west towards Mountain View will board at the regular westbound platform. Passengers heading eastbound towards Winchester, Alum Rock or Santa Teresa will board on the new eastbound platform. Riders will need to be segregated into four separate queuing lines: Mountain View (west), Winchester (east), Alum Rock (east), and Santa Teresa (east) until passenger loads subside.

Satellite Parking Facilities

VTA light rail service will provide opportunities for patrons to park away from the Stadium area, and ride light rail into the Stadium. The potential demand for satellite parking may influence the planned light rail stops and may require some new or modified park-and-ride facilities VTA currently has 21 park-and-ride lots along the light rail lines, providing 6,471 parking spaces. Stadium patrons could potentially use all the park-and-ride lots along the light rail lines. At other locations, patrons could transfer from local light rail service to the event day special service. Potential parking locations (illustrated in **Figure 5.2-2a**), and issues associated with these priority sites, are discussed below:

- Downtown Mountain View – Fee parking is available at this station, but is shared with Caltrain and is fully utilized on weekdays. The parking facility is owned and operated by Caltrain, and not VTA. In total, 338 parking spaces are provided for motorists, and 98 bike lockers and 20 bike racks are provided for bicyclists.



The location of parking facilities in relation to the Downtown Mountain View Station is illustrated in **Figure 5.2-2b**. Some patrons may attempt to park in the downtown area or adjacent neighborhoods. Previous planning had been done for a parking deck over the surface parking and that plan could be reactivated to provide more station parking.

- Hostetter – This light rail station is adjacent to I-680 in the Berryessa area of San Jose, the Great Mall, and has substantial parking. In total, 100 parking spaces are provided for motorists, and 12 bike lockers are provided for bicyclists. The location of parking facilities in relation to the Hostetter Station is illustrated in **Figure 5.2-2c**.
- I-880/Milpitas – This station, adjacent to I-880, has a large park-and-ride lot and adjacent VTA-owned property. In total, 275 parking spaces are provided for motorists, and 10 bike lockers are provided for bicyclists. The location of parking facilities in relation to the I-880/Milpitas Station is illustrated in **Figure 5.2-2d**.
- Great Mall – This light rail station is immediately adjacent to the Great Mall, and has substantial parking. Stadium parking would be located at the furthest distance from the shopping mall. In total, 93 parking spaces are provided for motorists using the Great Mall Station. The location of parking facilities in relation to the Great Mall Station is illustrated in **Figure 5.2-2e**.
- Guadalupe Line – Along the light rail line extending south from downtown San Jose, there are several large park-and-ride lots that would likely be served by the special Stadium service. These include Tamien, Curtner, Capitol, Branham, Ohlone/Chynoweth, Blossom Hill, Snell, Cottle, and Santa Teresa. The amount of parking available at each of these locations is shown on **Figure 5.2-2f**.
- Vasona Line – The Vasona line to Campbell has park-and-ride lots at the Bascom and Winchester stations. There is also parking at the San Jose/Diridon Caltrain station. The amount of parking available at each of these locations is shown on **Figure 5.2-2f**.

Measures to Control Illegal Parking Adjacent to VTA Stations

Congestion around the Stadium and the provision of attractive transit service to the facility may lead to overflow parking around some VTA stations, which could result in some level of illegal parking (e.g. restricted neighborhood permit parking). To guard against parking issues, the level of parking at park-and-ride lots will be closely monitored. If problems arise with overflow or illegal parking, there are several possible actions that could be pursued. If intrusion into neighborhoods is the issue, VTA and the City of Santa Clara would work with the affected city and possibly develop a permit parking program. In some locations, there may be opportunities to expand the lot with temporary parking spaces.

Downtown Mountain View parking could be a particular issue. Parking on event days will be monitored to determine utilization and availability. This approach could work to the extent that there is excess downtown parking during normal event hours.

Coordination with Caltrain (and BART eventually)

VTA's special light rail service on event days is designed to coordinate with Caltrain service for Stadium patrons. The details of one option for coordination are provided below.

The Mountain View station has a center platform and two tracks which means that two trains can load at the same time. To serve a fully loaded Caltrain arrival, this service plan assumes that trains operate in pairs on the Mountain View single-track segment. For example, on arrival of a Caltrain train before an event, both eastbound light rail trains would be waiting at the platform and load at the same time. The first train would depart and the second train would follow immediately at the minimum prescribed separation distance to maintain safety. Both trains would occupy the single-track segment at the same time. Once they entered the double track section, two westbound trains that had been holding on the westbound track would enter the single-track segment, separated by the minimum interval. There is also a storage track at the Mountain View station allowing storage of a third train. Therefore, when a Caltrain train arrives, VTA could potentially dispatch three outbound light rail trains one after the other, without allowing an inbound train to enter the single-track segment until the last outbound train had cleared this section. If needed to meet demand, this approach maximizes the passenger throughput of the single-track section.

After the conclusion of a Stadium event, VTA light rail trains would be expected to arrive at the Mountain View Station in 7.5-minute intervals. Patrons continuing onto Caltrain services would be expected to walk to the Caltrain boarding area, and board Caltrain trains.

Figure 5.2-2a: VTA Satellite Lots



Figure 5.2-2b: Downtown Mountain View VTA Station




Figure 5.2-2c: Hostetter Station



Figure 5.2-2d: I-880/Milpitas VTA Station




Figure 5.2-2e: Great Mall VTA Station





Figure 5.2-2f: Guadalupe Line and Vasona Line Parking Availability





Stadium Area Operations

Special accommodations will be made for VTA's light rail service on event days during peak usage periods. These accommodations include:

Passenger Loading/Queuing Areas

A passenger loading/queuing area will be provided north of the Stadium on Tasman Drive. The street in this area will be closed to vehicular traffic. This area will allow for easy, direct access to and from the Stadium for light rail users. Operations within the loading/queuing area outlined below. The following assumptions were made, per the findings of the *Transportation Management Plan for a New San Francisco 49ers Stadium in Santa Clara, CA*:

- Ridership Scenario
 - 5,000 eastbound
 - 2,500 westbound + 2,700 to transfer to Caltrain @ Mt View = 5,200 westbound
 - 10,200 total
- Post-event Passenger Arrivals at Station during Stadium Egress – percentages distributed in 7.5 min increments – as shown in **Figure 5.2-3a** and **Figure 5.2-3b**
 - 5% before end of event
 - 73% within 45 min of end of event
 - 22% within 75 min of end of event
- Light Rail Vehicle Capacity
 - 450 passengers per 3-car train

The following configuration, as illustrated in **Figure 5.2-4a** and **Figure 5.2-4b**, is proposed for implementation including the following specific characteristics:

- Existing Great America Platform is loaded from existing west side access for westbound only and eastbound uses a new “Event Only” platform south of the eastbound track
 - Headways
 - 7.5 min westbound
 - 7.5 min eastbound
 - Platform Access Rates
 - 220 passengers per minute for the westbound platform
 - Light Rail Vehicle Capacity
 - 450 passengers per 3-car train
 - Maximum Anticipated Off-Platform Queue Area
 - Westbound – 2,274 passengers = 9,096 square feet
 - Eastbound – 2,100 passengers = 8,400 square feet

This configuration generates the shortest queues possible while requiring the smallest queue area, primarily due to the service frequency provided. This configuration provides a short duration of substantial queuing (about 20 minutes).

Figure 5.2-3a: Post-Event Arrivals at VTA Great America Station (Westbound Egress)







Figure 5.2-3b: Post-Event Arrivals at VTA Great America Station (Eastbound Egress)



CONVENTION STREET

TASMAN DRIVE

GATE F

STADIUM

GATE A

NEW AT-GRADE CROSSWALK

EXISTING VIA LIGHT RAIL TRACKS

PARKING GARAGE

NEW LRT PLATFORM

EXISTING LRT PLATFORM

NEW LRT PLATFORM ACCESS POINTS

QUEUING AREA


6 BIKE LANE

12 LANES

0 50 100 FEET

N

Figure 5.2-4b: Great America Light Rail Station Platform Queuing Area



Fare Collection

With the potential for high transit rider volumes and high service frequencies, special provisions for fare collection may be necessary. It should be noted that at this time, VTA has developed a complete fare collection plan for Stadium events, including setting up kiosks at platforms and stationing ticket checkers at station entry points.

The most efficient fare collection approach is for all, or nearly all riders to purchase day passes when they board on their way to the event. These passes are sold at all light rail stations. However, demand to use the ticket vending machines, and the likelihood that many riders will not be familiar with ticket machines, suggests that additional manual sale of day passes could be desirable. Rider demand will be closely monitored to identify station requiring additional manual ticket sales.

After the event, most riders would already have their day pass for their return trip. As needed, the manual sale of single tickets could also be provided. If demand is high enough, a special temporary ticket kiosk could be set up. Use of the ticket vending machines would be discouraged or prevented, due to the constrained platform capacity and boarding plans.

At-Grade Crossing


Given the need to provide on-street queuing areas on the south side of Tasman Drive east of Convention Center, there may otherwise not be sufficient pedestrian capacity to allow for safe, orderly and efficient egress westward from the Stadium without an at-grade crossing on Tasman Drive east of the Great America VTA Station. Such a crossing allows pedestrians to move to the north side of Tasman, bypassing the main parking lot, vehicle congestion and the VTA LRT queuing areas.

The design of the crossing includes standard track panels and pedestrian and LRT signalization. Fences, with locked gates, are installed on both sides of the trackway, adjacent to the Tasman traffic lanes. An illustration of the at-grade crossing of Tasman Drive is provided in **Figure 5.2-5**.

Additionally, a number of physical modifications to the Station area are being implemented, and several game day operational strategies will be employed. First, a new event-only platform is under construction on the south side of the existing tracks with two new event-only access points from Tasman Drive. This new event-only platform and event-only access points will allow for the existing platform to be dedicated to westbound movements with the new platform being solely dedicated to eastbound movements. Unique eastbound and westbound event-only queuing areas will be provided on the closed portion of Tasman Drive east of Convention Center Circle and south of the Station. The crossing would operate for events with 20,000 attendees or higher (and potentially for events with lower attendance levels, at the discretion of the Santa Clara Chief of Police and the City of Santa Clara Traffic Engineer), when Tasman Drive is closed to traffic in the crossing location.



Figure 5.2-5: At-Grade Crossing of Tasman Drive



Future Light Rail Plans

VTA is advancing capital improvements identified in its 2010 *Light Rail System Analysis*, to enhance the capacity, market-responsiveness, and efficiency of Light Rail Transit (LRT) operations. The improvements reconfigure LRT to respond to increasing population and employment and the extension of BART service to San José. The VTA Board of Directors adopted the LRT Improvement Plan in 2010, with the foresight and intent that, when the first segment of the Silicon Valley Berryessa Extension (SVBX) is completed in 2017; local transit services will enable connectivity from throughout VTA's service area.

By anticipating growth in the markets VTA serves, and by increasing VTA's regional connectivity, the new LRT network will attract more riders and generate greater return on investment than existing operations. VTA has defined the LRT Efficiency Program by the following capital and operating improvements:

- The **Southern Express** will expand the pilot Commuter Express Service to an all-day schedule on the Santa Teresa to Alum Rock line, establish new service from Almaden to Mountain View, including direct service from Almaden to Downtown San José, and turn back Winchester service from Campbell in Downtown San José.
- The **Northern Express** introduces a new service between Alum Rock and Mountain View, to increase ridership and efficiency, to effectively connect BART and the job centers in north San José, Santa Clara, Sunnyvale, and Mountain View, and to anticipate employment growth throughout the Tasman and North First Street corridors. This service will be introduced in 2017, commensurate with the opening of VTA's Silicon Valley Rapid Transit - Berryessa Extension.
- The **First Street Speed Improvement** project has potential to increase maximum LRT speeds on North First Street from 35 to 45 mph, via a combination of signal prioritization, fencing and safety enhancements along the LRT right-of-way. Speed improvements on the Downtown Transit Mall are also planned.
- The **Transit Signal Priority** project will implement a system-wide real-time, reliable transit signal prioritization and light rail vehicle detection system to increase LRT operating speeds. This project is funded by a Transit Performance Initiative grant from the Metropolitan Transportation Commission.

Current planning work has demonstrated that, by advancing several capital improvements planned for 2017, VTA can gain system-wide operating and rider benefits well before BART service begins in 2017. This approach will also accustom VTA riders to reconfigured LRT services anticipating the initiation of BART service to Berryessa. Under this strategy, following completion of the capital improvements described below, three light rail services will operate with the following frequencies:

- **Almaden - Mountain View:** 15 minute headways with 30 minute midday headways from Tasman Station to Mountain View, 30 minute headways on weekends;
- **Santa Teresa - Alum Rock:** 15 minute headways all day; operate Express between Ohlone-Chynoweth and Downtown San José all day on weekdays, except after 8pm;
- **Winchester - Downtown San José:** 15-minute headways during peak, 30 minute headways midday and weekends.



However, LRT operations under this new reconfiguration can be delivered safely and efficiently only after three essential capital improvements are made. Without these capital improvements, VTA would have to engage in exceptional operating practices to deliver both regular and stadium event services. Even if operated with extreme precision, without capital improvements, the system will be vulnerable to cascading delays, uncertain train arrivals, long passenger wait times, and overcrowded trains. This vulnerability stems from the inherent constraints of single-track segments and the lack of a turnaround facility for the Winchester line in Downtown San José.

The frequency of service planned for 2017 to and from the Downtown Mountain View LRT station requires double-tracking the single-track segment between Mountain View and Whisman Stations, and adding storage capacity and a double crossover west of Old Ironsides LRT Station in the vicinity of the 49ers Stadium.

VTA has developed concepts for Phase I Double Track of the Mountain View single-track segment, LRV storage in the vicinity of the 49ers Stadium in Santa Clara, and a Winchester Turnaround in the vicinity of Downtown San José. Besides securing acceptance of preferred designs by the host cities, by adjacent transit properties, and by the California Public Utilities Commission, VTA must additionally secure the appropriate environmental clearances and find expeditious means of funding and contracting final design, material procurement, right-of-way acquisition, and construction of these projects, to have them ready for operation by August of 2014.

5.2.2 VTA Local Bus

In addition to light rail service, VTA provides regular bus service, and will provide supplemental bus service, to the area adjacent to the Stadium. These services will carry patrons living within the VTA service area to the Stadium area. The details associated with transit access with regard to VTA bus service are as follows:

Ridership

As with light rail, bus ridership levels are expected to increase substantially on event days, compared to normal Sunday service. It should be noted that as part of the collection of annual data described in section 2.1.4, it is expected that VTA will collect boarding and alighting data on its buses for the purposes of annual TMOP evaluation. Data is to be collected before the start of the NFL season (once on a Sunday and once on a Monday), and on all NFL game days at the Stadium.

Routes

VTA currently operates three regular routes in the Stadium area that run seven days a week. These lines share a common route terminus near Tasman Drive and Old Ironsides, adjacent to the Old Ironsides light rail station. The three regular lines are:

- Line 55 – This line serves Sunnyvale and Cupertino. The route accesses the Stadium area along Tasman from the west.
- Line 57 – This line serves areas in Santa Clara to the south, traveling along Kiely and Saratoga. Access to the Stadium area is along Great America Parkway from the south.
- Line 60 – This line serves areas in Santa Clara to the south, traveling primarily along Winchester Boulevard. Access to the Stadium area is along Great America Parkway from the south.

On event days, these regular routes will be adjusted to provide more efficient service to the Stadium area and to respond to the Stadium Transportation Management Plan. The stop for the route terminus will likely be near the current Old Ironsides terminus and will be located within convenient walking distance of the Stadium. Since none of the regular routes travel east along Tasman (which will be closed), the impact on regular and event-day riders will not be significant. Sunday service on these regular lines operate at frequencies of 45 to 60 minutes (for service related to weekday evening events, please see Section 6.3 of this document). Demand on these lines will be monitored and additional service added, if demand warrants. An illustration of the route map in the Stadium vicinity for these buses is provided in **Figure 5.2-6**.

VTA also provides express service to the Great America area. These lines operate in peak hours on weekdays only and would not operate for weekend events. These lines include:


- Express Route 140 – This line connects to the Fremont BART station, via Milpitas. The route accesses the Stadium area along Tasman from the east.
- Express Route 121 – This line serves Morgan Hill and Gilroy, traveling along US-101. The route accesses the Stadium area via Great America Parkway from the south.
- Route 321 – This line connects the Great America area to North First Street and North San Jose.
- Route 328 – This line provides commute service along Lawrence Expressway.
- Route 330 – This line provides commute service along San Tomas Expressway.

VTA will also operate new event-day only bus services, connecting other high-volume locations in the south bay directly with the Stadium. These supplemental routes will include:

- Route 251 – Connecting the Fremont BART Station with the Stadium;
- Route 252 – Connecting the Vallco Shopping Mall area in Cupertino with the Stadium;
- Route 253 – Connecting Gilroy and Morgan Hill with the Stadium;
- Route 254 – Connecting the Eastridge Shopping Center area in San Jose with the Stadium; and
- Route 255 – Connecting the Almaden area in San Jose with the Stadium.

Each supplemental route will use multiple buses, based on demand. Supplemental Route 251 (Fremont BART) will drop off passengers along northbound Great America Parkway (between Tasman Drive and Bunker Hill Lane), and exit north to SR 237. Midway through an event, all Supplemental Route 251 buses will stage along northbound Great America Parkway (between Tasman and Bunker Hill), and exit north. The remaining four Supplemental Routes will drop off passengers east of the Stadium along Tasman Drive (between Calle Del Sol and Lick Mill Boulevard), and depart via Calle Del Sol, Calle De Luna, and Lafayette Street. Midway through an event, one bus per Supplemental Route will stage along Tasman Drive between Calle Del Sol and Lick Mill Boulevard, and the remaining extra buses will wait along Tasman Drive east of Lick Mill Boulevard. When a bus is fully loaded, it will exit the area via Calle Del Sol, Calle De Luna, and Lafayette Street. Once a bus has departed the Tasman Drive loading area (i.e., between Calle Del Sol and Lick Mill Boulevard), a bus waiting along Tasman Drive east of Lick Mill Boulevard will be called to enter the loading area, and the process will repeat until all passengers have been served.

Figure 5.2-6: VTA Bus Routes



Stadium Area Ingress and Egress

Regular bus routes will operate along their regular routes to serve the Stadium on event days. Regular buses will arrive via Tasman (from the west) or Great America Parkway. Minor temporary routing changes may be needed. Buses will receive special access to those areas not open to general traffic.

VTA's Supplemental bus service will operate primarily along Great America Parkway, Tasman Drive, and Lafayette Street. Specifically, Supplemental Route 251 (Fremont BART) approach its loading / unloading area via eastbound Tasman Drive, and turning left on Great America Parkway. This Supplemental Route would then exit north along Great America Parkway towards SR 237. The remaining four Supplemental Routes will approach their loading / unloading areas via westbound Tasman Drive. These Supplemental Routes would then exit the area via Calle Del Sol, Calle De Luna, and Lafayette Street.

Pick Up and Drop Off

Regular bus service will utilize the current pick up and drop off stops near the current route terminus at Old Ironsides Drive and Tasman Drive. VTA's Supplemental bus service will use the designated passenger loading/queuing areas along Great America Parkway (between Tasman Drive and Bunker Hill Lane) and along Tasman Drive (between Calle Del Sol and Lick Mill Boulevard).

5.2.3 Other Public Bus

Until recently, events at Candlestick Park were served by several transit agencies, including San Francisco Muni, SamTrans and VTA. However, as a result of changes in regulations, the service previously operated by SamTrans and VTA is now provided by charter bus operators.


Currently, at Candlestick Park, San Francisco Muni operates regular service from several destinations in San Francisco directly to the Stadium. Many of the Muni patrons transfer from BART or other transit lines. It is not expected that Muni would operate to the Stadium in Santa Clara. Rather, current riders would use Caltrain or BART and transfer to bus or light rail near the Stadium.

Other public bus routes serving Candlestick are operated by Golden Gate Transit (from Marin County) and Tri-Delta Transit (from the East Bay). These public transit agencies may continue to serve Levi's® Stadium with direct express service. Should these choose to provide service to the Stadium, their buses would be included as part of the Chart Bus operations described in Section 5.2.4 below.

5.2.4 Charter Bus

All non-tailgating charter buses park within Green Lot 1, near the Hilton Hotel. There is space in this area to accommodate over 75 charter buses which exceeds the charter bus usage experienced to date. All non-tailgating, oversized vehicles including limos, shuttle vans, etc., are also directed to park in this location. Entry and exit is located at the newly installed 3-lane "Hilton Gate" in Green Lot 1 located just south of the Hilton Hotel on Great America Parkway. Charter buses and other oversized vehicles that are looking to tailgate are directed to Blue Lot 1 RV location.

Figure 5.2-7: Charter Bus Staging Area on Event Day



As shown in **Figure 5.3-7**, charter bus patrons would access the staging area from Old Glory Lane, Old Ironsides Drive, and Tasman Drive. Traffic officers would control the pedestrian crossings at the Great America Parkway / Old Glory Lane and Old Ironsides Drive / Tasman Drive intersections.

5.2.5 Caltrain

Caltrain provides rail service to the Stadium area from locations in San Francisco, San Mateo and Santa Clara counties. Service for approximately 2,000 to 3,000 Stadium attendees for Sunday afternoon events would be provided via regular Caltrain service, with a transfer to VTA light rail at the Mountain View station. Additional trains could also be provided, using available rolling stock, to meet demand. The details of Caltrain service on event days are as follows:

Operations Plan

Caltrain currently operates hourly service on weekends (for service related to weekday evening events, please see Section 6.0 of this document). The primary event day demand would be southbound trains for arrivals and northbound departure trains. Potential southbound trains at Mountain View for patrons arrive at 10:29 AM, 11:29 AM, and 12:29 PM. Additionally, a limited stop, Baby Bullet train arrives at 12:47 PM. Post event departures northbound at Mountain View are at 4:19 PM, 5:19 PM, and at 6:19 PM with a Baby Bullet train. Since travel time via light rail to the Great America station is about 20-25 minutes, arrivals before 12:00 PM and departures after 5:00 PM are preferred. The possibility of shifting the Baby Bullet trains for earlier arrival will be explored.

Currently, for sports events at SAP Center at San Jose and AT&T Park in San Francisco, Caltrain relies primarily on regular service, but will operate extra trains if demand warrants and will hold trains for a short time (up to 15 minutes) to provide departure flexibility. Special trains operate after the events as needed. These trains are easier for Caltrain to manage since the sports facilities are located at terminal stations. However, it is expected that there would be a similar operating plan for Stadium events.

Number of Trains

Two regular trains (Mountain View arrivals at 10:29 AM and 11:29 AM and departures at 5:19 PM and 6:19 PM) provide the best service for events, with the possibility of a third if the Baby Bullet train can be shifted earlier. Each train could carry up to 1,000 patrons to and from the event.

It should be noted that as part of the collection of annual data described in section 2.1.4, it is expected that Caltrain will collect boarding and alighting data on its trains for the purposes of annual TMOP evaluation. Data is to be collected before the start of the NFL season (once on a Sunday and once on a Monday), and on all NFL game days at the Stadium.

Train Size

Caltrain currently operates the maximum train size (five cars) that they provide at this time. Therefore, there is no current ability to expand train size. However, future conversion of Caltrain to an electrified operation may provide opportunities for increased capacity as well as increased service frequency.

Schedule

The schedule of Caltrain service to various event types at the facility will be described herein, both regular service, augmented service and/or special service.



Access to Stadium (via VTA Light Rail)

Currently, Caltrain does not provide direct access to the Stadium (Altamont Corridor Express (ACE) and Capitol Corridor do have access rights on the tracks adjacent to the Stadium). However, on event days, Caltrain will coordinate with VTA light rail to provide direct service to the Stadium via a transfer at the Mountain View Station. In addition, VTA Bus Line 60 operates from the Santa Clara Caltrain Station to the Stadium. Should there be a need for additional connecting (if VTA light rail cannot provide enough capacity for example), bus connections could be provided at the Mountain View and/or Lawrence Stations. The details of such an operation is provided in Section 5.8.

Loading/Unloading/Schedule

As described above, Caltrain will deliver patrons to the Mountain View station, where transfers to the VTA light rail service will occur. As demand warrants, VTA can stage light rail trains to serve the demand. However, this operation will be closely monitored and additional connecting buses provided as needed. The primary time period for connections will be between 10:30 AM and 12:00 PM before events and 5:00 PM to 6:15 PM after events.

Train Storage

Storage for additional trains needed to meet demand will occur at the terminals (San Francisco and San Jose). In particular, after events, the backup trains would be dispatched from San Jose as needed to prevent overcrowding and to ensure available capacity for regular Caltrain riders.

5.2.6 Capitol Corridor

Capitol Corridor could provide rail service to Sunday afternoon Stadium events for approximately 500 Stadium attendees via the current Amtrak route to Oakland and Sacramento. The details of potential Capitol Corridor service on event days are as follows:

Operations Plan

Capitol Corridor may consider adjusting the schedule of its regular service on event days to accommodate greater demand and better serve event times. Currently, the Great America ACE/Capitol station is served by westbound (to San Jose) arrivals on Sunday at 8:26 AM, 10:26 AM, and 1:26 PM and eastbound departures at 4:37 PM and 6:02 PM. There is also an eastbound arrival from San Jose at 1:02 PM and westbound departure at 5:01 PM that would serve San Jose patrons. For service related to weekday evening events, please see Section 6.0 of this document.

Number of Trains

As noted above, the current schedule provides several arrivals and departures at the Stadium. However, the primary arrival train would be the 10:26 AM and most departures would be on the 4:37 PM train. In the future, the Capitol Corridor might also be able to extend to San Jose the current train that terminates in Oakland at 11:15 AM, which would provide a timely arrival.

It should be noted that as part of the collection of annual data described in section 2.1.4, it is expected that Capitol Corridor will collect boarding and alighting data on its trains for the purposes of annual TMOP evaluation. Data is to be collected before the start of the NFL season (once on a Sunday and once on a Monday), and on all NFL game days at the Stadium.

Train Size

Capitol Corridor may elect to use longer trains for event day service to increase the number of patrons it can carry to the Stadium area. Current regular trains have five cars, but the trains could operate with up to eight cars, if needed due to demand.

Schedule

As discussed above, the primary arrival train from Oakland and Sacramento would be at 10:26 AM and the departure train at 4:37 PM, with a back-up train at 6:02 PM. If events run long, the 4:37 PM departure could potentially be held for a short period of time to serve patrons.

Loading/Unloading/Schedule

For Capitol Corridor service on event days, loading and unloading will occur at the Great America Station adjacent to the Stadium. An operational issue to be resolved is the order of loading, unloading, and general logistics at the Great America Station assuming the Capitol Corridor and ACE both provide service to the Stadium via this one station. After the event, based on the current Capitol Corridor schedule, it is likely that the regular 4:37 PM would first depart followed by the special ACE service. The regular Capitol Corridor westbound train arrives at 5:02 PM, although that train might need to be delayed to allow for the special ACE train departure.

After the event, patrons would walk the short distance to the station. Special queuing areas will be separated by temporary fencing, along with barricades, taping, and signage (identifying where to stand) placed to ensure orderly boarding of trains in both directions. Stadium Management staff will be responsible for implementing the Capitol Corridor queuing area. A layout of this loading area is provided in **Figure 5.2-8**.


Train Storage

Since regular service will be used, there will not likely be a need for train storage. However, if needed, storage is currently available at the San Jose station.

Passenger Parking

ACE and Capitol Corridor riders who leave a vehicle overnight use the existing parking lot adjacent to the Capitol Corridor Great America Station. As a result, that lot will be substantially occupied during event periods.

Figure 5.2-8: Great America Commuter Rail Station Platform Configuration



5.2.7 ACE

ACE could provide special rail service to Sunday afternoon Stadium events for approximately 700 to 900 Stadium attendees via the Central Valley. The details of ACE service on event days are as follows:

Operations Plan

ACE does not currently operate regular weekend service, but would run a special train to events. For service related to weekday evening events, please see Section 6.0 of this document.

Number of Trains

ACE will operate one special round trip train to Stadium events. As part of the collection of annual data described in section 2.1.4, it is expected that ACE will collect boarding and alighting data on its trains for the purposes of annual TMOP evaluation. Data is to be collected on all NFL game days at the Stadium.

Train Size

ACE currently operates six and seven car trains during weekdays. For special event day service, the train size would be up to seven cars.

Schedule

Special event day train service would be scheduled to best serve the event. Arrivals would likely occur about one hour and thirty minutes before the start of the event and departures would be flexible and timed to leave at a set time (30 to 45 minutes) after the end of the event. Specifically for Sunday afternoon football games, ACE would depart at 4:30 PM for games starting at 1:05 PM.

Loading/Unloading/Schedule

For special ACE service on event days, loading and unloading will occur at the Great America Station adjacent to the Stadium. An operational issue to be resolved is the order of loading, unloading, and general logistics at the Great America Station assuming the Capitol Corridor and ACE both provide service to the Stadium via this one station. After the event, based on the current Capitol Corridor schedule, it is likely that the regular 4:37 would first depart followed by the special ACE service. The regular Capitol Corridor westbound train arrives at 5:02, although that train might need to be delayed to allow for the special ACE train departure.

After the event, patrons would walk the short distance to the station. Special queuing areas will be separated by temporary fencing, along with barricades, taping, and signage (identifying where to stand) placed to ensure orderly boarding of trains in both directions. Stadium Management staff will be responsible for implementing the ACE queuing area. A layout of this loading area is provided in **Figure 5.2-8**.

Train Storage

A special ACE train would be stored in San Jose at the current ACE storage track location.

Passenger Parking

ACE and Capitol Corridor riders who leave a vehicle overnight use the existing parking lot adjacent to the Capitol Corridor Great America Station. As a result, that lot will be substantially occupied during event periods.



5.3 Pedestrian Access

Pedestrians arriving and departing the Stadium will be encouraged to use specific routes and designated pedestrian walkways. This goal will be achieved through a combination of permanent signage, temporary signs, changeable message signs, media releases, and mass marketing programs designed to inform the public and Stadium patrons about these travel routes. The use of various temporary traffic control devices, in conjunction with the deployment of gameday traffic control personnel, will give priority to the established travel routes, thereby minimizing the potential for conflict.

5.3.1 Roadway Closures / Pedestrian Only Areas

As noted in previous sections, Tasman Drive will be closed on event days to vehicles to provide space for transit loading, access to a number of roadways will be restricted to eliminate intrusions into residential neighborhoods and provide safe and adequate pedestrian loading and crossing areas. These areas and the preferred pedestrian walkways are described in this section of the TMOP.

Tasman Drive between the Convention Center Driveway and Centennial Boulevard will be closed to vehicular traffic during Stadium Events with anticipated attendance greater than 20,000 patrons. This area will prohibit vehicular traffic in order to allow for easy, direct access to and from the Stadium for light rail users. During events in which Tasman is closed, extended queuing areas would be on-street, in the prohibited section of eastbound Tasman Drive adjacent to the Great America VTA Station. Stadium Management staff will be responsible for implementing the VTA Light Rail queuing areas. New fencing shall be in place on both sides of the Tasman median along the extents of this segment to prohibit pedestrians from crossing at prohibited locations. Emergency vehicles would be able to use the closed section of westbound Tasman Drive. The Tasman Drive vehicular traffic closure would be in place from 1:00 AM to 9:00 PM on a Sunday game day, assuming a 1:00 PM afternoon start time.

Pedestrian paths of travel to several parking facilities and transit loading areas will not require pedestrians to cross vehicular traffic. Pedestrians traveling to parking facilities north of the Stadium area would walk through the designated "Transit and Pedestrian Area" located north of the Stadium on Tasman Drive, between Convention Circle and Centennial Boulevard.

5.3.2 Access to Transit

The TMOP seeks to make access to transit easy and efficient. Way-finding signage to each transit station shall be installed to clearly direct patrons to transit facilities. Pedestrian access routes to transit, including VTA Light Rail, VTA Bus, and ACE / Capitol Corridor, and the locations of directional signage, are illustrated in **Figure 5.3-2**.

VTA Light Rail

The Great America VTA Light Rail Station and passenger queuing area is shown in **Figure 5.3-3**. As shown, the majority of light rail riders would enter and exit the light rail within the designated "Transit and Pedestrian Area" (i.e., the area along Tasman Drive between Convention Center Circle and Centennial Boulevard, closed to vehicle traffic) located north of the Stadium site on Tasman Drive. The Great America VTA Light Rail Station platform is loaded from existing west end access for westbound only, and eastbound uses a new "Event Only" platform south of the eastbound track. The platform for westbound trains would load from the west end of the platform, via the east crosswalk of the Convention Center Circle / Tasman Drive intersection. Westbound passenger queuing would occur on-street, within the closed section of eastbound Tasman Drive. The platform for eastbound trains would load from the center of the platform, and at the east side of the platform. Eastbound passenger queuing would also occur on-street, within the closed section of eastbound Tasman Drive. VTA light rail queuing areas will be separated by stanchions and signage (identifying where to stand) placed to ensure orderly boarding of trains in both directions. All stanchions and signage shall be implemented by Stadium Management staff six hours prior to the start of an event, and removed after Stadium departure has concluded.

As many as 220 passengers per minute would be able to access the westbound platform, and 400 passengers per minute for the eastbound platform. Based on an expected 7.5-minute service frequency after the conclusion of an event, a maximum of 2,024 passengers are expected to queue for westbound trains, and 1,850 passengers for eastbound trains. Also, although most light rail patrons would utilize the closest station to Great America, the potential exists for riders to attempt to exit one stop east or west prior to reaching the Stadium. As alighting one station from the Stadium would result in increased delay for VTA trains, and would disrupt planned signalization approaching the Stadium, the Lick Mill and Old Ironsides VTA stations could be closed during events. Thus, additional signage will be added at the Lick Mill and Old Ironsides VTA stations and on VTA trains to notify riders of the temporary closure of these two stations.

VTA Supplemental Bus Routes

VTA will operate new event-day only bus services, connecting other high-volume locations in the south bay directly with the Stadium. Supplemental Route 251 (Fremont BART) loads and unloads passengers at Tasman Drive between Great America Parkway and Convention Center. Pedestrians walking between the Supplemental Route 251 loading area and the Stadium will use the sidewalks on Tasman Drive. The remaining four Supplemental Routes will load and unload passengers east of the Stadium along Tasman Drive, between Calle Del Sol and Lick Mill Boulevard. Pedestrians walking between this loading area and the Stadium will use the sidewalk along the north side of Tasman drive, and the pedestrian-only zone along Tasman Drive. The locations of VTA supplemental bus loading and unloading areas are illustrated in **Figure 5.3-4**.

Figure 5.3-9: Directional Signage and Access to Transit




Figure 5.3-10: Great America Light Rail Station Platform Queuing Area






Figure 5.3-11: VTA Supplemental Bus Route Staging Area on Event Days



ACE / Capitol Corridor

The Great America Commuter Rail station and passenger queuing area as shown in **Figure 5.2-8**. As shown, ACE and Capitol Corridor patrons would access the station either by walking along Tasman Drive, along Stars & Stripes Drive, or by walking along the new pedestrian pathway along the north edge of the 49ers Training Facility east of the Stadium to the cul-de-sac on Stars & Stripes Drive. Capitol Corridor passenger queuing will occur along the east sidewalk on Stars and Stripes Drive, from the northern end of the platform to the center of the platform. ACE passenger queuing will also occur along the east sidewalk on Stars and Stripes Drive, from the center of the platform to the southern end of the platform. The two queuing areas will be separated by stanchions and signage (identifying where to stand) placed to ensure orderly boarding of trains in both directions. All stanchions and signage shall be implemented six hours prior to the start of an event, and would be removed after Stadium departure has concluded.

Figure 5.3-12: Charter Bus Staging Area on Event Day



5.3.3 Access to Parking

Access to parking facilities may require pedestrians to cross traffic one or more times, or in some cases, not at all. The conflict points will be located at signalized intersections with crosswalks that serve as primary entry to identified parking areas. As shown in **Figure 5.3-7**, pedestrians would be able to access the event day parking facilities in the following ways:

- *Great America Main Parking Facilities* – Pedestrians traveling to the Stadium from Red Lot 1 or Green Lot 1 would utilize one of the pedestrian bridges across San Tomas Aquino Creek.
- *Off-Site Parking Northeast of Stadium* – Pedestrians traveling northeast of the Stadium would travel along Tasman Drive and would not encounter conflicts with vehicular traffic.
- *Off-Site Parking Northwest of Stadium* – Pedestrians traveling to parking areas northwest of the Stadium would cross Great America Parkway at either Tasman Drive or Bunker Hill Lane.
- *Off-Site Parking West of Stadium* – Pedestrians traveling to parking areas west of the Stadium would cross Great America Parkway at Old Glory Lane.
- *Off-Site Parking South of Stadium* – Pedestrians traveling to parking areas south of the Stadium would cross Great America Parkway at Old Glory Lane, and walk along the west sidewalk of Great America Parkway.


Crowded conditions are to be expected for each path during peak periods. To further facilitate pedestrian traffic, a new pedestrian crossing will be provided on Tasman Drive and three additional pedestrian-only bridges were constructed over San Tomas Aquino Creek south of Tasman Drive.

It should be noted that on event days, security screening stations shall be placed ahead of all Stadium pedestrian access points to screen all patrons for unpermitted items. No Stadium patrons will be permitted into the Stadium without first passing through a security screening station. As such, all security screening stations shall be placed six hours prior to the start of an event, and removed mid-game in order to maximize pedestrian flow away from the Stadium during the egress period. The area within which all patrons have been screened at security screening stations, the Stadium's security perimeter, is shown on **Figure 5.3-8**.

Figure 5.3-13: Pedestrian Access to Parking Facilities on Event Days



Figure 5.3-14: Stadium Security Perimeter





Designated Crossing Areas

Designated crossing areas will be placed at locations so pedestrians can travel to and from parking facilities with a minimal number of roadway crossings. Officers will be located at many of these crossing area locations to assist should any conflicts between vehicles and pedestrian occur. Additionally, pedestrian crossing of roadway or transit rights-of-way will occur at officer-monitored locations, or at intersections with pedestrian signals. The locations and control type of these crossing areas are identified below.

Control Type

In some cases, the designated crossing area may be placed at an officer-monitored intersection. In other cases, the designated crossing area may be under signal control or stop control. In each case, pedestrians will wait for traffic to yield, and then cross. Each intersection and the number of officers required to manage the gameday traffic flow are listed below:

- Great America Parkway / SR-237 Ramps (requires two officers);
- Great America Parkway / Great America Way (no officers required);
- Great America Parkway / Old Mountain View–Alviso Road (requires one officer);
- Great America Parkway / Bunker Hill Lane (requires one officer);
- Great America Parkway / Tasman Drive (requires three officers);
- Great America Parkway / Stadium North Driveway (requires one officer, post-event only);
- Great America Parkway / Old Glory Lane (requires three officers);
- Great America Parkway / Patrick Henry Drive (requires two officers);
- Great America Parkway / Mission College Boulevard (requires three officers);
- Great America Parkway / Our Lady Way (no officers required);
- Great America Parkway / U.S. 101 Northbound Ramps (one officer required);
- Great America Parkway / U.S. 101 Southbound Ramps (one officer required);
- Lawrence Expressway / Tasman Drive (requires two officers);
- Lawrence Expressway / Sandia Avenue (requires two officers);
- Patrick Henry Drive / Tasman Drive (requires two officers);
- Old Ironsides Drive / Tasman Drive (requires two officers);
- Convention Circle / Tasman Drive (requires one officer);
- Tasman Drive at-grade crossing (requires two officers);
- Centennial Boulevard / Tasman Drive (requires two officers);
- Calle Del Sol / Tasman Drive (requires two officers);
- Calle Del Sol / Calle De Luna (requires one officer);
- Lafayette Street / Calle De Luna (requires one officer);
- Lick Mill Boulevard / Tasman Drive (requires one officer);
- North 1st Street / Tasman Drive (requires two officers);
- Lafayette Street / Hogan Drive (no officers required);
- Marriott Parking Access / Mission College Boulevard (requires one officer);
- Freedom Circle / Agnew Road / Mission College Boulevard (requires one officer); and,
- Montague Expressway / Mission College Boulevard (requires two officers).

Street Crossing Prohibitions

Some locations may include a street crossing prohibition (signage or fencing) in order to minimize conflict points between pedestrians and vehicles, and to focus pedestrians into the safest crossing areas. In these cases, signage will be posted to alert pedestrians regarding prohibited crossing areas, or officers will be directing pedestrians to use designated sidewalks and crosswalks. These locations include:

- Great America Parkway / SR 237 Ramps: North crosswalk, south crosswalk;
- Great America Parkway / Great America Way: North crosswalk, south crosswalk;
- Great America Parkway / Old Mountain View Alviso Road: South crosswalk;
- Great America Parkway / Bunker Hill Lane: North crosswalk;
- Great America Parkway / Tasman Drive: South crosswalk, east crosswalk, west crosswalk;
- Great America Parkway / Old Glory Lane: East crosswalk;
- Great America Parkway / Patrick Henry Drive: North crosswalk, south crosswalk;
- Great America Parkway / Mission College Boulevard: North crosswalk, south crosswalk;
- Patrick Henry Drive / Tasman Drive: West crosswalk;
- Old Ironsides Drive / Tasman Drive: West crosswalk;
- Convention Center Circle / Tasman Drive: West crosswalk;
- Fenced Tasman Drive median between Convention Center Circle and Centennial Boulevard;
- Calle Del Sol / Tasman Drive: East crosswalk, west crosswalk; and
- Lick Mill Boulevard / Tasman Drive: East crosswalk, west crosswalk.

Residential Area Intrusion

Based on the locations of the off-site parking areas and transit stations relative to the Stadium, and given that pedestrians will choose to take the most direct route to/from the Stadium, it is unlikely that pedestrians will travel through residential areas. Officers shall be stationed on either end of Agnew Road, between Mission College Boulevard and Lafayette Street. Should local residents have any issue with pedestrian cut-through traffic, signage would be posted at neighborhoods to alert Stadium patrons that residential areas are to be avoided, and to explain that they do not provide quicker paths to the Stadium, parking facilities, or transit facilities. Further, the signage will include the Community Liaison's telephone number, should residents want to speak with someone personally to offer input. Based on findings, including feedback from area residents, adjustments to the TMOP will be proposed.

5.3.4 ADA Access

A conscious and ongoing effort will be made to accommodate all fans, including those living with disabilities. The primary supply of ADA parking for the Stadium will be provided within Red Lot 1, comprising a total of 200 spaces. As the legal requirement reserves one percent of the available parking spaces per lot or garage for the vehicles of individuals living with disabilities, the total of 200 ADA parking would be sufficient to meet ADA parking requirements for all patrons expected to arrive at the Stadium by automobile. However, it should be noted that existing ADA parking spaces within off-site lots contracted for event use would also be available. Additionally, it should be noted that Blue Lot 3 will serve as an additional parking supply for disabled patrons, offering 140 parking spaces.

Further, a total of 130 ADA parking spaces would be provided in lots designated specifically for Great America Theme Park use. On days when the Theme Park is in operation during a Stadium event, it is possible that some percentage of this surplus could be used as overflow ADA parking for the Stadium, if necessary. On days when the Theme Park is not in operation, the 130 ADA parking spaces would be added to the total of 200 ADA parking spaces, allowing for



an overall ADA parking supply of 330 spaces within Red Lot 1. Motorized carts would shuttle patrons between the 130-space ADA parking area and the Stadium security perimeter.


Supplemental ADA Shuttle

Patrons intending to use ADA parking spaces (not located within Red Lot 1 or Green Lot 1) will be encouraged to park within Blue Lot 1. As noted, Blue Lot 1 will serve as an additional parking supply for disabled patrons, offering 140 parking spaces. Additionally, Blue Lot 1 will serve as the Stadium's ADA paratransit pick-up and drop-off location. Disabled patrons parking in Blue Lot 3, or arriving by ADA Paratransit will be served by a supplemental shuttle offering a direct connection to the Stadium entrance. The supplemental shuttles will be similar to golf carts, and would transport Stadium patrons with special needs from Blue Lot 1 to Stadium. Additionally, Stadium patrons with special needs parked within Red Lot 1 or Green Lot 1 would receive shuttle service to the Stadium entrance. Shuttle service would be available beginning 1.5 hours prior to event time, with the last drop off occurring one hour following the conclusion of each event.

On-Demand Paratransit Shuttles

Paratransit is an alternative mode of flexible passenger transportation that does not follow fixed routes or schedules. This demand-responsive transport service would offer on-demand call-up door-to-door service from any origin within the Stadium service area to/from the Blue Lot 1 pick-up/drop-off zone, where passengers would transfer to the Stadium's supplemental ADA shuttle to reach the Stadium entrance. Stadium patrons with special needs who require paratransit services would call the Paratransit dispatcher to schedule a pick-up. Both the paratransit route to and from Blue Lot 1, as well as the supplemental shuttle route from Blue Lot 1 to the Stadium, are illustrated in **Figure 5.3-10**.

Figure 5.3-15: Paratransit and Pick-up / Drop-off Routes, and Supplemental ADA Shuttle Routes





5.4 Bicycle Access

5.4.1 Access Routes

Bicyclists are expected to access the Stadium by way of automobile ingress and egress routes, or via bicycle designated trails and facilities (i.e. the adjacent San Tomas Aquino Creek Trail). In the vicinity of the Stadium, there are several Class I and Class II bicycle facilities.

- San Tomas Aquino Creek Trail is a major north/south, paved, Class I (off-road) bikeway stretching from the central Santa Clara to Sunnyvale/Baylands Park, which intersects with Tasman Drive at the northwest corner of the Stadium. Currently, it is nearly continuous from the Bay Trail to El Camino Real as a multi-use trail for bicycles and pedestrians. South of El Camino Real, the trail is an on-street bicycle route with marked bicycle lanes along the streets. A Spur Trail to Homestead Road is under various stages of design and construction. The San Tomas Aquino Creek Trail is only accessible during daylight hours in the vicinity of the Stadium.
- Guadalupe River Trail is a major north/south, Class I (off-road) bikeway that provides direct access to/from Downtown San Jose and many outlying neighborhoods and intersects with Tasman Drive approximately 0.5 miles east of the Stadium. The Guadalupe River Trail is only accessible during daylight hours in the vicinity of the Stadium. The path is an 11 mile long multi-use trail for bicycles and pedestrians that runs along the banks of the Guadalupe River. Currently, it is composed of three discontinuous segments:
 - The “Upper Guadalupe River Trail” section links to three other trail systems (River Oaks Pathway, Los Alamitos Creek Trail, and Ryland Parkway Trail). The trail’s southern section is paved and runs from its southern terminus at Almaden Lake Park (at Coleman Road) to Chynoweth Avenue.
 - The paved trail resumes just south of Interstate 280 (I-280) at the intersection of Virginia and SR 87 and continues northward and ends just north of the Interstate 880 (I-880) undercrossing.
 - The “Lower Guadalupe River Trail” section connects with the Highway 237 Bikeway. This section is unpaved (gravel) and continues along the border of San Jose International Airport and terminates near the corner of Gold Street and SR 237 in the Alviso neighborhood.
- Great America Parkway is a north/south, Class II (signed and striped) bikeway that provides direct access to/from central Santa Clara and SR 237. The bicycle lane runs along Great America Parkway from Chromite Drive to SR 237. It connects with Lafayette Street south of SR 237 via Great America Way before continuing to its northern terminus, north of SR 237, where it connects via the Gold Street Connector. The Class II bikeway intersects with Tasman Drive at the northwest corner of Red Lot 1.
- Lafayette Street is a north/south Class II bikeway. The on-street, signed and striped bicycle lane runs along Lafayette Street from Agnew Street to its northern terminus, north of SR 237. It connects with Great America Parkway south of SR 237 via Great America Way before continuing to its northern terminus, north of SR 237, where it connects via the Gold Street Connector. The Class II bikeway intersects with Tasman Drive at the northwest corner of Red Lot 1.
- North 1st Street is a north/south Class II bikeway. The on-street, signed and striped bicycle lane runs along N 1st Street from E Brokaw Road/Airport Parkway to its northern terminus, south of SR 237, at Great America Way. It connects with the “Upper Guadalupe River Trail” to the south via Airport Parkway, and connects with “Lower Guadalupe River Trail” to the north via Great America Way. The Class II bikeway intersects with Tasman Drive approximately 1.5 miles east of the Stadium.
- Tasman Drive/Great Mall Parkway/Capitol Avenue is a Class II bikeway that runs along the north side of the Stadium in the east/west direction. The bicycle lane crosses “Lower Guadalupe River Trail” and continues

as Great Mall Parkway to the South Main Street intersection. It runs in the north/south direction and continues as Capitol Avenue to its southern terminates at East Capitol Expressway near the Alum Rock Transit Center.

- John W. Christian Greenbelt Trail/Prestcott is a discontinuous Class I and Class II bikeway that runs in the east/west direction from Duncan Avenue/Garner Avenue, near Moffet Park Station, to Calabazas Creek Trail, a Class I bikeway that connects with Great America Parkway via the Old Mountain View-Aviso Trail to the north. The Great America Parkway bikeway intersects with Tasman Drive at the northwest corner of Red Lot 1.

Bicycle facilities in the vicinity of the Stadium are illustrated in **Figure 5.4-1**.

Bicycle Traffic Diversions

During certain large events, bicycle traffic on the San Tomas Aquino Creek Trail will be diverted around the west stadium entry gates between the south end of the Stadium parking lot and Tasman Drive due to the trail's position within the Stadium's security perimeter. Gameday bicycle traffic will be diverted approximately 400 feet to the west, to bypass the Stadium security zone and event screening area. Bicycles will exit the Stadium parking lot at the intersection of Convention Circle/Tasman Drive and would reconnect with the San Tomas Aquino Creek Trail immediately north of Tasman Drive. The San Tomas Aquino Creek Trail detour is shown in **Figure 5.4-2**.

Tasman Drive will be closed to vehicles from Convention Center Circle to Stars & Stripes Drive during large events. Tasman will not, however, be closed to pedestrian or bicycle traffic, enabling commuters and other cyclists to pass through the Stadium area. For safety reasons, cyclists will likely be required to walk their bikes in pedestrian zones at certain peak times, perhaps causing some inconvenience for cyclists, but not prohibiting their passage into or through the area. All major intersections in the area will be controlled by police and standard traffic laws (including the prohibition of bicycle riding on sidewalks, or against traffic) will be in effect.

5.4.2 Bicycle Parking

Bicycle parking will be provided within Red Lot 1. For events exceeding 20,000 attendees, a bicycle valet service shall be provided that includes a dedicated, bicycle storage area with valet service for visitors, to the satisfaction of the Director of Public Works. The bicycle storage area shall provide enough space to house a minimum of 750 bicycles. It is anticipated that the bicycle parking capacity will exceed the expected bicycle parking demand. Additional bicycle parking facilities may be available in the outer parking lots.

Figure 5.4-1: Bicycle Routes




Figure 5.4-2: Bicycle Diversions on Event Day





Figure 5.4-3: Bicycle Parking Facilities



5.5 Parking

5.5.1 Employee Parking

Stadium employees will be required to park in designated employee parking areas. The details of employee parking are as follows:

Employee Parking Areas

The employee event day parking demand, as estimated in the Transportation Management Plan, is summarized in **Table 5.5-1**.

Table 5.5-1: Employee Event day Parking Demand

Mode of Travel	Number of Employees	Total Employee Vehicles
Automobile (90%)	2,610	1,740
Transit (10%)	290	0
Total	2,900	1,740

Source: San Francisco 49ers, 2006; AECOM, 2014.

To meet this estimated demand, employees may utilize parking within the following parking facilities:

- The top four floors of Yellow Lot 1 (the City of Santa Clara Tasman Parking Garage located on the north side of Tasman Drive, directly across from the Stadium), including 1,200 parking spaces;
- Green Lot 6 (the Great America Theme Park parking lot), located southeast of the Great America Theme Park, including 749 parking spaces;
- Purple Lot 3 (Prudentail) is a 1,000 stall garage that is made available for employee parking, located at Patrick Henry Drive and Great America Parkway in the northeast corner of the intersection.
- When demand calls for, Green Lot 5 (Mission College) is converted to employee parking. This is generally due to constraints with weekday events, where employee parking is less readily available.
- 49ers Training Facility parking lot, adjacent to the Stadium, including 195 parking spaces;

It is expected that event day employee parking demand will be met by the 49ers Training Facility parking lot, Yellow Lot 1, Green Lot 6, and Purple Lot 3. Employees driving to and from parking facilities would follow the vehicular paths of travel defined in Section 5.1 for ingress and egress. The Stadium will be directly accessible from Yellow Lot 1 by way of a mid-block crossing on Tasman Drive. The Stadium is also directly accessible from the 49ers Training Facility parking lot, as it is located adjacent to the Stadium. From Green Lot 6, employees would reach the Stadium via employee shuttles, which will drop employees off at Dignity Health Gate C..

For Stadium employees who choose to bike to the Stadium, bike racks will be provided at Gates A and F, 10 bike lockers and 10 bike racks will be provided between Gate E and the 49ers Training Facility, and 23 bike lockers will



be provided at Lot 8, south of the Stadium. Employees using this bicycle parking facilities would have direct access to Stadium entry points, as each employee bicycle parking location would be directly adjacent to the Stadium.

Hours of Arrival and Departure

Per the *Transportation Management Plan for a New San Francisco 49ers Stadium in Santa Clara, CA* (AECOM, 2009), 95 percent of employees are expected to arrive over three hours in advance of a Stadium event, which is before the heavy ingress period for patrons of a given event. Also, employees will depart after the heavy egress period of a Stadium event has concluded. Thus, ingress and egress conflicts are not anticipated.

5.5.2 Patron Parking

Parking for patrons is to be provided in numerous locations, all within a reasonable walking distance to the Stadium. Approximately 19,000 parking spaces will be provided for patrons, approximately half of which would be located in parking facilities controlled by the City of Santa Clara. The remaining half of the parking supply would be provided off-site by permits with property owners for use on event days.

Patron Parking Areas

Patron parking will be provided in a number of surface parking lots and garages located in the vicinity of the Stadium. During event days, approximately 26,500 spaces are expected to be available for patrons across as many as 28 parking facilities surrounding the Stadium. As the estimated parking demand is approximately 19,000 spaces, the remainder of the parking supply is for contingency purposes should actual demand exceed estimated demand as a result of patron travel behavior (e.g., higher automobile mode shares) or other factors.

Season Ticket Holder Parking Areas

It is estimated that approximately 75 percent of all Stadium patrons during 49ers games will be season ticket holders, who would be assigned to specific parking lots through designated access routes, not matter their origin. For example, parking pass holders parking in Red Lot 1 will need to access this lot via a certain route, regardless of whether their origin is north, south, east, or west of the Stadium. All parking lots in the immediate vicinity of the Stadium would be designated for season ticket holders, with a small number of premium ticket holders (e.g., suite and club patrons) provided with designated spaces in certain lots closest to the Stadium. Spaces would not be designated for other ticketholders, who would be permitted to park in any space in their assigned lot(s). During event days, approximately 15,000 spaces would be provided for season ticket holders.

Season ticket holders will be notified of their assigned parking facility (and assigned parking space, if appropriate) in detailed informational packets to be mailed out with their tickets, including the associated ingress and egress routes for their assigned parking facility. For 49ers games, all ticketing is done electronically, and thus and parking passes and distributed electronically.

General Admission Parking Areas

General admission parking will primarily be located in facilities further from the Stadium, although some parking spaces in close proximity to the Stadium may also be open to general admission parkers. During events, general admission parking spaces would be provided for patrons paying with cash or credit card, distributed along each compass direction to accommodate vehicles coming from any direction. Locations of lots offering general admission parking spaces will be clearly identified by event day signage.

Hotel Parking Areas

In addition to ticketed and cash parking, additional parking spaces would be located in hotel parking areas operated owned and operated by nearby hotels. While these parking facilities would not be under the control of the City of Santa Clara or offered through permits with the 49ers for use by Stadium patrons, it is expected that a substantial portion of the parking spaces in these facilities would be used by Stadium patrons, either as privately-operated event-day parking or as parking for Stadium patrons who choose to stay at these hotels. However, it should be noted that should a hotel choose to rent their parking spaces out for Stadium event use, said hotel would be required to enter into parking contracts and obtain City off-site parking permits. Because of the proximity of these hotels to the Stadium, the majority of guests at these hotels on event days are expected to be Stadium patrons. These parking areas account for a total of 2,926 parking spaces in the vicinity of the Stadium, per **Table 5.5-2**.

Parking Supply and Locations

Approximately 28 parking facilities would be in use on event days, and are summarized in **Table 5.5-2**. The location of these facilities is illustrated in **Figure 5.5-1**. It should be noted that Lots immediately adjacent to the Stadium or 49ers Headquarters (player parking, Fire Department, Police Department, public relations staff, medical teams, TV production trucks, and administrative staff) may not be open to Stadium patrons.



Figure 5.5-1: Gameday Parking Facilities



Table 5.5-2: Stadium Parking Program

Parking Facility	Facility Use	Parking Spaces		
		Total Supply	Available to Patrons on Event Day	
City-Controlled Facilities				
	Yellow Lot 1	Ticketed	1,798	250
	Yellow Lot 2	Ticketed	314	304
	Yellow Lot 3	Ticketed	444	428
	Red Lot 1	Ticketed	1,220	1,212
	Red Lot 2	Ticketed	2,173	592
	Green Lot 1	Ticketed	4,997	4,500
	Subtotal		10,946	7,286
Outer Lots				
Red Lot 3	Ticketed / Cash	606	538	
Red Lot 4	Ticketed / Cash	825	782	
Red Lot 5	Ticketed / Cash	477	445	
Red Lot 7	Rideshare Lot	3,110	600	
Green Lot 2	Ticketed / Cash	1490	426	
Green Lot 3	Ticketed / Cash	758	732	
Purple Lot 3	Employee Parking	963	963	
Green Lot 4	Ticketed / Cash	1,577	1,497	
Green Lot 5	Ticketed / Cash	672	636	
Blue Lot 1	Ticketed / Cash	5,081	5,008	
Avatar	Hotel Parking	--	300	
Hilton	Hotel Parking	--	200	
Hyatt	Hotel Parking	--	295	
Marriott	Hotel Parking	--	1,200	
Biltmore	Hotel Parking	--	254	
Embassy Suites	Hotel Parking	--	291	
Hyatt House	Hotel Parking	--	164	
Plaza Suites	Hotel Parking	--	222	
Subtotal		15,559	14,553	



Outer Lots			
2901 Tasman + 2952 Bunker Hill	3rd Party Parking	705	635
4701 Patrick Henry Drive	3rd Party Parking	445	393
3118 Patrick Henry Drive	3rd Party Parking	116	65
3000 Patrick Henry Drive	3rd Party Parking	125	120
2950 Patrick Henry Drive	3rd Party Parking	137	120
2278 Calle De Luna	3rd Party Parking	85	85
2231 Calle De Luna	3rd Party Parking	65	60
2220 Calle De Luna	3rd Party Parking	140	140
2200 Calle De Luna	3rd Party Parking	82	80
2232 Calle Del Mundo	3rd Party Parking	35	35
2311 Calle Del Mundo	3rd Party Parking	30	30
2346 Calle Del Mundo	3rd Party Parking	24	24
2101 Tasman Drive	3rd Party Parking	406	350
2354 Calle Del Mundo	3rd Party Parking	20	20
Subtotal		2,415	2,157
Total		--	23,996

Source: San Francisco 49ers, 2017.

Notes: The parking program is subject to minor changes throughout the year.

Parking Access Plan

On all event days, parking facilities will be configured to control access, similar to the roadway network. However, the number of parking facilities used for a given event will vary depending on the size of the event. Where necessary, driveways may be coned off, and signage will be placed to direct patrons to proper access points. Access routes to the Stadium parking facilities are illustrated in **Figures 5.5-2a** and **5.5-2b**. However, it should be noted that this policy is subject to change based on the discretion of the Santa Clara Chief of Police, or his/her designee.

Parking Hours

In general, Stadium parking will be permitted approximately four hours before the start of an event start. Stadium parking will be prohibited before and after these periods to minimize the period of potential disturbance (subject to approval by the City of Santa Clara Chief of Police). Assuming a 1:00 PM to 1:30 PM start for Sunday games, parking will be permitted from 9:00 AM to 7:00 PM. For Saturday evening games beginning at 5:00 PM to 5:30 PM, parking will be permitted from 1:00 PM to 11:00 PM.

Parking hours for weekday games on Mondays, Thursdays, or Fridays are discussed in more detail in Chapter 6. In general, arrivals are expected to be more concentrated, and the designated hours for parking would begin later than for weekend games.

Areas of Parking Restrictions

Stadium parking would be restricted in all areas where it is not expressly permitted. These areas include residential neighborhoods, certain areas within off-site parking lots and other nearby facilities not designated for event day parking use. Areas where parking will be restricted are illustrated in **Figure 5.5-3**. Restriction of parking in these areas by Stadium patrons would be implemented through use of street closures to Stadium traffic (e.g., to restrict parking in on-street spaces in residential neighborhoods) and the hierarchy of control measures described in Section 5.1.1 (to restrict parking in off-site parking facilities for which permits for event day parking use have not been secured). It is recommended that business property owners whose parking facilities would not designated for event day parking use consider purchasing and installing “NO EVENT DAY PARKING” signage, as well as private security.

This aerial map of the University City area in San Diego displays various lots highlighted in different colors and numbered. The map includes street names such as Mortuary Street, Laporte St, and University City Blvd. A legend in the bottom right corner identifies the colors: Yellow Lot, Red Lot, Green Lot, Blue Lot, Purple Lot, and Other Lots. The highlighted lots are numbered 1 through 7, with some areas containing multiple numbers. The map also shows the San Diego River and surrounding urban development.

Legend:

- Yellow Lot
- Red Lot
- Green Lot
- Blue Lot
- Purple Lot
- Other Lots

Figure 5.5-2b: Vehicular Paths of Travel – Egress



Figure 5.5-3: Areas of Parking Prohibitions



Measures to Protect Property Owners

Parking intrusion into restricted areas will be controlled and enforced via a hierarchy of control measures that escalates in effectiveness until intrusion is minimized to an acceptable level:

1. Initially, cones and "ROAD CLOSED TO STADIUM TRAFFIC" signs shall be placed at the appropriate residential streets.
2. Should unacceptable levels of neighborhood intrusion occur, curbside signage shall be provided noting that on-street parking is prohibited for Stadium traffic, in addition to the placement of cones and "ROAD CLOSED TO STADIUM TRAFFIC" signs.
3. Should unacceptable levels of neighborhood intrusion continue to occur, traffic control officers will be assigned to neighborhood entrances to monitor all vehicle entry to residential streets, in addition to the placement of cones, "ROAD CLOSED TO STADIUM TRAFFIC" signs, and curbside signage.
4. Finally, should unacceptable levels of neighborhood intrusion continue to occur, a Residential Permit Parking program may be instituted if requested by the impacted neighborhoods, and should the affected city concur. In addition to the placement of cones, "ROAD CLOSED TO STADIUM TRAFFIC" signs, curbside signage, and the assignment of officers to monitor vehicle entry, signage noting that the area is designated for Residential Permit Parking only shall be installed.


ADA Parking

The primary supply of ADA parking will be provided within Green Lot 1 & Red Lot 1 (i.e., the parking facility located directly adjacent to the Stadium, along its west side), comprising a total of approximately 400 spaces—sufficient to meet ADA parking requirements for all patrons expected to arrive at the Stadium by vehicles. However, it should be noted that existing ADA parking spaces within off-site lots contracted for event use would also be available. On days when Great America is not open, an additional 130 ADA spaces in the Great America-only lot would be available for use by Stadium patrons with disabilities, bringing the total supply of ADA parking to 330 spaces (Red Lot 1 and Green Lot 1 combined).

Motorized carts will shuttle patrons with disabilities between the ADA parking area and the Stadium security perimeter. These measures would be in compliance with ADA accessibility requirements for parking and Stadium access. The location of ADA parking spaces in Red Lot 1 is illustrated in **Figure 5.5-4**.

ADA parking already provided in existing off-site parking facilities would also be available for use by patrons with disabilities. However, patrons intending to use ADA parking spaces (not located within Red Lot 1 or Green Lot 1) will be encouraged to park within Blue Lot 1, as disabled patrons parked at Blue Lot 1 will be served by a supplemental shuttle offering a direct connection to the Stadium.

Figure 5.5-4: Red Lot 1 ADA Parking



Tailgating

“Tailgating” is defined as the use of any item (including tables, chairs, free-standing canopies or umbrellas, awnings attached to recreational vehicles, coolers, barbeques, grills, games, generators, televisions, sound systems, food or drink, food or drink preparation or serving equipment, or other items as identified by the City Manager or designee) for the purpose of an outdoor gathering by one or more people prior to, during or after a scheduled stadium event. Tailgating will be permitted only within the designated event day parking facilities, and only in areas within these facilities where it is not expressly prohibited. Areas where tailgating will be prohibited are illustrated in **Figure 5.5-5**. Tailgating will be prohibited in parking structures, in surface lots within 750 feet of residences, and in surface lots within 750 feet of school buildings on weekday evenings and Saturdays (tailgating will be permitted in surface lots within 750 feet of school buildings on Sundays). Posted signage and security patrols of parking areas prior to, during, and after events will enforce these restrictions.

All tailgating equipment must be confined within each party's parking space, and amplified music or sound is not permitted (specifically within the Great America parking lot, the Golf and Tennis Club area, and lots within the Stadium security perimeter). Tents or canopies exceeding an eight-foot by eight-foot footprint and vehicles measuring more than 17 feet in length and / or eight feet in width will also not be permitted. Appropriate provisions (charcoal disposal, etc.) will be provided in the designated tailgating areas.

Tailgating Permitted

Tailgating Sunday Events Only

Limited Tailgating (No Open Flame)

No Tailgating

No Open Flame

5.6 Taxi and Pedicab Access

Taxi Service Access

The Stadium will be served by taxi. Taxis will load, unload, and stage along Calle De Luna, east of Calle Del Sol. All inbound taxis are directed to use Lafayette Street to Calle De Luna. **Figure 5.6-1.**

Uber Service Access

The Stadium will be served by Uber based on demand. Red Lot 7, located at 5451 Great America Parkway, will be used as a dedicated Uber Lot. Uber vehicles will stage, pick up, and drop off passengers at this lot, according to operational plan developed in conjunction with all traffic management parties. A defined route has been put in place for vehicles access ingress and egress. Inbound vehicles from Hwy 237 are directed to utilize North First Street until they reach Gold Street. Once at that location, vehicles will turn right and head south to Great America Way. Inbound vehicles from US101 will utilize Montague Expy eastbound to Lafayette Street. Once at that street, they will turn left onto Great America Way. At Great America Way, all vehicles will turn left to enter the staging location. **Figure 5.6-2.**

Pedicab Service Access

The Stadium will be served by Pedicabs (i.e., a bicycle taxi service), based on demand. Pedicab operators will enter the Stadium area via northbound Great America Parkway, and park within the Great America Theme Park passenger pick-up / drop-off area located along Great America Parkway (north of Old Glory Lane). Pedicabs will load, unload, and stage within the Great America Theme Park passenger pick-up / drop-off area, and transport patrons to parking facilities, as requested. Pedicab staging area and routes are illustrated **Figure 5.6-3.**

Figure 5.6-1: Taxi Staging Area on Event Days



Figure 5.6-2: Uber Service Access Routes





Figure 5.6-3: Pedicab Staging Area and Routes



5.7 Emergency Vehicle Access Plan

5.7.1 Ambulance

Ingress and Egress Plans

Emergency vehicles would be permitted to use the restricted section of Tasman Drive immediately adjacent to the Stadium, although they would be required to travel at slow speeds to ensure pedestrian safety. Access to all sides of the Stadium would be provided via the Stadium's Main Lot (Red Lot 1 and Green Lot 1), Tasman Drive, and Centennial Boulevard. Traffic control officers would be directed to prioritize emergency vehicle access through officer-controlled intersections during events.

Emergency vehicle access routes from both Tasman Drive and Great America Parkway are illustrated in **Figure 5.7-1**.

Staging Areas

Parking immediately to the south side of the Stadium would be dedicated for use by the Police Department, Fire Department, medical / ambulance providers, and other designated users. Specific staging areas for storage of ambulances and other emergency vehicles will be identified by the relevant agencies and providers.

Providers

Event providers of ambulance service, along with their contact information, responsibilities and representatives will be identified by the Stadium Manager.

5.7.2 Police

On-Site Facilities

The Santa Clara Police Department will operate a Temporary Holding Facility (THF) on-site for the purpose of processing event arrestees. Adjacent to the THF will be a conference room that will be used for briefing staff prior to deployment, report writing and issuing equipment. The Police Department will also staff several stations in the Stadium Command Center to oversee Stadium Law Enforcement Operations and the TMOP.

Off-Site Facilities

As part of the Public Safety Plan the Police Department will identify specific locations outside the Stadium for staging mutual aid.

Ingress and Egress Plans

As part of the TMOP's traffic plan, any closed street will have a designated emergency vehicle lane which will be coned off and used exclusively for that purpose. Responding emergency personnel will coordinate with Stadium Command Post and officer controlled intersections to facilitate emergency vehicle movement.

Figure 5.7-1: Emergency Vehicle Access



5.7.3 Fire

Deputy Fire Marshalls will be deployed inside the Stadium to monitor fire alarm systems in the lower-level Fire Command Center and to report emergency situations to the Fire Department representative in the Stadium Command Center. Deputy Fire Marshalls will also roam the Stadium to ensure compliance with fire and life safety regulations. The Fire Department will also staff a station in the Stadium Command Center to oversee Stadium Fire Operations including medical responses.

Off-Site Facilities

The Fire Department will deploy Fire assets in the Main Parking Lot of the Stadium. They will have the ability to respond to calls for service in the surrounding parking lot area, utilizing a Fire Department parking lot patrol vehicle.

Ingress and Egress Plans

As part of the TMOP's traffic plan, any closed street will have a designated emergency vehicle lane which will be coned off and used exclusively for that purpose. Responding emergency personnel will coordinate with Stadium Command Post and officer controlled intersections to facilitate emergency vehicle movement.

5.7.4 Stadium Traffic Operations Center

The Stadium's Traffic Operations Center will be a designated space within the Stadium (connected with the Traffic Operations Center at the Santa Clara City Hall) that is linked to cameras and signal controllers at specific intersections, allowing for remote changes to signal operations to occur. It is expected that VTA staff members, Police staff, Fire staff, City planning staff / engineering staff, and Stadium Authority staff will have access to the Stadium's Traffic Operations Center.



5.8 TMOP Contingency Planning

Instances may occur where transit use is higher than anticipated, and/or vehicular arrival patterns and parking facility use are different than expected. The TMOP must be flexible enough to account for these instances, and contingency plans must be implemented.

5.8.1 Transit Access

Transit ridership during ingress will be closely monitored in order to determine transit capacity needs during egress. If ingress transit ridership totals are greater than anticipated, transit capacity for egress will be expanded to ensure that patrons leaving an event by transit are able to do so in a safe and efficient manner.

Given that Capitol Corridor and ACE would be expected to offer one train each to and from the Stadium, it is expected that riders arriving by these transit providers will also depart by these transit providers. Should higher-than-expected ridership by VTA light rail occur (including riders transferring from Caltrain to VTA), VTA will supplement its light rail service with special express buses carrying passengers directly from the Stadium to the Mountain View VTA / Caltrain Station during egress. The number of supplemental express buses to be provided will be determined by the Stadium Manager, based on the number of passengers arriving by VTA light rail. VTA supplemental express buses will stage within the closed section of Tasman Drive, in the westbound direction, adjacent the Great America VTA Station. During egress, patrons would be ushered either into westbound VTA trains, or into supplemental express buses.

5.8.2 Vehicular Access and Parking

The potential exists for patrons to fill lots unevenly (i.e., lots north of the Stadium may be filled faster than lots south of the Stadium). Given that ingress routes are designed to direct patrons to a specific set of parking facilities, we must have a plan to re-route patrons to other lots without substantially disrupting the TMOP's ingress plan.

For each event, the Stadium Manager will identify lots where cash and / or overflow vehicles will be accommodated, and will communicate the location of these lots to traffic personnel. If the circumstance arises where lots are filling unevenly, and / or it becomes apparent that particular lots will soon likely be full and unable to accommodate additional vehicles while ingress is still underway, cars will be directed to alternate lots via identified routes on the streets or highways surrounding the Stadium.

Redirecting Patrons from North of the Stadium

1. Highway Changeable Message Signs (CMS) directing cash customers to the Great America Parkway / SR 237 ramps south should be adjusted such that they are no longer reflect this. Cash customers would instead be directed towards cash lots via the Lawrence Expressway / SR 237 ramps, the Lawrence Expressway / US 101 ramps, or the Great America Parkway / US 101 ramps.
2. Cash customers that continue to come from SR 237 would be directed south along Great America Parkway, right onto Old Mountain View Alviso Road, left onto Patrick Henry, and across Tasman Drive to cash lots south of the Stadium. Street CMS directing cash customers to lots north of the Stadium would be adjusted to reflect this as well.

Redirecting Patrons from South of the Stadium

1. Highway CMS directing cash customers to the Great America Parkway / US 101 ramps would be adjusted such that they are no longer reflecting this. Cash customers would instead be directed towards cash lots via the Lawrence Expressway / SR 237 ramps, the Lawrence Expressway / US 101 ramps, or the Great America Parkway / SR 237 ramps.
2. Cash customers that continue to come from US 101 would be directed north along Great America Parkway, and across Tasman Drive to cash lots north of the Stadium. Street CMS directing cash customers to lots south of the Stadium would be adjusted to reflect this re-route.

Redirecting Patrons from West of the Stadium

1. Highway CMS directing cash customers to the Lawrence Expressway / SR 237 ramps or the Lawrence Expressway / US 101 ramps would be adjusted such that they are no longer reflecting this. Cash customers would instead be directed towards cash lots via the Great America parkway / SR 237 ramps, or the Great America Parkway / US 101 ramps.
2. Cash customers that continue to come from Lawrence Expressway would continue east along Tasman Drive, and be directed either left or right at Tasman Drive towards cash lots north or south of the Stadium. Street CMS directing cash customers to lots west of the Stadium would be adjusted to reflect this re-route.

Additionally, as a final measure, the Santa Clara Police Department may identify on-street parking along Patrick Henry Drive, Old Ironsides Drive, Old Glory Way, Old Mountain View Alviso Road, Betsy Ross Drive, Bunker Hill Lane, Freedom Circle, or Hichborn Drive for parking purposes. These streets would be designated as restricted on event days, and would only be available if absolutely necessary.



This page intentionally left blank.



6.0 Weekday Considerations

In addition to planned procedures for event days, the TMOP provides a plan for weekdays leading up to events, and instances where events are to occur on a weekday. Though most NFL games are scheduled for Sunday afternoons, there is the potential for some games to occur on Monday or Thursday evening, and pre-season games could also occur on Friday or Saturday evening.

6.1 Advanced Communication

6.1.1 Patrons

Stadium patrons attending weekday events will be given substantial advanced notice regarding entrance and exit procedures, including acceptable hours to arrive at parking facilities (so as not to interfere with weekday business). Patrons should expect substantial delays traveling to weekday events, so patience, early arrival, and use of transit (including VTA light rail and buses, Caltrain, and Capital Corridor trains) will be encouraged and emphasized. In particular, specific details on gameday transit service to and from the stadium will be provided to encourage patrons to use public transportation in lieu of private vehicles.

This information will be contained in the information packets mailed to season ticket holders and disseminated on the 49ers website and via print (newspaper) and radio outlets. Ticket holders with email addresses on file will also receive email notification of special weekday rules regarding arrival and parking.

6.1.2 Area Businesses

Area businesses that anticipate providing parking for events will be required to obtain an off-site parking permit from the City. These area businesses regularly using any of the off-site parking facilities designated as event day parking will need to vacate these spaces approximately five hours prior to the start of an event. Setup of trash, portable toilets, and other facilities at off-site event day parking facilities will take place the night prior to the event. Contracts secured by the Stadium Manager for use of off-site parking facilities on weekdays will include provisions to this effect in order to provide adequate patron parking for weekday events and minimize conflicts between area businesses and Stadium traffic. Should any of the property owners agreeing to provide their parking facilities for use on weekend events refuse to provide their parking on weekday events, the Stadium Manager will contract with other property owners with parking facilities in the vicinity of the Stadium or make other arrangements as needed to ensure that an adequate supply of patron parking is provided for weekday events.

Contracts signed between the Stadium Manager and nearby property owners for use of their parking facilities will include requirements for property owners to ensure that businesses and employees regularly using their facilities are notified of the need to vacate parking spaces approximately five hours prior to the start of a game, in advance of weekday events. These notices will also include information regarding alternative options for travel (e.g., transit) and recommended ingress and egress routes arriving in and leaving the area before and during the pre-game period. VTA light rail and bus vehicles will also begin advertising these special provisions one week before weekday events via in-vehicle public announcement (PA) systems and / or paper flyers or advertisements. Area businesses with parking that is not included among the Stadium's weekday event day parking facilities would not be subject to provisions to vacate parking spaces approximately five hours prior to the start of a game, but would be similarly notified of Stadium-related impacts to the transportation network in advance of weekday Stadium events through emails, fliers, newspaper, and radio outlets.

6.1.3 Changeable Message Signs


Four days in advance of a weekday event, changeable message signs are to be placed at key locations (e.g., nearby freeway ramps and key roadways) to warn drivers to expect traffic congestion due to stadium-related traffic. Signs will indicate the day and time of the event, warn drivers that substantial congestion is expected, and recommend alternative routes using other freeway ramps or streets to avoid stadium-related traffic. The locations of the message signs are shown in **Figure 5.1-2**. These locations have been selected for sign placement because they serve high volumes of traffic, and because they offer direct access to the Stadium site.

6.2 Vehicle Access

Lane adjustments implemented for weekend events for the vehicle ingress period may not be possible for weekday events given the large number of employees needing to leave the area. Though area businesses whose parking facilities will not be used for event parking will be provided with advanced communication and instructions, employees of these businesses may not choose to vacate the area five hours prior to the start of an event, which may place them in conflict with stadium-related traffic flows entering the area. Retaining inbound and outbound access on the surrounding roadway network will minimize the impact of weekday events on these employees and provide them with a means of leaving the area. However, the transit- and pedestrian-only zone along Tasman Drive between Convention Circle and Centennial Boulevard must be in effect for large events on weekdays, beginning five hours before the start of an event, to ensure adequate pedestrian space for stadium patrons arriving by foot from surrounding parking facilities and allow for the efficient discharge of passengers arriving by light rail and bus. While inbound lane reconfigurations would not occur, changes to signal timing would be implemented to optimize stadium-bound traffic flows as well as normal weekday traffic patterns.

While lane adjustments during the vehicle ingress period (other than the Tasman Drive closure) would not be implemented for weekday events, it is expected that the majority of employees in the surrounding area will have departed by football game halftime (two hours after the start of an evening event). All other provisions for the vehicle egress period for weekend events would also be in effect for weekday events. Any employees remaining in the area would still be able to leave the stadium area by following the designated vehicle egress routes for stadium traffic, as shown in **Figure 6-1**.

Figure 6-1: Proposed Outbound Lane Configurations and Control



6.3 Transit Access

Similar to automobile considerations, special measures on transit services and facilities will be required before and after weekday events. This could primarily affect arrivals for weekday evening events by all modes of transit service, as event arrivals could coincide with PM peak commute traffic for surrounding uses. Weekday event departure activity could occur after typical commute hours. The available capacity of transit service for the inbound movement could be limited by the demands of regular transit riders during the evening peak commute period.

Post-game VTA light rail service for weekday stadium events will be similar to that for weekend stadium events. Regular weekday evening service after 8:00 PM on VTA's Mountain View – Winchester light rail line currently operates on 30-minute headways in each direction, but special event service could be provided for weekday stadium patrons based on demand. These provisions could include longer trains (three cars) and increased frequencies, in line with gameday transit service for weekend stadium events. Similarly, as ACE could provide special weekend service to accommodate demand to the Stadium for Sunday football games. However, ACE will run its normal schedule on weekdays. As such, patrons in the San Jose area could ride ACE trains to arrive at the Stadium for weekday evening events, but would require an alternate means of travel after the conclusion of the event.

Other transit services, such as VTA buses, Caltrain, and Capitol Corridor, will provide their regular service on weekday evenings. Currently, three VTA bus lines serve the Stadium area, the 55, 57, and 60. During Stadium ingress, the 55 provides four buses per hour, the 57 provides two buses per hour, and the 60 provides two buses per hour. During Stadium egress, all three bus lines provide one bus per hour. Assuming a carrying capacity of 45 passengers per bus, VTA buses could transport 360 patrons per hour during ingress, and 135 patrons per hour during egress assuming service will not be augmented for the weekday event. This level of ridership would be lower than what would be expected for football games on Sunday afternoons when additional rolling stock could be available. Caltrain could provide hourly service before and after all weekday Stadium events, similar to weekend service. Capitol Corridor does not currently offer service from the Stadium area after the time that most weekday events conclude, and an augmentation would be necessary to serve weekday games.

During weekday games and major events when Tasman Drive is closed, VTA Bus lines 140 and 330 will need to be rerouted as they currently operate along Tasman Drive. These two bus lines would be rerouted from Tasman Drive to Great America Parkway, Great America Way, Lafayette Street, Calle De Luna, and Calle Del Sol before resuming their normal route on Tasman Drive.

6.4 Parking

While most commercial parking in the stadium area is vacant during weekend events, this will not be the case during weekday events. During weekday events, parking lots intended for use as event parking in commercial areas near the Stadium, outside of stadium controlled and owned spaces, will need to be vacated prior to the beginning of stadium ingress. Thus, as stated previously, special agreements with these commercial properties will be required in order for a large weekday event to occur. Daytime users of parking spaces in these facilities would be directed by their respective employers and/or property owners to vacate the facility approximately five hours prior to the start of an event. While it is likely that not all spaces would be vacated before the pre-game arrival of stadium patrons, the standard roadway network (except minor changes to signal timing and the closure of Tasman Drive between Convention Center Circle and Centennial Boulevard) would remain in effect until football halftime to allow any remaining employees of these businesses to easily leave the area in any direction. After halftime, lane adjustments would be implemented similar to weekend events, but employees would still be able to leave the area using the designated vehicle egress routes for stadium traffic.



Based on historic information on stadium patron travel and parking behavior at Candlestick Park, a weekday evening game would generate a demand for approximately 1,500 additional parking spaces above a weekend game. As such, the Stadium Manager would need to provide additional parking beyond the parking program for weekend events, most likely by securing the use of additional parking spaces in existing off-site parking facilities.

6.5 Residential/Business Notifications and Communications

Communication regarding anticipated traffic and parking will be a key to holding a successful large-scale weekday event in the Stadium. This includes advance proactive communication with both residents and businesses to inform them of the event, date and measures to be taken during these periods. To enable maximum capacity, and thus reduce the period of congestion, during a weekday event residents and businesses in the surrounding area will need to adjust their travel behaviors accordingly.

Prior to a weekday event, potentially impacted business property owners as well as residents in the area bounded by Lawrence Expressway, Guadalupe River, SR 237, and US 101 will be notified by the Stadium Manager either by email or regular mail (the Stadium Manager may also consider circulating an annual schedule of events to residents). Additionally, as part of the community outreach for businesses and residents, the Stadium Manager will develop a smartphone application that community members can sign up for to receive recorded telephone messages containing information regarding the event time as well as the extent of any expected lane or street closures, as well as designated local access routes to avoid Stadium-related traffic, before, during, and after weekday games. The notices will also contain information regarding which off-site parking facilities will need to be vacated approximately five hours prior to the start of an event, as employees and visitors of other businesses in the area, as well as local area residents, may otherwise regularly use these designated off-site Stadium parking facilities.

Information disseminated through changeable message signs or other signage, online via the 49ers website, via radio, or in print as part of the Stadium's general communications program as described in Section 6.1 would also serve to notify residents and businesses of the associated effects of weekday stadium events on local transportation conditions.

This page intentionally left blank.



7.0 Integration/Coordination with Nearby Facilities

7.1 Great America Theme Park

Stadium activity may coincide with Great America Theme Park activity. When this occurs, safe and efficient access for Great America Theme Park patrons must be maintained. To accommodate this level of event traffic, reconfiguration of the surrounding roadway network for some periods of time before and after events would ensure safe and efficient travel to and from the Stadium. As a result, access to Great America Theme Park can be made most efficient by entering and exiting via designated roadways. This section of the TMOP describes what changes may occur on Stadium event days, and how access to Great America Theme Park will be provided.

7.1.1 Great America Theme Park Parking During Events

As detailed in section 5.5 of the TMOP, parking on event days for patrons is expected to occur in numerous parking lots within walking distance of the Stadium, including the shared Stadium / Great America Theme Park parking lot. The Theme Park is open on weekends from late March in the spring until late May, plus Spring Break week; every day from late May until Labor Day; and thereafter on weekends until New Year's Eve. In addition, the Theme Park would be open for other special events through agreement that may be held throughout the year. Of this total (approximately 150 operating days), 6-12 of those days may coincide with NFL events (depending on whether one or two teams use the stadium as a home venue). Of those 6-12 NFL events, 2-4 of those days would be pre-season games which typically would have lesser impacts on parking and traffic). The possibility of NFL-Theme Park conflicts could be restricted to those few days (6-12 maximum) in August, September, and October (toward the end of the Theme Park's season) when the Park would be open and events could occur on the same days. Other events (less than 20 per year) could be scheduled by the Stadium Manager in cooperation with the Theme Park to minimize access and parking conflicts. On occasions when the Theme Park is operating and a Stadium event is scheduled, coordination between both parties is necessary to ensure efficient flow of vehicles into and out of the two adjacent venues. This section of the TMOP outlines procedures for Great America Theme Park attendee parking during Stadium events.

Parking Supply

Dependant upon Great America Theme Park attendance projections, parking supply is allocated sufficiently for their use, and the remainder is utilized for stadium parking.

Figure 7-1: Great America Theme Park Parking Supply on Event Day





Event Day Parking Lot Operations

Given the lower cost of Great America Theme Park parking (daily parking passes range from \$15 to \$22, season parking passes range from \$55 to \$75, or free season parking with other passes) versus Stadium event parking, and the proximity of the designated Theme Park parking lot to the Stadium, it is possible that some Stadium patrons may attempt to park in the designated Theme Park parking lot. Methods to prevent Stadium patrons from parking in the designated Theme Park parking lot will be determined through ongoing meetings between Great America staff, the Stadium Manager, and the City of Santa Clara Police Department; and will be implemented ahead of dual-use events.

7.1.2 Great America Theme Park Vehicle Access during Events

It is a goal of the TMOP to ensure safe and efficient access for Great America patrons on Stadium event days coinciding with Great America operation. This section of the TMOP describes a detailed access plan specifically for Great America patrons, identifies where advanced signage will be placed, and outlines how the message of event day access will be relayed to patrons.

Access Plan

The Stadium is located northeast of the Great America Theme Park on Tasman Drive, adjacent to the Great America parking lot. In general, Stadium-related traffic is expected to use the same major access routes to and from the site as Great America Theme Park patrons. In the event that Stadium activity coincides with Great America Theme Park activity, safe and efficient access for Great America Theme Park patrons must be maintained. To accommodate the level of Stadium event traffic, the reconfiguration of the surrounding roadway network would be required for some periods of time before and after events to ensure safe and efficient travel to and from the Stadium. As a result, access to the Great America Theme Park can be achieved most efficiently by entering and exiting via designated roadways and directions. This section discusses changes to the roadway network and circulation patterns that will occur on Sunday afternoon event days, and details how access to Great America Theme Park will be provided.

Entering the Theme Park

Automobiles destined for the Theme Park parking lot would be able to enter the designated parking facilities via Great America Parkway from both the north and the south. However, Theme Park patrons will be encouraged to enter from the south, via U.S. 101 and Great America Parkway, as this is the easiest access route. Theme Park patrons will be encouraged to enter from the south by way of posted signage, as well as via online notifications on the Great America website. Automobiles approaching from the east on Tasman Drive would be diverted towards Mission College Boulevard via Lick Mill Boulevard and Montague Expressway.

It should be noted that the majority of Theme Park patron arrivals for typical Theme Park operation days are unlikely to conflict with the Stadium egress period, as Stadium events will typically conclude between 4:00 PM and 5:00 PM, when Theme Park arrivals tend to be very low. However, some degree of Theme Park patron arrivals will occur during the Stadium egress period. Further, special events at the Theme Park, such as the "Halloween Haunt," may begin at 5:30 PM, conflicting with the Stadium's egress period for Sunday afternoon events. In these instances where Theme Park patron arrival would occur during Stadium egress, patrons destined for the Theme Park parking lot would continue to be able to enter the designated parking facilities via Great America Parkway from both the north and the south, with entry from the south being the preferred point of entry. Automobiles approaching from the east on Tasman Drive would continue to be diverted towards Mission College Boulevard via Lick Mill Boulevard and Montague Expressway, as the Tasman Drive closure would remain in effect during Stadium egress.

Exiting the Theme Park

Theme Park patron departure is unlikely to conflict with the Sunday afternoon Stadium ingress period, as Stadium ingress will typically occur between 8:00 AM and 1:00 PM, when Theme Park departures tend to be minimal. Based on traffic counts collected at all Great America vehicular access points, only a small percentage of Great America departures occur between the hours of 8:00 AM and 1:00 PM on Sundays. Automobiles exiting the Great America Theme Park designated parking facility during the Stadium ingress period must do so from the driveway at the Great America Parkway / Old Glory Lane intersection, where they will be required to turn left onto southbound Great America Parkway towards U.S. 101.

Automobiles exiting the Great America Theme Park designated parking facility from the driveway at the Great America Parkway / Old Glory Lane intersection during the Stadium egress period, or after the egress period has concluded would be able to:

1. Exit north along Great America Parkway then west along Tasman Drive towards the Lawrence Expressway; or,
2. Exit south along Great America Parkway to US-101.

An illustration of traffic flow in the vicinity of the Great America Theme Park on event days is provided in **Figures 7-2a** and **7-2b**. It should be noted that Great America traffic flow is shown against the Stadium ingress period.

Figure 7-2a: Access to Great America Theme Park on Event Day – Inbound





Figure 7-2b: Access to Great America Theme Park on Event Day – Outbound





Advanced Signage

In order to notify traffic approaching the impacted area of event day roadway configuration and access changes, changeable message signs and directional signage are to be used. The changeable message signs shall be posted at each of the area's major access roadways. Each sign will indicate that a Stadium event will be occurring, and will recommend an alternate route. The locations of the changeable message signs, including the message to be displayed at each location, is shown in **Figure 7-3**.

Temporary directional signage will be placed throughout the Stadium area, in areas where signage currently exists, to clearly identify alternate routes for Great America Theme Park related traffic. The locations of all advanced signage are illustrated in **Figure 7-3**.

Communication

Concurrent events have the potential to create increased traffic congestion and conflicts. Collaboration and coordination between the Stadium Manager and the Theme Park will be required to ensure implementation of an integrated set of event management strategies and to ensure the dissemination of credible traveler information. Public awareness strategies and communications strategies for implementation include:

- Education on ticket purchase and/or with tickets
- Brochures and mailers
- Press releases and media alerts
- Telephone hotline
- Smartphone application
- Web-based dissemination


7.2 Techmart and Convention Center Vehicle Access during Events

Similar to Great America, Stadium activity may coincide with Techmart and Convention Center activity. In the event that this occurs, safe and efficient access for Techmart and Convention Center patrons must be maintained. To accommodate this level of event traffic, reconfiguration of the surrounding roadway network for some periods of time before and after events would ensure safe and efficient travel to and from the Stadium. As a result, access to the Techmart and Convention Center, can be achieved most efficiently by entering and exiting via designated roadways. This section of the TMOP describes what changes may occur on Stadium event days, and how access to Techmart and the Convention Center will be provided.

Access Plan

The Stadium is located southeast of the Techmart and Convention Center on Tasman Drive, adjacent to the Great America parking lot. Vehicular access to the area east of the Convention Center's Tasman Drive entrance would be strictly prohibited on event days, as the area along Tasman Drive between the Convention Center Tasman Drive entrance and Centennial Boulevard would be designated for pedestrian and light rail transit use only. On event days, police officers will regulate traffic flow at the Great America Parkway / Bunker Hill Lane intersection and ensure that patrons of Techmart and the Convention Center can gain access to these facilities.

Figure 7-3: Advanced Signage





Entering Techmart and the Convention Center

Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, the most efficient method of accessing the Techmart and Convention Center parking areas is by entering from the north on southbound Great America Parkway, and turning left at the Bunker Hill Lane entrance. Access to the Techmart and Convention Center entrance on Tasman Drive and the eastbound left-turn at the Tasman Drive/Convention Center entrance will be prohibited as part of the Tasman Drive closure.

Exiting Techmart and the Convention Center

Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, Techmart and Convention Center patrons would be required to make a right-turn out of the parking lot and exit onto northbound Great America Parkway towards SR 237. An illustration of traffic flow in the vicinity of Techmart and the Convention Center on event days is provided as **Figure 7-4**.

Advanced Signage

In order to notify traffic approaching the impacted area of event day roadway changes, changeable message signs and directional signage are to be used. The changeable message signs shall be posted at each of the major access roadways. Each sign will indicate that a Stadium event will be occurring, and will recommend an alternate route. The locations of the changeable message signs, including the message to be displayed at each location, is shown in **Figure 7-3**.


Directional signage will be placed throughout the Stadium area to clearly identify alternate routes for Techmart and Convention Center related traffic. The locations of all advanced signage are illustrated in **Figure 7-3**.

Communication

Concurrent events have the potential to create increased traffic congestion and conflicts. Collaboration and coordination between the Stadium Manager and Techmart and the Convention Center will be required to ensure implementation of an integrated set of event management strategies and to ensure the dissemination of credible traveler information. The Stadium Manager shall communicate the Stadium's anticipated Annual Events Calendar to all neighboring property owners so that they may plan accordingly, and collect annual event scheduling information from Techmart and the Convention Center. Public awareness strategies and communications strategies for implementation include:

- Brochures and mailers
- Press releases and media alerts
- Telephone hotline
- Web-based dissemination
- Smartphone application
- Public meetings

Figure 7-4: Access to Techmart, Convention Center, and the Hyatt Hotel on Event Days





7.3 Santa Clara Youth Soccer Park Vehicle Access during Events

Stadium activity may coincide with Santa Clara Youth Soccer Park activities. In the event that this occurs, safe and efficient access, and parking, for youth soccer park users must be maintained. To accommodate event day levels of traffic, reconfiguration of the surrounding roadway network for some periods of time before and after events would ensure safe and efficient travel to and from the Stadium. As a result, access to this facility can be achieved most efficiently by entering and exiting via designated roadways. This section of the TMOP describes what changes may occur on Stadium event days and how access to the Santa Clara Youth Soccer Park will be provided.

Access Plan

The Stadium is located west of the Youth Soccer Park. On event days, police officers will regulate traffic flow and prohibit vehicles from traveling along Tasman Drive between Convention Center Circle and Centennial Boulevard. Vehicular access to the area west of the Centennial Boulevard / Tasman Drive intersection would be strictly prohibited on event days, as the area along Tasman Drive between Convention Center Circle and Centennial Boulevard would be designated for pedestrian and transit use only. Traffic officers would control the pedestrian crossings at the intersection of Centennial Boulevard and Stars & Stripes Drive.

Entering the Santa Clara Youth Soccer Park

Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, Santa Clara Youth Soccer Park can only be accessed by patrons from the east access point at the cul-de-sac on Stars & Stripes Drive. Youth Soccer Park related traffic will make a right turn onto northbound Centennial Boulevard from westbound Tasman Drive, turn right onto Stars & Stripes Drive, and continue to the parking lot access point at the end of the cul-de-sac.

Exiting the Santa Clara Youth Soccer Park

Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, Santa Clara Youth Soccer Park patrons would be required to exit the facility via the access point at the cul-de-sac on Stars & Stripes Drive. Youth Soccer Park related traffic would make a left turn onto southbound Centennial Boulevard from westbound Stars & Stripes Drive, and would then be required to turn left onto eastbound Tasman Drive towards North 1st Street. An illustration of traffic flow in the vicinity of the Santa Clara Youth Soccer Park on event days is provided as **Figure 7-5**.


Advanced Notice

Advance notice for scheduled users of the soccer facilities will be sent via the City Scheduler directly to each user.

Communication

Concurrent events have the potential to create increased traffic congestion and conflicts. Collaboration and coordination between the Stadium Manager and the Santa Clara Youth Soccer Park will be required to ensure implementation of an integrated set of event management strategies and to ensure the dissemination of credible traveler information. The Stadium Manager shall communicate the Stadium's anticipated Annual Events Calendar to all neighboring property owners so that they may plan accordingly, and collect annual event scheduling information from the Santa Clara Youth Soccer Park. Public awareness strategies and communications strategies for implementation are described in Section 7.1.2.

Figure 7-5: Access to Santa Clara Youth Soccer Park on Event Days





7.4 Santa Clara Golf & Tennis Club Vehicle Access during Events

For large events, the Santa Clara Golf Course was utilized during the first two years of operation. However, through research collected it was discovered it was unnecessary and proved to be a stressful task for staff during both set up/tear down and event day. Therefore, Stadium activity coincides with Santa Clara Tennis Club activities. In the event that this occurs, safe and efficient access, and parking, for Tennis Club users must be maintained. To accommodate event day levels of traffic, reconfiguration of the surrounding roadway network for some periods of time before and after events would ensure safe and efficient travel to and from the Stadium. As a result, access to this facility can be achieved most efficiently by entering and exiting via designated roadways. This section of the TMOP describes what changes may occur on event days and how access to the Santa Clara Tennis Club will be provided.

Access Plan

The Stadium is located south of the tennis club. On event days, police officers will regulate traffic flow and prohibit vehicles from traveling along Tasman Drive between Convention Circle and Centennial Boulevard. Vehicular access to the area west of the Centennial Boulevard / Tasman Drive intersection would be strictly prohibited on event days, as the area along Tasman Drive between Convention Circle and Centennial Boulevard would be designated for pedestrian and transit use only. Traffic officers would control the pedestrian crossings at the intersection of Centennial Boulevard and Stars & Stripes Drive.

Entering the Tennis Club

Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, Santa Clara Tennis Club can be only accessed by patrons from westbound Tasman Drive by making a right turn onto northbound Centennial Boulevard from westbound Tasman Drive and continuing onto Stars & Stripes Drive to the parking lot entrance(s). Users of these facilities will park on-street adjacent to the Santa Clara Tennis Club.

Exiting the Santa Clara Tennis Club


Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, Santa Clara Tennis Club patrons would be required to exit the club by making a right turn from Stars & Stripes Drive onto southbound Centennial Boulevard, followed by a left turn onto eastbound Tasman Drive towards North 1st Street. An illustration of traffic flow near the Santa Clara Tennis Club on event days is provided as **Figure 7-6**.

Advanced Signage

In order to notify traffic approaching the impacted area of event day roadway changes, changeable message signs and directional signage are to be used. The changeable message signs shall be posted at each of the major access roadways. Each sign will indicate that there is a Stadium event will be occurring, and will recommend an alternate route. The locations of the changeable message signs, including the message to be displayed at each location, is shown in **Figure 7-3**.

Directional signage shall be placed throughout the Stadium area to clearly identify alternate routes for Santa Clara Tennis Club related traffic. The locations of all advanced signage are illustrated in **Figure 7-3**.

Figure 7-6: Access to Santa Clara Tennis Club on Event Day





Communication

Concurrent events have the potential to create increased traffic congestion and conflicts. Collaboration and coordination between the Stadium Manager and the Santa Clara Tennis Club will be required to ensure implementation of an integrated set of event management strategies and to ensure the dissemination of credible traveler information. The Stadium Manager shall communicate the Stadium's anticipated Annual Events Calendar to all neighboring property owners so that they may plan accordingly, and collect annual event scheduling information from the Santa Clara Tennis Club. Public awareness strategies and communications strategies for implementation are described in Section 7.1.2.

7.5 David's Restaurant and Banquet Facility Vehicle Access during Events

Stadium activity may coincide with activity at David's Restaurant and Banquet Facility. In the event that this occurs, safe and efficient access for facility users must be maintained. To accommodate event day levels of traffic, reconfiguration of the surrounding roadway network for some periods of time before and after events would ensure safe and efficient travel to and from the Stadium. As a result, access to this facility can be made most efficiently by entering and exiting via designated roadways. This section of the TMOP describes what changes may occur on Stadium event days and how access to David's Restaurant and Banquet Facility will be provided.

Access Plan

The Stadium is located south of the restaurant facility. On event days, police officers will regulate traffic flow and prohibit vehicles from traveling along Tasman Drive between Convention Circle and Centennial Boulevard. Vehicular access to the area west of the Centennial Boulevard / Tasman Drive intersection would be strictly prohibited on event days, as the area along Tasman Drive between Convention Circle and Centennial Boulevard would be designated for pedestrian and transit use only. Traffic officers would control the pedestrian crossings at the intersection of Centennial Boulevard and Stars & Stripes Drive.


Entering David's Restaurant and Banquet Facility

Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, David's Restaurant and Banquet Facility can only be accessed by patrons from westbound Tasman Drive, by making a right turn onto northbound Centennial Boulevard from westbound Tasman Drive, and a left turn onto westbound or eastbound Stars & Stripes Drive to access the facility's parking lot. During Stadium events, David's Restaurant and Banquet Facility's parking supply would be monitored by facility personnel to ensure efficient flow of vehicles in or out of the area.

Exiting David's Restaurant and Banquet Facility

Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, David's Restaurant and Banquet Facility patrons would be required to exit the facility by accessing southbound Centennial Boulevard followed by a left turn onto eastbound Tasman Drive towards North 1st Street. An illustration of traffic flow in the vicinity of David's Restaurant and Banquet Facility on event days is provided as **Figure 7-7**.

Figure 7-7: Access to David's Restaurant on Event Day





Advanced Signage

In order to notify traffic approaching the impacted area of event day roadway changes, changeable message signs and directional signage are to be used. The changeable message signs shall be posted at each of the major access roadways. Each sign will indicate that there is a Stadium event will be occurring, and will recommend an alternate route. The locations of the changeable message signs, including the message to be displayed at each location, is shown in **Figure 7-3**.

Directional signage shall be placed throughout the Stadium area to clearly identify alternate routes for David's Restaurant and Banquet Facility related traffic. The locations of all advanced signage are illustrated in **Figure 7-3**.

Communication

Concurrent events have the potential to create increased traffic congestion and conflicts. Collaboration and coordination between the Stadium Manager and David's Restaurant and Banquet Facility will be required to ensure implementation of an integrated set of event management strategies and to ensure the dissemination of credible traveler information. The Stadium Manager shall communicate the Stadium's anticipated Annual Events Calendar to all neighboring property owners so that they may plan accordingly, and collect annual event scheduling information from David's Restaurant and Banquet Facility. Public awareness strategies and communications strategies for implementation are described in Section 7.1.2.

7.6 Our Lady of Peace Church and Shrine

Stadium activity may coincide with Our Lady of Peace Church and Shrine activity. In the event that this occurs, safe and efficient access, and parking, for Church and Shrine users must be maintained. To accommodate event day levels of traffic, reconfiguration of the surrounding roadway network for some periods of time before and after events would ensure safe and efficient travel to and from the Stadium. As a result, access to this facility can be made most efficiently by entering and exiting via designated roadways. This section of the TMOP describes what changes may occur on Stadium event days and how access to the Our Lady of Peace Church and Shrine will be provided.

Access Plan

The Stadium is located northeast of the Our Lady of Peace Church and Shrine. Vehicular access to the Church and Shrine area would be provided via Great America Parkway, Mission College Boulevard, and Our Lady's Way.

Entering Our Lady of Peace Church and Shrine

With the reconfiguration of the roadway network to accommodate Stadium traffic on event days, Our Lady of Peace Church and Shrine will be accessible by making a left turn onto Mission College Boulevard from northbound Great America Parkway, and entering the parking lot directly from Mission College Boulevard. The Church and Shrine will also be accessible by making a u-turn at the Great America Parkway / Mission College Boulevard intersection (i.e., from northbound Great America Parkway onto southbound Great America Parkway), turning right onto Our Lady's Way, and entering the parking lot directly from Our Lady's Way.

Exiting Our Lady of Peace Church and Shrine

Due to the reconfiguration of the roadway network to accommodate Stadium traffic on event days, Church and Shrine patrons would be required to exit the facility via Our Lady's Way. Church and Shrine related traffic would either travel eastbound along Our Lady's Way, and make a right turn onto southbound Great America Parkway; or travel westbound along Our Lady's Way, and make a left turn onto southbound Mission College Boulevard.

An illustration of traffic flow in the vicinity of the Our Lady of Peace Church and Shrine on event days is provided as **Figure 7-8**.

Advanced Notice

In order to notify traffic approaching the impacted area of event day roadway changes, changeable message signs and directional signage are to be used. The changeable message signs shall be posted at each of the major access roadways. Each sign will indicate that there is a Stadium event will be occurring, and will recommend an alternate route. The locations of the changeable message signs, including the message to be displayed at each location, is shown in **Figure 7-3**.

Directional signage shall be placed throughout the Stadium area to clearly identify alternate routes for Church and Shrine related traffic. The locations of all advanced signage are illustrated in **Figure 7-3**.

Communication

Concurrent events have the potential to create increased traffic congestion and conflicts. Collaboration and coordination between the Stadium Manager and Our Lady of Peace Church and Shrine will be required to ensure implementation of an integrated set of event management strategies and to ensure the dissemination of credible traveler information. The Stadium Manager shall communicate the Stadium's anticipated Annual Events Calendar to all neighboring property owners so that they may plan accordingly, and collect annual event scheduling information from Our Lady of Peace Church and Shrine. Public awareness strategies and communications strategies for implementation are described in Section 7.1.2.

7.7 Great America Commuter Rail Station

Stadium activity may coincide with general use of the Great America Commuter Rail Station by ACE and Capitol Corridor. Both ACE and Capitol Corridor will have services during weeknight events that will require passengers to access the station via personal auto, ACE provided shuttles, and by private employer shuttles. Currently, ACE provides eight shuttle routes that carry passengers between the Great America Commuter Rail Station, and the Cities of Palo Alto, Mountain View, Sunnyvale, Santa Clara, San Jose, and Milpitas. Each shuttle is timed with ACE train weekday peak hour arrivals and departures. Capitol Corridor provides two shuttle routes carrying passengers between nearby businesses and the Great America Commuter Rail Station. Both ACE and Capitol Corridor shuttles currently stage along Stars and Stripes Drive, adjacent to the Station. Capitol Corridor shuttle routes currently approach the Station from the west via Tasman Drive, and exit to the east via Tasman Drive. ACE shuttle routes currently approach the Station from both the east and west via Tasman Drive. For weekday events that would necessitate a closure of Tasman Drive, shuttle routes would need to be augmented, and shuttle schedules would need to be adjusted accordingly. The shuttles reroutes would likely include a detour to Great America Way (north of the Stadium area), to Mission College Boulevard and Agnew Road (south of the Stadium area), and to Lafayette Street (east of the Stadium area).



This page intentionally left blank.



8.0 Main Lot Modifications

Design plans for modifications to the facility's main parking lot (Green Lot 1 and Red Lot 1 – the area bordered by the Stadium, Tasman Drive, Great America Parkway and the Great America Theme Park - have been restructured to better serve event day flows of vehicle and pedestrian traffic. Those modifications include the following

The Convention Center/Tasman driveway was retained, but it is now closed to vehicular traffic during peak egress periods immediately following the end of an event. Observations during peak egress flows during the past year showed that the large numbers of pedestrians crossing at this location significantly impacted its vehicular capacity. This closure eliminates the vehicular/pedestrian conflict at this location and allows for a free flow of westbound pedestrians during post game conditions. Additional westbound pedestrian corridor capacity has been put in place within the northerly edge of Red Lot 1. This corridor relieves pedestrian conflicts with the VTA Light Rail queues that are established in the southerly lanes of Tasman Drive during egress.

The existing driveway on Great America Parkway just south of the Hilton Hotel has been widened from two lanes to three. This improvement supports the closure of the Convention Center driveway by providing a better means of access to northbound Great America Parkway during post event periods. It should be noted that this driveway was used only by Charter Buses during season 1; however, it is now being successfully used by both charter buses and automobiles during post event egress. Charter Buses now enter their parking area through a new two-lane driveway on Great America Parkway between the main entrance/exit at Old Glory Lane and the newly widened driveway just south of the Hilton Hotel. During non-event periods when the theme park is open, this driveway serves as the theme park drop-off lot entry. Along with the improvement above, this modification enables the Convention Center drive entry to be closed while offering an improved means for accessing Great America Parkway during egress.

This new two-lane driveway on Great America Parkway is served by a two-lane roadway stretching east-west through the westerly portion of the main lot, including cuts through the north-south landscaped median which currently divides the main lot. This new two-lane drive, together with a similar drive cut through the median slightly to the north, provides better egress for motorists parked in the westerly portion of Green Lot 1.

East of the existing toll booths entrance, the primary east-west roadway through the main lot connecting Great America Parkway to Gate C has been moved to the north. This provides a number of benefits, including providing a pedestrian walk path on a direct line between Great America Parkway and Gate C. It also increases the number of parking spaces south of the main roadway and pedestrian walkway. As the pedestrian/vehicular conflict between Green 1 and Red 1 was one of the main issues encountered, providing more spaces south (i.e. out of the conflict) allows for quicker and more efficient egress from Green 1 during the Southbound Great America Parkway counter-flow operation

Some of the parking stalls and aisles in Green 1 and the northwestern portion of Red 1 have been rotated 90 degrees to provide a smoother flow of traffic onto the internal collector roadways in these lots.

9.0 Development of Operating Budget

The operating budget for all elements of the TMOP shall be maintained by the Stadium Manager, and revised annually based on input received from all working groups. Detailed tasks and associated costs will be organized within a

separate operating budget document, rather than within the TMOP itself. However, the cost estimations are expected to include (but are not limited to) the following items:

- Development and circulation of Annual Events Calendar;
- Implementation of traffic signal improvements;
- Establishment of Stadium security perimeter on event days;
- Implementation of parking and traffic control plans on event days, including:
 - Event day signal modifications;
 - Arrangement of parking facilities and stationing of ticket takers;
 - Placement of signage and coning to control the direction of traffic flow;
 - Placement of changeable message signs;
 - Stationing of officers at select intersections; and
 - Circulation of event day information to ticket holders, as well as to local businesses and area residents.
- Implementation of transit adjustments on event days, including:
 - Tasman Drive at-grade crossing; and
 - Transit queuing areas.
- Data collection efforts, including:
 - Event day observations;
 - Aerial photography;
 - Transit ridership on event days, and non-event days; and
 - Analysis of collected data.
- Preparation of reports and data for working group review; and
- Continued coordination with nearby facilities.

Each year, the operating budget is to be reviewed and approved by the City Council of Santa Clara.

EXHIBIT C

Guy B. Wallace (SBN 176151)
 gwallace@schneiderwallace.com
 Sarah Colby (SBN 194475)
 scolby@schneiderwallace.com
 Jennifer A. Uhrowczik (SBN 302212)
 juhrowczik@schneiderwallace.com
 SCHNEIDER WALLACE COTTRELL KONECKY
 WOTKYNs LLP
 2000 Powell Street, Suite 1400
 Emeryville, CA 94608
 Tel: (415) 421-7100
 Fax: (415) 421-7105

Linda M. Dardarian (SBN 131001)
 ldardarian@gbdhlegal.com
 Andrew P. Lee (SBN 245903)
 alee@gbdhlegal.com
 GOLDSTEIN, BORGEn, DARDARIAn & HO
 300 Lakeside Drive, Suite 1000
 Oakland, CA 94612
 Tel: (510) 763-9800
 Fax: (510) 835-1417

Attorneys for Plaintiffs and the Proposed Classes
 (Additional Counsel for Plaintiffs listed on following page)

UNITED STATES DISTRICT COURT
NORTHERN DISTRICT OF CALIFORNIA
SAN JOSE DIVISION

ABDUL NEVAREZ, PRISCILLA NEVAREZ, and
 SEBASTIAN DEFRANCESCO, on behalf of
 themselves and all others similarly situated,

Plaintiffs,

vs.

FORTY NINERS FOOTBALL COMPANY, LLC,
 a Delaware limited liability company, et al.,

Defendants.

Case No.: 5:16-cv-07013

**NOTICE OF SITE INSPECTIONS
 PURSUANT TO FRCP 34**

Before: Hon. Lucy H. Koh
 Complaint Filed: December 7, 2016
 Trial Date: April 22, 2019

1 Adam B. Wolf (SBN 215914)
awolf@prwlegal.com
2 Catherine Cabalo (SBN 248198)
ccabalo@prwlegal.com
3 PEIFFER ROSCA WOLF ABDULLAH CARR & KANE
4 4 Embarcadero Center, 14th Floor
San Francisco, CA 94104
Tel: (415) 766-3592
5 Fax: (415) 402-0058

6 Attorneys for Plaintiffs and the Proposed Classes
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28


PLEASE TAKE NOTICE that on October 30 and 31, 2017, beginning at 9:00 a.m. and continuing until completed or 5:00 p.m., Plaintiffs will conduct site inspections as permitted by Rule 34(a)(2) of the Federal Rules of Civil Procedure of the pedestrian right of way, including sidewalks, crosswalks, curb ramps, and other pedestrian walkways at the following locations:

1. Great America Parkway from Old Mountain View-Alviso Road to Mission College Boulevard.
2. Tasman Drive from Calabazas Creek to Lafayette Street.
3. Mission College Boulevard from Great America Parkway to the driveway separating Mission College Lot B and C.
4. Patrick Henry Drive from Bunker Hill Lane to Great America Parkway.
5. Democracy Way from Patrick Henry Drive to Old Ironsides Drive.
6. Old Ironsides Drive from Bunker Hill Lane to Patrick Henry Drive.
7. Marie P. DeBartolo Way from Tasman Drive to end.
8. Stars and Stripes Drive from Tasman Drive toward the Yellow Lots to end.
9. Centennial Boulevard from Stars and Stripes Drive to Tasman Drive.
10. All parking lots and pedestrian walkways serving them, including but not limited to, the following: Premium Red Lot 1, Premium Red Lot 3, Red Lot 4, Red Lot 5, Red Lot 7, Premium Red Lot VIP, RV Blue Lot, Blue Lot 1, Blue Lot 2, Blue Lot 3, Premium Green Lot 1, 2T Premium Lot 2, 2NT Premium Green Lot 2, Green Lot 3, Green Lot 4, Green Lot 5, RV Green Lot, Premium Yellow Lot VIP, Premium Yellow Lot 1, Premium Yellow Lot 2, Premium Yellow Lot 3.

Dated: September 29, 2017

Respectfully submitted,

GOLDSTEIN, BORGEN, DARDARIAN & HO



Andrew P. Lee

Attorneys for Plaintiffs and the Proposed Classes

EXHIBIT D

2007 SAN FRANCISCO BUILDING CODE

AB-014

ADMINISTRATIVE BULLETIN

- AB-014** :
- DATE** : September 16, 1998 (Updated 01/01/08 for code references)
- SUBJECT** : Inspection
- TITLE** : **Dimensional Tolerances for New and Existing Construction**
- PURPOSE** : This bulletin details dimensional tolerances which can be accepted by field inspection personnel from the Department of Building Inspection when reviewing on-site construction work. This bulletin is the procedural implementation of the California Building Code, Section 1101B.4 and 1104B.5, Dimensional Tolerances, which amends the State code to permit jurisdictions to allow dimensional tolerances which meet industry standards. These tolerances should allow construction to proceed with dimensions as shown on the plans or in the code that are not exact but are within the standards accepted by the industry, the Department and the community.
- REFERENCES** : 2007 San Francisco Building Code
 - Sections 1101B.4 and 1104B.5 Dimensional Tolerances
 2007 San Francisco Plumbing Code
 2007 San Francisco Electrical Code
The Handbook of Construction Tolerances, McGraw Hill, 1994, David Kent Ballast, editor.
- DISCUSSION** : The application of dimensional construction tolerances is necessary because structures cannot be built which conform precisely to code defined absolute dimensions without deviation. This bulletin defines the limits of those deviations within which administrative approval can be routinely granted. Any deviations beyond these must be addressed in the form of "unreasonable hardships" through the standard Documentation of Unreasonable Hardship process. These tolerances are based on industry standards for materials and methods of construction and are not intended to approve any incorrect dimensions or design changes. These are not code changes but approvals for variance based on as-built conditions. This applies to both new construction and the remodeling of existing structures.

One of the bases of the Department's construction tolerance standards is the 1994 Edition of the Handbook of Construction Tolerances, edited by David Kent Ballast. This is a commonly used reference book regarding industry standards for tolerances and, as excerpted below, is adopted by this bulletin as representing the standards for tolerances within the City and County of San Francisco. Please note that some adjustments and additions to these tolerances have been made inasmuch as the Handbook of Construction Tolerances does not specifically address disabled access issues. Where specific accessibility conditions needed to be addressed, such standards have been added as needed. Per Section 1101B.4, dimensions that are not stated as "maximum" or "minimum" are absolute. The Department may administratively modify and/or add to the below referenced standards as necessary to meet the intent of the codes.

AB-014

2007 SAN FRANCISCO BUILDING CODE

Standard tolerances will be based upon the nominal manufactured dimensions of fabricated goods.

Note that the State Historical Building Code provides other remedies for variations which may be addressed through the provisions of Administrative Bulletin No. AB-013. This applies to all qualified historic properties. In cases where the State Historical Building Code is applied, that code takes precedence over the regular Building Code requirements.

The following tolerances are to be used:

- a. Concrete paving.
Standard: Plus or minus 1/4" over 10' for drives, parking surfaces, sidewalks and other site paving.
Ref. ACI117-06
- b. Concrete slabs for flatness and straightness.
Standard: Bull-float slab is plus or minus 1/2" over 10'.
Ref. ACI117-06 and ASTM E1155-96
- c. Cast-in-place concrete walls:
Standard: Plumb is 1/4" in 10'.
Ref. ACI117-06
- d. Concrete masonry unit and masonry construction.
Standard: 1/4" in 10' vertical or horizontal
Ref. ACI117-06
- e. Brick wall construction.
Standard: 1/4" in 10' vertical or horizontal
Ref. ACI117-06
- f. Granite and marble installation.
Standard: 1/4" in 10' vertical or horizontal.
Ref. Dimension Stone Design Manual VII, Marble Institute of America, Inc. 2007
- g. Limestone installation.
Standard: 1/4" in 10' vertical or horizontal.
Ref. Various industry standards
- h. Slate tile installation for flooring or walls.
Standard: Vertical or horizontal 1/4" in 10'.
- i. Wood floor framing and sub-flooring.
Standard: 1/4" in 10' horizontal tolerance.
Ref. Spectext, Section 06112, Framing and Sheathing by the Construction Sciences Research Foundation, 2006
- j. Floor and wall tile.
Standard: 1/4" in 8' for wall and flooring. This does not apply to thresholds.
Ref. ANSI A108.1, A108.4, and A108.5

2007 SAN FRANCISCO BUILDING CODE

AB-014

- k. Terrazzo flooring.
Standard: 1/4" in 10'
Ref. Terrazzo Information Guide, the National Terrazzo and Mosaic Association, 1993
- l. Wood flooring.
Standard: 1/4" in 10'
Ref. ANSI/HPMA LHF, 1982
- m. Other stone installation.
Standard: 1/4" in 10'
Ref. Dimensions, Stone Design Manual IV, 1991
- n. Cabinets and counter tops.
Standard: 1/4" in 12' out of parallel with the floor; 1/8" variation in clear width.
Ref. Quality Standards for the Professional Remodeler, Second Edition, National Association of Homebuilders, Remodelers Council, 1991
- o. Flatness of counter tops.
Standard: 1/4" per 8'.
Ref. Architectural Woodwork Quality Standards, Architectural Woodwork Institute, 1993
- p. Storefront installation.
Standard: Storefront systems to be vertical plus or minus 1/8" in 12';
Ref. Aluminum Storefront and Entrance Manual, American Architectural Manufacturers Association, 1987
- q. Framing for gypsum wallboard.
Standard: 1/8" in 10' vertical and horizontal.
Ref. GA-216
- r. Wallboard partitions, ceilings, and trim.
Standard: 1/4" in 10'
Ref. ANSI A108.11, and GA-216
- s. Installation of lath and plaster.
Standard: 1/4" per 10'
Ref. ASTM C926
- t. Clear opening at doors.
Standard: plus or minus 3/8"
Ref. None.
- u. Plumbing fixture installation
Standard: plus or minus 1/2" measured from the finished wall or floor.
Ref. None

AB-014

2007 SAN FRANCISCO BUILDING CODE

- v. Handrail dimensions.
Nominal handrails not to vary more than 3/16" in diameter from code dimension; height plus or minus 3/16" measured from finished floor.
Ref. None.
- w. Threshold.
Standard: 1/8" variation in threshold height is permitted above the finished floor surface.
Ref. None
- x. Knee clearance under wall mounted plumbing fixtures, including lavatories, drinking fountains, urinals and toilets.
Standard: Mounting height above finished floor equals plus or minus 3/8". Within a 30" wide area, centered on the accessible basin or fixture, there may be a variation of 1/4" in height between the lower edge of the counter and the finished floor.
Ref. None
- y. Switches, receptacles, pull stations, controls and similar devices.
Standard: Plus or minus 1/2" vertically.
Ref. None
- z. Door operating pressure.
Standard: Plus or minus 1/2 pound.
Ref. None
- aa. Operating pressures for faucets, flush valves and miscellaneous hardware.
Standard: Plus or minus 1/2 pound.
Ref. None
- bb. Other elements. Other constructed elements which are not specifically regulated shall be permitted to have a construction tolerance of 1/4" plus or minus unless, in the opinion of the district inspector, such variation impedes access, except that grab bars and handrails shall be not more than the maximum horizontal distance from the adjoining wall surface than is permitted by the regular code.

Approved by the Building Inspection Commission on September 16, 1998

Originally signed by:
Frank Y. Chiu, Director
November 12, 1998

EXHIBIT E

REQUIRED ACCESSIBLE PARKING BASED ON PARKING TOTALS FROM STADIUM'S TMOP, DISCOVERY DOCUMENT SC04249			
LOT	TOTAL SPACES	REQUIRED ACC SPACES	OF WHICH ARE VAN
TICKETED			
RED 3	538	11	2
RED 4	782	16	3
RED 5	445	9	2
RED 7	600	12	2
GREEN 2	426	9	2
GREEN 3	732	15	3
GREEN 4	1497	25	5
GREEN 5	636	13	3
BLUE 1	5008	61	11
SUBTOTALS	10664	171	33
CITY OWNED			
YELLOW 1	250	7	2
YELLOW 2	304	8	2
YELLOW 3	428	9	2
RED 1	1212	23	4
GREEN 1	4500	55	10
SUBTOTALS	6694	102	20
TICKETED	10664	171	33
CITY OWNED	6694	102	20
TOTALS	17358	273	53

EXHIBIT F




EXHIBIT G

Parking Lots Detailed Findings Report with Photographs

- Red Parking Lot 1
- Yellow Parking Lot 1 –Parking Structure
- Yellow Parking Lot 2
- Yellow Parking Lot 3
- Blue Lot 1
- Green Parking Lot 2
- Red Parking Lot 3
- Red Parking Lot 4
- Red Parking Lot 5
- Red Parking Lot 7



FACILITY ACCESS CONSULTING

7040 Avenida Encinas #104-114, Carlsbad CA 92011

ABBREVIATIONS

AA	Access Aisle		Lav	Lavatory
Abv	Above		LL	Lower Level
ACC	Accessible		Manuv	Maneuvering
Adj	Adjacent		MARR	Multiple Accommodation Restroom
Approx	Appromiately		Max	Maximum
AFF	Above Finish Floor		Min	Minimum
Asph	Asphalt		MMARR	Men's Multiple Accommodation Restroom
BCT	Baby Changing Table		N	North
Blw	Below		NE	Northeast
BOH	Back of House		NW	Northwest
Btm	Bottom		Obst.	Obstructed
Btwn	Between		Ped	Pedestrian
CL	Center Line		Perp.	Perpendicular
Clr.	Clear/Clearance		PROW	Public Right Of Way
Cls.	Clearances		PTD	Paper Towel Dispenser
Conc	Concrete		QSF	Quick Serve Food
CPS	Composite Play Structure		ROT	Route Of Travel
CRASCA	Construction-Related Accessibility Standards Compliance Act (CA Civil Code 55.51-55.545)		RR	Restroom
CR	Curb Ramp		RS	Running Slope
CS	Cross Slope		S.B.	See Below
d	Deep		S	South
DAS	Designated Accessible Parking Stall		SARR	Single Accommodation Restroom
Dr	Door		SCD	Seat Cover Dispenser
DW	Detectable Warning		SD	Soap Dispenser
EAO	Employee Area Only		SE	Southeast
E	East		Spec.	Specifications
Elev	Elevator		SW	Sidewalk
EPC	Elevated Play Component		SW	Southwest
ER	Electrical Receptacle		TC	Toilet Compartment
Ext	Exterior		TD	Truncated Domes
Flr	Floor		TPD	Toilet Paper Dispenser
Furn.	Furniture		UL	Upper Level
FV	Flush Valve		Vert.	Vertical
GB	Grab Bar		W	West
GLPC	Ground Level Play Component		w	wide
h	High		WC	Water Closet
HR	Hand Rail		WMARR	Womens Multiple Accommodation Restoom
Int	Interior		WR	Waste Receptacle

Parking Lots Detailed Findings Report with Photographs

Red Parking Lot 1

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

10. Parking: Red Lot 1**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1001	#5 PARKING STALL	198 DAS	
1002	#5 PARKING STALL	64 DAS at gate A.	64 DAS
1003	#5 PARKING STALL	64 DAS at gate A.	Stalls A16, A15, A11, A7
1004	#5 PARKING STALL	56 DAS at gate B.	DAS E1.
1005	#5 PARKING STALL	56 DAS at gate B.	DAS F1
1006	#5 PARKING STALL	56 DAS at gate B.	DAS G1
1007	#5 PARKING STALL	56 DAS at gate B.	DAS H1
1008	#5 PARKING STALL	56 DAS at gate B.	DAS H3/H4
1009	#5 PARKING STALL	198 DAS.	DAS 13 and 14 in all 4 rows E, F, G, H (8 DAS total).
1010	#11 ACC ROUTE OF TRAVEL	56 DAS at gate B.	198 DAS, security device.
1011	#11 ACC ROUTE OF TRAVEL	56 DAS at gate B.	Route between parking and bridge to gate B.
1012	#5 PARKING STALL	78 DAS at gate C.	DAS I1
1013	#5 PARKING STALL	78 DAS at gate C.	DAS I3.
1014	#5 PARKING STALL	78 DAS at gate C.	DAS I4.
1015	#5 PARKING STALL	78 DAS at gate C.	DAS I5/I6
1016	#5 PARKING STALL	78 DAS at gate C.	DAS I19
1017	#5 PARKING STALL	78 DAS at gate C.	DAS J13
1018	#5 PARKING STALL	78 DAS at gate C.	
1019	#5 PARKING STALL	128 DAS at gate C.	20 DAS, L1 through L20.
1020	#2 PARKING LOT	198 DAS at gates A, B and C.	198 DAS spaces including 15 spaces that are designated vans accessible.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1001

FEATURE: #5 PARKING STALL


LOCATION: 198 DAS

MEMO:

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	I.D. sign with contrasting ISA (White on blue background per CVC 22511.7(b)(1)) is provided and located with bottom at min. 60" high. (ADAS 502.6)	ISA is not the standard symbol.
C03	I.D. sign is min. 70" square in size and reflectorized. (2013 CBC 11B-502.6.1)	Signs are not reflectorized.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1002

FEATURE: #5 PARKING STALL

LOCATION: 64 DAS at gate A.

MEMO: 64 DAS

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B23	Access aisle is marked to discourage parking -in California: with "NO PARKING" in white with min. 12" high letters located at tail end of access aisle. (ADAS 502.3.3)	Access aisle markings are faded (NO PARKING).



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 10. Parking: Red Lot 1****SEQ.
#****1003****FEATURE: #5 PARKING STALL****LOCATION: 64 DAS at gate A.****MEMO: Stalls A16, A15, A11, A7****Notes:**

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	I.D. sign with contrasting ISA (White on blue background per CVC 22511.7(b)(1)) is provided and located with bottom at min. 60" high. (ADAS 502.6)	None



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1004

FEATURE: #5 PARKING STALL

LOCATION: 56 DAS at gate B.


MEMO: DAS E1.

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 2.7%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1005

FEATURE: #5 PARKING STALL

LOCATION: 56 DAS at gate B.

MEMO: DAS F1

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 4.2%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1006

FEATURE: #5 PARKING STALL

LOCATION: 56 DAS at gate B.

MEMO: DAS G1

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 5.4%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1007

FEATURE: #5 PARKING STALL

LOCATION: 56 DAS at gate B.

MEMO: DAS H1

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 5.9%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 10. Parking: Red Lot 1****SEQ.
#****1008****FEATURE: #5 PARKING STALL****LOCATION: 56 DAS at gate B.****MEMO: DAS H3/H4****Notes:**

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Pothole in access aisle serving both DAS that is 3/4" deep by 6" wide by 7" long.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1009

FEATURE: #5 PARKING STALL

LOCATION: 198 DAS.

MEMO: DAS 13 and 14 in all 4 rows E, F, G, H (8 DAS total).

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Detectable warnings are unnecessary and obstruct the access aisle for all 8 DAS.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1010

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: 56 DAS at gate B.

MEMO: 198 DAS, security device.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	If clear width is less than 36", it is min. 32" clear for 24" long max. and reduced width segments are separated by min. 48" long by 36" wide segments. (ADAS 403.5.1)	25" wide at the btm., 28" wide at the top at all security devices.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1011

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: 56 DAS at gate B.

MEMO: Route between parking and bridge to gate B.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	5.0% to 5.7% for 40' L between DAS and security device, up to 5.8% just East of security device.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1012

FEATURE: #5 PARKING STALL

LOCATION: 78 DAS at gate C.

MEMO: DAS I1

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Two holes 1" in diameter.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1013

FEATURE: #5 PARKING STALL

LOCATION: 78 DAS at gate C.


MEMO: DAS I3.

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Two holes 1" in diameter.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1014

FEATURE: #5 PARKING STALL

LOCATION: 78 DAS at gate C.

MEMO: DAS I4.

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Two holes 1" in diameter.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1015

FEATURE: #5 PARKING STALL

LOCATION: 78 DAS at gate C.

MEMO: DAS I5/I6

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	One hole in access aisle serving both DAS that is 1" in diameter.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1016

FEATURE: #5 PARKING STALL

LOCATION: 78 DAS at gate C.

MEMO: DAS I19

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Access aisle is marked to define a width of min. 5' wide. (ADAS 502..3.1)	No access are provided, stall is 9' wide.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1017

FEATURE: #5 PARKING STALL

LOCATION: 78 DAS at gate C.

MEMO: DAS J13

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C06	Signs are positioned with bottom min. 60" above surface of parking space, and are visible from, and located at projected width at head end, or are immediately adjacent to parking space.	None



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1018

FEATURE: #5 PARKING STALL

LOCATION: 78 DAS at gate C.


MEMO:

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard parking spaces are closer to the bridge to gate C.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1019

FEATURE: #5 PARKING STALL

LOCATION: 128 DAS at gate C.

MEMO: 20 DAS, L1 through L20.

Notes:

For identification purposes Red Lot 1 DAS are numbered West to East and designated by letters North to South.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Parking space is marked to define a width of min.8' wide (9' CBC). (ADAS 502.2)	New surface markings are painted over old markings and determining extent of DAS is difficult.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 10. Parking: Red Lot 1

SEQ.
#

1020

FEATURE: #2 PARKING LOT

LOCATION: 198 DAS at gates A, B and C.

MEMO: 198 DAS spaces including 15 spaces that are designated vans accessible.

Notes:

Prior to March 15th 2012, 24 van stalls would have been required.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
A12	1 van stall provided for every 6 required acc stalls. (ADAS 208.2.4)	33 van stalls required, 15 provided.

Parking Lots Detailed Findings Report with Photographs

Yellow Parking Lot 1 –Parking Structure

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

1. Parking: Yellow Lot 1 Parking Structure

Facility Access Compliance Survey Report - Contents:

Seq #	Feature	Location	Memo
1101	#5 PARKING STALL	3 DAS at LD.	NE single DAS.
1102	#5 PARKING STALL	2 DAS at LD just South of exit.	
1103	#11 ACC ROUTE OF TRAVEL	2 DAS at LD just South of exit.	Route from North stall of pair located South of exit at LD to electrical vehicle charging station.
1104	#5 PARKING STALL	12 DAS at 1A at SW corner.	Northern double DAS.
1105	#5 PARKING STALL	12 DAS at 1A at SW corner.	Second double DAS from North, South designated as van.
1106	#5 PARKING STALL	12 DAS at 1A at SW corner.	Third DAS from North.
1107	#5 PARKING STALL	12 DAS at 1A at SW corner.	Fourth double DAS from North.
1108	#5 PARKING STALL	12 DAS at 1A at SW corner.	Van stall near SW corner.
1109	#5 PARKING STALL	12 DAS at 1A at SW corner.	Southern double DAS.
1110	#11 ACC ROUTE OF TRAVEL	12 DAS at 1A at SW corner.	Route to elevator at the W side (in front of 11 DAS).
1111	#5 PARKING STALL	12 DAS at 1A at SW corner.	DAS at E side of elevator.
1112	#5 PARKING STALL	12 DAS at 1D at SE corner.	Northern double DAS.
1113	#5 PARKING STALL	12 DAS at 1D at SE corner.	Second double DAS from North.
1114	#5 PARKING STALL	12 DAS at 1D at SE corner.	Third double DAS from North.
1115	#5 PARKING STALL	12 DAS at 1D at SE corner.	Fourth double DAS from North.
1116	#5 PARKING STALL	12 DAS at 1D at SE corner.	Van DAS near SE corner.
1117	#5 PARKING STALL	12 DAS at 1D at SE corner.	Southern double DAS, North side designated van.
1118	#5 PARKING STALL	12 DAS at 1D at SE corner.	Southern DAS.
1119	#11 ACC ROUTE OF TRAVEL	12 DAS at 1D at SE corner.	Route to SE corner at E side (in front of 12 DAS).
1120	#5 PARKING STALL	12 DAS at 1D at SE corner.	
1121	#5 PARKING STALL	12 DAS at 1A at SW corner.	
1122	#54 REACH RANGE & OPERATING MECHANISMS	1A at SW corner.	Emergency call box serving 12 DAS located here.
1123	#54 REACH RANGE & OPERATING MECHANISMS	1D at SE corner.	Emergency call box serving 12 DAS located here.
1124	#54 REACH RANGE & OPERATING MECHANISMS	LD at NE corner.	Emergency call box serving 5 DAS located here.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1101

FEATURE: #5 PARKING STALL

LOCATION: 3 DAS at LD.

MEMO: NE single DAS.

Notes:

Access for route lead to North side of Stars and Stripes Blvd.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	Access aisle extends the full length of the parking space. (ADAS 502.3.2)	Access aisle is obstructed by 38" to bollard at East DAS.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	For middle and West stalls must pass behind other vehicles.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1102


FEATURE: #5 PARKING STALL

LOCATION: 2 DAS at LD just South of exit.

MEMO:


Notes:

North space is signed for electrical vehicle charging only, however the charging cable for 2 DAS does not reach, and if it did it would obstruct the pedestrian accessible route to Stars and Stripes Blvd.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure****SEQ.
#****1103****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: 2 DAS at LD just South of exit.****MEMO: Route from North stall of pair located South of exit at LD to electrical vehicle charging station.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	If vehicle is parked in adjacent stall to S, the route is completely obstructed by the vehicle.
B03	If clear width is less than 36", it is min. 32" clear for 24" long max. and reduced width segments are separated by min. 48" long by 36" wide segments. (ADAS 403.5.1)	20" to wheel stop if no vehicle park to the South.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1104

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1A at SW corner.

MEMO: Northern double DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 3.1% at head end of stalls and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1105

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1A at SW corner.

MEMO: Second double DAS from North, South designated as van.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 2.8% at head end of stalls and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1106

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1A at SW corner.

MEMO: Third DAS from North.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 3.1% at head end of North stall and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure**SEQ.
#****1107****FEATURE: #5 PARKING STALL****LOCATION: 12 DAS at 1A at SW corner.****MEMO: Fourth double DAS from North.****Notes:**

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1108

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1A at SW corner.

MEMO: Van stall near SW corner.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B13	Van parking space is marked to define a width of 11' wide (12' CBC) with 5' wide access aisle or 8' wide (9' CBC) with 8' wide access aisle. (ADAS 502.2, 502.3.1)	Access aisle obstructed by column (50" to column). Overall 13' wide to column stall portion is 9' wide.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1109

FEATURE: #5 PARKING STALL


LOCATION: 12 DAS at 1A at SW corner.

MEMO: Southern double DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 2.8% at North stall.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1110

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: 12 DAS at 1A at SW corner.

MEMO: Route to elevator at the W side (in front of 11 DAS).

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C42	Accessible routes coincide with or are located in the same area as general circulation paths. Where circulation paths are interior, required accessible routes are also interior (ADAS 206.3)	Route is exterior and exposed to weather whereas the route for the general public is interior and not exposed to weather.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1111

FEATURE: #5 PARKING STALL


LOCATION: 12 DAS at 1A at SW corner.

MEMO: DAS at E side of elevator.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Access aisle is marked to define a width of min. 5' wide. (ADAS 502..3.1)	Access aisle obstructed by concrete waste receptacle (28" to waste receptacle).



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure**SEQ.
#****1112****FEATURE: #5 PARKING STALL****LOCATION: 12 DAS at 1D at SE corner.****MEMO: Northern double DAS.****Notes:**

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1113

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1D at SE corner.

MEMO: Second double DAS from North.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up tp 3.5% in stalls and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1114

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1D at SE corner.

MEMO: Third double DAS from North.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 3.5% in stalls and access aisles.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1115

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1D at SE corner.

MEMO: Fourth double DAS from North.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 3.0% at North stall and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1116

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1D at SE corner.

MEMO: Van DAS near SE corner.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B13	Van parking space is marked to define a width of 11' wide (12' CBC) with 5' wide access aisle or 8' wide (9' CBC) with 8' wide access aisle. (ADAS 502.2, 502.3.1)	Access aisle obstructed by column (5' to column). Stall is 9' wide.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1117

FEATURE: #5 PARKING STALL

LOCATION: 12 DAS at 1D at SE corner.

MEMO: Southern double DAS, North side designated van.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 2.5% at South stall and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure**SEQ.
#****1118****FEATURE: #5 PARKING STALL****LOCATION: 12 DAS at 1D at SE corner.****MEMO: Southern DAS.****Notes:**

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1119

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: 12 DAS at 1D at SE corner.

MEMO: Route to SE corner at E side (in front of 12 DAS).

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C42	Accessible routes coincide with or are located in the same area as general circulation paths. Where circulation paths are interior, required accessible routes are also interior (ADAS 206.3)	Route is exterior and exposed to weather whereas the route for the general public is interior and not exposed to weather.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1120

FEATURE: #5 PARKING STALL



LOCATION: 12 DAS at 1D at SE corner.

MEMO:

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	There are standard stalls that are closer to the SE entrance than are these 12 DAS.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1121

FEATURE: #5 PARKING STALL





LOCATION: 12 DAS at 1A at SW corner.

MEMO:

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	There are standard stalls that are closer to the SW entrance than are 10 of these DAS.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1122

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS



LOCATION: 1A at SW corner.

MEMO: Emergency call box serving 12 DAS located here.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B21	Unobstructed forward or side approach reach range is min 15" to max 48" AFF. (ADAS 308.2.1, 308.3.1)	Help button is 52" AFF.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1123

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS


LOCATION: 1D at SE corner.

MEMO: Emergency call box serving 12 DAS located here.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B21	Unobstructed forward or side approach reach range is min 15" to max 48" AFF. (ADAS 308.2.1, 308.3.1)	Help button is 52 1/2" AFF.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 11. Parking: Yellow Lot 1 Parking Structure

SEQ.
#

1124

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: LD at NE corner.

MEMO: Emergency call box serving 5 DAS located here.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B21	Unobstructed forward or side approach reach range is min 15" to max 48" AFF. (ADAS 308.2.1, 308.3.1)	Help button is 52" AFF.



Parking Lots Detailed Findings Report with Photographs

Yellow Parking Lot 2

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011



13. Yellow Lot 2**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1301	#2 PARKING LOT	Lot with 304 spaces.	
1302	#11 ACC ROUTE OF TRAVEL	Access to public right of way.	To dirt pass at SE corner of lot.
1303	#11 ACC ROUTE OF TRAVEL	Access to public right of way.	Asphalt and concrete path at NE corner of lot leads to SW corner of Stars and Stripes Dr. and Centennial Blvd.
1304	#12 RAMP	Access to public right of way.	Asphalt and concrete path at NE corner of lot leads to SW corner of Stars and Stripes Dr. and Centennial Blvd.
1305	#11 ACC ROUTE OF TRAVEL	Access to public right of way.	Middle drive entrance at the N side of the lot.
1306	#11 ACC ROUTE OF TRAVEL	Access to public right of way.	Vehicular entrance at NW corner of lot.
1307	#11 ACC ROUTE OF TRAVEL	Access to public right of way.	Dirt pedestrian path at SW corner of lot.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 13. Yellow Lot 2****SEQ.
#****1301****FEATURE: #2 PARKING LOT****LOCATION: Lot with 304 spaces.****MEMO:****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
C10	Required number of acc stalls are provided as follows: 1-25=1, 26-50=2, 51-75=3, 76-100=4, 101-150=5, 151-200=6, 201-300=7, 301-400=8, 401-500=9, 501-1000=2% of total, 1001+=20+1 for each 100 over 1000. (ADAS 208.2)	8 required none provided
A12	1 van stall provided for every 6 required acc stalls. (ADAS 208.2.4)	2 required none provided



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 13. Yellow Lot 2****SEQ.
#****1302****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Access to public right of way.****MEMO: To dirt pass at SE corner of lot.****Notes:**

These lead to NW corner of Tasman Dr. and Centennial Blvd.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Dirt surface.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Multiple edges over 1 1/2" high.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Steep uphill routes.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 13. Yellow Lot 2****SEQ.
#****1303****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Access to public right of way.****MEMO: Asphalt and concrete path at NE corner of lot leads to SW corner of Stars and Stripes Dr. and Centennial Blvd.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	loose rocks, sand and gravel.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4 high vertical edge.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 13. Yellow Lot 2****SEQ.
#****1304****FEATURE: #12 RAMP****LOCATION: Access to public right of way.****MEMO: Asphalt and concrete path at NE corner of lot leads to SW corner of Stars and Stripes Dr. and Centennial Blvd.****Notes:**

Concrete portion is approx. 7' long and up to 6.5% running slope.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Landings are sloped 1:48 (2.08%) max. and are firm, stable and slip resistant without gaps or edges. (ADAS 405.7.1)	Btm. landing up to 4.8% and loose gravel, sand and rocks.
B31	Handrails are provided at both sides (ADA: except at ramp with max 6" rise / 72" run) (CBC: except adjacent to assembly seating, or at door landing ramp with max 6" rise / 72" run). (ADAS 405.8)	Overall height is over 6" and longer than 72".



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 13. Yellow Lot 2****SEQ.
#****1305****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Access to public right of way.****MEMO: Middle drive entrance at the N side of the lot.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Loose rocks.
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	Large gaps over 2" deep x 12" wide along transition to concrete.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Up to 2 1/2" high vertical edge at transition of concrete.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 13. Yellow Lot 2****SEQ.
#****1306****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Access to public right of way.****MEMO: Vehicular entrance at NW corner of lot.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Loose rocks, gravel and sand.
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	Up to 2" deep gaps over 12" wide along transition to concrete.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Up to 1" high vertical edge.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 13. Yellow Lot 2****SEQ.
#****1307****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Access to public right of way.****MEMO: Dirt pedestrian path at SW corner of lot.****Notes:**

Leads to N side of Tasman Dr.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Loose rocks, gravel and sand.
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	Multiples gaps.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Multiple vertical edges over 1/2" high.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Steep hillside.



Parking Lots Detailed Findings Report with Photographs

Yellow Parking Lot 3

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

14. Yellow Lot 3**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1401	#2 PARKING LOT	Entire Lot.	428 spaces.
1402	#11 ACC ROUTE OF TRAVEL	Pedestrian walkway to public right of way.	Dirt pathway at middle of W side of lot.
1403	#11 ACC ROUTE OF TRAVEL	Pedestrian walkway to public right of way.	Dirt pedestrian path at NW corner of lot.
1404	#11 ACC ROUTE OF TRAVEL	Pedestrian walkway to public right of way.	Vehicular drive by near NW corner.
1405	#11 ACC ROUTE OF TRAVEL	Pedestrian walkway to public right of way.	To dirt path at S side of lot.
1406	#11 ACC ROUTE OF TRAVEL	Pedestrian walkway to public right of way.	East vehicular drive.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 14. Yellow Lot 3****SEQ.
#****1401****FEATURE: #2 PARKING LOT****LOCATION: Entire Lot.****MEMO: 428 spaces.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
C10	Required number of acc stalls are provided as follows: 1-25=1, 26-50=2, 51-75=3, 76-100=4, 101-150=5, 151-200=6, 201-300=7, 301-400=8, 401-500=9, 501-1000=2% of total, 1001+=20+1 for each 100 over 1000. (ADAS 208.2)	None provided, 9 required.
A12	1 van stall provided for every 6 required acc stalls. (ADAS 208.2.4)	None provided, 2 required.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 14. Yellow Lot 3****SEQ.
#****1402****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Pedestrian walkway to public right of way.****MEMO: Dirt pathway at middle of W side of lot.****Notes:**

Asphalt and dirt leading to E side of Centennial Blvd.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Dirt, rocks, gravel and sand.
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	Multiples gaps at asphalt to dirt transition.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	4" high vertical edge at concrete.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Running slope 17.7% for approx. 12" at asphalt to dirt transition.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 14. Yellow Lot 3****SEQ.
#****1403****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Pedestrian walkway to public right of way.****MEMO: Dirt pedestrian path at NW corner of lot.****Notes:**

Leads to SE corner of Stars and Stripes Dr. and Centennial Blvd.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Dirt, gravel, sand and rocks.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3" high vertical edge at concrete to dirt, 3" at wood planting strip, and 1" at asphalt to dirt.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	19.7% at asphalt to dirt, 16.9% at dirt.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 14. Yellow Lot 3****SEQ.
#****1404****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Pedestrian walkway to public right of way.****MEMO: Vehicular drive by near NW corner.****Notes:**

Leads to S side of Stars and Stripes Dr.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Rocks, sand, gravel and dirt.
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	1 1/2" deep gap over 12" wide along transition to concrete.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Multiples edges up to 1 1/2".



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 14. Yellow Lot 3****SEQ.
#****1405****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Pedestrian walkway to public right of way.****MEMO: To dirt path at S side of lot.****Notes:**

Leads to N side of Tasman Dr.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Dirt
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Steep hillside.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 14. Yellow Lot 3****SEQ.
#****1406****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Pedestrian walkway to public right of way.****MEMO: East vehicular drive.****Notes:**

Leads to S side of Stars and Stripes Dr.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Rocks, gravel, sand and dirt.
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	Up to 2 1/2" deep gap over 18" wide along transition to concrete.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Multiple edges up to 1 1/2".



Parking Lots Detailed Findings Report with Photographs

Blue Lot 1

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

15. Blue Lot 1**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1501	#5 PARKING STALL	19 stalls at the N side of the lot at Democracy Wy.	
1502	#11 ACC ROUTE OF TRAVEL	19 stalls at the N side of the lot at Democracy Wy.	Walkway along N side (in front of) row of DAS.
1503	#12 RAMP	19 stalls at the N side of the lot at Democracy Wy.	Asphalt ramp at W end of walkway at N side of DAS.
1504	#11 ACC ROUTE OF TRAVEL	19 stalls at the N side of the lot at Democracy Wy.	From shelter to nearest portable toilets.
1505	#54 REACH RANGE & OPERATING MECHANISMS	19 stalls at the N side of the lot at Democracy Wy.	Hand washing station at portable toilet serving DAS.
1506	#54 REACH RANGE & OPERATING MECHANISMS	19 stalls at the N side of the lot at Democracy Wy.	Accessible portable toilet near DAS.
1507	#5 PARKING STALL	26 DAS at NE corner.	NE DAS at center island.
1508	#5 PARKING STALL	26 DAS at NE corner.	NE corner DAS at N end of row of DAS at E side.
1509	#54 REACH RANGE & OPERATING MECHANISMS	26 DAS at NE corner.	Hand washing station at portable toilets serving DAS.
1510	#54 REACH RANGE & OPERATING MECHANISMS	26 DAS at NE corner.	Accessible portable toilet.
1511	#11 ACC ROUTE OF TRAVEL	26 DAS at NE corner.	Walkway in front of E row of stalls.
1512	#11 ACC ROUTE OF TRAVEL	26 DAS at NE corner.	Asphalt connection to public right of way at Old Ironsides.
1513	#5 PARKING STALL	14 DAS at E side of parking lot.	
1514	#54 REACH RANGE & OPERATING MECHANISMS	14 DAS at E side of parking lot.	Hand wash station at portable toilet serving DAS.
1515	#54 REACH RANGE & OPERATING MECHANISMS	14 DAS at E side of parking lot.	Accessible portable toilet.
1516	#11 ACC ROUTE OF TRAVEL	14 DAS at E side of parking lot.	Walkway along E side (in front of) row of DAS.
1517	#12 RAMP	14 DAS at E side of parking lot.	Asphalt walkway to public right of way at Old Ironsides.
1518	#12 RAMP	26 DAS at NE corner.	Concrete walkway to Democracy Wy.
1519	#2 PARKING LOT	26 DAS at NE corner.	
1520	#12 RAMP	NW corner of lot.	
1521	#2 PARKING LOT	Entire lot.	508 spaces.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1501****FEATURE: #5 PARKING STALL****LOCATION: 19 stalls at the N side of the lot at Democracy Wy.****MEMO:****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Parking space is marked to define a width of min.8' wide (9' CBC). (ADAS 502.2)	West to stalls are obstructed by shelter.
B12	Access aisle is marked to define a width of min. 5' wide. (ADAS 502..3.1)	8 of the 11 access aisles are 58" to 59" wide.
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Stalls and access aisles at eastern 3 stalls are partially covered by leaves and dirt.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 15. Blue Lot 1

SEQ.
#

1502

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: 19 stalls at the N side of the lot at Democracy Wy.

MEMO: Walkway along N side (in front of) row of DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Partially covered by leaves and dirt.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1503****FEATURE: #12 RAMP****LOCATION: 19 stalls at the N side of the lot at Democracy Wy.****MEMO: Asphalt ramp at W end of walkway at N side of DAS.****Notes:**

Approx. 12' long from 4.0% to 6.5% slope. Route to the ADA mobility shuttle.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope of ramp is 1:48 (2.08%) max. (ADAS 405.3)	2.6% to 4.0%.
B12	Landings are sloped 1:48 (2.08%) max. and are firm, stable and slip resistant without gaps or edges. (ADAS 405.7.1)	Top landing up to 3.2%.
B31	Handrails are provided at both sides (ADA: except at ramp with max 6" rise / 72" run) (CBC: except adjacent to assembly seating, or at door landing ramp with max 6" rise / 72" run). (ADAS 405.8)	None. Approx. 12' long.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1504****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: 19 stalls at the N side of the lot at Democracy Wy.****MEMO: From shelter to nearest portable toilets.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Multiple raised edges 1" high.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 15. Blue Lot 1

SEQ.
#

1505

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS


LOCATION: 19 stalls at the N side of the lot at Democracy Wy.

MEMO: Hand washing station at portable toilet serving DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	Operable parts are operable with one hand, using max 5lbs force, and not requiring tight grasping, pinching, or twisting of the wrist. (ADAS 309.4)	Water is foot operated, not hand operated.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 15. Blue Lot 1

SEQ.
#

1506

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: 19 stalls at the N side of the lot at Democracy Wy.

MEMO: Accessible portable toilet near DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B21	Unobstructed forward or side approach reach range is min 15" to max 48" AFF. (ADAS 308.2.1, 308.3.1)	Hand sanitizer 54" high.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1507****FEATURE: #5 PARKING STALL****LOCATION: 26 DAS at NE corner.****MEMO: NE DAS at center island.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B12	Access aisle is marked to define a width of min. 5' wide. (ADAS 502..3.1)	Varies from 0" to 94".



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1508****FEATURE: #5 PARKING STALL****LOCATION: 26 DAS at NE corner.****MEMO: NE corner DAS at N end of row of DAS at E side.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B12	Access aisle is marked to define a width of min. 5' wide. (ADAS 502..3.1)	Obstructed by equipment.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 15. Blue Lot 1

SEQ.
#

1509

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: 26 DAS at NE corner.

MEMO: Hand washing station at portable toilets serving DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	Operable parts are operable with one hand, using max 5lbs force, and not requiring tight grasping, pinching, or twisting of the wrist. (ADAS 309.4)	Water operated by foot pump.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1510****FEATURE: #54 REACH RANGE & OPERATING MECHANISMS****LOCATION: 26 DAS at NE corner.****MEMO: Accessible portable toilet.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B21	Unobstructed forward or side approach reach range is min 15" to max 48" AFF. (ADAS 308.2.1, 308.3.1)	51 3/4" to hand sanitizer.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1511****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: 26 DAS at NE corner.****MEMO: Walkway in front of E row of stalls.****Notes:**

Necessary route of travel for all DAS in this area.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Obstructed by trees and plants.
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Surface obstructed by leaves, dirt and debris.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1512****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: 26 DAS at NE corner.****MEMO: Asphalt connection to public right of way at Old Ironsides.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Up to 3.1% convoluted asphalt surface.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1513****FEATURE: #5 PARKING STALL****LOCATION: 14 DAS at E side of parking lot.****MEMO:****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B23	Access aisle is marked to discourage parking -in California: with "NO PARKING" in white with min. 12" high letters located at tail end of access aisle. (ADAS 502.3.3)	North stall markings are worn away.
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Slopes at the southern 8 stalls and access aisles are excessive up to 4.6%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 15. Blue Lot 1

SEQ.
#

1514

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: 14 DAS at E side of parking lot.

MEMO: Hand wash station at portable toilet serving DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	Operable parts are operable with one hand, using max 5lbs force, and not requiring tight grasping, pinching, or twisting of the wrist. (ADAS 309.4)	Water operation by foot pedal.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1515****FEATURE: #54 REACH RANGE & OPERATING MECHANISMS****LOCATION: 14 DAS at E side of parking lot.****MEMO: Accessible portable toilet.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B21	Unobstructed forward or side approach reach range is min 15" to max 48" AFF. (ADAS 308.2.1, 308.3.1)	55" to hand sanitizer.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1516****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: 14 DAS at E side of parking lot.****MEMO: Walkway along E side (in front of) row of DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Completely obstructed by bushes and trees.
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Covered by leaves, dirt and debris.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1517****FEATURE: #12 RAMP****LOCATION: 14 DAS at E side of parking lot.****MEMO: Asphalt walkway to public right of way at Old Ironsides.****Notes:**

Approx. 12' long with running slope from 4.7% to 9.0%.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope is 1:12 (8.33%) max. (ADAS 405.2)	Up to 9.0%, running slope undulates from high to low and surface is not planar.
B31	Handrails are provided at both sides (ADA: except at ramp with max 6" rise / 72" run) (CBC: except adjacent to assembly seating, or at door landing ramp with max 6" rise / 72" run). (ADAS 405.8)	None, approx. 12' long.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1518****FEATURE: #12 RAMP****LOCATION: 26 DAS at NE corner.****MEMO: Concrete walkway to Democracy Wy.****Notes:**

Not the indicated accessible route to the public right of way. Approx. 12' long with running slope from 2.4% to 8.0%.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope of ramp is 1:48 (2.08%) max. (ADAS 405.3)	Cross slope is 4.0% at the top.
B12	Landings are sloped 1:48 (2.08%) max. and are firm, stable and slip resistant without gaps or edges. (ADAS 405.7.1)	Btm. Landing is 3.9%, top landing is 5.0% and top landing partially covered by debris.
B14	Top landing is min. 60" long. (ADAS 405.7.3)	Top landing is 48".
B31	Handrails are provided at both sides (ADA: except at ramp with max 6" rise / 72" run) (CBC: except adjacent to assembly seating, or at door landing ramp with max 6" rise / 72" run). (ADAS 405.8)	None, approx. 12' long.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 15. Blue Lot 1

**SEQ.
#**

1518

FEATURE: #12 RAMP

LOCATION: 26 DAS at NE corner.

MEMO: Concrete walkway to Democracy Wy.

Notes:

Not the indicated accessible route to the public right of way. Approx. 12' long with running slope from 2.4% to 8.0%.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 15. Blue Lot 1****SEQ.
#****1519****FEATURE: #2 PARKING LOT****LOCATION: 26 DAS at NE corner.****MEMO:****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
A5	Acc parking stalls are located on the shortest ACC route from parking to ACC entrance. (ADAS 208.3.1)	Many standard stalls are closer to both walkways to the public right of way, at the E side and the N side, than are some of the DAS.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 15. Blue Lot 1

SEQ.
#

1520

FEATURE: #12 RAMP

LOCATION: NW corner of lot.

MEMO:

Notes:

No accessible stalls located here, route leads to SE corner of Democracy Wy. And Patrick Henry Dr.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope is 1:12 (8.33%) max. (ADAS 405.2)	Up to 11.1%.
B12	Landings are sloped 1:48 (2.08%) max. and are firm, stable and slip resistant without gaps or edges. (ADAS 405.7.1)	Vegetation at the btm. transition. Top landing 3.1%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 15. Blue Lot 1

SEQ.
#

1521

FEATURE: #2 PARKING LOT

LOCATION: Entire lot.

MEMO: 508 spaces.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C10	Required number of acc stalls are provided as follows: 1-25=1, 26-50=2, 51-75=3, 76-100=4, 101-150=5, 151-200=6, 201-300=7, 301-400=8, 401-500=9, 501-1000=2% of total, 1001+=20+1 for each 100 over 1000. (ADAS 208.2)	61 required, 59 provided.
A12	1 van stall provided for every 6 required acc stalls. (ADAS 208.2.4)	10 required, 9 provided.

Parking Lots Detailed Findings Report with Photographs

Green Parking Lot 3

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

16. Green Lot 3**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1601	#5 PARKING STALL	N side of building 4899	Single DAS
1602	#5 PARKING STALL	S side of building 4899.	Double DAS.
1603	#5 PARKING STALL	N side of building 4667.	Double DAS, W side designated van.
1604	#5 PARKING STALL	S side of building 4667.	Single DAS
1605	#5 PARKING STALL	N side of building 4655.	Double DAS
1606	#5 PARKING STALL	W side of building 4655.	Single DAS.
1607	#5 PARKING STALL	S side of building 4655.	Single van DAS.
1608	#5 PARKING STALL	N side of building 4633.	2 DAS, E side designated van.
1609	#5 PARKING STALL	S side of building 4633.	1 double and 2 single van DAS.

Facility Access Consulting, Inc.


NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1601****FEATURE: #5 PARKING STALL****LOCATION: N side of building 4899****MEMO: Single DAS****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1602****FEATURE: #5 PARKING STALL****LOCATION: S side of building 4899.****MEMO: Double DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1603****FEATURE: #5 PARKING STALL****LOCATION: N side of building 4667.****MEMO: Double DAS, W side designated van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1604****FEATURE: #5 PARKING STALL****LOCATION: S side of building 4667.****MEMO: Single DAS****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1605****FEATURE: #5 PARKING STALL****LOCATION: N side of building 4655.****MEMO: Double DAS****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1606****FEATURE: #5 PARKING STALL****LOCATION: W side of building 4655.****MEMO: Single DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1607****FEATURE: #5 PARKING STALL****LOCATION: S side of building 4655.****MEMO: Single van DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1608****FEATURE: #5 PARKING STALL****LOCATION: N side of building 4633.****MEMO: 2 DAS, E side designated van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 16. Green Lot 3****SEQ.
#****1609****FEATURE: #5 PARKING STALL****LOCATION: S side of building 4633.****MEMO: 1 double and 2 single van DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles.



Parking Lots Detailed Findings Report with Photographs

Green Parking Lot 2

April 4, 2018



FACILITY ACCESS CONSULTING

7040 Avenida Encinas #104-114, Carlsbad CA 92011

17. Green Lot 2**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1701	#5 PARKING STALL	S of parking structure.	4 DAS including one designated van.
1702	#11 ACC ROUTE OF TRAVEL	N side of parking structure.	Route of travel for all DAS at parking structure located at N side leading to Great America Pky.
1703	#5 PARKING STALL	W side of Citrix building.	8 DAS including one designated van.
1704	#9 PARALLEL CURB RAMP	Walkway in front row of DAS at W side of Citrix building.	Curb ramp at N pair of DAS.
1705	#9 PARALLEL CURB RAMP	Walkway in front row of DAS at W side of Citrix building.	Curb ramp at DAS pair second from N.
1706	#9 PARALLEL CURB RAMP	Walkway in front row of DAS at W side of Citrix building.	Curb ramp at DAS pair third from N.
1707	#9 PARALLEL CURB RAMP	Walkway in front row of DAS at W side of Citrix building.	Curb ramp at S pair of DAS.
1708	#11 ACC ROUTE OF TRAVEL	Route from 8 DAS at W side of Citrix to PROW at Great America Pky.	Between DAS and SW corner of building.
1709	#9 PARALLEL CURB RAMP	Route from 8 DAS at W side of Citrix to PROW at Great America Pky.	At SW corner of building.
1710	#10 CURB RAMP	Route from 8 DAS at W side of Citrix to PROW at Great America Pky.	S side of Citrix building, W side of service drive.
1711	#11 ACC ROUTE OF TRAVEL	Route from 8 DAS at W side of Citrix to PROW at Great America Pky.	S side of Citrix building across service drive.
1712	#9 PARALLEL CURB RAMP	Route from 8 DAS at W side of Citrix to PROW at Great America Pky.	S side of Citrix building, E side of service drive.
1713	#5 PARKING STALL	7 DAS at S side of N Citrix building.	Including one designated van.
1714	#11 ACC ROUTE OF TRAVEL	Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.	Along front of row of DAS.
1715	#10 CURB RAMP	Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.	At SW corner of N Citrix building.
1716	#10 CURB RAMP	Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.	At S side of service drive.
1717	#11 ACC ROUTE OF TRAVEL	Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.	Across service drive.
1718	#11 ACC ROUTE OF TRAVEL	Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.	Between service drive and PROW at Tasman Dr.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1701****FEATURE: #5 PARKING STALL****LOCATION: S of parking structure.****MEMO: 4 DAS including one designated van.****Notes:**

This is the exit for all DAS inside parking structure located at the S side.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many standard spaces are closer to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 17. Green Lot 2

**SEQ.
#**

1702

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: N side of parking structure.

MEMO: Route of travel for all DAS at parking structure located at N side leading to Great America Pky.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1703****FEATURE: #5 PARKING STALL****LOCATION: W side of Citrix building.****MEMO: 8 DAS including one designated van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many spaces are closer to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1704****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Walkway in front row of DAS at W side of Citrix building.****MEMO: Curb ramp at N pair of DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope is 1:48 (2.08%) max. (ADAS 405.3)	3.5%
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	3.1%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1705****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Walkway in front row of DAS at W side of Citrix building.****MEMO: Curb ramp at DAS pair second from N.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope is 1:48 (2.08%) max. (ADAS 405.3)	3.2% at N ramp, 2.8% at S ramp.
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	3.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 17. Green Lot 2

SEQ.
#

1706

FEATURE: #9 PARALLEL CURB RAMP


LOCATION: Walkway in front row of DAS at W side of Citrix building.

MEMO: Curb ramp at DAS pair third from N.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope is 1:48 (2.08%) max. (ADAS 405.3)	3.0% at S ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 17. Green Lot 2

SEQ.
#

1707

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Walkway in front row of DAS at W side of Citrix building.

MEMO: Curb ramp at S pair of DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	3.2%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1708****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Route from 8 DAS at W side of Citrix to PROW at Great America Pky.****MEMO: Between DAS and SW corner of building.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 120' L is 3.5% to 5.4%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1709****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Route from 8 DAS at W side of Citrix to PROW at Great America Pky.****MEMO: At SW corner of building.****Notes:**

Curb ramp must be used as part of sidewalk.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope is 1:48 (2.08%) max. (ADAS 405.3)	3.0% at N ramp.
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	3.2%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 17. Green Lot 2

SEQ.
#

1710

FEATURE: #10 CURB RAMP

LOCATION: Route from 8 DAS at W side of Citrix to PROW at Great America Pky.

MEMO: S side of Citrix building, W side of service drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope of ramp is 1:48 (2.08%). (ADAS 405.3)	3.8%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1711****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Route from 8 DAS at W side of Citrix to PROW at Great America Pky.****MEMO: S side of Citrix building across service drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 20' L is 3.1% to 4.4%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1712****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Route from 8 DAS at W side of Citrix to PROW at Great America Pky.****MEMO: S side of Citrix building, E side of service drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope is 1:12 (8.33%) max. (ADAS 405.2)	16.1% at N ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1713****FEATURE: #5 PARKING STALL****LOCATION: 7 DAS at S side of N Citrix building.****MEMO: Including one designated van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many standard spaces are closer to the public right of way.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1714****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.****MEMO: Along front of row of DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 80' L is 2.6% to 3.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1715****FEATURE: #10 CURB RAMP****LOCATION: Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.****MEMO: At SW corner of N Citrix building.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope of ramp is 1:48 (2.08%). (ADAS 405.3)	2.6% to 3.7%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1716****FEATURE: #10 CURB RAMP****LOCATION: Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.****MEMO: At S side of service drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	8.8% to 10.4%.
B04	Cross slope of ramp is 1:48 (2.08%). (ADAS 405.3)	3.1%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1717****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.****MEMO: Across service drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	4.0%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 17. Green Lot 2****SEQ.
#****1718****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Route between 7 DAS at S side of N Citrix building and PROW at Tasman Dr.****MEMO: Between service drive and PROW at Tasman Dr.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 100' L is 2.6% to 4.0%.



Parking Lots Detailed Findings Report with Photographs

Red Parking Lot 3

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

18. Red Lot 3**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1801	#5 PARKING STALL	4 DAS at E side of E building.	N double DAS, S designated as van.
1802	#5 PARKING STALL	4 DAS at E side of E building.	S double DAS
1803	#5 PARKING STALL	N side of E building.	Double DAS.
1804	#5 PARKING STALL	N side of NW building.	4 DAS including one designated van.
1805	#5 PARKING STALL	W side of NW building.	Single van DAS.
1806	#5 PARKING STALL	S side of NW building.	Double DAS, W stall designated van.
1807	#5 PARKING STALL	N side of SW building.	Double DAS.
1808	#5 PARKING STALL	W side of SW building.	Double DAS, N designated as van.
1809	#5 PARKING STALL	S side of SW building.	Double DAS, W designated as van.
1810	#5 PARKING STALL	3 DAS at S side of E building.	Double DAS.
1811	#5 PARKING STALL	3 DAS at S side of E building.	Single DAS.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1801****FEATURE: #5 PARKING STALL****LOCATION: 4 DAS at E side of E building.****MEMO: N double DAS, S designated as van.****Notes:**

Across the drive aisle from walkway to public right of way at Great America Pky.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	3.8% to 4.1% at head end of stalls and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1802****FEATURE: #5 PARKING STALL****LOCATION: 4 DAS at E side of E building.****MEMO: S double DAS****Notes:**

Across the drive aisle from walkway to public right of way at Great America Pky.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	3.6% to 5.4% at head end of stalls and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1803****FEATURE: #5 PARKING STALL****LOCATION: N side of E building.****MEMO: Double DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1804****FEATURE: #5 PARKING STALL****LOCATION: N side of NW building.****MEMO: 4 DAS including one designated van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1805****FEATURE: #5 PARKING STALL****LOCATION: W side of NW building.****MEMO: Single van DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1806****FEATURE: #5 PARKING STALL****LOCATION: S side of NW building.****MEMO: Double DAS, W stall designated van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 18. Red Lot 3

SEQ.
#

1807

FEATURE: #5 PARKING STALL



LOCATION: N side of SW building.

MEMO: Double DAS.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1808****FEATURE: #5 PARKING STALL****LOCATION: W side of SW building.****MEMO: Double DAS, N designated as van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1809****FEATURE: #5 PARKING STALL****LOCATION: S side of SW building.****MEMO: Double DAS, W designated as van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Parking space is marked to define a width of min.8' wide (9' CBC). (ADAS 502.2)	Markings worn and faded.
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1810****FEATURE: #5 PARKING STALL****LOCATION: 3 DAS at S side of E building.****MEMO: Double DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Parking space is marked to define a width of min.8' wide (9' CBC). (ADAS 502.2)	Markings worn and faded.
B23	Access aisle is marked to discourage parking -in California: with "NO PARKING" in white with min. 12" high letters located at tail end of access aisle. (ADAS 502.3.3)	Markings worn and faded.
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	3.3% at access aisle.
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 18. Red Lot 3****SEQ.
#****1811****FEATURE: #5 PARKING STALL****LOCATION: 3 DAS at S side of E building.****MEMO: Single DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Parking space is marked to define a width of min.8' wide (9' CBC). (ADAS 502.2)	Markings worn and faded.
B23	Access aisle is marked to discourage parking -in California: with "NO PARKING" in white with min. 12" high letters located at tail end of access aisle. (ADAS 502.3.3)	Markings worn and faded.
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	5.5%
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



Parking Lots Detailed Findings Report with Photographs

Red Parking Lot 4

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

19. Red Lot 4**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1901	#5 PARKING STALL	N side of building 3.	Double DAS, W side designated as van.
1902	#5 PARKING STALL	N side of building 2.	Double DAS.
1903	#5 PARKING STALL	4 DAS at W side of building 1	Northern pair, N designated as van.
1904	#5 PARKING STALL	4 DAS at W side of building 1	Southern pair.
1905	#5 PARKING STALL	4 DAS at W side of building 1	Single DAS, farthest E from entrance.
1906	#5 PARKING STALL	6 DAS at the E side of building 4.	Southern pair.
1907	#5 PARKING STALL	6 DAS at the E side of building 4.	Middle double DAS, S designated as van.
1908	#5 PARKING STALL	6 DAS at the E side of building 4.	Northern double DAS.
1909	#2 PARKING LOT	Lot portion used by Levi's Stadium.	825 stalls at N half of lot.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 19. Red Lot 4****SEQ.
#****1901****FEATURE: #5 PARKING STALL****LOCATION: N side of building 3.****MEMO: Double DAS, W side designated as van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Parking space is marked to define a width of min.8' wide (9' CBC). (ADAS 502.2)	Obstructed by portable toilet.
B12	Access aisle is marked to define a width of min. 5' wide. (ADAS 502..3.1)	Obstructed by portable toilet.
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	18.5% at tail end of stalls and access aisles at swale.
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Detectable warnings placed in the access aisle which are unnecessary.
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 19. Red Lot 4

**SEQ.
#**

1901

FEATURE: #5 PARKING STALL

LOCATION: N side of building 3.

MEMO: Double DAS, W side designated as van.

Notes:

--

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 19. Red Lot 4****SEQ.
#****1902****FEATURE: #5 PARKING STALL****LOCATION: N side of building 2.****MEMO: Double DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	15.4% at tail end of stalls and access aisles at swale.
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Detectable warnings placed in the access aisle which are unnecessary.
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.





NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 19. Red Lot 4****SEQ.
#****1903****FEATURE: #5 PARKING STALL****LOCATION: 4 DAS at W side of building 1****MEMO: Northern pair, N designated as van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 19. Red Lot 4****SEQ.
#****1904****FEATURE: #5 PARKING STALL****LOCATION: 4 DAS at W side of building 1****MEMO: Southern pair.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 19. Red Lot 4****SEQ.
#****1905****FEATURE: #5 PARKING STALL****LOCATION: 4 DAS at W side of building 1****MEMO: Single DAS, farthest E from entrance.****Notes:**

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	6.7% at access aisle.
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 19. Red Lot 4****SEQ.
#****1906****FEATURE: #5 PARKING STALL****LOCATION: 6 DAS at the E side of building 4.****MEMO: Southern pair.****Notes:**

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 19. Red Lot 4****SEQ.
#****1907****FEATURE: #5 PARKING STALL****LOCATION: 6 DAS at the E side of building 4.****MEMO: Middle double DAS, S desginted as van.****Notes:**

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 19. Red Lot 4****SEQ.
#****1908****FEATURE: #5 PARKING STALL****LOCATION: 6 DAS at the E side of building 4.****MEMO: Northern double DAS.****Notes:**

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 19. Red Lot 4

SEQ.
#

1909

FEATURE: #2 PARKING LOT

LOCATION: Lot portion used by Levi's Stadium.

MEMO: 825 stalls at N half of lot.

Notes:

Southern 3 buildings and lots not available during events.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C10	Required number of acc stalls are provided as follows: 1-25=1, 26-50=2, 51-75=3, 76-100=4, 101-150=5, 151-200=6, 201-300=7, 301-400=8, 401-500=9, 501-1000=2% of total, 1001+=20+1 for each 100 over 1000. (ADAS 208.2)	17 required, 14 provided.

Parking Lots Detailed Findings Report with Photographs

Red Parking Lot 5

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

20. Red Lot 5**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
2001	#5 PARKING STALL	4 DAS N side of N building	E pair of DAS, E designated as a van.
2002	#5 PARKING STALL	4 DAS N side of N building	Western pair.
2003	#5 PARKING STALL	4 DAS at E side of N building. Near N end.	Southern pair.
2004	#5 PARKING STALL	4 DAS at E side of N building. Near N end.	Northern pair.
2005	#5 PARKING STALL	S side of N building.	Double DAS, W designated as van.
2006	#10 CURB RAMP	Route between double DAS at S side of N building and walkway at N side of S building.	Curb ramp at N side of planter.
2007	#5 PARKING STALL	S side of S building.	Single DAS.
2008	#5 PARKING STALL	3 DAS S of entrance at E side of S building.	Single van stall.
2009	#5 PARKING STALL	3 DAS S of entrance at E side of S building.	Double DAS.
2010	#5 PARKING STALL	4 DAS at N side of entrance at E side of S building.	Southern pair.
2011	#5 PARKING STALL	4 DAS at N side of entrance at E side of S building.	Northern pair.


Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 20. Red Lot 5****SEQ.
#****2001****FEATURE: #5 PARKING STALL****LOCATION: 4 DAS N side of N building****MEMO: E pair of DAS, E designated as a van.****Notes:**

Appears recently constructed. There is no public right of way sidewalk at the drive aisle.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 5.0% at E stall.
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 20. Red Lot 5

SEQ.
#

2002

FEATURE: #5 PARKING STALL

LOCATION: 4 DAS N side of N building


MEMO: Western pair.

Notes:

Appears recently constructed. There is no public right of way sidewalk at the drive aisle.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 20. Red Lot 5

SEQ.
#

2003

FEATURE: #5 PARKING STALL

LOCATION: 4 DAS at E side of N building. Near N end.

MEMO: Southern pair.

Notes:

Appears recently constructed. There is no public right of way sidewalk at the drive aisle.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Asphalt patch along entire length of S stall creates slopes up to 8.2%.
B32	Stall & access aisle has no gaps or changes in level and is firm, stable and slip resistant. (ADAS 502.4)	Asphalt patch across entire length of S stall creates depression over 1 1/2" deep.
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 20. Red Lot 5****SEQ.
#****2004****FEATURE: #5 PARKING STALL****LOCATION: 4 DAS at E side of N building. Near N end.****MEMO: Northern pair.****Notes:**

Appears recently constructed. There is no public right of way sidewalk at the drive aisle.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 20. Red Lot 5

SEQ.
#

2005

FEATURE: #5 PARKING STALL

LOCATION: S side of N building.

MEMO: Double DAS, W designated as van.

Notes:

Appears recently constructed. There is no public right of way sidewalk at the drive aisle.


CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 20. Red Lot 5****SEQ.
#****2006****FEATURE: #10 CURB RAMP****LOCATION: Route between double DAS at S side of N building and walkway at N side of S building.****MEMO: Curb ramp at N side of planter.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	Running slope 12.6% to 14.2%.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.7%.
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	Left side 46.3%, right side 25.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 20. Red Lot 5

SEQ.
#

2007

FEATURE: #5 PARKING STALL

LOCATION: S side of S building.



MEMO: Single DAS.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 20. Red Lot 5****SEQ.
#****2008****FEATURE: #5 PARKING STALL****LOCATION: 3 DAS S of entrance at E side of S building.****MEMO: Single van stall.****Notes:**

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 20. Red Lot 5****SEQ.
#****2009****FEATURE: #5 PARKING STALL****LOCATION: 3 DAS S of entrance at E side of S building.****MEMO: Double DAS.****Notes:**

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%). (ADAS 502.4)	Up to 7.8% at N stall.
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.
C42	Accessible route from stall does not pass behind other parked cars. (2013 CBC 11B-502.7.1).	Must pass behind other vehicles en route to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 20. Red Lot 5

SEQ.
#

2010

FEATURE: #5 PARKING STALL

LOCATION: 4 DAS at N side of entrance at E side of S building.

MEMO: Southern pair.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 20. Red Lot 5

**SEQ.
#**

2011


FEATURE: #5 PARKING STALL

LOCATION: 4 DAS at N side of entrance at E side of S building.

MEMO: Northern pair.

Notes:

Appears recently constructed. Conforms to standards used.



Parking Lots Detailed Findings Report with Photographs

Red Parking Lot 7

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

21. Red Lot 7**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
2100	#5 PARKING STALL	3 DAS at W side of S entrance to 5451 building.	Single van stall.
2101	#5 PARKING STALL	3 DAS at W side of S entrance to 5451 building.	Double DAS.
2102	#5 PARKING STALL	2 DAS at E side of S entrance to 5451 building.	Double DAS, W designated van.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 21. Red Lot 7****SEQ.
#****2100****FEATURE: #5 PARKING STALL****LOCATION: 3 DAS at W side of S entrance to 5451 building.****MEMO: Single van stall.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 21. Red Lot 7****SEQ.
#****2101****FEATURE: #5 PARKING STALL****LOCATION: 3 DAS at W side of S entrance to 5451 building.****MEMO: Double DAS.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 21. Red Lot 7****SEQ.
#****2102****FEATURE: #5 PARKING STALL****LOCATION: 2 DAS at E side of S entrance to 5451 building.****MEMO: Double DAS, W designated van.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B41	Stall is located as close as practical to entrance. (ADAS 208.3.1)	Many other standard stalls are closer to routes to the public right of way.



EXHIBIT H

Public Right of Way Detailed Findings Report with Photographs

- Great America Parkway from Old Mountain View-Alviso Road to Mission College Boulevard.
- Tasman Drive from Calabasas Creek to Lafayette Street.
- Mission College Boulevard from Great America Parkway to the driveway separating Mission College Lot B and C.
- Patrick Henry Drive from Bunker Hill Lane to Great America Parkway.
- Democracy Way from Patrick Henry Drive to Old Ironside Drive.
- Old Ironsides Drive from Bunker Hill Lane to Patrick Henry Drive
- Marie DeBartolo Way from Tasman Drive to end.
- Stars and Stripes Drive from Tasman Drive toward the Yellow Lots to end.
- Centennial Boulevard from Stars and Stripes Drive to Tasman Drive.
- Bunker Hill Lane from Patrick Henry Drive to Great America Parkway.



FACILITY ACCESS CONSULTING

7040 Avenida Encinas #104-114, Carlsbad CA 92011

ABBREVIATIONS

AA	Access Aisle		Lav	Lavatory
Abv	Above		LL	Lower Level
ACC	Accessible		Manuv	Maneuvering
Adj	Adjacent		MARR	Multiple Accommodation Restroom
Approx	Appromiately		Max	Maximum
AFF	Above Finish Floor		Min	Minimum
Asph	Asphalt		MMARR	Men's Multiple Accommodation Restroom
BCT	Baby Changing Table		N	North
Blw	Below		NE	Northeast
BOH	Back of House		NW	Northwest
Btm	Bottom		Obst.	Obstructed
Btwn	Between		Ped	Pedestrian
CL	Center Line		Perp.	Perpendicular
Clr.	Clear/Clearance		PROW	Public Right Of Way
Cls.	Clearances		PTD	Paper Towel Dispenser
Conc	Concrete		QSF	Quick Serve Food
CPS	Composite Play Structure		ROT	Route Of Travel
CRASCA	Construction-Related Accessibility Standards Compliance Act (CA Civil Code 55.51-55.545)		RR	Restroom
CR	Curb Ramp		RS	Running Slope
CS	Cross Slope		S.B.	See Below
d	Deep		S	South
DAS	Designated Accessible Parking Stall		SARR	Single Accommodation Restroom
Dr	Door		SCD	Seat Cover Dispenser
DW	Detectable Warning		SD	Soap Dispenser
EAO	Employee Area Only		SE	Southeast
E	East		Spec.	Specifications
Elev	Elevator		SW	Sidewalk
EPC	Elevated Play Component		SW	Southwest
ER	Electrical Receptacle		TC	Toilet Compartment
Ext	Exterior		TD	Truncated Domes
Flr	Floor		TPD	Toilet Paper Dispenser
Furn.	Furniture		UL	Upper Level
FV	Flush Valve		Vert.	Vertical
GB	Grab Bar		W	West
GLPC	Ground Level Play Component		w	wide
h	High		WC	Water Closet
HR	Hand Rail		WMARR	Womens Multiple Accommodation Restoom
Int	Interior		WR	Waste Receptacle

Public Right of Way Detailed Findings Report with Photographs

Great America Parkway from Old Mountain View-Alviso Road to Mission College Boulevard.

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

1. Great America Pky.

Facility Access Compliance Survey Report - Contents:

Seq #	Feature	Location	Memo
1	#10 CURB RAMP	Int. of Old Mountain View.	SW corner diagonal type.
2	#10 CURB RAMP	Into Old Mountain View.	NW corner diagonal type.
3	#9 PARALLEL CURB RAMP	Into Old Mountain View.	NE corner.
4	#9 PARALLEL CURB RAMP	Into Old Mountain View.	SE corner.
5	#11 ACC ROUTE OF TRAVEL	E side of street	Between Old Mountain View and Santa Clara Convention Center entrance drive.
6	#9 PARALLEL CURB RAMP	Int. of Santa Clara Convention Center entrance drive at E side of street.	N side
7	#9 PARALLEL CURB RAMP	Int. of Santa Clara Convention Center entrance drive at E side of street.	S side
8	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Santa Clara Convention Center entrance drive and Bunker Hill Lane.
9	#9 PARALLEL CURB RAMP	Int. of Bunker Hill Lane.	NE corner.
10	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Bunker Hill Lane.	NE corner E crossing button.
11	#10 CURB RAMP	Int. of Bunker Hill Lane.	SE corner diagonal type.
12	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Bunker Hill Lane and Hyatt Regency entrance drive.
13	#10 CURB RAMP	Int. of Hyatt Regency entrance drive at E side of street.	N side perpendicular type.
14	#10 CURB RAMP	Int. of Hyatt Regency entrance drive at E side of street.	S side perpendicular type.
15	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Hyatt Regency entrance Drive and Tasman Drive.
16	#9 PARALLEL CURB RAMP	Int. of Tasman Drive.	NE corner.
17	#11 ACC ROUTE OF TRAVEL	Int. of Tasman Drive.	E crossing of Tasman Drive.
18	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Tasman Drive.	Mid crossing button at E crossing of Tasman Drive.
19	#10 CURB RAMP	Int. of Tasman Drive.	SE corner perpendicular type.
20	#11 ACC ROUTE OF TRAVEL	Int. of Tasman Drive.	Between SE curb ramp and E crossing.
21	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Tasman Drive and Hilton entrance drive.
22	#10 CURB RAMP	Int. of Hilton entrance drive at E side of street.	N side perpendicular type.
23	#10 CURB RAMP	Int. of Hilton entrance drive at E side of street.	S side perpendicular type.
24	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Hilton entrance drive and Stadium Parking entrance drive.
25	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Stadium Parking entrance drive and Old Glory Ln.
26	#10 CURB RAMP	Int. of Old Glory Lane.	NE corner diagonal type.
27	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Old Glory Lane.	NE corner at E crossing.
28	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Old Glory Lane.	NE corner at N crossing.
29	#10 CURB RAMP	Int. of Old Glory Lane.	SE corner perpendicular type.
30	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Old Glory Lane.	SE corner at E crossing.
31	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Old Glory Lane and Great America Drive entrance.
32	#10 CURB RAMP	Int. of Great America entrance drive at E side of street.	E side of drive.
33	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Great America entrance drive and entrance drive to address 4555.

Facility Access Consulting, Inc.

1. Great America Pky.

Facility Access Compliance Survey Report - Contents:

Seq #	Feature	Location	Memo
34	#11 ACC ROUTE OF TRAVEL	E side of street.	Between drive aisle at address 4555 and Patrick Henry Drive.
35	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	NE corner.
36	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	SE corner.
37	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Patrick Henry Drive and entrance Drive to address 4551.
38	#11.1 HAZARDS	E side of street.	Between Patrick Henry Drive and entrance Drive to address 4551.
39	#9 PARALLEL CURB RAMP	Int. of Drive aisle to address 4551 at E side of street.	S side.
40	#9 PARALLEL CURB RAMP	Int. of drive aisle to address 4551 at E side of street.	S side.
41	#11 ACC ROUTE OF TRAVEL	E side of street.	Between drive aisle to address 4551 and drive aisle to address 4401.
42	#10 CURB RAMP	Int. of drive aisle to address 4401 at E side of street.	N side perpendicular type.
43	#10 CURB RAMP	Int. of drive aisle to address 4401 at E side of street.	S side perpendicular type.
44	#11 ACC ROUTE OF TRAVEL	E side of street.	Between Drive aisle to address 4401 and Mission College Blvd.
45	#10 CURB RAMP	Int. of Mission College Blvd.	NE corner perpendicular type.
46	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Mission College Blvd.	NE corner at turn pocket island serving E crossing.
47	#11 ACC ROUTE OF TRAVEL	Int. of Mission College Blvd.	E crossing of Mission College Blvd.
48	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Mission College Blvd.	Mid crossing button at E crossing of Mission College Blvd.
49	#10 CURB RAMP	Int. of Mission College Blvd.	SE corner turn pocket island serving E crossing of Mission College Blvd.
50	#10 CURB RAMP	Int. of Mission College Blvd.	SE corner turn pocket island serving crossing to SE corner of Great America Pky.
51	#10 CURB RAMP	Int. of Mission College Blvd.	SE corner turn pocket serving crossing to turn pocket island
52	#10 CURB RAMP	Int. of Mission College Blvd.	SW corner serving crossing of turn pocket.
53	#10 CURB RAMP	Int. of Mission College Blvd.	SW corner turn pocket island serving crossing to SW corner.
54	#10 CURB RAMP	Int. of Mission College Blvd.	SW corner turn pocket island serving W crossing of Mission College Blvd.
55	#11 ACC ROUTE OF TRAVEL	Int. of Mission College Blvd.	W crossing of Mission College Blvd.
56	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Mission College Blvd.	Mid crossing button at W crossing of Mission College Blvd.
57	#10 CURB RAMP	Int. of Mission College Blvd.	NW corner turn pocket island serving W crossing of Mission College Blvd.
58	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Mission College Blvd.	NW corner turn pocket island serving W crossing of Mission College Blvd.
59	#10 CURB RAMP	Int. of Mission College Blvd.	NW corner turn pocket island serving N crossing of Great America Pky.
60	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Mission College Blvd.	NW corner turn pocket island serving N crossing of Great America Pky.
61	#11 ACC ROUTE OF TRAVEL	Int. of Mission College Blvd.	N crossing of Great America Pky.
62	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Mission College Blvd.	Mid crossing button at N crossing of Great America Pky.
63	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Mission College Blvd.	NE corner turn pocket island serving N crossing of Great America Pky.
64	#10 CURB RAMP	Int. of Mission College Blvd.	NW corner perpendicular type.

Facility Access Consulting, Inc.

1. Great America Pky.

Facility Access Compliance Survey Report - Contents:

Seq #	Feature	Location	Memo
65	#11 ACC ROUTE OF TRAVEL	W side of street.	Between Mission College Blvd. and retail entrance Drive to th N.
66	#10 CURB RAMP	Int. of retail drive N of Mission College Blvd. at W side of street.	S side of drive.
67	#11 ACC ROUTE OF TRAVEL	W side of street.	Between retail drive N of Mission College Blvd. and Patrick Henry Drive.
68	#10 CURB RAMP	Int. of Patrick Henry Drive.	SW corner diagonal type.
69	#10 CURB RAMP	Int. of Patrick Henry Drive.	NW corner diagonal type.
70	#11 ACC ROUTE OF TRAVEL	W side of street.	Between Patrick Henry Drive and the lateral walkway to Green Lot #3.
71	#11 ACC ROUTE OF TRAVEL	W side of street.	Between lateral walkway to Green Lot #3 and Old Glory Lane
72	#10 CURB RAMP	Int. of Old Glory Lane.	SW corner perpendicular type serving W crossing.
73	#10 CURB RAMP	Int. of Old Glory Lane.	NW corner perpendicular type serving W crossing.
74	#10 CURB RAMP	Int. of Old Glory Lane.	NW corner perpendicular type serving N crossing.
75	#11 ACC ROUTE OF TRAVEL	Int. of Old Glory Lane.	N crossing of Great America Pky.
76	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Old Glory Lane.	Mid crossing button at N crossing of Great America Pky.
77	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Old Glory Lane and retail drive to address 4980.
78	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between retail entrance at address 4980 and Tasman Drive.
79	#11 ACC ROUTE OF TRAVEL	Int. of Tasman Drive.	S crossing of Great America Pky.
80	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Tasman Drive.	Mid crossing button at S crossing of Great America Pky.
81	#10 CURB RAMP	Int. of Tasman Drive.	SW corner diagonal type.
82	#11 ACC ROUTE OF TRAVEL	Int. of Tasman Drive.	W crossing of Tasman Drive.
83	#10 CURB RAMP	Int. of Tasman Drive.	NW corner diagonal type
84	#11 ACC ROUTE OF TRAVEL	Int. of Tasman Drive.	N crossing of Great America Pky.
85	#11 ACC ROUTE OF TRAVEL	W side of street.	Between Tasman Drive and Bunker Hill Lane.
86	#10 CURB RAMP	Int. of Bunker Hill Lane.	SW corner combination parallel and diagonal type.
87	#9 PARALLEL CURB RAMP	Int. of Bunker Hill Lane.	NW corner serves both W and N crosswalks.
88	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Bunker Hill Lane and southern retail entrance drive S of Old Mountain View Rd.
89	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between southern retail entrance and Old Mountain View Rd.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

1

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Mountain View.

MEMO: SW corner diagonal type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	16.8% at btm. 3", 11.9% at btm. 3" to 8" portion.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 1. Great America Pky.****SEQ.
#****2****FEATURE: #10 CURB RAMP****LOCATION: Into Old Mountain View.****MEMO: NW corner diagonal type.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	11.7% at btm. 2", 8.8% at top 24" portion.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	3/4" high vertical edge at asphalt transition.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	6.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

3

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Into Old Mountain View.

MEMO: NE corner.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C11	Min. 48" x 48" turning space is provided at bottom of curb ramp. (ADAS 403.3)	19.0% for 3" L (approx. 5/8" H difference) 43" from btm. of curb ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

4

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Into Old Mountain View.

MEMO: SE corner.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	16.0% for 2" (approx. 7/8" H difference).



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 1. Great America Pky.****SEQ.
#****5****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: E side of street****MEMO: Between Old Mountain View and Santa Clara Convention Center entrance drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 130' L is 2.5% to 5.0% and 3.2% at sign post.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	10.8% and 12.2% at drive apron sides at S side of bridge.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

6

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Santa Clara Convention Center entrance drive at E side of street.

MEMO: N side

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 405.4)	sand and debris
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1 1/8" high vertical edge



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 1. Great America Pky.****SEQ.
#****7****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of Santa Clara Convention Center entrance drive at E side of street.****MEMO: S side****Notes:**

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B06 406.2)	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS	3/4" high vertical edge



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

8

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between Santa Clara Convention Center entrance drive and Bunker Hill Lane.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 40' L is 2.5% to 4.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

9

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Bunker Hill Lane.

MEMO: NE corner.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	5/8" vertical edge
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.3%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

10

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Bunker Hill Lane.

MEMO: NE corner E crossing button.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	3.8% back side, 4.6% front side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

11

FEATURE: #10 CURB RAMP

LOCATION: Int. of Bunker Hill Lane.

MEMO: SE corner diagonal type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	9.1% across curb face.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	5.8%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

**SEQ.
#**

12


FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between Bunker Hill Lane and Hyatt Regency entrance drive.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

13

FEATURE: #10 CURB RAMP

LOCATION: Int. of Hyatt Regency entrance drive at E side of street.

MEMO: N side perpendicular type.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	18.1% at btm. 2", 13.4% at btm. 2" to 6" portion.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

14

FEATURE: #10 CURB RAMP

LOCATION: Int. of Hyatt Regency entrance drive at E side of street.

MEMO: S side perpendicular type.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	11.8% at btm. 6"



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

15

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between Hyatt Regency entrance Drive and Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	2 3/4" high vertical edge at S end.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	40' L is 2.6% to 3.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

16

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Tasman Drive.

MEMO: NE corner.

Notes:

Appears recently constructed and in repave zone

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

17

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Tasman Drive.

MEMO: E crossing of Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C40	Where pedestrian access routes cross rails: the route surface is flush with the outer edges of rails and the surface between rails is aligned with the top of the rail. (PROWAG R302.7.1)	1/2" to 3/4" elevation difference between route and rails (2 sets of 2 rails = 8 instances).



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

18

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Tasman Drive.

MEMO: Mid crossing button at E crossing of Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	25" reach depth from clear space.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

19

FEATURE: #10 CURB RAMP

LOCATION: Int. of Tasman Drive.

MEMO: SE corner perpendicular type.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	10.7% at btm. 6".
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.6%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

20

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Tasman Drive.

MEMO: Between SE curb ramp and E crossing.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	11.1%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

21

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between Tasman Drive and Hilton entrance drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	3 gaps at utility cover, up to 1 1/2" W.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 10' L is 2.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

**SEQ.
#**

22

FEATURE: #10 CURB RAMP

LOCATION: Int. of Hilton entrance drive at E side of street.

MEMO: N side perpendicular type.

Notes:

Conforms to standards used.



-

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

23

FEATURE: #10 CURB RAMP


LOCATION: Int. of Hilton entrance drive at E side of street.

MEMO: S side perpendicular type.

Notes:


CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	9.9% at btm. 6".



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 1. Great America Pky.****SEQ.
#****24****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: E side of street.****MEMO: Between Hilton entrance drive and Stadium Parking entrance drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B14	1/4" to 1/2" level changes are beveled at max 1:2 (vert:horiz) slope. (ADAS 303.3)	Two 1/2" vertical edges at utility cover.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 20' L is 3.2% to 3.3%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

25

FEATURE: #11 ACC ROUTE OF TRAVEL



LOCATION: E side of street.

MEMO: Between Stadium Parking entrance drive and Old Glory Ln.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Three vertical edges 5/8" to 1 1/4" S of bus stop.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 270' L is 2.7% to 4.2%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

26

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Glory Lane.

MEMO: NE corner diagonal type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	9.5% generally, 15.2% across curb face.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge.
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	11.7% at right side.
B19	DIAGONAL: If curb ramp is located at marked crossing, 48" min. clear space is provided within the markings. (ADAS 406.6)	0" to CW markings (no landing in CW).



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

27

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Old Glory Lane.

MEMO: NE corner at E crossing.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	3.8%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

28

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Old Glory Lane.

MEMO: NE corner at N crossing.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	3.5%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

29

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Glory Lane.

MEMO: SE corner perpendicular type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	5/8" elevation difference in approx. 2" btm. Portion.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

30

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS


LOCATION: Int. of Old Glory Lane.

MEMO: SE corner at E crossing.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	3.4%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

31

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between Old Glory Lane and Great America Drive entrance.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS


COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 40' L is 3.9% to 4.5%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.**SEQ.
#****32****FEATURE: #10 CURB RAMP****LOCATION: Int. of Great America entrance drive at E side of street.****MEMO: E side of drive.****Notes:**

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

33

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.



MEMO: Between Great America entrance drive and entrance drive to address 4555.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 110' L is 2.5% to 4.3%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	2 hills comprising approx. 55' L running slope up to 6.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

34

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between drive aisle at address 4555 and Patrick Henry Drive.

Notes:

Conforms to standards used.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 320' L is 2.5% to 5.1%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

**SEQ.
#**

35

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: NE corner.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

36

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: SE corner.

Notes:

Conforms to standards used.



-

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

37

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between Patrick Henry Drive and entrance Drive to address 4551.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 90' L is 2.6% to 4.8%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Up to 6.9% for approx. 10' L at hill.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

38

FEATURE: #11.1 HAZARDS

LOCATION: E side of street.

MEMO: Between Patrick Henry Drive and entrance Drive to address 4551.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Abrupt changes in level over 4" high are identified either by a curb or guide rail. (28 CFR 35.130(a), ADAS 405.9, CBC 11B-303.5)	Over 4" drop off, approx. 20' L at one side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

39

FEATURE: #9 PARALLEL CURB RAMP



LOCATION: Int. of Drive aisle to address 4551 at E side of street.

MEMO: S side.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope is 1:12 (8.33%) max. (ADAS 405.2)	9.5% at btm. 6".



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

40

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of drive aisle to address 4551 at E side of street.

MEMO: S side.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

41

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between drive aisle to address 4551 and drive aisle to address 4401.

Notes:

Sidewalk with artificial hills. Cross slope in conjunction with running slope.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 60' L is 2.6% to 5.1%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Up to 6.1% at hill.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

42

FEATURE: #10 CURB RAMP

LOCATION: Int. of drive aisle to address 4401 at E side of street.


MEMO: N side perpendicular type.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	12.0%
B04	Cross slope of ramp is 1:48 (2.08%). (ADAS 405.3)	4.6%
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	15.6% left side, 15.9% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

43

FEATURE: #10 CURB RAMP

LOCATION: Int. of drive aisle to address 4401 at E side of street.

MEMO: S side perpendicular type.

Notes:

Conforms to standards used.



-

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

44

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of street.

MEMO: Between Drive aisle to address 4401 and Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 250' L is 2.5% to 8.0%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

45

FEATURE: #10 CURB RAMP

LOCATION: Int. of Mission College Blvd.

MEMO: NE corner perpendicular type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	11.6% w/ 32.2% at btm. 1" and 19.9% at btm. 1" to 6".
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.1%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.9% at right side, 12.3% at left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

46

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Mission College Blvd.

MEMO: NE corner at turn pocket island serving E crossing.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	3.2%
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	Approx. 52" H, 21" from clear space.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

47

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Mission College Blvd.

MEMO: E crossing of Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Obstructed by mid-crossing island to 0" wide.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Sign indicates to push button and wait for walk signal, however, user who cannot step up the curb must wait in traffic lanes.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

48

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Mission College Blvd.

MEMO: Mid crossing button at E crossing of Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	Over 24" from clear space in crossing.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

49

FEATURE: #10 CURB RAMP

LOCATION: Int. of Mission College Blvd.

MEMO: SE corner turn pocket island serving E crossing of Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	8.7% and 14.2% across curb face.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge.
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	18.0% right side, 15.8% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 1. Great America Pky.****SEQ.
#****50****FEATURE: #10 CURB RAMP****LOCATION: Int. of Mission College Blvd.****MEMO: SE corner turn pocket island serving crossing to SE corner of Great America Pky.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	16.4% and 23.2% across curb face.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	3/4" gap at asphalt transition.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge.
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	18.0% right side, 15.8% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

51

FEATURE: #10 CURB RAMP

LOCATION: Int. of Mission College Blvd.

MEMO: SE corner turn pocket serving crossing to turn pocket island

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	12.9%
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.2%
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	17.3% left side, 14.7% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

52

FEATURE: #10 CURB RAMP

LOCATION: Int. of Mission College Blvd.

MEMO: SW corner serving crossing of turn pocket.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	11.6% and 12.6% across curb face.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	3/8" high vertical edge.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	34" L.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.0%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.3% left side, 12.6% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

53

FEATURE: #10 CURB RAMP

LOCATION: Int. of Mission College Blvd.

MEMO: SW corner turn pocket island serving crossing to SW corner.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	15.0% to 17.3%
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	2" W gap at btm. Landing.
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	25.0% left side, 25.9% right side
B21	Islands - each curb ramp has a min. 48" long x 36" wide level landing at the top of the curb ramp, with the 48" length in the direction of the running slope of the curb ramp it serves. (ADAS 406.7)	18" L to adjacent curb ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

54

FEATURE: #10 CURB RAMP

LOCATION: Int. of Mission College Blvd.

MEMO: SW corner turn pocket island serving W crossing of Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	9.8% to 11.0%
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.9%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	29.8% left side, 16.1% right side.
B21	Islands - each curb ramp has a min. 48" long x 36" wide level landing at the top of the curb ramp, with the 48" length in the direction of the running slope of the curb ramp it serves. (ADAS 406.7)	18" to adjacent curb ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

55

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Mission College Blvd.

MEMO: W crossing of Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Obstructed by mid crossing island to 6" W.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Sign indicates to push button and wait for walk signal, however user who cannot step up the curb must wait in traffic lanes.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

56

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Mission College Blvd.

MEMO: Mid crossing button at W crossing of Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	Over 24" from clear space in crossing.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

57

FEATURE: #10 CURB RAMP


LOCATION: Int. of Mission College Blvd.

MEMO: NW corner turn pocket island serving W crossing of Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	13.6% to 14.3%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	17.3% left side, 22.4% right side.
B21	Islands - each curb ramp has a min. 48" long x 36" wide level landing at the top of the curb ramp, with the 48" length in the direction of the running slope of the curb ramp it serves. (ADAS 406.7)	3" to adjacent curb ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

58

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Mission College Blvd.

MEMO: NW corner turn pocket island serving W crossing of Mission College Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	18.9%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

59

FEATURE: #10 CURB RAMP

LOCATION: Int. of Mission College Blvd.

MEMO: NW corner turn pocket island serving N crossing of Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	11.4%
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	5.8% running slope at top landing.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	3/8" high vertical edge.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.0%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	15.1% left side, 15.7% right side.
B21	Islands - each curb ramp has a min. 48" long x 36" wide level landing at the top of the curb ramp, with the 48" length in the direction of the running slope of the curb ramp it serves. (ADAS 406.7)	33" to one adjacent curb ramp, 31" to a second adjacent curb ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

60

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Mission College Blvd.

MEMO: NW corner turn pocket island serving N crossing of Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	21.7%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

61

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Mission College Blvd.

MEMO: N crossing of Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Obstructed by mid crossing island to approx. 12" W.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Sign indicates to push button and wait for walk signal, however user who cannot step up the curb must wait in traffic lanes.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

62

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Mission College Blvd.

MEMO: Mid crossing button at N crossing of Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	Over 24" away from clear space in crossing.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

63

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Mission College Blvd.

MEMO: NE corner turn pocket island serving N crossing of Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	Approx. 52" AFF with reach of 21" over curb from clear space.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

64

FEATURE: #10 CURB RAMP

LOCATION: Int. of Mission College Blvd.

MEMO: NW corner perpendicular type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	19.7% to 20.8%.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	1 3/4" gap at btm. Landing.
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	26.9% left side, 16.0% right side.
B21	Islands - each curb ramp has a min. 48" long x 36" wide level landing at the top of the curb ramp, with the 48" length in the direction of the running slope of the curb ramp it serves. (ADAS 406.7)	3" to one adjacent curb ramp, 33" to a second adjacent curb ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

65

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: W side of street.

MEMO: Between Mission College Blvd. and retail entrance Drive to the N.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 240' L is 2.5% to 4.7%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

66

FEATURE: #10 CURB RAMP

LOCATION: Int. of retail drive N of Mission College Blvd. at W side of street.

MEMO: S side of drive.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

67

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: W side of street.

MEMO: Between retail drive N of Mission College Blvd. and Patrick Henry Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	Up to 2" W gap approx. 45' L.
B13	Gaps/openings are oriented perpendicular to dominant direction of travel. (ADAS 302.3)	Approx. 45' L gap in direction of travel.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 50' L is 2.7% to 3.0%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Approx. 10' L is up to 10.0%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

68

FEATURE: #10 CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: SW corner diagonal type.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	20.0% at btm. 2", 13.1% at btm. 2" to 6" (otherwise 7.4%).
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.3%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

69

FEATURE: #10 CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: NW corner diagonal type.

Notes:

Appears recently constructed.



CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	9.2% at btm. 6".
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.4%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 1. Great America Pky.****SEQ.
#****70****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: W side of street.****MEMO: Between Patrick Henry Drive and the lateral walkway to Green Lot #3.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	Approx. 80' L gap exceeding 1/2" W in direction of travel.
B13	Gaps/openings are oriented perpendicular to dominant direction of travel. (ADAS 302.3)	Approx. 80' L gap exceeding 1/2" W in direction of travel.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1" and 1 1/2" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 770' L is 2.5% to 5.7%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

71

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of street.

MEMO: Between lateral walkway to Green Lot #3 and Old Glory Lane.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1 1/2" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Appox. 50' L is 2.7% to 6.0%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

72

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Glory Lane.

MEMO: SW corner perpendicular type serving W crossing.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	15.0%
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.5%
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	14.4% right side, 14.5% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

73

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Glory Lane.


MEMO: NW corner perpendicular type serving W crossing.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

74

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Glory Lane.

MEMO: NW corner perpendicular type serving N crossing.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	6.9%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

75

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Old Glory Lane.

MEMO: N crossing of Great America Pky.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	User who cannot step up the curb must wait in traffic lanes.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

76

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Old Glory Lane.

MEMO: Mid crossing button at N crossing of Great America Pky.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	Over 28" from clear space and approx. 49" AFF.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

77


FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.

MEMO: Between Old Glory Lane and retail drive to address 4980.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

78

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.



MEMO: Between retail entrance at address 4980 and Tasman Drive.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 280' L is 2.7% to 6.1%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

79

FEATURE: #11 ACC ROUTE OF TRAVEL



LOCATION: Int. of Tasman Drive.

MEMO: S crossing of Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Sign indicates to push button and wait for walk signal, however, user who cannot step up the curb must wait in traffic lanes.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

80

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Tasman Drive.



MEMO: Mid crossing button at S crossing of Great America Pky.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	27" away from clear space.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

81

FEATURE: #10 CURB RAMP

LOCATION: Int. of Tasman Drive.

MEMO: SW corner diagonal type.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.5%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

82

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Tasman Drive.


MEMO: W crossing of Tasman Drive.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C40	Where pedestrian access routes cross rails: the route surface is flush with the outer edges of rails and the surface between rails is aligned with the top of the rail. (PROWAG R302.7.1)	Up to 1" H mounds at all 4 rails.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

83

FEATURE: #10 CURB RAMP

LOCATION: Int. of Tasman Drive.

MEMO: NW corner diagonal type

Notes:

Conforms to standards used



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

84

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Tasman Drive.

MEMO: N crossing of Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	User who cannot step up the curb must wait in traffic lanes.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

85

FEATURE: #11 ACC ROUTE OF TRAVEL




LOCATION: W side of street.

MEMO: Between Tasman Drive and Bunker Hill Lane.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 80' L is 2.7% to 4.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

86

FEATURE: #10 CURB RAMP

LOCATION: Int. of Bunker Hill Lane.

MEMO: SW corner combination parallel and diagonal type.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	16.4% Across curb face.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

87

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Bunker Hill Lane.

MEMO: NW corner serves both W and N crosswalks.

Notes:

Appears recently constructed and in repave zone. Counter slope at btm. creates 23.6% "V".


CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	13.1% gutter meets opposite slope of 10.5% for combined slope of 23.6%.
C11	Min. 48" x 48" turning space is provided at bottom of curb ramp. (ADAS 403.3)	10.5% Across curb face.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 1. Great America Pky.****SEQ.
#****88****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: W side of the street.****MEMO: Between Bunker Hill Lane and southern retail entrance drive S of Old Mountain View Rd.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	2" gap at transition to bridge and 1" gap at raised crack.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1 1/2" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 40' L is 2.6% to 3.6% and 7.5% to 8.3% at 2 driveway aprons at each side of the bridge.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	14.8% and 27.0% at 2 driveway aprons at each side of bridge.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 1. Great America Pky.

SEQ.
#

89

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: W side of the street.

MEMO: Between southern retail entrance and Old Mountain View Rd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4" and 7/8" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 240' L is 2.6% to 7.5%.



Public Right of Way Detailed Findings Report with Photographs

Tasman Drive from Calabasas Creek to Lafayette Street.

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

2. Tasman Dr.

Facility Access Compliance Survey Report - Contents:

Seq #	Feature	Location	Memo
201	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	NE corner serving N crossing of Patrick Henry drive.
202	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	NW corner serving N crossing of Patrick Henry Drive.
203	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	NW corner serving W crossing of Tasman Drive.
204	#11 ACC ROUTE OF TRAVEL	N side of the street.	Between Patrick Henry Drive and Calabasas Creek Trail
205	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between Calabasas Creek Trail and lateral walkway to Blue Lot #3.
206	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between lateral walkway to Blue Lot #3 and Patrick Henry Drive.
207	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	SW corner serving W crossing of Tasman Drive.
208	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	SW corner serving S crossing of Patrick Henry Drive.
209	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	SE corner serving S crossing of Patrick Henry Drive.
210	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	SE corner serving E crossing of Patrick Henry Drive.
211	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between Patrick Henry drive and Old Ironsides Drive.
212	#9 PARALLEL CURB RAMP	Int. of Old Ironsides Drive.	SW corner serving W crossing of Old Ironsides Drive.
213	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Old Ironsides Drive.	SW corner serving W crossing of Old Ironsides Drive.
214	#9 PARALLEL CURB RAMP	Int. of Old Ironsides Drive.	SW corner serving S crossing of Tasman Drive.
215	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Old Ironsides Drive.	SW corner serving S crossing of Tasman Drive.
216	#11 ACC ROUTE OF TRAVEL	Int. of Old Ironsides Drive.	SE corner diagonal type
217	#11 ACC ROUTE OF TRAVEL	Int. of Old Ironsides Drive.	S crossing of Tasman Drive.
218	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Old Ironsides Drive.	SE corner serving S crossing of Tasman Drive.
219	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between Old Ironsides Drive and Citrix Drive entrance and access to 2T Premium Green Lot #2.
220	#11 ACC ROUTE OF TRAVEL	S side of the street.	From Citrix Drive entrance and access to 2T Premium Green Lot #2 and Great America Pky.
221	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between Great America Pky. and Convention Center.
222	#9 PARALLEL CURB RAMP	Int. of Convention Center.	SW corner serving as diagonal ramp.
223	#9 PARALLEL CURB RAMP	Int. of Convention Center.	SE corner serving as diagonal ramp.
224	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Convention Center.	SE corner serving E crossing of Tasman Drive.
225	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between Convention Center and Stadium entrance.
226	#10 CURB RAMP	Int. of M.P. Bartolo Wy.	SW corner serving W crossing of Tasman Drive.
227	#10 CURB RAMP	Int. of M.P. Bartolo Wy.	SW corner serving S crossing of M.P. Bartolo Wy.
228	#11 ACC ROUTE OF TRAVEL	Int. of M.P. Bartolo Wy.	S crossing of Tasman Drive.
229	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between M.P. Bartolo Wy. And stair to Metro rail at E.
230	#10 CURB RAMP	Int. of Centennial Blvd.	NE corner serving N crossing of Centennial Blvd.
231	#10 CURB RAMP	Int. of Centennial Blvd.	NW corner diagonal type.
232	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Centennial Blvd.	NW corner serving N crossing of Centennial Blvd.
233	#54 REACH RANGE & OPERATING MECHANISMS	Int. of Centennial Blvd.	NW corner serving W crossing of Tasman Drive.
234	#11 ACC ROUTE OF TRAVEL	N side of the street.	Between Centennial Blvd. and Santa Clara Convention Center entrance Drive.
235	#10 CURB RAMP	Int. of Santa Clara Convention Center entrance drive at N side of street.	E side perpendicular type.

Facility Access Consulting, Inc.

2. Tasman Dr.**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
236	#10 CURB RAMP	Int. of Santa Clara Convention Center entrance drive at N side of street.	W side perpendicular type.
237	#11 ACC ROUTE OF TRAVEL	N side of the street.	Between Santa Clara Convention Center entrance drive and Convention Center.
238	#10 CURB RAMP	Int. of Convention Center.	NE corner diagonal type.
239	#10 CURB RAMP	Int. of Convention Center.	NW corner diagonal type
240	#11 ACC ROUTE OF TRAVEL	N side of the street.	Between Convention Center and Great America Pky.
241	#11 ACC ROUTE OF TRAVEL	N side of the street.	Between Great America Pky. And Old Ironsides Drive.
242	#10 CURB RAMP	Int. of Old Ironsides Drive.	NE corner diagonal type.
243	#9 PARALLEL CURB RAMP	Int. of Old Ironsides Drive.	NW corner serving N crossing of Old Ironsides Drive.
244	#9 PARALLEL CURB RAMP	Int. of Old Ironsides Drive.	NW corner serving W crossing of Tasman Drive.
245	#11.1 HAZARDS	N side of the street.	Between Old Ironsides Drive and Patrick Henry Drive.
246	#9 PARALLEL CURB RAMP	Int. of Patrick Henry Drive.	NE corner serving E crossing of Tasman Drive.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.**SEQ.
#****201****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of Patrick Henry Drive.****MEMO: NE corner serving N crossing of Patrick Henry drive.****Notes:**

Appears recently constructed and in repave zone.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

202

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: NW corner serving N crossing of Patrick Henry Drive.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B06 406.2)	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS	1/2" high vertical edge.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

**SEQ.
#**

203

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: NW corner serving W crossing of Tasman Drive.

Notes:

Appears recently constructed and in repave zone. Conforms to standards used



-

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

204

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: N side of the street.


MEMO: Between Patrick Henry Drive and Calabasas Creek Trail

Notes:

Sidewalk dead ends near Calabasas Creek with no curb access. This is an approx. 740' long accessible route dead end from Patrick Henry.


CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Sidewalk ends near Calabasas Creek trail.
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	1 3/4" W at expansion joint
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Up to 4.9% at driveway aprons.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	9.6% and 11.5% at 2 driveway aprons.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****205****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: Between Calabasas Creek Trail and lateral walkway to Blue Lot #3.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 160' L is 2.5% to 4.9% and up to 11.1% at Driveway apron.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	14.7% and 14.6% at drive aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****206****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: Between lateral walkway to Blue Lot #3 and Patrick Henry Drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 30' L is 3.2% to 3.7%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

207

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: SW corner serving W crossing of Tasman Drive.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope is 1:48 (2.08%) max. (ADAS 405.3)	3.0% at W side ramp.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	17.7% for 2" L at gutter.
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	3.2% to 3.6%
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.7%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****208****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of Patrick Henry Drive.****MEMO: SW corner serving S crossing of Patrick Henry Drive.****Notes:**

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.0% generally and 25.0% for 1" L.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****209****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of Patrick Henry Drive.****MEMO: SE corner serving S crossing of Patrick Henry Drive.****Notes:**

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B02	The width of curb ramp is 36" min. (ADAS 405.5)	Partially obstructed by landscaping.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	2.5% to 3.2%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

210

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: SE corner serving E crossing of Patrick Henry Drive.

Notes:

Appears recently constructed and in repave zone.



CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.6% for 2" L.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****211****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: Between Patrick Henry drive and Old Ironsides Drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Landscape reduces width to 33" W at light post and 34" W near Ironsides drive.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 220' L is 2.6% to 4.5% and 5 drive aisles causing slopes from 4.5% to 10.8%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	5 drive aisles causing slopes in 10 sections from 12.2% to 19.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

212

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Old Ironsides Drive.

MEMO: SW corner serving W crossing of Old Ironsides Drive.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope is 1:48 (2.08%) max. (ADAS 405.3)	3.4% at W side ramp.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	3/8" high vertical edge.
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	Up to 3.3%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

213

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Old Ironsides Drive.

MEMO: SW corner serving W crossing of Old Ironsides Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	3.3% at cross walk button.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****214****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of Old Ironsides Drive.****MEMO: SW corner serving S crossing of Tasman Drive.****Notes:**

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 405.4)	1 1/8" high vertical edge at asphalt transition.
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	3.1%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

215

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Old Ironsides Drive.

MEMO: SW corner serving S crossing of Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	3.3% at cross walk button.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

216

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Old Ironsides Drive.

MEMO: SE corner diagonal type

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B14	1/4" to 1/2" level changes are beveled at max 1:2 (vert:horiz) slope. (ADAS 303.3)	7.0%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

217

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Old Ironsides Drive.


MEMO: S crossing of Tasman Drive.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	2" openings at grate near SE corner.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

218

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Old Ironsides Drive.

MEMO: SE corner serving S crossing of Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	13.1% at cross walk button.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

219

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between Old Ironsides Drive and Citrix Drive entrance and access to 2T Premium Green Lot #2.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 100' L is 2.6% to 5.1%.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****220****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: From Citrix Drive entrance and access to 2T Premium Green Lot #2 and Great America Pky.****Notes:**

Appears recently constructed.


CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 100' L is 2.7% to 4.1%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****221****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: Between Great America Pky. and Convention Center.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 340' L is 2.5% to 5.0% and 6.9% across Hilton drive aisle.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	15.2% and 21.4% at Hilton drive aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

**SEQ.
#**

222

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Convention Center.

MEMO: SW corner serving as diagonal ramp.

Notes:

Appears recently constructed and in repave zone.. Conforms to standards used



-

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****223****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of Convention Center.****MEMO: SE corner serving as diagonal ramp.****Notes:**

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B02	The width of curb ramp is 36" min. (ADAS 405.5)	Obstructed by traffic cones.
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	2.4% to 3.0% and 4.9% across curb face.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.7%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

224

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Convention Center.

MEMO: SE corner serving E crossing of Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	4.1% at cross walk button.
B41	Side reach over an obstruction greater than 10"d is max 46" AFF where the obstruction is max 34"AFF, and reach depth is no more than 24". (ADAS 308.3.2)	25" reach over curb to cross walk button.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****225****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: Between Convention Center and Stadium entrance.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 120' L is 2.8% to 3.5% and 2.7% across drive aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****226****FEATURE: #10 CURB RAMP****LOCATION: Int. of M.P. Bartolo Wy.****MEMO: SW corner serving W crossing of Tasman Drive.****Notes:**

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B02	The width of curb ramp is 36" min. (ADAS 405.5)	Obstructed by bollard.
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	Up to 8.6%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

227

FEATURE: #10 CURB RAMP

LOCATION: Int. of M.P. Bartolo Wy.

MEMO: SW corner serving S crossing of M.P. Bartolo Wy.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	Up to 9.2%.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.6%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

228

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of M.P. Bartolo Wy.

MEMO: S crossing of Tasman Drive.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	2.8% to 3.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****229****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: Between M.P. Bartolo Wy. And stair to Metro rail at E.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B13	Gaps/openings are oriented perpendicular to dominant direction of travel. (ADAS 302.3)	2" W at bridge.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1" high vertical edge at bridge.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Long unbroken length of excessive running slope generally 4.5% and up to 6.3% at bridge.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****230****FEATURE: #10 CURB RAMP****LOCATION: Int. of Centennial Blvd.****MEMO: NE corner serving N crossing of Centennial Blvd.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	8.3% cross slope at top landing and 1/2" high vertical edge at asphalt transition at btm. Landing.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	2 edges, one at each side of curb line.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	11.2%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

231

FEATURE: #10 CURB RAMP

LOCATION: Int. of Centennial Blvd.

MEMO: NW corner diagonal type.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	7.3% cross slope at top landing.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	11.9%
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	19.8% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

232

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Centennial Blvd.

MEMO: NW corner serving N crossing of Centennial Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	7.1% at cross walk button.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

233

FEATURE: #54 REACH RANGE & OPERATING MECHANISMS

LOCATION: Int. of Centennial Blvd.

MEMO: NW corner serving W crossing of Tasman Drive.

Notes:


CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B11	The clear floor space is without changes in level except for slopes up to 1:48 (2.08%). (ADAS 305.2)	5.4% at cross walk button.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****234****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: N side of the street.****MEMO: Between Centennial Blvd. and Santa Clara Convention Center entrance Drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1" high vertical edge at W side of bridge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	9.8% at drive aisle at W side of bridge.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	7.8% at drive aisle at E side of bridge that appears recently constructed, 11.2% and 26.4% at drive aisle at W side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****235****FEATURE: #10 CURB RAMP****LOCATION: Int. of Santa Clara Convention Center entrance drive at N side of street.****MEMO: E side perpendicular type.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	10.8% to 12.0%
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	1 1/2" gap and 3/4" high vertical edge at asphalt transition at btm. Landing.
B11		None
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	19.6% right side, 15.8% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****236****FEATURE: #10 CURB RAMP****LOCATION: Int. of Santa Clara Convention Center entrance drive at N side of street.****MEMO: W side perpendicular type.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	11.1% to 12.4% and 25.6% at bottom 6".
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	1 1/2" W gap on bottom landing and gap, and 3/4 high vertical edge on ramp (broken concrete).
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	12.5%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	23.9% right side, 11.4% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****237****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: N side of the street.****MEMO: Between Santa Clara Convention Center entrance drive and Convention Center.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

CODE	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	CSC LOW VOLTAGE utility cover is not secured and shifts under load.
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	3" x 3" gap at street light utility cover.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Over 1/2" high vertical edge at unsecured CST LOW VOLTAGE utility cover.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 50 L is 2.7% to 4.6%.





NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****238****FEATURE: #10 CURB RAMP****LOCATION: Int. of Convention Center.****MEMO: NE corner diagonal type.****Notes:**

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	10.8% at btm. 6", generally 10.6% to 11.5%.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	9.1% running slope at top landing and 3/4" high vertical edge at btm. Landing.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.9%
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	18.2% right side, 14.6% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

239

FEATURE: #10 CURB RAMP

LOCATION: Int. of Convention Center.

MEMO: NW corner diagonal type

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	21.2% at btm 6".
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.3%
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	13.1% left side, 15.1% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

240

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: N side of the street.

MEMO: Between Convention Center and Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 300' L is 2.6% to 5.0%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

241

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: N side of the street.

MEMO: Between Great America Pky. And Old Ironsides Drive.

Notes:

Reduces sidewalk to 42" W for approx. 90' L at planters. Conforms to standards used



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

242

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Ironsides Drive.

MEMO: NE corner diagonal type.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	Up to 9.1% and 13.6% at btm. 6".
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.3%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	11.3% right side, 11.1% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

243

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Old Ironsides Drive.

MEMO: NW corner serving N crossing of Old Ironsides Drive.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	2 edges at btm. 3/8" high vertical edge at truncated domes, 3/8" high vertical edge at curb.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 2. Tasman Dr.****SEQ.
#****244****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of Old Ironsides Drive.****MEMO: NW corner serving W crossing of Tasman Drive.****Notes:**

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B06 406.2)	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS	3/8" high vertical edge.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

245

FEATURE: #11.1 HAZARDS

LOCATION: N side of the street.

MEMO: Between Old Ironsides Drive and Patrick Henry Drive.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B11	Abrupt changes in level over 4" high are identified either by a curb or guide rail. (28 CFR 35.130(a), ADAS 405.9, CBC 11B-303.5)	Approx. 6" high drop off at one side for approx. 20' L at new concrete sidewalk.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 2. Tasman Dr.

SEQ.
#

246

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Patrick Henry Drive.

MEMO: NE corner serving E crossing of Tasman Drive.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	7.6% across curb face.



Public Right of Way Detailed Findings Report with Photographs

Mission College Boulevard from Great America Parkway to the driveway separating Mission College Lot B and C.

.

April 4, 2018



FACILITY ACCESS CONSULTING

7040 Avenida Encinas #104-114, Carlsbad CA 92011

3. Mission College Blvd.**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
301	#11 ACC ROUTE OF TRAVEL	S side of the street.	Across the driveway at the W side of Green Lot #5.
302	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between lateral walkways leading to, and located at W and E sides of Green Lot #5.
303	#11 ACC ROUTE OF TRAVEL	S side of the street.	Across the driveway between Green Lots #4 and #5.
304	#10 CURB RAMP	S side of the street.	Perpendicular type serving crossing of Mission College Blvd. at W side of Green Lot #4.
305	#11 ACC ROUTE OF TRAVEL	S side of the street, changing to W side of the street.	Between curb ramp at W side of Green Lot #4 to driveway at S side of Green Lot #4.
306	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between driveway at S side of Green Lot #4 to intersection of (different) Mission College Blvd.
307	#9 PARALLEL CURB RAMP	Int. of (different) Mission College Blvd.	NW corner functioning as diagonal type, serving W and N crossings.
308	#9 PARALLEL CURB RAMP	Int. of (different) Mission College Blvd.	SW corner functioning as diagonal type, serving W and S crossings.
309	#9 PARALLEL CURB RAMP	Int. of (different) Mission College Blvd.	SE corner serving crossing to right turn pocket island.
310	#11 ACC ROUTE OF TRAVEL	S side of (different) Mission College Blvd.	Between Mission College Blvd. and Great America Pky.
311	#11 ACC ROUTE OF TRAVEL	N side of (different) Mission College Blvd.	Between Great America Pky. And Mission College Blvd.
312	#9 PARALLEL CURB RAMP	Int. of (different) Mission College Blvd.	NE corner serving crossing to right turn pocket island.
313	#11 ACC ROUTE OF TRAVEL	E side of the street, changing to N side of the street.	Between (different) Mission College Blvd. and crossing to W side of Green Lot #4.
314	#10 CURB RAMP	N side of the street.	At crossing at W side of Green Lot #4. Perpendicular type.
315	#11 ACC ROUTE OF TRAVEL	N side of the street.	Westward from the crossing to W side of Green Lot #4.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 3. Mission College Blvd.****SEQ.
#****301****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: Across the driveway at the W side of Green Lot #5.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	8.7%
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	16.8% and 10.1%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 3. Mission College Blvd.

SEQ.
#

302

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: S side of the street.

MEMO: Between lateral walkways leading to, and located at W and E sides of Green Lot #5.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 180' L is 2.8% to 3.9%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 3. Mission College Blvd.

SEQ.
#

303

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: S side of the street.

MEMO: Across the driveway between Green Lots #4 and #5.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Exceeds 8.3% at sides of drive apron



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 3. Mission College Blvd.****SEQ.
#****304****FEATURE: #10 CURB RAMP****LOCATION: S side of the street.****MEMO: Perpendicular type serving crossing of Mission College Blvd. at W side of Green Lot #4.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	Up to 9.3%.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	Configuration unnecessarily precludes use of top landing from either side, effectively making this a curb ramp without a top landing.
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	11.0% left side, 15.4% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 3. Mission College Blvd.

SEQ.
#

305

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street, changing to W side of the street.

MEMO: Between curb ramp at W side of Green Lot #4 to driveway at S side of Green Lot #4.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	2 vertical edges, 1" and 1 1/4" H.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 460' L is to 9.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 3. Mission College Blvd.

SEQ.
#

306

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.

MEMO: Between driveway at S side of Green Lot #4 to intersection of (different) Mission College Blvd.

Notes:


CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 80' L is 2.8% to 3.7%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 3. Mission College Blvd.****SEQ.
#****307****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of (different) Mission College Blvd.****MEMO: NW corner functioning as diagonal type, serving W and N crossings.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.7%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 3. Mission College Blvd.

SEQ.
#

308

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of (different) Mission College Blvd.

MEMO: SW corner functioning as diagonal type, serving W and S crossings.

Notes:


CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	Up to 2.7%.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	5.5%
B14	If curb ramp is located at marked crossing, the transition is wholly contained within the markings. (ADAS 406.5)	W crosswalk is approx. 15' away from the curb ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 3. Mission College Blvd.****SEQ.
#****309****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of (different) Mission College Blvd.****MEMO: SE corner serving crossing to right turn pocket island.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 405.4)	1/2" high vertical edge at one side on ramp surface.
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	8.9% for 3" L across curb face.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	11.1%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 3. Mission College Blvd.

SEQ.
#

310

FEATURE: #11 ACC ROUTE OF TRAVEL




LOCATION: S side of (different) Mission College Blvd.

MEMO: Between Mission College Blvd. and Great America Pky.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	Two vertical edges, 1" and 1 1/4" H.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 110' L is 2.7% to 3.7% and 5.9% at drive aisle.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	11.5% and 8.3% at drive aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 3. Mission College Blvd.****SEQ.
#****311****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: N side of (different) Mission College Blvd.****MEMO: Between Great America Pky. And Mission College Blvd.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 200' L is 2.6% to 5.2% and 6.6% to 7.9% across three drive aisles.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	9.6% to 13.4% at each side of three drive aisles (6 places).





NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 3. Mission College Blvd.****SEQ.
#****312****FEATURE: #9 PARALLEL CURB RAMP****LOCATION: Int. of (different) Mission College Blvd.****MEMO: NE corner serving crossing to right turn pocket island.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	10.4%
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.8% and 10.4% across curb face.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 3. Mission College Blvd.****SEQ.
#****313****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: E side of the street, changing to N side of the street.****MEMO: Between (different) Mission College Blvd. and crossing to W side of Green Lot #4.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 470' L is 2.7% to 6.6% and 7.2% across drive aisle.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	8.3% and 10.4% at drive aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 3. Mission College Blvd.

SEQ.
#

314

FEATURE: #10 CURB RAMP

LOCATION: N side of the street.

MEMO: At crossing at W side of Green Lot #4. Perpendicular type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	6.0%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.3% left side, 12.0% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 3. Mission College Blvd.

SEQ.
#

315

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: N side of the street.

MEMO: Westward from the crossing to W side of Green Lot #4.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Sidewalk dead ends into dirt.



Public Right of Way Detailed Findings Report with Photographs

Patrick Henry Drive from Bunker Hill Lane to Great America Parkway.

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

4. Patrick Henry Dr.**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
401	#11 ACC ROUTE OF TRAVEL	N side of the street.	From the dead end of the sidewalk at address 3378 to Old Ironsides Drive.
402	#9 PARALLEL CURB RAMP	Int. of Old Ironsides Drive.	NW corner serving N crossing of Old Ironsides Drive.
403	#11 ACC ROUTE OF TRAVEL	Int. of Old Ironsides Drive.	N crossing of Old Ironsides Drive.
404	#10 CURB RAMP	Int. of Old Ironsides Drive.	NE corner diagonal type.
405	#11 ACC ROUTE OF TRAVEL	N side of the street.	Between Old Ironsides Drive and Great America Pky.
406	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between Great America Pky. And Old Ironsides Drive.
407	#10 CURB RAMP	Int. of Old Ironsides Drive.	SE corner serving E crossing of Patrick Henry Drive.
408	#11 ACC ROUTE OF TRAVEL	S and W side of the street.	Between Old Ironsides Drive and curb ramp leading to S Pedestrian entrance to Blue Lot #1.
409	#10 CURB RAMP	Crossing at S Pedestrian entrance to Blue Lot #1.	W side of the street, perpendicular type.
410	#10 CURB RAMP	Crossing at S Pedestrian entrance to Blue Lot #1.	E side of the street, perpendicular type.
411	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between crossings leading to S and N pedestrian entrances to Blue Lot #1.
412	#10 CURB RAMP	Crossing at N pedestrian entrance to Blue Lot #1.	W side of the street.
413	#11 ACC ROUTE OF TRAVEL	Crossing at N pedestrian entrance to Blue Lot #1.	E side of the street.
414	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between crossing to N pedestrian entrance to Blue Lot #1 and Democracy Wy.
415	#10 CURB RAMP	Int. of Democracy Wy.	SW corner serving S crossing of Patrick Henry Drive.
416	#10 CURB RAMP	Int. of Democracy Wy.	SE corner diagonal type.
417	#11 ACC ROUTE OF TRAVEL	Int. of Democracy Wy.	W side of street between SW and NW curb ramps.
418	#10 CURB RAMP	Int. of Democracy Wy.	NW corner
419	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Democracy Wy. And Tasman Drive.
420	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Tasman Drive and Bunker Hill Lane.
421	#9 PARALLEL CURB RAMP	Int. of Bunker Hill Lane.	SW corner serving S crossing of Patrick Henry Drive.
422	#11 ACC ROUTE OF TRAVEL	Int. of Bunker Hill Lane.	West side of the street - Between curb ramp at SW corner and entrance drive aisle to Red Lot #5.
423	#11 ACC ROUTE OF TRAVEL	Int. of Bunker Hill Lane.	Between drive aisle and pedestrian walkway, both leading to Red Lot #5.
424	#9 PARALLEL CURB RAMP	Int. of Bunker Hill Lane.	SE corner serving S crossing of Patrick Henry Drive.
425	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between Bunker Hill Lane and Tasman Drive.
426	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between Tasman Drive and Democracy Wy.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

401

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: N side of the street.

MEMO: From the dead end of the sidewalk at address 3378 to Old Ironsides Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 20' L is 2.7%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

402

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Old Ironsides Drive.

MEMO: NW corner serving N crossing of Old Ironsides Drive.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	7.6% for 3" L across curb face.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.8%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

403

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Old Ironsides Drive.

MEMO: N crossing of Old Ironsides Drive.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	6.2% for portion between crosswalk and curb ramp at NE corner.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

404

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Ironsides Drive.


MEMO: NE corner diagonal type.

Notes:

In repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	12.5% for 6" across curb face.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.9%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	10.5% right side, 10.9% left side.
B19	DIAGONAL: If curb ramp is located at marked crossing, 48" min. clear space is provided within the markings. (ADAS 406.6)	7" clear to lines.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

405

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: N side of the street.


MEMO: Between Old Ironsides Drive and Great America Pky.

Notes:

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 110' L is 2.7% to 6.3%, and up to 8.2% at driveway apron.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Approx. 100' L is 5.4% to 10.4% and up to 16.1% at driveway apron.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

406

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between Great America Pky. And Old Ironsides Drive.

Notes:

Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 50' L is 2.5% o 3.9% and up to 5.8% at driveway apron.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	13.7% and 18.4% at driveway apron.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

407

FEATURE: #10 CURB RAMP


LOCATION: Int. of Old Ironsides Drive.

MEMO: SE corner serving E crossing of Patrick Henry Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.9% right side, 11.9% left side.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 4. Patrick Henry Dr.****SEQ.
#****408****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S and W side of the street.****MEMO: Between Old Ironsides Drive and curb ramp leading to S Pedestrian entrance to Blue Lot #1.****Notes:**

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	6" wide gap at address 3000 driveway apron.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4" to 1" high vertical edges at 5 places.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 520' L is 2.6% to 10.5%, including 10 drive aprons and 6 hills.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	10.3% to 18.8% at 14 sides of drive aprons, 10.0% to 13.6% at 10 sides of hills.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

409

FEATURE: #10 CURB RAMP

LOCATION: Crossing at S Pedestrian entrance to Blue Lot #1.

MEMO: W side of the street, perpendicular type.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	6.3%
B18	If curb ramp is located at marked crossing, the transition is wholly contained within the markings. (ADAS 406.5)	Approx. half of transition is not within markings.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

410

FEATURE: #10 CURB RAMP

LOCATION: Crossing at S Pedestrian entrance to Blue Lot #1.

MEMO: E side of the street, perpendicular type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	13.4%
B18	If curb ramp is located at marked crossing, the transition is wholly contained within the markings. (ADAS 406.5)	Approx. half of transition is not within markings.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

411

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.




MEMO: Between crossings leading to S and N pedestrian entrances to Blue Lot #1.

Notes:

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 40' L is 3.5% to 5.8% at 1 hill and drive apron.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Approx. 120' L is 6.3% to 10.4% at sides of 3 hills and 1 drive apron.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

412

FEATURE: #10 CURB RAMP

LOCATION: Crossing at N pedestrian entrance to Blue Lot #1.



MEMO: W side of the street.

Notes:

Excessive slope of side flares must be used by pedestrians using sidewalk.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.9%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	16.8% left side, 14.2% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

413

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Crossing at N pedestrian entrance to Blue Lot #1.

MEMO: E side of the street.

Notes:

No curb access at marked crossing.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	6" high vertical edge at curb and 2" high vertical edge at walkway leading to Blue Lot #1.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

414

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.


MEMO: Between crossing to N pedestrian entrance to Blue Lot #1 and Democracy Wy.

Notes:

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	2 3/4" W gap.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 60' L is 3.5% to 9.7%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	5.9% to 15.0% at 6 sides of hills and 1 driveway apron.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

415

FEATURE: #10 CURB RAMP

LOCATION: Int. of Democracy Wy.


MEMO: SW corner serving S crossing of Patrick Henry Drive.

Notes:

Excessive slope of side flares must be used by pedestrians using sidewalk.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	Covered with plant debris.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	8.6%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.0% left side, 15.0% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

416

FEATURE: #10 CURB RAMP

LOCATION: Int. of Democracy Wy.

MEMO: SE corner diagonal type.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	16.8% across curb face and up to 8.8% general slope.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.1%
B19	DIAGONAL: If curb ramp is located at marked crossing, 48" min. clear space is provided within the markings. (ADAS 406.6)	22" clear to markings.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

417

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Democracy Wy.

MEMO: W side of street between SW and NW curb ramps.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	5.7% at driveway apron.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	13.0% and 14.1% at driveway apron.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

418

FEATURE: #10 CURB RAMP

LOCATION: Int. of Democracy Wy.

MEMO: NW corner

Notes:

Excessive slope of side flares must be used by pedestrians using sidewalk.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	12.4% across curb face.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	1 1/2" W gap at asphalt transition at btm. landing and ramp covered by plant debris.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.1%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	15.1% right side, 16.2% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

419

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.



MEMO: Between Democracy Wy. And Tasman Drive.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	33" clear at bus sign post.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4" to 2" high vertical edges at 4 places.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 180' L is 3.6% to 7.0%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	9.0% at hill.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

420

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.

MEMO: Between Tasman Drive and Bunker Hill Lane.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 150' L is 2.8% to 4.3%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

421

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Bunker Hill Lane.


MEMO: SW corner serving S crossing of Patrick Henry Drive.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	3/8" high vertical edge
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	6.2%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

422

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Bunker Hill Lane.

MEMO: West side of the street - Between curb ramp at SW corner and entrance drive aisle to Red Lot #5.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	32 1/2" W at dirt portion.
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Dirt surface for approx. 20' L.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	2 1/2" high vertical edge at end of concrete.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Portion of concrete is 3.2%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

423

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: Int. of Bunker Hill Lane.

MEMO: Between drive aisle and pedestrian walkway, both leading to Red Lot #5.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Obstructed by 2 sign posts utility cover and tree.
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Grass surface.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

424

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Bunker Hill Lane.

MEMO: SE corner serving S crossing of Patrick Henry Drive.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	The width of curb ramp is 36" min. (ADAS 405.5)	Obstructed by traffic cone.
B03	Running slope is 1:12 (8.33%) max. (ADAS 405.2)	8.6% and 1" at btm. is 18.2%.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 405.4)	Partially covered with debris.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	6.8%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

425

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.


MEMO: Between Bunker Hill Lane and Tasman Drive.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 120' L is 2.6% to 3.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 4. Patrick Henry Dr.

SEQ.
#

426

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.


MEMO: Between Tasman Drive and Democracy Wy.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Obstructed by plants.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1 1/4" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 120' L is 2.8% to 8.2%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	5.6% to 10.2% at 5 sides of hills.



Public Right of Way Detailed Findings Report with Photographs

Democracy Way from Patrick Henry Drive to Old Ironside Drive.

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

5. Democracy Wy.**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
501	#11 ACC ROUTE OF TRAVEL	N side of the street.	From Patrick Henry Drive E to end of sidewalk.
502	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between Patrick Henry Drive and W drive entrance leading to Blue Lot #1.
503	#11.1 HAZARDS	S side of the street.	Between Patrick Henry Drive and W drive entrance leading to Blue Lot #1.
504	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between W and E drive entrances leading to Blue Lot #1.
505	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between E drive entrance and pedestrian lateral walkway, both leading to Blue Lot #1.
506	#11 ACC ROUTE OF TRAVEL	S side of the street.	Lateral pedestrian walk to Blue Lot #1.
507	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between lateral pedestrian walk to Blue Lot #1 and Old Ironsides Drive.
508	#9 PARALLEL CURB RAMP	Int. of Old Ironsides Drive.	SW corner serving W crossing of Democracy Wy.
509	#10 CURB RAMP	Int. of Old Ironsides Drive.	NW corner diagonal type.
510	#10 CURB RAMP	Int. of Old Ironsides Drive.	NE corner serving N crossing of Old Ironsides Drive.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 5. Democracy Wy.****SEQ.
#****501****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: N side of the street.****MEMO: From Patrick Henry Drive E to end of sidewalk.****Notes:**

Excessive running slope occurs in conjunction with cross slope. No indication that sidewalk ends from vantage point of curb ramp at W end.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Covered with Pine needles and sidewalk dead ends.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1" and 1 1/2" high vertical edges.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 40' L is 3.5% to 6.1%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Approx. 40' L is 5.3% to 12.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 5. Democracy Wy.

SEQ.
#

502

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between Patrick Henry Drive and W drive entrance leading to Blue Lot #1.

Notes:

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 100' L is 2.6% to 4.7%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Apporx. 60' L is 5.8% to 7.2%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 5. Democracy Wy.

SEQ.
#

503

FEATURE: #11.1 HAZARDS

LOCATION: S side of the street.

MEMO: Between Patrick Henry Drive and W drive entrance leading to Blue Lot #1.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Abrupt changes in level over 4" high are identified either by a curb or guide rail. (28 CFR 35.130(a), ADAS 405.9, CBC 11B-303.5)	Drop off at one side exceeds 4" H near top of hill.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 5. Democracy Wy.

SEQ.
#

504

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between W and E drive entrances leading to Blue Lot #1.

Notes:

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4" to 2" high vertical edges at 8 places.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 220' L is 2.6% to 4.5%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Apporx. 10' L is up to 8.9%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 5. Democracy Wy.

SEQ.
#

505

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.


MEMO: Between E drive entrance and pedestrian lateral walkway, both leading to Blue Lot #1.

Notes:

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1" to 1 1/4" high vertical edges at 4 places.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 200' L is 2.6% to 6.8%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Up to 7.8% at 2 hills and approx. 20' L is 7.8% to 10.3%.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 5. Democracy Wy.****SEQ.
#****506****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: S side of the street.****MEMO: Lateral pedestrian walk to Blue Lot #1.****Notes:**

Accessible parking nearby.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Entire length is 5.7% to 11.2%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 5. Democracy Wy.

SEQ.
#

507

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: S side of the street.

MEMO: Between lateral pedestrian walk to Blue Lot #1 and Old Ironsides Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Apporx. 10' L is 2.9%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 5. Democracy Wy.

SEQ.
#

508

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Old Ironsides Drive.

MEMO: SW corner serving W crossing of Democracy Wy.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	9.2% across curb face.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.2%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 5. Democracy Wy.

SEQ.
#

509

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Ironsides Drive.

MEMO: NW corner diagonal type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	14.7% across curb face.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.4%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.2% right side, 12.0% left side.
B19	DIAGONAL: If curb ramp is located at marked crossing, 48" min. clear space is provided within the markings. (ADAS 406.6)	35" clear within markings.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 5. Democracy Wy.

SEQ.
#

510

FEATURE: #10 CURB RAMP


LOCATION: Int. of Old Ironsides Drive.

MEMO: NE corner serving N crossing of Old Ironsides Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	16.8% across curb face.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	3.5% cross slope at top landing.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	24" L.
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.9%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.6% left side, 13.7% right side.



Public Right of Way Detailed Findings Report with Photographs

Old Ironsides Drive from Bunker Hill Lane to Patrick Henry Drive

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

6. Old Ironsides Dr.

Facility Access Compliance Survey Report - Contents:

Seq #	Feature	Location	Memo
601	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Democracy Wy. And Tasman Drive.
602	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Tasman Drive and Bunker Hill Lane.
603	#9 PARALLEL CURB RAMP	Int. of Bunker Hill Lane.	SW corner serving S crossing of Old Ironsides Drive.
604	#11 ACC ROUTE OF TRAVEL	Int. of Bunker Hill Lane.	SE corner across from curb ramp at SW corner.
605	#9 PARALLEL CURB RAMP	Int. of Bunker Hill Lane.	SW corner serving W crossing of Bunker Hill Drive.
606	#11 ACC ROUTE OF TRAVEL	Int. of Bunker Hill Lane.	NW corner across from curb ramp at SW corner.
607	#11 ACC ROUTE OF TRAVEL	E side of the street.	From dead end at bus stop to Tasman Drive.
608	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between Tasman Drive and Democracy Wy. NE corner.
609	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between Democracy Wy. NE corner and N drive aisle to Green Lot #2.
610	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between N and S drive aisles to Green Lot #2.
611	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between S drive aisle to Green Lot #2 and Old Glory Lane.
612	#9 PARALLEL CURB RAMP	Int. of Old Glory Lane.	NE corner acting as diagonal type.
613	#10 CURB RAMP	Int. of Old Glory Lane.	SE corner diagonal type.
614	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between Old Glory Lane and N drive aisle to Green Lot #3.
615	#11.1 HAZARDS	E side of the street.	Between Old Glory Lane and N drive aisle to Green Lot #3.
616	#10 CURB RAMP	E side of the street.	N side of N drive aisle to Green Lot #3.
617	#10 CURB RAMP	E side of the street.	S side of N drive aisle to Green Lot #3.
618	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between N and middle drive aisles to Green Lot #3.
619	#11.1 HAZARDS	E side of the street.	Between N and middle drive aisles to Green Lot #3.
620	#10 CURB RAMP	E side of the street.	N side of middle drive aisle to Green Lot #3.
621	#10 CURB RAMP	E side of the street.	S side of middle drive aisle to Green Lot #3.
622	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between middle and S drive aisles to Green Lot #3.
623	#11.1 HAZARDS	E side of the street.	Between middle and S drive aisles to Green Lot #3.
624	#11 ACC ROUTE OF TRAVEL	E side of the street.	Across S drive aisle leading to Green Lot #3.
625	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between S drive aisle leading to Green Lot #3 and Patrick Henry Drive.
626	#11.1 HAZARDS	E side of the street.	Between S drive aisle leading to Green Lot #3 and Patrick Henry Drive.
627	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Patrick Henry Drive and sidewalk dead end to the N.
628	#9 PARALLEL CURB RAMP	Int. of Old Glory Lane.	SW corner serving S crossing of Old Ironsides Drive.
629	#11 ACC ROUTE OF TRAVEL	Int. of Old Glory Lane.	Between SW and NW curb ramps at W side of street.
630	#9 PARALLEL CURB RAMP	Int. of Old Glory Lane.	NW corner serving N crossing of Old Ironsides Drive.
631	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Old Glory Lane and S central drive aisle to Green Lot #3.
632	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between S central and N central drive aisles to Green Lot #3.
633	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between N central drive aisle and S pedestrian walkway, both leading to Green Lot #3.
634	#11 ACC ROUTE OF TRAVEL	W side of the street.	S pedestrian walkway to Green Lot #3.
635	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between N and S pedestrian walkways that lead to Green Lot #3, including N drive aisle leading to Lot.
636	#11 ACC ROUTE OF TRAVEL	W side of the street.	N pedestrian walkway to Green Lot #3.
637	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between N pedestrian walkway leading to Green Lot #3 and Democracy Wy.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****601****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: W side of the street.****MEMO: Between Democracy Wy. And Tasman Drive.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	7.6% for approx. 20' L at driveway apron.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	20.8% and 25.6% at sides of driveway apron.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****602****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: W side of the street.****MEMO: Between Tasman Drive and Bunker Hill Lane.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 70' L is 2.8% to 3.9%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

603

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Bunker Hill Lane.

MEMO: SW corner serving S crossing of Old Ironsides Drive.

Notes:

Appears recently constructed. There is no sidewalk or curb access at SE corner.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	6.8%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****604****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: Int. of Bunker Hill Lane.****MEMO: SE corner across from curb ramp at SW corner.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	No sidewalk.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	No curb access.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

605

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Bunker Hill Lane.


MEMO: SW corner serving W crossing of Bunker Hill Drive.

Notes:

Appears recently constructed. There is no curb ramp at NW corner.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.4%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

606

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Bunker Hill Lane.

MEMO: NW corner across from curb ramp at SW corner.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	No curb ramp.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

607

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.

MEMO: From dead end at bus stop to Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 10' L is up to 4.7% near Tasman Drive.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

608

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.

MEMO: Between Tasman Drive and Democracy Wy. NE corner.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 120' L is 2.7% to 4.4%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

609

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.

MEMO: Between Democracy Wy. NE corner and N drive aisle to Green Lot #2.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	7.5% at one side of hill.




NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****610****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: E side of the street.****MEMO: Between N and S drive aisles to Green Lot #2.****Notes:**

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	1" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 260' L is 3.1% to 5.6%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	6.0% at one side of hill.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

**SEQ.
#**

611

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.

MEMO: Between S drive aisle to Green Lot #2 and Old Glory Lane.

Notes:

Conforms to standards used.

-

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

612

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Old Glory Lane.

MEMO: NE corner acting as diagonal type.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	9.6% across curb face.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.7%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

613

FEATURE: #10 CURB RAMP

LOCATION: Int. of Old Glory Lane.

MEMO: SE corner diagonal type.

Notes:

Excessive side flare slopes must be used by pedestrians using sidewalk.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	14.3% for 3" L at btm.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.4%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.6% left side, 13.8% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

614

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.


MEMO: Between Old Glory Lane and N drive aisle to Green Lot #3.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 50' L is 2.7% to 6.8%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	9.1% and 17.7% at 2 sides of hills.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

615

FEATURE: #11.1 HAZARDS

LOCATION: E side of the street.

MEMO: Between Old Glory Lane and N drive aisle to Green Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Abrupt changes in level over 4" high are identified either by a curb or guide rail. (28 CFR 35.130(a), ADAS 405.9, CBC 11B-303.5)	Approx. 10' L has 9" high drop off at one side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****616****FEATURE: #10 CURB RAMP****LOCATION: E side of the street.****MEMO: N side of N drive aisle to Green Lot #3.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	10.3%
B04	Cross slope of ramp is 1:48 (2.08%). (ADAS 405.3)	3.7%
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	1/2" high vertical edge and 2" W gap.
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	None provided and up to 3" H drop off.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

617

FEATURE: #10 CURB RAMP

LOCATION: E side of the street.

MEMO: S side of N drive aisle to Green Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	10.4%
B04	Cross slope of ramp is 1:48 (2.08%). (ADAS 405.3)	3.6%
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	3/4 high vertical edge and 1" W gap.
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	None provided and up to 4" drop off.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

618

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.

MEMO: Between N and middle drive aisles to Green Lot #3.

Notes:

Sidewalk with artificial hills. Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 160' L is 2.7% to 4.8%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	8.8% at side of one hill.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

619

FEATURE: #11.1 HAZARDS

LOCATION: E side of the street.

MEMO: Between N and middle drive aisles to Green Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Abrupt changes in level over 4" high are identified either by a curb or guide rail. (28 CFR 35.130(a), ADAS 405.9, CBC 11B-303.5)	6" drop off along portion of one side approx. 20' L.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****620****FEATURE: #10 CURB RAMP****LOCATION: E side of the street.****MEMO: N side of middle drive aisle to Green Lot #3.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B04	Cross slope of ramp is 1:48 (2.08%). (ADAS 405.3)	6.4%
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	6.1% running slope at top landing, 8.6% cross slope at btm. landing.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	3/4" high vertical edge and 1" W gap.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

621

FEATURE: #10 CURB RAMP

LOCATION: E side of the street.

MEMO: S side of middle drive aisle to Green Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	12.3%
B04	Cross slope of ramp is 1:48 (2.08%). (ADAS 405.3)	4.0%
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	12.2% running slope at top landing, 6.9% cross slope at btm. landing.
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	3/4" high vertical edge and 2" W gap.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

622

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.


MEMO: Between middle and S drive aisles to Green Lot #3.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	3/4" W gaps at 2 places.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	2" high vertical edge
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 200' L is 2.9% to 5.4%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	11.1% at side of one hill.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

623

FEATURE: #11.1 HAZARDS

LOCATION: E side of the street.

MEMO: Between middle and S drive aisles to Green Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Abrupt changes in level over 4" high are identified either by a curb or guide rail. (28 CFR 35.130(a), ADAS 405.9, CBC 11B-303.5)	Approx. 30' L drops off up to 9" high at one side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****624****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: E side of the street.****MEMO: Across S drive aisle leading to Green Lot #3.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	7.2%
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Up to 14.5%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

625

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.


MEMO: Between S drive aisle leading to Green Lot #3 and Patrick Henry Drive.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 220' L is 2.7% to 6.5%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	7.9% and 7.1% at 2 sides of hills.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

626

FEATURE: #11.1 HAZARDS

LOCATION: E side of the street.

MEMO: Between S drive aisle leading to Green Lot #3 and Patrick Henry Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Abrupt changes in level over 4" high are identified either by a curb or guide rail. (28 CFR 35.130(a), ADAS 405.9, CBC 11B-303.5)	Drop off along one side exceeds 4" H for approx. 40' L.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

627

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.

MEMO: Between Patrick Henry Drive and sidewalk dead end to the N.

Notes:

Route not surveyed for other barriers.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Approximate 700' long dead end with no indication at intersection of Patrick Henry Drive that the route is not accessible.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

628

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Old Glory Lane.

MEMO: SW corner serving S crossing of Old Ironsides Drive.

Notes:

Leads to S drive aisle to Blue Lot #1.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B06	Transition to walk, gutter or street is flush and free of abrupt changes. (ADAS 406.2)	3/8" high vertical edge.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	10.3%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

**SEQ.
#**

629

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Old Glory Lane.

MEMO: Between SW and NW curb ramps at W side of street.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

630

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: Int. of Old Glory Lane.

MEMO: NW corner serving N crossing of Old Ironsides Drive.

Notes:

Appears recently constructed. Combined curb and gutter slope is 24.5%.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
C12	Turning space at bottom of curb ramp slopes 1:48 (2.08%) max. in any direction (ADAS 403.3)	10.7% across curb face.
B13	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	13.8%



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****631****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: W side of the street.****MEMO: Between Old Glory Lane and S central drive aisle to Green Lot #3.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	5' L is 5.3%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

**SEQ.
#**

632

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.

MEMO: Between S central and N central drive aisles to Green Lot #3.

Notes:

Conforms to standards used.



-

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

633

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: W side of the street.

MEMO: Between N central drive aisle and S pedestrian walkway, both leading to Green Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 40' L is 2.7% to 3.5%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 6. Old Ironsides Dr.****SEQ.
#****634****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: W side of the street.****MEMO: S pedestrian walkway to Green Lot #3.****Notes:****CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS**

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Up to 3.7%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Up to 7.4%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

635

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.

MEMO: Between N and S pedestrian walkways that lead to Green Lot #3, including N drive aisle leading to Lot.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

636

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.

MEMO: N pedestrian walkway to Green Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Up to 5.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 6. Old Ironsides Dr.

SEQ.
#

637

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: W side of the street.

MEMO: Between N pedestrian walkway leading to Green Lot #3 and Democracy Wy.

Notes:

Sidewalk with artificial hills.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	5.9% at one side of hill.



Public Right of Way Detailed Findings Report with Photographs

Marie DeBartolo Way from Tasman Drive to end.

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

7. Marie P. Bartolo Wy.

Facility Access Compliance Survey Report - Contents:

Seq #	Feature	Location	Memo
701	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between Tasman Drive and curb ramp at parking lot.
702	#9 PARALLEL CURB RAMP	E side of the street.	At parking lot.
703	#10 CURB RAMP	At stadium gate at S end.	SE corner.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 7. Marie P. Bartolo Wy.

**SEQ.
#**

701

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E side of the street.

MEMO: Between Tasman Drive and curb ramp at parking lot.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 7. Marie P. Bartolo Wy.

**SEQ.
#**

702

FEATURE: #9 PARALLEL CURB RAMP

LOCATION: E side of the street.

MEMO: At parking lot.

Notes:

Conforms to standards used.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 7. Marie P. Bartolo Wy.

SEQ.
#

703

FEATURE: #10 CURB RAMP

LOCATION: At stadium gate at S end.

MEMO: SE corner.

Notes:

Appears recently constructed and in repave zone.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

CODE	CONDITION DESCRIPTION	ACTUAL
B16	Maximum slope of flared sides is 1:10 (10.0%). (ADAS 406.2)	10.8% right side.



Public Right of Way Detailed Findings Report with Photographs

Stars and Stripes Drive from Tasman Drive toward the Yellow Lots to end

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

8. Stars and Stripes Dr.**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
801	#6 VAN PARKING STALL	E side of street near metro station under Tasman Drive overpass.	Double parking stall, right side designated as Van stall.
802	#11 ACC ROUTE OF TRAVEL	E and N sides of the street.	Between Tasman Drive overpass and intersection of Centennial Blvd.
803	#10 CURB RAMP	Int. of Centennial Blvd.	NE curb ramp serving E crossing of Stars and Stripes Drive.
804	#11 ACC ROUTE OF TRAVEL	Int. of Centennial Blvd.	N side of street between NE and NW curb ramps.
805	#10 CURB RAMP	Int. of Centennial Blvd.	NW curb ramp serving W crossing of Stars and Stripes Drive.
806	#10 CURB RAMP	Int. of Centennial Blvd.	SW corner diagonal type.
807	#10 CURB RAMP	Int. of Centennial Blvd.	SE corner diagonal type.
808	#11 ACC ROUTE OF TRAVEL	N side of the street.	Between Centennial Blvd. and the parking structure entrance at W end.
809	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between the parking structure entrance at the W end to W drive entrance to Yellow Lot #2.
810	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between W and E entrance drives to Yellow Lot #2.
811	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between E drive entrance to Yellow Lot #2 and Centennial Blvd.
812	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between Centennial Blvd. and W drive entrance to Yellow Lot #3.
813	#11 ACC ROUTE OF TRAVEL	S side of the street.	Between W and E drive entrances to Yellow Lot #3.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

801

FEATURE: #6 VAN PARKING STALL



LOCATION: E side of street near metro station under Tasman Drive overpass.

MEMO: Double parking stall, right side designated as Van stall.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B31	Slopes do not exceed 1:48 (2.08%)	Up to 3.0% at portions of both spaces and access aisle.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

802

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: E and N sides of the street.




MEMO: Between Tasman Drive overpass and intersection of Centennial Blvd.

Notes:

Excessive cross/running slope occurs in conjunction.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 120' L is 2.7% to 5.6%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	11.1% to 16.7% at 10 sides of driveway aprons.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

803

FEATURE: #10 CURB RAMP

LOCATION: Int. of Centennial Blvd.

MEMO: NE curb ramp serving E crossing of Stars and Stripes Drive.

Notes:

Excessive side flare and running slopes must be used by pedestrians using sidewalk.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	12.2% to 13.3%.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	7.8%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	16.7% right side, 15.3% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

804

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Centennial Blvd.

MEMO: N side of street between NE and NW curb ramps.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 70' L is 3.5% to 4.1%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

805

FEATURE: #10 CURB RAMP

LOCATION: Int. of Centennial Blvd.

MEMO: NW curb ramp serving W crossing of Stars and Stripes Drive.

Notes:

Excessive side flare and running slopes must be used by pedestrians using sidewalk.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	11.5% to 13.0%.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	Debris on btm. Landing.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	11.7% right side, 14.4% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

806

FEATURE: #10 CURB RAMP

LOCATION: Int. of Centennial Blvd.

MEMO: SW corner diagonal type.

Notes:

Excessive side flare and running slopes must be used by pedestrians using sidewalk.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	9.1% to 12.6%.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	1/2" high vertical edges on ramp and btm. Landing.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	18.6% right side, 14.1% left side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

807

FEATURE: #10 CURB RAMP

LOCATION: Int. of Centennial Blvd.

MEMO: SE corner diagonal type.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B03	Running slope of ramp is 1:12 (8.33%) max. (ADAS 405.2)	8.5% to 11.3%.
B05	Surface of ramp and landings complies with requirements for an accessible path of travel (stable, firm, slip-resistant, without gaps over 1/2" wide or edges over 1/4" high). (ADAS 302.1, 403.2, 403.3, 403.4)	1 1/2" high vertical edge at asphalt transition at btm. landing.
B11	Top landing is as wide as the ramp and 36" min. in length. (ADAS 406.4)	None
B14	Counter slopes of adjoining gutters and road surfaces immediately adjacent to and within 24 inches of the curb ramp are not steeper than 1:20 (5.0%). (ADAS 406.2)	9.1%
A17	Where no top landing is provided at an existing ramp, side flare slopes are 8.33% max. (ADAS 406.4)	13.9% left side, 12.5% right side.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

808

FEATURE: #11 ACC ROUTE OF TRAVEL



LOCATION: N side of the street.

MEMO: Between Centennial Blvd. and the parking structure entrance at W end.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	30" car overhang potentially reduces 60" wide sidewalk to 30" clear width at 14 parking spaces.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 300' L is 2.6% to 7.8%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	11.9% to 16.6% at 4 sides of driveway apron.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

809

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between the parking structure entrance at the W end to W drive entrance to Yellow Lot #2.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B11	Surface is firm, stable and slip-resistant. (ADAS 302.1)	Partially covered with gravel at drive entrance.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

810

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between W and E entrance drives to Yellow Lot #2.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	30" car overhang potentially reduces 60" wide sidewalk to 30" clear width at 23 parking spaces.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	10' L is 3.0%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

811

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between E drive entrance to Yellow Lot #2 and Centennial Blvd.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	30" car overhang potentially reduces 60" wide sidewalk to 30" clear width at 13 parking spaces and 33" clear at fire hydrant.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 20' L is 2.6% to 3.1%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

812

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between Centennial Blvd. and W drive entrance to Yellow Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	30" car overhang potentially reduces 60" wide sidewalk to 30" clear width at 4 parking stalls and partially obstructed by plants.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 8. Stars and Stripes Dr.

SEQ.
#

813

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street.

MEMO: Between W and E drive entrances to Yellow Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	30" car overhang potentially reduces 60" wide sidewalk to 30" clear width at 27 parking spaces.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4" high vertical edge at tree.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	3.1% at tree.



Public Right of Way Detailed Findings Report with Photographs

Centennial Boulevard from Stars and Stripes Drive to Tasman Drive

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

9. Centennial Blvd.**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
901	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between Stars and Stripes Drive and the dirt path to Yellow Lot #3.
902	#11 ACC ROUTE OF TRAVEL	E side of the street.	Between dirt path to Yellow Lot #3 and Tasman Drive.
903	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between Stars and Stripes Drive and the pedestrian entrance to Yellow Lot #2.
904	#11 ACC ROUTE OF TRAVEL	W side of the street.	Between pedestrian entrance to Yellow Lot #2 and Tasman Drive.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 9. Centennial Blvd.

SEQ.
#

901

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: E side of the street.

MEMO: Between Stars and Stripes Drive and the dirt path to Yellow Lot #3.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B02	36" min. clear width of exterior walkway. (ADAS 403.5.1)	Obstructed by plants at N end.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	5/8" and 3/4" high vertical edges.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 9. Centennial Blvd.

SEQ.
#

902

FEATURE: #11 ACC ROUTE OF TRAVEL



LOCATION: E side of the street.

MEMO: Between dirt path to Yellow Lot #3 and Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 40' L is 3.0% to 4.4%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 9. Centennial Blvd.

SEQ.
#

903

FEATURE: #11 ACC ROUTE OF TRAVEL


LOCATION: W side of the street.

MEMO: Between Stars and Stripes Drive and the pedestrian entrance to Yellow Lot #2.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	5' L is 3.8%.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 9. Centennial Blvd.

SEQ.
#

904

FEATURE: #11 ACC ROUTE OF TRAVEL



LOCATION: W side of the street.

MEMO: Between pedestrian entrance to Yellow Lot #2 and Tasman Drive.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	5/8" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 110' L is 2.6% to 4.0%.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	Up to 5.8%, generally matching street slope.



Public Right of Way Detailed Findings Report with Photographs

Bunker Hill Lane from Patrick Henry Drive to Great America Parkway

April 4, 2018



FACILITY ACCESS CONSULTING
7040 Avenida Encinas #104-114, Carlsbad CA 92011

12. Bunker hill Ln.**Facility Access Compliance Survey Report - Contents:**

Seq #	Feature	Location	Memo
1201	#11 ACC ROUTE OF TRAVEL	S side of the street	Between Patrick Henry Dr and Old Ironsides Dr.
1202	#11 ACC ROUTE OF TRAVEL	Int. of Old Ironsides Dr.	West crossing.
1203	#11 ACC ROUTE OF TRAVEL	Int. of Old Ironsides Dr.	S and E crossings.
1204	#11 ACC ROUTE OF TRAVEL	North side of the street	Between Old Ironsides Dr. and Great America Pky.

Facility Access Consulting, Inc.

NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 12. Bunker hill Ln.

SEQ.
#

1201

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: S side of the street


MEMO: Between Patrick Henry Dr and Old Ironsides Dr.

Notes:

Appears recently constructed.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	At drive aisle near Patrick Henry Dr. up to 6.2% for approx. 8'.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 12. Bunker hill Ln.

SEQ.
#

1202

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Old Ironsides Dr.

MEMO: West crossing.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	No curb ramp at N side of street.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT

FACILITY/SITE: 12. Bunker hill Ln.

SEQ.
#

1203

FEATURE: #11 ACC ROUTE OF TRAVEL

LOCATION: Int. of Old Ironsides Dr.

MEMO: S and E crossings.

Notes:

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	No curb ramp access at SE corner or N side of the street.



NEVAREZ V 49ERS - ACCESSIBILITY ASSESSMENT**FACILITY/SITE: 12. Bunker hill Ln.****SEQ.
#****1204****FEATURE: #11 ACC ROUTE OF TRAVEL****LOCATION: North side of the street****MEMO: Between Old Ironsides Dr. and Great America Pky.****Notes:**

All except W end appears recently constructed and sidewalk does not continue to the W.

CONDITIONS THAT DO NOT CONFORM TO NEW CONSTRUCTION STANDARDS

COD	CONDITION DESCRIPTION	ACTUAL
B12	Gaps/openings in ground or floor surfaces do not allow the passage of a sphere more than 1/2" in diameter. (ADAS 302.3)	Pothole, 4" wide x 9" L x 1 1/2" deep.
B15	No level changes greater than 1/2" (except by accessible ramp or other means). (ADAS 303.4)	3/4" high vertical edge.
B16	Cross slope (perpendicular to direction of travel) is 1:48 (2.08%) max. (ADAS 403.3)	Approx. 30' L is 2.5% to 3.6% and 7.0% at drive aisle.
B17	Running slope (parallel to direction of travel) is 1:20 (5.0%) max. (ADAS 403.3)	11.3% and 11.3% at drive aisle.







EXHIBIT I



DRAWN BY: K. TRAN
 CHECKED BY: F. AMIN
 APPROVED BY: G. GOMEZ
 DATE: MAY 2015


RESIDENTIAL DRIVEWAY WITH ATTACHED SIDEWALK

CITY OF SANTA CLARA


ST-4

PAGE: 4

SC04584

**NOTES:**

1. W.P. JOINTS REQUIRED ON CENTERLINE FOR DRIVEWAYS 12' TO 20' WIDE. DRIVEWAYS 24' TO 30' WIDE SHALL HAVE 2 W.P. JOINTS EVENLY SPACED (AT 1/3 AND 2/3 POINTS).
2. PLACE SCORE MARKS AT 1/4 POINTS ON DRIVEWAYS 12' TO 20' WIDE AND AT 1/6 POINTS ON DRIVEWAYS 24' TO 30' WIDE.
3. 18" WIDE BAND OF PAVEMENT SHALL BE REMOVED AND REPLACED. SEE NOTE 5 OF GENERAL NOTES (APPENDIX) FOR REQUIREMENTS.
4. DEPRESSED DRIVEWAY, DRIVEWAY APPROACH, GROOVED BORDERS, AND RAMPS SHALL HAVE A THICKNESS OF 5" P.C.C. OVER 4" A.B. GROOVED BORDERS, RAMPS, DEPRESSED DRIVEWAY, DRIVEWAY APPROACH, CURB AND GUTTER SHALL BE MONOLITHIC.
5. IF THE EXISTING ON-SITE IMPROVEMENTS DO NOT MATCH THE GRADE OF THE REAR OF THE NEW DRIVEWAY, SUFFICIENT EXISTING IMPROVEMENTS SHALL BE RECONSTRUCTED TO PRODUCE A SMOOTH, USABLE SURFACE WITH A CHANGE IN GRADE NOT EXCEEDING 10%.



DRAWN BY: K. TRAN
 CHECKED BY: F. AMIN
 APPROVED BY: G. GOMEZ
 DATE: MAY 2015



DEPRESSED DRIVEWAY FOR EX. 5' ATTACHED SIDEWALK

CITY OF SANTA CLARA

ST-6

PAGE: 6

SC04586



SECTION A-A

NO SCALE

NOTES:

1. END REBAR 3" FROM COLD JOINT FOR GUTTER AND 12" FROM COLD JOINT FOR RAMPS.
2. DEPRESSED DRIVEWAY, DRIVEWAY APPROACH, GROOVED BORDERS, AND RAMPS SHALL HAVE A THICKNESS OF 5" P.C.C. OVER 4" A.B. GROOVED BORDERS, RAMPS, DEPRESSED DRIVEWAY, DRIVEWAY APPROACH, CURB AND GUTTER SHALL BE MONOLITHIC.
3. 18" WIDE BAND OF PAVEMENT SHALL BE REMOVED AND REPLACED. SEE NOTE 5 OF GENERAL NOTES (APPENDIX), FOR REQUIREMENTS.
4. JOINT/SCORE MARK: SEE TABLE ON ST-8.
5. USE OF DETAIL ST-7 IS ALLOWED ONLY WITH WRITTEN APPROVAL OF CITY ENGINEER.
6. IF THE EXISTING ON-SITE IMPROVEMENTS DO NOT MATCH THE GRADE OF THE REAR OF THE NEW DRIVEWAY, SUFFICIENT EXISTING IMPROVEMENTS SHALL BE RECONSTRUCTED TO PRODUCE A SMOOTH, USABLE SURFACE WITH A CHANGE IN GRADE NOT EXCEEDING 10%.



DRAWN BY: K. TRAN

CHECKED BY: F. AMIN

APPROVED BY: G. GOMEZ

DATE: MAY 2015

DEPRESSED COMMERCIAL
DRIVEWAY FOR
EX. 5' ATTACHED SIDEWALK

CITY OF SANTA CLARA

ST-7

PAGE: 7

SC04587



-
6. SEE DESIGN CRITERIA FOR MINIMUM RIGHT-OF-WAY RADII.
- 1" 5' MIN. 6" 6" 1" 3/4" 1/2" R 2% 2% 3' 2" (MAX.) 4" 4" 1 1 6" 6" 1 1
- TRUNCATED DOME PANEL
- TOP OF SIDEWALK
- SCORE MARK
- CURB
- FLOW LINE
- LIP DETAIL
- LIP OF GUTTER
- PAVEMENT
- 5 1/4" MIN.*
- 2%
- 2%
- 3'
- 2" (MAX.)
- 4"
- 4"
- 1
- 1
- 6"
- 6"
- 1
- 1
- P.C.C.
- CLASS 2 A.B.
- TRANSVERSE BROOM FINISH SEE NOTE 4
- *TOP OF BACK CURB SHALL BE ADJUSTED HIGHER TO MATCH EXISTING ADJACENT GRADE
- SECTION A-A
- NO SCALE
- LIP DETAIL
- NO SCALE
- 1"
- 1/2"
- 1"
- 1"
- 8.33%
- 2%
- 8.33%
- FLOW LINE
- LIP OF GUTTER
- 1"
- 6' MIN. RAMP
- 5' LANDING
- 6' MIN. RAMP
- 1"
- ELEVATION VIEW
- NO SCALE




CURVED CURB RAMP

ST-14

CITY OF SANTA CLARA

PAGE: 14

SC04590



NOTES:

1. CURB RAMPS SHALL HAVE DETECTABLE WARNING SURFACES (GROOVING AND TRUNCATED DOMES). SEE DETAIL ST-16 FOR GROOVING DETAILS AND TRUNCATED DOME DETAILS.
2. 18" WIDE BAND OF PAVEMENT SHALL BE REMOVED AND REPLACED. SEE NOTE 5 OF GENERAL NOTES (APPENDIX) FOR REQUIREMENTS.
3. CURB RAMPS FOR SEPARATED SIDEWALKS SHALL BE DESIGNED ON AN INDIVIDUAL BASIS.
4. THE SURFACE OF RAMP SHALL HAVE A TRANSVERSE BROOMED SURFACE TEXTURE ROUGHER THAN THE SURROUNDING SIDEWALK.



DRAWN BY: K. TRAN

CHECKED BY: F. AMIN

APPROVED BY: G. GOMEZ

DATE: OCTOBER 2013

STRAIGHT CURB RAMP

CITY OF SANTA CLARA

ST-15

PAGE: 15

SC04591

EXHIBIT J

**FOR PUBLICATION
UNITED STATES COURT OF APPEALS
FOR THE NINTH CIRCUIT**

ROGER A. LONG; RONALD RAY
SMITH; and DISABLED RIGHTS
ACTION COMMITTEE, a Utah
nonprofit corporation,
Plaintiffs-Appellants-
Cross-Appellees.

Nos. 99-16468
99-16497

v.

COAST RESORTS, INC., a Nevada
corporation; COAST HOTELS AND

D.C. No.
CV-97-01570-RLH

CASINOS, INC., a Nevada
corporation; COAST WEST, INC., a
Nevada corporation,
Defendants-Appellees-
Cross-Appellants.

OPINION

Appeal from the United States District Court
for the District of Nevada
Roger L. Hunt, Magistrate Judge, Presiding

Argued and Submitted
November 16, 2000--San Francisco, California

Filed October 3, 2001

Before: Alex Kozinski, Michael Daly Hawkins, and
Marsha S. Berzon, Circuit Judges.

Opinion by Judge Hawkins

14157

14158

14159

14160

COUNSEL

Richard F. Armknecht (argued), III, Salt Lake City, Utah, for the plaintiffs-appellants/cross-appellees.

Barry Lieberman (argued), Las Vegas, Nevada, for the defendants-appellees/cross-appellants.

Thomas E. Chandler (argued), Timothy J. Moran and Jessica Dunsay Silver, Civil Rights Division, Department of Justice, Washington, D.C., for amicus curiae United States of America.

OPINION

HAWKINS, Circuit Judge:

This appeal arises out of a suit brought by two disabled individuals and a non-profit disabled rights advocacy organization against the Orleans Hotel and Casino in Las Vegas, Nevada ("the Orleans"), which is owned and operated by the appellees. The suit, which was disposed of by the magistrate judge through summary judgment, alleged several areas of

non-compliance with the Americans with Disabilities Act ("ADA"). Appellants challenge the adverse summary judgment of several of the allegations of non-compliance, argue that their Nevada state law damages claim should have survived summary judgment, and ask for a recalculation of attorney's fees. The Orleans cross-appeals the one instance of non-compliance found by the magistrate judge and argues that appellants' appeal is not timely.

FACTS AND PROCEDURAL HISTORY

This suit was brought under the ADA's enforcement provision, 42 U.S.C. § 12188(a), which incorporates the remedies and procedures set forth in the Civil Rights Act of 1964.¹ After a visit to the Orleans in the fall of 1997, the plaintiffs brought suit citing several ADA Accessibility Guidelines ("Guidelines")² and alleging five areas of non-compliance: (1) 819 of the 839 hotel rooms had bathroom doorways with a clear opening smaller than the thirty-two inches required by the Guidelines; (2) two of the four slot change kiosks³ in the

¹ The Civil Rights Act of 1964 contains a citizen suit provision at 42 U.S.C. § 2000a-3(a):

Whenever any person has engaged or there are reasonable grounds to believe that any person is about to engage in any act or practice prohibited by section 2000a-2 of this title, a civil action for preventative relief, including an application for permanent or temporary injunction, restraining order, or other order, may be instituted by the person aggrieved

² The Guidelines are created by the United States Department of Justice ("DOJ"). At 42 U.S.C. § 12186(b), Congress directs DOJ to "[issue] regulations . . . that include standards applicable to facilities" covered by the ADA. The implementing regulations were issued on July 26, 1991, and include architectural standards for newly constructed public accommodations and commercial facilities entitled the Standards for Accessible Design, found at 28 C.F.R. Part 36. The Guidelines are specific design standards listed in Appendix A of the Standards for Accessible Design. Id.

³ The slot change kiosks make change for patrons in the slot machine area of the Orleans.

casino did not have accessible service counters; (3) the employee work areas at the four change kiosks were elevated and inaccessible to wheelchairs; (4) two of the three casino bars did not have accessible bar counters or table seating; and (5) three of the nine pool cabanas were not located on a wheelchair accessible route.⁴ The complaint sought declaratory judgment, injunctive relief, and litigation expenses under the ADA and damages under Nevada Revised Statutes § 651.070 ("Nevada ADA"). The parties stipulated to all facts relevant to summary judgment and this appeal.

The Orleans moved for summary judgment and the plaintiffs cross-moved for partial summary judgment. Following a hearing, the magistrate judge entered judgment granting in part and denying in part both motions. On issues relevant to this appeal, the magistrate judge found that: (1) plaintiffs had not shown injury sufficient to continue with their damages claim under the Nevada ADA; (2) while the bathroom door width was a "technical violation" of the Guidelines, there had been "substantial compliance with the spirit of the law" and therefore no injunctive relief was merited; (3) wheelchair users were not denied "full and fair enjoyment " of the facilities merely because three of the nine pool cabanas were inaccessible; (4) the two inaccessible bars in the "pit" area were in violation of the ADA; and (5) the slot change kiosks were not in violation because supervisors were not required to enter the kiosks. We have jurisdiction under 28 U.S.C. § 1291.

ANALYSIS

I. Timeliness of the Appeal

The magistrate judge entered an "order and judgment" on December 31, 1998. An amendment in the form of a separate judgment correcting a few typographical errors was entered

⁴ The complaint contained other alleged violations. These alleged violations were dropped from the case after they were remedied by the Orleans.

January 12, 1999. The Orleans contends that the relevant date of judgment is the former; appellants contend it is the latter. The issue is critical because appellants filed a Motion for Clarification on January 26, which would be timely only under the later date of judgment. Fed. R. App. P. 4(a)(4)(iii - iv) (party has ten days after judgment, excluding legal holidays and weekends, to file a Rule 59 motion and toll the appeals clock).

Federal Rule of Civil Procedure 58 requires that "[e]very judgment shall be set forth on a separate document." Our case law requires a mechanical application of Rule 58 so as to avoid the inequity of a party being denied the opportunity to appeal because of a failure to realize which of several documents or docket entries constituted "entry" of judgment. See Beaudry Motor Co. v. Abko Props., Inc., 780 F.2d 751 (9th Cir. 1986). Thus, we held in Paddack v. Morris, 783 F.2d 844, 846 (9th Cir. 1986), that Rule 58's separate judgment requirement was not satisfied by a district court's seven-page order detailing facts and legal analysis, but instead only by its subsequent filing of a five-line judgment. Here, the "order and judgment" entered on December 31, 1998 was not a final judgment because it did not constitute separate entry of judgment, but rather contained facts and legal analysis. The district court entered its final judgment on January 12, 1999, when it issued a judgment on a separate document. Thus, this appeal was timely filed.

II. Bathroom Door Width

Guideline 9.4 requires that: "Doors and doorways designed to allow passage into and within all sleeping units or other covered units shall comply with [Guideline] 4.13.5." Guideline 4.13.5 requires that such doorways have a minimum opening of thirty-two inches. It is undisputed that the doorway between the sink area (which is open to the bedroom area) and the room containing the toilet and bathtub/shower is only twenty-eight inches wide in the 819 "standard" rooms

at the Orleans. The Orleans puts forward two arguments justifying non-compliance.

A. Applicability of Guideline 9.4

First, the Orleans contends that Guideline 9.4 does not apply to bathroom doors because the bathroom is not part of the "sleeping unit." To support this contention, the Orleans points out that Guideline 9.2, which addresses requirements for accessible units, distinguishes sleeping rooms from bathrooms. The Orleans argues that the explicit inclusion of bathrooms in 9.2 leads to a presumption that the lack of an explicit reference to bathrooms in 9.4 means that Congress intended to exclude bathrooms from 9.4 altogether. The Orleans's construction of Guideline 9.4 fails to comport with the language of the Guideline itself or the legislative history.

The Orleans's construction of Guideline 9.4 is illogical and would render some of the Guideline's language inoperative. The term "sleeping unit," when used in connection with a hotel, implies the entirety of the individual hotel guest unit -- the bedroom, bathroom, and other private spaces occupied exclusively by a guest. The fact that Guideline 9.4 refers to doors "within" sleeping "units" rather than "within" sleeping "rooms" signals that all facilities connected to the sleeping room are covered. In other words, a sleeping "unit" is larger than a sleeping "room," not, as the Orleans suggests, smaller.

Even if "sleeping unit" does refer to just the sleeping area, Guideline 9.4 would still cover the bathroom door: the door from the bedroom to the bathroom is, indisputably, a door "into" the sleeping area from the bathroom, just as the door from the hall is a door "into" the sleeping area. So even if "sleeping unit" does refer just to the sleeping area, Guideline 9.4 would still cover the bathroom door. Although here there is a second door within the bathroom, it defies logic to think that the intent was to allow hotels to render the bedroom inaccessible from part of a guest's bathroom; the more sensible

conclusion is that both the bathroom doors are doors "into" the bedroom from the toilet area, since one has to go through both to get to the bedroom.

Finally, the regulators who wrote Guideline 9.4 had specific guidance on the accessibility of hotel bathrooms from Congress' deliberations on the statute. The congressional reports accompanying passage of the ADA made it clear that "all doors and doorways designed to allow passage into and within all hotel rooms and bathrooms [are required] to be sufficiently wide to allow passage by individuals who use wheelchairs" H.R. Rep. No. 485, Pt. 2, 101st Cong., 2d Sess. 118 (1990); S. Rep. No. 116, 101st Cong., 1st Sess. 70 (1989) (emphasis added).

Thus, the magistrate judge correctly ruled that Guideline 9.2 applies to the interior bathrooms at the Orleans and was violated.

B. No Substantial Compliance or Undue Burden Exception

Though the magistrate judge found that Guideline 9.2 applies to the bathroom doors, he nonetheless declined to order injunctive relief because "[w]hile this may be a technical violation of the language of the Guidelines, the Court finds there has been substantial compliance with the spirit of the law. Considering the enormous expense required to modify the structure, and the near absence of hardship and that constituting a minimal inconvenience to wheelchair users, this Court is loathe [sic] to grant injunctive relief to Plaintiffs on this issue."

The magistrate judge's ruling was in error. In enacting the ADA, Congress adopted two distinct systems for regulating building accessibility: one to apply to existing facilities (those designed and constructed for occupancy before January 26, 1993) and another to apply to later-constructed facilities. 42

U.S.C. §§ 12183(a)(1) and 12182(b)(2)(A)(iv). The grandfathered facilities must remove barriers to accessibility only to the extent that such removal is "readily achievable." 42 U.S.C. § 12182(b)(2)(A)(iv). "Readily achievable" is defined as "easily accomplishable and able to be carried out without much difficulty or expense." 42 U.S.C. § 12181(9).

In contrast to grandfathered facilities, the ADA requires that newly constructed facilities be "readily accessible and usable by individuals with disabilities." 42 U.S.C. § 12183(a)(1). We need not decide whether the ADA forecloses the possibility that a court might exercise its equitable discretion in fashioning relief for violations of § 12183(a), see e.g., Tenn. Valley Auth. v. Hill, 437 U.S. 153, 174 (1978), because there is no room for discretion here even if it exists. This violation resulted in the very discrimination the statute seeks to prevent: it denied individuals with disabilities access to public accommodations. Moreover, the only statutory defense for noncompliance -- structural impracticability -- does not apply to the Orleans because the terrain on which it is constructed has no unique characteristics which would make accessibility unusually difficult to achieve. See 42 U.S.C. § 12183(a)(1). Thus, we reverse the magistrate's determination that, because the Orleans demonstrated obedience to the spirit of the ADA, plaintiffs were not entitled to injunctive relief. The issue is remanded to the magistrate judge for entry of an injunction ordering that the bathroom doors be brought into compliance with Guideline 9.2.

III. The Pool Cabanas

The swimming pool area at the Orleans has nine pool cabanas, five large and four small. Of these, three large and three small ones are located on an accessible route. The accessible cabanas are just as close to the pool as the non-accessible cabanas.

Not surprisingly, the Guidelines do not contain specific accessibility requirements ("scoping requirements") for pool

cabanas. Where there are no scoping requirements for a particular type of facility, "then a reasonable number, but at least one, must be accessible." ADA Title III Technical Assistance Manual III - 5.300. Placing six of the nine pool cabanas on an accessible route is reasonable and complies with the ADA. The magistrate judge's decision on this issue is affirmed.

IV. Employee Work Areas in the Slot Change Kiosks

The ADA's citizen suit provision allows civil actions for injunctive relief to be brought "by the person aggrieved. . . ." 42 U.S.C. § 2000a-3(a). Neither of the individual plaintiffs, Long and Smith, works at the Orleans and plaintiffs have not alleged how they are in any way aggrieved by a violation occurring in an area accessible only to employees. Also, while the Supreme Court has long recognized that an association may have standing as the representative of its members, see e.g., Warth v. Seldin, 422 U.S. 490, 511 (1975), the Disabled Rights Action Committee has not alleged that any of its members are employees of the Orleans or would have occasion to enter the working areas of the slot change kiosks. See Hunt v. Wash. State Apple Adver. Comm'n, 432 U.S. 333, 343 (1977) (for representative standing to lie, at least one member must have standing on their own). Accordingly, these plaintiffs do not have standing to challenge any non-compliance in the employee area of the slot change kiosks.

V. Slot Change Kiosk Counters

Guideline 7.2(2) provides:

At ticketing counters, teller stations in a bank, registration counters in hotels and motels, box office ticket counters, and other counters that may not have a cash register but at which goods or services are sold or distributed either:

(i) a portion of the main counter which is a minimum of 36 in[ches] [] in length shall be provided with a maximum height of 36 in[ches] []; or

(ii) an auxiliary counter with a maximum height of 36 in[ches] [] in length shall be provided with a maximum height of 36 in[ches] []; or

(iii) equivalent facilitation

The parties agree that two of the four slot change kiosks do not comply with Guideline 7.2(2). The magistrate judge found that the Orleans was nonetheless not in violation because Guideline 7.2(2) solely requires accessibility at the "main counter."

The magistrate judge's ruling was in error. The term "main counter" in Guideline 7.2(2)(i) serves only to distinguish the main counter at a particular station from the "auxiliary counter" at that same station discussed in Guideline 7.2(2)(ii). The provision applies to each of the stations, not just a "main" station. A merchant cannot circumvent the Guideline by declaring one counter to be the "main counter." Such an interpretation is contrary to a plain reading of the Guideline. We reverse the magistrate on this issue and remand for issuance of an injunction.

VI. The Bar Counters

Guideline 5.2 reads, in pertinent part:

Where food or drink is served at counters exceeding 34 in[ches] [] in height for consumption by customers seated on stools or standing at the counter, a portion of the main counter which is 60 in[ches][] in length minimum shall be provided in compliance with [Guideline] 4.32 or service shall be available at accessible tables within the same area.

The Orleans has three bars around its "pit" area. Two of these bars, the Alligator Bar and the Crawfish Bar, do not have counters that comply with Guideline 5.2. The other bar, the Mardi Gras Bar, has such a counter.

The magistrate judge held that the Orleans violated Guideline 5.2 because each of the bars might have a different ambiance, so exclusion from any one bar curtailed "full and equal enjoyment of these facilities." This ruling was in error. Guideline 5.2, while based on the general concept of full and equal enjoyment, contains two alternatives for compliance. First, the counter can be accessible. The parties agree that the Alligator and Crawfish Bars lack accessible counters. Second, service can be available at "accessible tables within the same area." The parties agree that the Mardi Gras Bar contains such seating. But the magistrate judge failed to determine whether the seating provided at the Mardi Gras Bar is "within the same area" as the Alligator and Crawfish Bars. The magistrate judge's ruling is vacated and the issue is remanded for decision as to whether the seating provided at the Mardi Gras Bar is "within the same area" as the Alligator and Crawfish Bars.

VII. Nevada ADA Claim

In addition to their request for injunctive relief under the ADA, plaintiffs also sought damages under Nevada Revised Statutes 651.090.⁵ A plain reading of that statute

⁵ Nev. Rev. Stat. 651.090 reads, in pertinent part:

1. Any person who:

(a) Withholds, denies, deprives or attempts to withhold, deny or deprive any other person of any right or privilege secured by NRS 651.070

[I]s liable to the person whose rights pursuant to NRS 651.070 . . . are affected for actual damages, to be recovered by a civil action in a court in and for the county in which the infringement of the civil rights occurred or in which the defendant resides.

demonstrates, and plaintiffs do not dispute, that a recovery must be based on "actual damages" or, to put it another way, monetarily compensable injury. When the Orleans moved for summary judgment, it did so as to all of plaintiffs' claims. After the Orleans so moved, it was plaintiffs' responsibility to explain to the magistrate judge why a triable issue of fact existed on damages. Plaintiffs admit that they defaulted on this duty. Thus, summary judgment was properly granted for the Orleans on the plaintiffs' Nevada ADA claims.

VIII. Attorney's Fees

We need not decide plaintiffs' appeal of their fee award because we must vacate the award to allow the district court to recalculate it in light of our holdings in this case.

CONCLUSION

This appeal was timely filed. The magistrate judge's ruling that the non-compliance of the bathroom doors in the "standard" rooms does not require injunctive relief is REVERSED and the issue is REMANDED for issuance of such injunctive relief. The magistrate judge's ruling that the pool cabanas comply with the ADA is AFFIRMED. The magistrate judge's ruling that the elevated employee work areas inside the slot change kiosks do not violate the ADA is REVERSED and the issue is REMANDED for issuance of proper injunctive relief. The magistrate judge's ruling that the slot change kiosk counters are not in violation of the ADA is REVERSED and the issue is REMANDED for issuance of proper injunctive relief. The magistrate judge's ruling that the seating at the

Nev. Rev. Stat. 651.070 reads, in pertinent part:

All persons are entitled to the full and equal enjoyment of the . . . facilities . . . and accommodations of any place of public accommodation, without discrimination or segregation on the ground of . . . disability.

bars in the "pit" area violates the ADA is VACATED and the issue is remanded for a factual determination pursuant to this opinion. The magistrate judge's ruling that plaintiffs did not allege injury sufficient to survive summary judgment on a claim under the Nevada ADA is AFFIRMED. Finally, the award of attorney's fees is VACATED and fees will be recalculated after proper disposition of the remanded issues. Costs on appeal to plaintiffs-appellants. The Motion to Strike Portions of Reply Brief for Coast Resorts, Inc., or, in the Alternative, for Leave to File Surreply Brief, by plaintiffs-appellants, is DENIED AS MOOT.

AFFIRMED IN PART, REVERSED IN PART, AND
REMANDED.

14172

EXHIBIT K


NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_0031



JM_0036




JM_0037



JM_0038



JM_0116



JM_0118


NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_0119



JM_0132



JM_0255



JM_0258



JM_0291



JM_0292

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_0447



JM_0448



JM_0449



JM_0450



JM_0453



JM_0454

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_0456



JM_0457




JM_0459



JM_0460



JM_0495



JM_0496

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_0498



JM_0500



JM_2006



JM_2007



JM_2011




JM_2012

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS




JM_2013



JM_2038



JM_2043



JM_2066



JM_2067



JM_2068

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_2070




JM_2090



JM_2091



JM_2276



JM_2277



JM_2294


NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_2407



JM_2408



JM_2436



JM_2455



JM_2475



JM_2477

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_2508




JM_2509



JM_2537



JM_2538



JM_2539



JM_2540

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS




JM_3141




JM_3142



JM_3159



JM_3160




JM_3161



JM_3163


NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS




JM_3164




JM_3165



JM_3166



JM_3167



JM_3168



JM_3169

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS




JM_3170



JM_3408



JM_3409



JM_3427



JM_3428



JM_3435

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_4118



JM_4120



JM_4130



JM_4135



JM_4516



JM_5763

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5764



JM_5765



JM_5766



JM_5767



JM_5768



JM_5769

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5770



JM_5771



JM_5773



JM_5775



JM_5776



JM_5777


NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5778



JM_5779



JM_5780



JM_5781



JM_5782



JM_5783


NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS




JM_5784




JM_5785



JM_5790



JM_5791



JM_5792



JM_5793

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5794



JM_5795



JM_5796



JM_5800




JM_5801



JM_5802

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5803



JM_5805



JM_5806



JM_5807



JM_5808



JM_5809

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5810



JM_5811



JM_5812



JM_5813



JM_5814



JM_5815

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5816



JM_5817



JM_5818



JM_5819




JM_5820



JM_5821


NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS




JM_5822




JM_5823



JM_5824



JM_5825



JM_5826



JM_5827

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5828



JM_5829



JM_5830



JM_5831



JM_5832



JM_5837

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5838



JM_5839



JM_5840



JM_5844



JM_5845



JM_5847

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5848




JM_5850



JM_5851



JM_5852



JM_5855



JM_5857

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5858



JM_5859



JM_5860



JM_5861



JM_5862



JM_5863

NEVAREZ V 49ERS - LEVI'S STADIUM PHOTOS



JM_5864



JM_5865

EXHIBIT L

RESTROOM IDENTIFIER		ENTRANCE DOOR(S)					RR SIGN		ACCESSIBLE TOILET COMPARTMENT(S)										ACCESSIBLE TOILET(S)				AMBULATORY ACCESSIBLE TOILET					OTHER ELEMENTS					PHOTOS
ROOM (AS SHOWN IN CONSTRUCTION DOCUMENTS)	RESTROOM TYPE	LOCATION (IF MULTIPLE ENTRANCE DOORS)	DOOR OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	DOES NOT OPEN AT LEAST 90 DEGREES	EXCESSIVE WIDE GAP AT THRESHOLD	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	NO ISA AT ENTRANCE	NO ISA AT OVERHEAD SIGN	LOCATION (IF MULTIPLE ACC COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	EXCESSIVE FLOOR SLOPE	RR BABY TABLE LOCATED INSIDE	DEPLOYED BABY TABLE PREVENTS ENTRY	WIDTH OBSTRUCTED BY MOUNTED ITEMS	WASTE REC. OBSTRUCTS CLEARANCE	SEAT TOO LOW	INCORRECT LOCATION RELATIVE TO SIDE WALL	TP DISPENSER INCORRECTLY LOCATED	LOCATION (IF MULTIPLE AMIB COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs)	LAV MIRROR OBSTRUCTED BY VIDEO DISPLAY	URINAL FLUSH VALVE BUTTON TOO HIGH	INSUFFICIENT KNEE CLEARANCE AT BABY TABLE	ADDITIONAL ASPECTS				
03.03.03	MEN'S		8		1"					X	X												X	X	13		X			NO ACCESSIBLE COAT HOOK AT ACCESSIBLE TOILET COMPARTMENT	JM_266-JM_287		
03.10.02	WOMEN'S		8			33.75"	not 60" min.			X	X									18.75"			X	X								JM_289-JM_300	
03.12.01	ALL GENDER		9		1"																											JM_303-JM_311	
03.12.02	MEN'S	NW	7							X	X										X		X	X	13		X					JM_313-JM_328	
(continued, see abv.)		NE	8																														
03.12.03	WOMEN'S	NE	8							X	X	7.0											X	X								JM_330-JM_328	
(continued, see abv.)		SE																															
03.22.01	WOMEN'S	S	10							X	X										X		X	X								JM_341-JM_350	
(continued, see abv.)		N	7																														
03.26.02	MEN'S	SE	8						E	X	X	9.0									X	E	X	X	10		X					JM_353-JM_385	
(continued, see abv.)		NE	8						W	X	X	10.0										W	X	X									
(continued, see abv.)		SW	8																														
(continued, see abv.)		NW	7																														
03.29.01	WOMEN'S	SW	7						NE	X	X										X	NE	X	X								JM_388-JM_406	
(continued, see abv.)		SE	7						NW	X	X										X	NW	X	X									
03.43.02	WOMEN'S						X			X	X	7.0			X		X				X		X	X								JM_418-JM_427	
03.44.02	MEN'S						X			X	X				X						X		X	X			X					JM_428-JM_438	
03.47.04	ALL GENDER		14										40"					40"													LAVATORY & TOILET CLEARANCES OBSTRUCTED BY PULL-OUT STEPS	JM_2017-JM_2031	
03.53.04	ALL GENDER												43.5"					43.5"										X				JM_475-JM_482	
03.56.05	MEN'S						X			X	X	22.0									X		X	X			X					JM_484-JM_493	
03.57.02	WOMEN'S						X			X	X										X		X	X	7							JM_495-JM_506	
03.70.03	WOMEN'S	W	8						NW	X	X	6.0										NW	X	X								JM_21-JM_107	
(continued, see abv.)		NE	8						NE	X	X			3.0%							X	NE	X	X									
(continued, see abv.)		SE	7						S	X	X	7.0									X	S	X	X	8								

RESTROOM IDENTIFIER		ENTRANCE DOOR(S)					RR SIGN		ACCESSIBLE TOILET COMPARTMENT(S)								ACCESSIBLE TOILET(S)				AMBULATORY ACCESSIBLE TOILET					OTHER ELEMENTS				PHOTOS		
ROOM (AS SHOWN IN CONSTRUCTION DOCUMENTS)	RESTROOM TYPE	LOCATION (IF MULTIPLE ENTRANCE DOORS)	DOOR OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	DOES NOT OPEN AT LEAST 90 DEGREES	EXCESSIVE WIDE GAP AT THRESHOLD	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	NO ISA AT ENTRANCE	NO ISA AT OVERHEAD SIGN	LOCATION (IF MULTIPLE ACC COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	EXCESSIVE FLOOR SLOPE	RR BABY TABLE LOCATED INSIDE	DEPLOYED BABY TABLE PREVENTS ENTRY	WIDTH OBSTRUCTED BY MOUNTED ITEMS	WASTE REC. OBSTRUCTS CLEARANCE	SEAT TOO LOW	INCORRECT LOCATION RELATIVE TO SIDE WALL	TP DISPENSER INCORRECTLY LOCATED	LOCATION (IF MULTIPLE AMB COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs)	LAV MIRROR OBSTRUCTED BY VIDEO DISPLAY	URINAL FLUSH VALVE BUTTON TOO HIGH	INSUFFICIENT KNEE CLEARANCE AT BABY TABLE	ADDITIONAL ASPECTS			
03.74.02	MEN'S	NW	8		1.5"					X	X	13.0											X	X	15		X			ACCESSIBLE URINAL TOO HIGH	JM_110- JM_159	
(continued, see abv.)		SW	8		0.75"																											
(continued, see abv.)		NE	8		1"																											
(continued, see abv.)		SE	7		1"																											
03.74.03	ALL GENDER		9											6.3%					16"	19.5"										REAR GRAB BAR AT ACCESSIBLE TOILET INCORRECTLY POSITIONED	JM_2002- JM_2013	
03.77.02	WOMEN'S	NW	8							X	X												X	X	6							JM_160- JM_181
(continued, see abv.)		SW	7																													
03.84.01	MEN'S	W								X	X	25.0										X		X	X	14		X				JM_185- JM_208
(continued, see abv.)		S	6																													
03.84.02	WOMEN'S	W	8			44.75" not 60" min.		NE	X	X	6.0											NE	X	X								JM_211- JM_230
(continued, see abv.)		E	8					E	X	X	9.0										X	E	X	X	7							
03.89.03	ALL GENDER		9			7" not 18" min	X							7.1%																		JM_3046- JM_3047
03.89.05	WOMEN'S	N	8							X	X	7.0								18.5"			X	X								JM_233- JM_241
03.96.03	MEN'S		6							X	X										X		X	X		X						JM_243- JM_253
04.02.01	WOMEN'S	N	8					X	NW	X					X	X					X	NW	X	X								JM_3114- JM_3128
(continued, see abv.)		S	7					X	NE						X	X					X	NE										
04.06.01	ALL GENDER											48.5"						48.5"			X							X				JM_3132- JM_3142
04.08.01	MEN'S		8					X		X	X				X	X					X		X	X		X						JM_3144- JM_3158
04.43.01	WOMEN'S		7					X							X						X		X	X								JM_2256- JM_2262
04.43.02	MEN'S		10					X		X					X	X				18.5"	X		X	X			X					JM_2236- JM_2254
04.44.01	WOMEN'S		10					X		X					X	X			16"		X		X	X							VENDING ALCOVE NOT WIDE ENOUGH	JM_2214- JM_2234
04.44.02	MEN'S		8					X		X					X	X							X	X			X					JM_2197- JM_2212
04.47.02	ALL GENDER		11									48"	6.8%					X										X			ENTRANCE DOOR CLOSING TOO QUICKLY	JM_2176- JM_2187
04.53.02	ALL GENDER		12									45.5"						48"		18.5"								X				JM_2137- JM_2148

RESTROOM IDENTIFIER		ENTRANCE DOOR(S)					RR SIGN		ACCESSIBLE TOILET COMPARTMENT(S)								ACCESSIBLE TOILET(S)				AMBULATORY ACCESSIBLE TOILET					OTHER ELEMENTS				PHOTOS	
ROOM (AS SHOWN IN CONSTRUCTION DOCUMENTS)	RESTROOM TYPE	LOCATION (IF MULTIPLE ENTRANCE DOORS)	DOOR OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	DOES NOT OPEN AT LEAST 90 DEGREES	EXCESSIVE WIDE GAP AT THRESHOLD	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	NO ISA AT ENTRANCE	NO ISA AT OVERHEAD SIGN	LOCATION (IF MULTIPLE ACC COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	EXCESSIVE FLOOR SLOPE	RR BABY TABLE LOCATED INSIDE	DEPLOYED BABY TABLE PREVENTS ENTRY	WIDTH OBSTRUCTED BY MOUNTED ITEMS	WASTE REC. OBSTRUCTS CLEARANCE	SEAT TOO LOW	INCORRECT LOCATION RELATIVE TO SIDE WALL	TP DISPENSER INCORRECTLY LOCATED	LOCATION (IF MULTIPLE AMB COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs)	LAV MIRROR OBSTRUCTED BY VIDEO DISPLAY	URINAL FLUSH VALVE BUTTON TOO HIGH	INSUFFICIENT KNEE CLEARANCE AT BABY TABLE	ADDITIONAL ASPECTS		
04.56.02	MEN'S		9					X		X					X	X		45.5"	16.25"		X		X	X			X		INSUFFICIENT LENGTH OF ACCESSIBLE TOILET COMPARTMENT	JM_2075-JM_2097	
04.57.01	WOMEN'S		12					X							X	X					X		X	X					VENDING ALCOVE NOT WIDE ENOUGH	JM_2054-JM_2073	
04.57.02	MEN'S		11					X		X					X	X					X		X	X			X				JM_2279-JM_2287
04.57.03	WOMEN'S		11					X							X						X		X	X							JM_2289-JM_2295
04.92.01	WOMEN'S		8					X		X		X			X						X		X	X							JM_3081-JM_3092
04.98.01	MEN'S	NW	11					X		X	X	17.0	41.5"		X	X		41.5"	16.25"		X		X	X			X				JM_3093-JM_3108
(continued, see abv.)		NE	9					X																							
05.06.02	ALL GENDER		9																		X					X		X			JM_2422-JM_2433
05.08.04	MEN'S		9	X			X								X						X					X	X				JM_2435-JM_2448
05.08.05	WOMEN'S		11	X											X											X					JM_2449-JM_2554
05.22.02	MEN'S		11	X		38" not 48" min.									X	X					X						X				JM_2461-JM_2474
05.24.02	WOMEN'S		9			38" not 48" min.									X	X					X										JM_2479-JM_2489
05.29.03	WOMEN'S		13												X						X										JM_2492-JM_2499
05.30.03	MEN'S		10	X											X						X						X				JM_2501-JM_2511
05.42.04	WOMEN'S		10					X		X					X	X					X										JM_3183-JM_3193
05.43.03	MEN'S		10					X		X					X	X				X	X						X				JM_3195-JM_3210
05.47.05	ALL GENDER		10									46.5"						46.5"											X		JM_3212-JM_3220
05.53.05	ALL GENDER		12									46"						46"		18.5"									X		JM_3222-JM_3231
05.56.05	MEN'S		7					X		X				4.3%	X	X					X						X				JM_3235-JM_3247
05.57.03	WOMEN'S		7					X		X					X	X					X								X		JM_3249-JM_3257
05.70.03	WOMEN'S		10					X							X	X					X										JM_2335-JM_2343
05.70.04	MEN'S		7					X							X	X					X						X				JM_2324-JM_2333
05.76.05	WOMEN'S		11			X		X						2.5%	X	X					X										JM_2354-JM_2363
05.76.06	MEN'S		9												X	X					X						X				JM_2365-JM_2377

RESTROOM IDENTIFIER		ENTRANCE DOOR(S)					RR SIGN		ACCESSIBLE TOILET COMPARTMENT(S)								ACCESSIBLE TOILET(S)				AMBULATORY ACCESSIBLE TOILET					OTHER ELEMENTS				PHOTOS	
ROOM (AS SHOWN IN CONSTRUCTION DOCUMENTS)	RESTROOM TYPE	LOCATION (IF MULTIPLE ENTRANCE DOORS)	DOOR OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	DOES NOT OPEN AT LEAST 90 DEGREES	EXCESSIVE WIDE GAP AT THRESHOLD	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	NO ISA AT ENTRANCE	NO ISA AT OVERHEAD SIGN	LOCATION (IF MULTIPLE ACC COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	EXCESSIVE FLOOR SLOPE	RR BABY TABLE LOCATED INSIDE	DEPLOYED BABY TABLE PREVENTS ENTRY	WIDTH OBSTRUCTED BY MOUNTED ITEMS	WASTE REC. OBSTRUCTS CLEARANCE	SEAT TOO LOW	INCORRECT LOCATION RELATIVE TO SIDE WALL	TP DISPENSER INCORRECTLY LOCATED	LOCATION (IF MULTIPLE AMB COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs)	LAV MIRROR OBSTRUCTED BY VIDEO DISPLAY	URINAL FLUSH VALVE BUTTON TOO HIGH	INSUFFICIENT KNEE CLEARANCE AT BABY TABLE	ADDITIONAL ASPECTS		
05.92.03	MEN'S		10	X											X						X					X	X			JM_2397-JM_2408	
05.92.04	WOMEN'S		8	X			X								X					16.5"						X				JM_2382-JM_2395	
05.93.02	ALL GENDER		8																							X		X		JM_2412-JM_2419	
06.43.03	MEN'S		10					X		X				3.7%	X	X					X						X			JM_3307-JM_3319	
06.43.05	WOMEN'S		11					X		X				3.2%	X	X					X									JM_3321-JM_3330	
06.47.05	ALL GENDER		12										47"	4.1%	X	X		47"			X									JM_3299-JM_3305	
06.47.05	ALL GENDER		12										49"	4.1%				49"										X		JM_3299-JM_3305	
06.53.05	ALL GENDER		6										45"	4.9%				45"										X		JM_3288-JM_3294	
06.56.04	MEN'S		7					X						3.7%	X	X					X						X			JM_3273-JM_3284	
06.57.03	WOMEN'S		7					X		X				6.7%	X	X					X									JM_3260-JM_3271	
07.04.01	WOMEN'S	NE	11					X		X	X												X	X						JM_2587-JM_2595	
(continued, see abv.)		SE	8					X																							
07.08.01	MEN'S	NE	9					X		X	X									18.5"			X	X	25		X			JM_2569-JM_2503	
(continued, see abv.)		SE	10					X																							
07.12.02	ALL GENDER		11											7.1%																JM_2564-JM_2568	
07.16.01	WOMEN'S	N	7					X		X	X										X		X	X						JM_2552-JM_2562	
(continued, see abv.)		E	7					X																							
07.20.01	MEN'S	N	7					X		X	X												X	X	16		X		NO SEMI AMBULANTORY STALL PROVIDED		JM_2543-JM_2550
(continued, see abv.)		E	7					X																				X			
07.28.01	WOMEN'S	SE	10					X		X	X				X								X	X						JM_2518-JM_2528	
(continued, see abv.)		SW	7					X																							
07.29.01	MEN'S		6					X		X	X										X		X	X			X			JM_2531-JM_2540	
07.42.05	WOMEN'S		8					X		X				4.5%																JM_3334-JM_3344	
07.43.03	MEN'S		8					X		X				3.8%	X	X					X						X			JM_3346-JM_3360	

RESTROOM IDENTIFIER		ENTRANCE DOOR(S)					RR SIGN		ACCESSIBLE TOILET COMPARTMENT(S)								ACCESSIBLE TOILET(S)				AMBULATORY ACCESSIBLE TOILET				OTHER ELEMENTS				PHOTOS			
ROOM (AS SHOWN IN CONSTRUCTION DOCUMENTS)	RESTROOM TYPE	LOCATION (IF MULTIPLE ENTRANCE DOORS)	DOOR OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	DOES NOT OPEN AT LEAST 90 DEGREES	EXCESSIVE WIDE GAP AT THRESHOLD	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	NO ISA AT ENTRANCE	NO ISA AT OVERHEAD SIGN	LOCATION (IF MULTIPLE ACC COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs.)	WASTE RECEPTACLE OBSTRUCTS CLEARANCE	EXCESSIVE FLOOR SLOPE	RR BABY TABLE LOCATED INSIDE	DEPLOYED BABY TABLE PREVENTS ENTRY	WIDTH OBSTRUCTED BY MOUNTED ITEMS	WASTE REC. OBSTRUCTS CLEARANCE	SEAT TOO LOW	INCORRECT LOCATION RELATIVE TO SIDE WALL	TP DISPENSER INCORRECTLY LOCATED	LOCATION (IF MULTIPLE AMIB COMPARTMENTS)	DOOR DOES NOT CLOSE AUTOMATICALLY	DOOR REQUIRES TWO HANDS TO OPERATE	DOOR LATCH OPERATION REQUIRES EXCESSIVE FORCE (lbs)	LAV MIRROR OBSTRUCTED BY VIDEO DISPLAY	URINAL FLUSH VALVE BUTTON TOO HIGH	INSUFFICIENT KNEE CLEARANCE AT BABY TABLE		ADDITIONAL ASPECTS		
07.47.05	ALL GENDER		12										41"	4.4%				41"											X		JM_3365-JM_3371	
07.53.05	ALL GENDER		12										42.5"	7.7%				42.5"											X		JM_3374-JM_3384	
07.56.04	MEN'S		13					X		X				7.1%	X	X					X							X			JM_3388-JM_3402	
07.57.03	WOMEN'S		11					X		X				5.2%	X	X					X										JM_3404-JM_3413	
07.72.03	MEN'S		6					X		X	X	25.0		6.6%	X									X	X			X			JM_3003-JM_3014	
07.73.01	WOMEN'S		8					X		X	X										X		X	X							JM_3016-JM_3020	
07.83.01	MEN'S	S	7					X		X	X												X	X			X				JM_3024-JM_3030	
(continued, see abv.)		E	8					X																								
07.85.01	WOMEN'S	W	9					X		X	X										X		X	X	12						JM_3033-JM_3044	
(continued, see abv.)		E						X																								
07.89.03	ALL GENDER		9					X						7.1%																	JM_3051-JM_3057	
07.92.01	MEN'S	NE	7					X		X	X												X	X			X				JM_3059-JM_3071	
(continued, see abv.)		SE	7					X																								
07.95.01	WOMEN'S	NE	9					X		X	X												X	X							JM_3074-JM_3078	
(continued, see abv.)		SE	8					X																								
NRG TERRACE	MEN'S		10					X							X		X				X							X			URINALS ARE TOO HIGH	JM_5852-JM_5865
NRG TERRACE	WOMEN'S		10					X							X																	JM_5833-JM_5839
MELLON CLUB W	ALL GENDER		11											5.3%	X						X					X		X				JM_5760-JM_5773
MELLON CLUB W	WOMEN'S		11												X		X				X					X						JM_5786-JM_5802
MELLON CLUB W	MEN'S		10				X								X		X				X					X	X				ACC COMPARTMENT DOOR IS LOCATED INCORRECTLY (EXCESSIVE HINGE SIDE JAMB WIDTH)	JM_5773-JM_5785

EXHIBIT M

FOR PUBLICATION

**UNITED STATES COURT OF APPEALS
FOR THE NINTH CIRCUIT**

ROBIN FORTYUNE,
Plaintiff-Appellee,

v.

CITY OF LOMITA,
Defendant-Appellant.

No. 12-56280

D.C. No.
2:11-cv-06644-DDP-JCG

OPINION

Appeal from the United States District Court
for the Central District of California
Dean D. Pregerson, District Judge, Presiding

Argued and Submitted
February 13, 2014—Pasadena, California

Filed September 5, 2014

Before: Richard A. Paez and Jacqueline H. Nguyen, Circuit
Judges, and J. Frederick Motz, Senior District Judge.*

Opinion by Judge Paez

* The Honorable J. Frederick Motz, Senior District Judge for the U.S. District Court for the District of Maryland, sitting by designation.

SUMMARY**

Americans with Disabilities Act

Affirming the district court's denial of a motion to dismiss, the panel held that Title II of the Americans with Disabilities Act requires local governments to provide accessible on-street parking in the absence of regulatory design specifications for on-street parking facilities.

The panel stated that the text of the ADA, the relevant implementing regulations, and the Department of Justice's interpretation of its own regulations all led it to conclude that public entities must ensure that all normal governmental functions are reasonably accessible to disabled persons, irrespective of whether the DOJ has adopted technical specifications for the particular types of facilities involved. The panel held that the plaintiff had stated claims under the ADA and the California Disabled Persons Act based on the defendant city's alleged failure to provide accessible on-street diagonal stall parking.

** This summary constitutes no part of the opinion of the court. It has been prepared by court staff for the convenience of the reader.

COUNSEL

Robert Brockman, Jr. (argued), Matthew Racine, and Lee H. Roistacher, Daley & Heft LLP, Solana Beach, California, for Defendant-Appellant.

Maria Michelle Uzeta (argued), Russell C. Handy, and Mark D. Potter, Potter Handy LLP, San Diego, California, for Plaintiff-Appellee.

Thomas E. Perez, Assistant Attorney General, Christopher Chen-Hsin Wang (argued), and Mark Lenard Gross, United States Department of Justice, Civil Division, Washington, D.C., for Amicus Curiae the United States.

Alison Daly Alpert, Best, Best & Kreiger, San Diego, California, for Amicus Curiae League of California Cities.

OPINION

PAEZ, Circuit Judge:

In this case, we must decide whether Title II of the Americans with Disabilities Act (“ADA”) requires local governments to provide accessible on-street parking in the absence of regulatory design specifications for on-street parking facilities. We hold that it does.

I. BACKGROUND

Robin Fortune is a paraplegic who uses a wheelchair for mobility. He filed suit against the City of Lomita (“City”) in state court, alleging that he experiences “great difficulty,

discomfort and, even[] fear for his safety” when frequenting facilities in the City because none of the City’s public on-street parking is accessible to people with disabilities. He brought claims under the ADA, 42 U.S.C. §§ 12101 *et seq.*, and the California Disabled Persons Act (“CDPA”), Cal. Civ. Code §§ 54 *et seq.*

The City removed the case to federal court, and moved to dismiss Fortune’s complaint under Federal Rule of Civil Procedure 12(b)(6). The City argued that, absent the adoption of ADA implementing regulations specifically targeted toward on-street parking, it is not required to provide accessible on-street parking. The district court denied the motion to dismiss, concluding that “the broad language of the ADA requires public entities to ensure that all services, including on-street parking, are reasonably accessible to and usable by individuals with disabilities.”¹ The City filed a motion to certify the district court’s order for interlocutory appeal pursuant to 28 U.S.C. § 1292(b), which the district court granted. The City then timely petitioned for leave to appeal, and a motions panel of this court granted the petition.

¹ Fortune’s complaint alleged that the City did not provide parallel or diagonal stall on-street parking. However, before the district court issued a ruling on the City’s motion to dismiss, Fortune voluntarily dismissed his claims with respect to parallel on-street parking. Consequently, the district court’s order and this appeal concern only whether Fortune has stated claims based on the City’s failure to provide accessible diagonal stall on-street parking.

II. JURISDICTION AND STANDARD OF REVIEW

We have jurisdiction pursuant to 28 U.S.C. § 1292(b).² We review de novo a district court order denying a motion to dismiss pursuant to Federal Rule of Civil Procedure 12(b)(6). *Dunn v. Castro*, 621 F.3d 1196, 1198 (9th Cir. 2010); *Camacho v. Bridgeport Fin., Inc.*, 430 F.3d 1078, 1079 (9th Cir. 2005). The district court's interpretation of the ADA and the CDPA are questions of law subject to de novo review. *Skaff v. Meridien N. Am. Beverly Hills, LLC*, 506 F.3d 832, 837 (9th Cir. 2007); *Molski v. Foley Estates Vineyard & Winery, LLC*, 531 F.3d 1043, 1046 (9th Cir. 2008).

III. ANALYSIS

“Congress enacted the ADA in 1990 to remedy widespread discrimination against disabled individuals.” *PGA Tour, Inc. v. Martin*, 532 U.S. 661, 674 (2001). The statute provides a “comprehensive,” “broad mandate” to eliminate discrimination against disabled persons, addressing both “outright intentional exclusion” as well as the “failure to make modifications to existing facilities and practices.” *Id.* at 675 (internal quotation marks and citations omitted); *see also Cohen v. City of Culver City*, 754 F.3d 690, 694 (9th Cir.

² “A non-final order may be certified for interlocutory appeal where it ‘involves a controlling question of law as to which there is substantial ground for difference of opinion’ and where ‘an immediate appeal from the order may materially advance the ultimate termination of the litigation.’” *See Reese v. BP Exploration (Alaska) Inc.*, 643 F.3d 681, 687–88 (9th Cir. 2011) (quoting 28 U.S.C. § 1292(b)). “A substantial ground for difference of opinion exists where reasonable jurists might disagree on an issue’s resolution” *Id.* at 688. We are satisfied that the district court and the motions panel of this court correctly determined that certification was appropriate in this case.

2014); 42 U.S.C. § 12101(b)(1). “We construe the language of the ADA broadly to advance its remedial purpose.” *Cohen*, 754 F.3d at 695.

Title II of the ADA, the provision at issue in this case, applies to state and local governments. *Id.* at 694; 42 U.S.C. § 12131. It provides that “no qualified individual with a disability shall, by reason of such disability, be excluded from participation in or be denied the benefits of the services, programs, or activities of a public entity, or be subjected to discrimination by any such entity.” 42 U.S.C. § 12132. The ADA was modeled on the Rehabilitation Act, which prohibited any “program or activity” that received federal funds from discriminating against disabled individuals. 29 U.S.C. § 794(a); *Pierce v. Cnty. of Orange*, 526 F.3d 1190, 1216 n.27 (9th Cir. 2008); *Bay Area Addiction Research & Treatment, Inc. v. City of Antioch* (“BAART”), 179 F.3d 725, 731–32 (9th Cir. 1999). The Rehabilitation Act defines “program or activity” as “all of the operations of . . . a department, agency, special purpose district, or other instrumentality of a State or of a local government.” 29 U.S.C. § 794(b). We have recognized that the term “services, programs, or activities” as used in the ADA is similarly broad, “‘bringing within its scope anything a public entity does.’” *Barden v. City of Sacramento*, 292 F.3d 1073, 1076 (9th Cir. 2002) (brackets omitted) (quoting *Lee v. City of L.A.*, 250 F.3d 668, 691 (9th Cir. 2001)). Whether a particular public function is covered by the ADA turns simply on whether it is “‘a normal function of a government entity.’” *Id.* (quoting *BAART*, 179 F.3d at 731).

Recognizing the broad reach of the ADA, we have held that Title II requires public entities to maintain accessible public sidewalks, notwithstanding the fact that no

implementing regulations specifically addressed sidewalks. *Id.* at 1076–78. In *Barden*, we explained that local governments must maintain accessible sidewalks because “maintaining public sidewalks is a normal function of a city and ‘without a doubt something that the City does.’” *Id.* at 1176 (brackets omitted) (quoting *Hason v. Med. Bd.*, 279 F.3d 1167, 1173 (9th Cir. 2002)). The same reasoning leads us to conclude that local governments must maintain accessible on-street public parking.

The City argues that *Barden* is distinguishable because, in that case, existing regulations concerning curb ramps clearly contemplated sidewalk accessibility. Here, however, the City contends that no existing regulation implicates on-street parking. The City’s argument fails for several reasons. First, although the *Barden* court noted that its conclusion was “consistent with” an existing curb ramp regulation, its holding was based on the text of the ADA. *See id.* at 1076–77 (interpreting the phrase “services, programs, or activities” and considering similar text in the Rehabilitation Act). Second, we have previously recognized that, as a general matter, the lack of specific regulations cannot eliminate a statutory obligation. *See Reich v. Mont. Sulphur & Chem. Co.*, 32 F.3d 440, 444–45 (9th Cir. 1994) (explaining that although the Occupational Safety and Health Act contemplated that the Secretary of Labor would promulgate specific safety standards, such regulations could only “amplify and augment” the statute’s general duty clause and their absence did not “displace” the statutory mandate to provide a safe workplace).

Third, existing regulations *do* require accessible on-street parking. Two regulations in particular apply to public on-street parking. The first is 28 C.F.R. § 35.150, which applies

to all existing facilities.³ Pursuant to this regulation, public entities must “operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.” 28 C.F.R. § 35.150(a). Because the provision of public on-street parking is a “service, program, or activity,” 28 C.F.R. § 35.150(a) applies to it. Under the regulation, however, public entities have some flexibility in handling existing inaccessible facilities. For instance, they are not required to make structural changes to all existing on-street parking facilities if they can make public on-street parking accessible by other means, such as by providing accessible on-street parking at other nearby sites. 28 C.F.R. § 35.150(b)(1); *cf. Cohen*, 754 F.3d at 697 (noting that in order to comply with 28 C.F.R. § 35.150, a public entity may require disabled individuals to “take a marginally longer route” (internal quotation marks omitted)). But, at bottom, the regulation mandates program accessibility for all normal governmental functions, including the provision of on-street public parking.

The second regulation, 28 C.F.R. § 35.151, governs only facilities that were constructed or modified after the ADA’s

³ The regulations define the term “facility” as “all or any portion of buildings, structures, sites, complexes, equipment, rolling stock or other conveyances, roads, walks, passageways, parking lots, or other real or personal property.” 28 C.F.R. § 35.104. The United States Department of Justice (“DOJ”), in its amicus brief, argues that on-street parking areas are facilities because they constitute parking lots or portions of the road. We need not address these arguments because, if nothing else, on-street parking areas qualify as “other real . . . property.” *See* Black’s Law Dictionary 1412 (10th ed. 2014) (defining “real property” as “[l]and and anything growing on, attached to, or erected on it, excluding anything that may be severed without injury to the land”).

effective date. Unlike 28 C.F.R. § 35.150, it requires that “each facility” constructed or altered after June 26, 1992 be “readily accessible to and usable by individuals with disabilities.” 28 C.F.R. § 35.151(a)(1), (b)(1). By its terms, then, this regulation extends to newly constructed or altered on-street parking facilities. The City seeks to avoid this conclusion by pointing out that the technical specifications governing newly constructed or altered facilities are silent with respect to on-street parking. In addition to the general mandate of accessibility set forth in subsections (a)(1) and (b)(1), 28 C.F.R. § 35.151 also requires that newly constructed or altered facilities meet the technical standards set forth in the Uniform Federal Accessibility Standards (“UFAS”), the 1991 Standards for Accessible Design (“1991 Standards”), or the 2010 Standards for Accessible Design (“2010 Standards”). *See id.* § 35.151(c).⁴ The UFAS, the 1991 Standards, and the 2010 Standards contain detailed specifications for a range of different facilities, but none of them address on-street parking.⁵ However, nothing in 28 C.F.R. § 35.151 suggests that when technical specifications do not exist for a particular type of facility, public entities have no accessibility obligations. In fact, such an interpretation of the regulation cannot be reconciled with subsections (a)(1) and (b)(1), which mandate that “each”

⁴ The UFAS is available at <http://www.access-board.gov/guidelines-and-standards/buildings-and-sites/about-the-aba-standards/ufas>. The 1991 Standards are available at 28 C.F.R. § 36, App. D. The 2010 Standards are available at <http://www.access-board.gov/attachments/article/983/ADASTandards.pdf>. Which standard applies depends on the date of construction or alteration.

⁵ They do contain specifications for parking lots and parking structures. *See* UFAS §§ 4.1.1, 4.6; 1991 Standards §§ 4.1.2, 4.6; 2010 Standards §§ 208, 502.

newly constructed or altered facility be readily accessible. Therefore, we read 28 C.F.R. § 35.151 to require that all public on-street parking facilities constructed or altered after the ADA's effective date be accessible.

Our interpretation of 28 C.F.R. § 35.151 is also consistent with the DOJ's interpretation. The DOJ issues a Technical Assistance Manual ("TA Manual") to assist individuals and entities to understand their rights and obligations under the ADA.⁶ In a 1994 supplement to the TA Manual, the DOJ offered the following guidance on complying with 28 C.F.R. § 35.151 when neither the UFAS nor the Americans with Disabilities Act Accessibility Guidelines for Buildings and Facilities ("ADAAG")⁷ contained specifications for a type of facility:

In such cases the technical requirements of the chosen standard should be applied to the extent possible. If no standard exists for particular features, those features need not comply with a particular design standard. However, the facility must still be designed

⁶ The TA Manual for Title II of the ADA is available at <http://www.ada.gov/taman2.html>.

⁷ The ADAAG contains the Architectural and Transportation Barriers Compliance Board's ("Access Board") proposed accessibility. By statute, the Access Board sets the floor for the DOJ's ADA regulations. 42 U.S.C. § 12134(c). The ADAAG itself, however, is not one of the technical specification standards listed in 28 C.F.R. § 35.151(c). The 1994 supplement to the TA Manual likely refers to the ADAAG because, even though as a general matter the ADAAG does not define the governing accessibility standards, the 1991 Standards adopted the ADAAG in full. *See* 28 C.F.R. § 36, App. D.

and operated to meet other title II requirements, including program accessibility.

1994 Supplement to TA Manual, II-6.2100 (citation omitted).⁸ Moreover, the DOJ's amicus brief also sets forth this interpretation of 28 C.F.R. § 35.151.

An agency's interpretation of its own regulations is entitled to deference. *Auer v. Robbins*, 519 U.S. 452, 461 (1997). The DOJ's interpretation of its ADA implementing regulations is entitled to “controlling weight unless it is plainly erroneous or inconsistent with the regulation.” *Miller v. Cal. Speedway Corp.*, 536 F.3d 1020, 1028 (9th Cir. 2008) (quoting *Bowles v. Seminole Rock & Sand Co.*, 325 U.S. 410, 414 (1945)). The TA Manual is such “an interpretation[,] . . . and, as such, is entitled to significant weight as to the meaning of the regulation[s].” *Id.* (quoting *Disabled Rights Action Comm. v. Las Vegas Events, Inc.*, 375 F.3d 861, 875–76 (9th Cir. 2004)). Additionally, an agency's interpretation of its own regulations as advanced in an amicus brief is also entitled to deference. *Chase Bank, USA, N.A. v. McCoy*, 131 S. Ct. 871, 880–82 (2011); *Auer*, 519 U.S. at 461. Accordingly, even if we had doubts about the applicability of 28 C.F.R. § 35.151 to facilities for which no technical specifications exist, we would be bound to defer to the DOJ's interpretation of the regulation because it is not “plainly erroneous or inconsistent with the regulation.” *Miller*, 536 F.3d at 1028 (internal quotation marks omitted).

The City contends that another DOJ publication, an informal guidance publication entitled “ADA Guide for Small

⁸ The 1994 supplement to the TA Manual is available at <http://www.ada.gov/taman2up.html>.

Towns,” supports its position.⁹ That publication states only that “[t]he ADA Standards have technical requirements for parking lots and garages but no technical requirements for the design of on-street parking.” ADA Guide for Small Towns, Part II.A. This statement does not support the City’s argument that public on-street parking need not be accessible; it provides only that no technical specifications exist for public on-street parking facilities.

The City also points to certain text in “Using ADAAG,” a 2003 Access Board technical bulletin, that supposedly stands for the proposition that public entities have no obligations under the ADA absent specific technical guidelines.¹⁰ But like the “ADA Guide for Small Towns,” “Using ADAAG” does not actually advance such a position. The text the City relies on merely states that “[t]he DOJ and [the Department of Transportation] rules describe all of the ADA obligations of covered entities arising from titles II and III of the [ADA].” Access Board, “Using ADAAG,” 1 (2003).¹¹ This statement says nothing about how the DOJ regulations apply to facilities for which no specifications exist. Furthermore, later in the bulletin, the Access Board explains that when there are “no provisions in ADAAG for a facility type, element, or feature,” such facilities are

⁹ The ADA Guide for Small Towns is available at <http://www.ada.gov/smtown.htm#anchor12335>.

¹⁰ At the time the parties submitted their briefs, “Using ADAAG” was available on the Access Board’s website. Since then, this document has been removed from the website.

¹¹ The Department of Transportation is responsible for administering certain provisions of the ADA not at issue in this case. *See, e.g.*, 42 U.S.C. §§ 12149, 12164.

nevertheless subject to other ADA requirements, including the duty to provide equal opportunity. In many cases it will be feasible to provide access by incorporating basic elements specified in ADAAG, such as ramps and other parameters of an accessible route. . . . [I]n new construction and alterations, a reasonable number, but at least one of each type of element should be designed to be accessible.

Id. at 8. Accordingly, the Access Board, like the DOJ, understood the ADA to impose general accessibility requirements on public entities even in the absence of technical specifications for a particular facility. Moreover, even if the bulletin did support the City's position, the Access Board's understanding of the ADAAG is not entitled to any deference. *See Miller*, 536 F.3d at 1031 ("Whatever the Access Board thought of its own guidelines, the Department of Justice adopted the text of the guidelines themselves, not the Access Board's interpretation of that text.").

Nor are we persuaded that the City should be exempted from the general mandate of the ADA and its implementing regulations simply because the Access Board has proposed guidelines that do contain technical specifications for on-street parking.¹² We have previously interpreted existing regulations to require certain accommodations even when the Access Board was in the midst of addressing the specific issue before us. *See Or. Paralyzed Veterans of Am. v. Regal*

¹² *See* Access Board, Proposed Accessibility Guidelines for Pedestrian Facilities in the Public Right-of-Way (July 26, 2011), <http://www.access-board.gov/attachments/article/743/nprm.pdf>.

Cinemas, Inc., 339 F.3d 1126, 1132–33 (9th Cir. 2003) (deferring to the DOJ’s interpretation of how a regulation applied in an unanticipated situation without reference to ongoing Access Board rulemaking); *id.* at 1133–34 (Kleinfeld, J., dissenting) (emphasizing that the Access Board had promulgated directly on-point proposed guidelines). We see no reason to conclude otherwise here.

Finally, the City’s due process argument is unavailing. The City contends that because it was not on notice that accessible on-street parking was required until, at the earliest, the DOJ’s amicus brief in this litigation, allowing Fortune’s claims to proceed would violate its right to due process. Entities regulated by administrative agencies have a due process right to fair notice of regulators’ requirements. *United States v. AMC Entm’t, Inc.*, 549 F.3d 760, 768–70 (9th Cir. 2008). Here, however, the DOJ made it known in 1994, in a publicly available supplement to the TA Manual, that public entities have a general obligation to ensure that governmental services are reasonably accessible even when no technical specifications exist for a particular type of facility. 1994 Supplement to TA Manual, II-6.2100. In *AMC*, we recognized that a significantly less public announcement—the filing of an amicus brief in separate litigation—could provide adequate prospective notice of prohibited conduct. *See id.* at 770. Consequently, it is simply untrue that the City lacked notice that the ADA’s general mandate applied even absent technical specifications.¹³

¹³ Any further consideration of the City’s due process argument would be premature because due process constrains the remedies that may be imposed. *See AMC*, 549 F.3d at 768–70. If Fortune prevails, when crafting a remedy, the district court will have to consider carefully what

IV. CONCLUSION

The text of the ADA, the relevant implementing regulations, and the DOJ's interpretation of its own regulations all lead us to conclude that public entities must ensure that all normal governmental functions are reasonably accessible to disabled persons, irrespective of whether the DOJ has adopted technical specifications for the particular types of facilities involved. Accordingly, we hold that Fortune has stated claims under the ADA and the CDPA¹⁴ based on the City's alleged failure to provide accessible on-street diagonal stall parking.

AFFIRMED.

level of accessibility the City should have known was legally required for diagonal stall on-street parking. *See id.*

¹⁴ A violation of the ADA constitutes a violation of the CDPA. *Cohen*, 754 F.3d at 701; *Hubbard v. SoBreck, LLC*, 554 F.3d 742, 745 (9th Cir. 2008); Cal. Civ. Code § 54(c).

EXHIBIT N

UNITED STATES DISTRICT COURT
DISTRICT OF MINNESOTA
FOURTH DIVISION

Civil Action No. 4-96-995

Judge Tunheim

UNITED STATES OF AMERICA,

Plaintiff,

v.

ELLERBE BECKET, INC.,

Defendant.

CONSENT ORDER

A. Background

1. On October 10, 1995, The United States filed a complaint to enforce title III of the Americans with Disabilities Act (the "ADA"), 42 U.S.C. §§ 12181 through 12189, against Ellerbe Becket, Inc. ("Ellerbe"), an architectural firm headquartered in Minneapolis, Minnesota.

2. The complaint filed by the United States alleges that Ellerbe has engaged in a pattern or practice of discrimination in violation of title III of the Americans with Disabilities Act of 1990 ("ADA"), 42 U.S.C. §§ 12101 through 12189, by participating in the design and construction of several new sports stadiums and arenas which are not readily accessible to and usable by individuals with disabilities. See 28 C.F.R. § 36.406, and 28 C.F.R. Part 36, Appendix A ("the Standards for Accessible Design"). The complaint alleges that in several stadiums and arenas designed and constructed by Ellerbe for first occupancy after January 26, 1993, Ellerbe has failed to provide wheelchair seating locations that offer people with physical disabilities lines of sight that are comparable to those for members of the general public, in that most or all of the wheelchair locations do not provide a line of sight to the floor, ice, or playing field over other spectators, when those other spectators stand up. See Standards § 4.33.3.

3. Ellerbe denies that it has violated title III of the ADA. This agreement is a compromise of disputed claims and does not represent, and should not be construed to be, an admission of liability on the part of Ellerbe.

4. During the pendency of this action, Ellerbe filed a Motion to Dismiss on the grounds that architects are not liable for violations of title III of the ADA and therefore may not be subjected to enforcement actions brought by the United States.

The Court denied this motion, holding that architects may have liability under title III. *United States v. Ellerbe Becket, Inc.*, 976 F.Supp. 1262 (D. Minn. 1997). Ellerbe continues to maintain that title III of the ADA does not provide a cause of action against architects; however, for purposes of this agreement only, Ellerbe does not contest the Court's jurisdiction.

B. Agreement of the Parties

Accordingly, by consent of the parties, it is hereby ORDERED and DECREED that:

1. This Court has jurisdiction of this action under 42 U.S.C. § 12188(b)(1)(B) and 42 U.S.C. §§ 1331 and 1345. The Court may grant declaratory and other relief pursuant to 28 U.S.C. §§ 2201 and 2202.
2. Venue is proper in this district.
3. Ellerbe has participated in the design of assembly areas, sports stadiums and arenas that have been or will be occupied after January 26, 1993.
4. Ellerbe enters into this Consent Order for the purpose of avoiding litigation, and shall not dispute the validity of this Consent Order, or the authority of the Department of Justice to institute this action.
5. The terms of this order shall apply to assembly area projects in the United States, with fixed seating that seats four or more people, for which Ellerbe provides design services after the date of this order, if the facility being designed is one at which spectators can be expected to stand for some or all of any event to be held in that facility. This includes, but is not limited to, sports stadiums and arenas. Ellerbe shall design these facilities such that all or substantially all of the wheelchair seating locations in the facility provide persons with physical disabilities lines of sight that are comparable to those for members of the general public. For purposes of this order, Ellerbe shall calculate sight lines for wheelchair seating locations as described in the Department of Justice publication entitled "Accessible Stadiums." (Exhibit A to this order). In making these calculations, Ellerbe shall employ the average anthropometric dimensions set forth in Exhibit B to this order, on designs commenced after the date of this order.
6. Ellerbe shall provide to counsel for the United States annual reports on the status of its compliance with this order. These reports shall be provided no later than February 1 in each of 1999, 2000, and 2001. For each project in the United States involving an assembly area (including sports stadiums or arenas) with fixed seating that seats four or more people, where people can be expected to stand during an event, for which Ellerbe provides design services after the date of this order, or since the date of its last annual report, whichever is more recent, the reports shall describe with particularity the project name and location, the client contact names, mailing addresses, and telephone numbers, the number of wheelchair seating locations, and the placement of wheelchair seating locations which provide lines of sight over standing spectators.
7. With respect to projects designed by Ellerbe as of the date of this Agreement, the United States shall not commence any enforcement action which otherwise might be brought against Ellerbe for alleged violations of the ADA requirement that, as to assembly areas with fixed seating that seat four or more people, where spectators can be expected to stand during an event, including sports stadiums and arenas, all or substantially all wheelchair seating locations must provide people with physical disabilities lines of sight that are comparable to those for members of the general public.
8. The parties shall negotiate in good faith to resolve any dispute relating to the interpretation or implementation of this order before bringing the matter to the Court's attention.
9. If the United States believes that Ellerbe has violated this order or any requirement contained herein, it may move this Court for an appropriate order for the enforcement of this order, including civil contempt sanctions. The Court shall retain jurisdiction of this action to enforce the provisions of this order through December 31, 2001, unless the Court determines it is necessary to extend any of its requirements, in which case those requirements shall be extended.
10. This agreement relates solely to the facts and events alleged in the United States' complaint. This agreement does not remedy, and shall not be construed to remedy, any other violations of the ADA, or any violations of other federal law. Nothing in this order shall preclude the United States from filing a separate action under the ADA for any alleged violations of the ADA not precluded herein. In such actions, the United States may seek all remedies provided in 42 U.S.C. § 12188. Nothing in this order shall relieve Ellerbe of the obligation to comply with all other provisions of the Standards for Accessible Design when engaged in the design or construction of any facility, whether or not covered by the terms of this order.

11. In the event that there are changes in the legal requirements governing the design of wheelchair seating locations in assembly areas (including sports stadiums and arenas), whether by modification of the Department of Justice's regulation implementing title III of the ADA (currently codified at 28 C.F.R. Part 36, including Appendix A, the Standards for Accessible Design), by act of Congress, or by decision of the United States Supreme Court, Ellerbe shall thereafter conform its conduct to whatever new or different design requirements are adopted, enacted, or held to be binding.

12. This Consent Order shall be binding on Ellerbe as well as any subsidiary or successor in interest.

13. This instrument reflects the entire agreement between the parties.

SO ORDERED this 24th day of March, 1998.

/s/ John R. Tunheim
United States District Judge

Agreed and Consented to:

For Plaintiff United States of America:

BILL LANN LEE
Acting Assistant Attorney General for Civil Rights

ALLISON J. NICHOL
THOMAS M. CONTOIS
HAROLD L. JACKSON
Attorneys
Civil Rights Division
U.S. Department of Justice
Post Office Box 66738
Washington, D.C. 20035-6738
(202) 514-6014

ROBERT SMALL
Assistant U.S. Attorney
Minnesota Bar No. 10212X
600 U.S. Courthouse
300 South Fourth Street
Minneapolis, Minnesota 55415
(612) 664-5684

For Defendant Ellerbe Becket, Inc.:

Lewis J. Baker, Esquire
WATT, TIEDER, HOFFAR & FITZGERALD, L.L.P.
7929 Westpark Drive, Suite 400
McLean, Virginia 22102
(703) 749-1000

Philip L. Bruner, Esquire
Mary Cullen Yeager, Esquire
FAEGRE & BENSON, L.L.P.
2200 Norwest Center
90 South Seventh Street
Minneapolis, Minnesota 55402-3901
(612)336-3000


Vincent W. King, Esquire
310 Fourth Avenue South
Suite 500
Minneapolis, MN 55415
(612)288-9225

EXHIBIT B

The average anthropometric dimensions employed shall be: (1) average eye height for a person sitting in a wheelchair is 47.45"; (2) horizontal distance from the eye of an average person sitting in a wheelchair to the edge of the tier on which the wheelchair rests is 30"; (3) average head height of a standing spectator is 67.65"; (4) average eye height of a standing spectator is 63.45"; and (5) average shoulder height of a standing spectator is 55.65".


[Return to Enforcement](#)

EXHIBIT O



Shoulder
height of
standing
spectator in
front =
55.65" AFF

TYPICAL LUXURY SUITE SIGHTLINE FROM WHEELCHAIR ACCESSIBLE SEAT
Vantage point: eye height of a standing spectator = 63.45" AFF




Shoulder
height of
standing
spectator in
front =
55.65" AFF

TYPICAL LUXURY SUITE SIGHTLINE FROM WHEELCHAIR ACCESSIBLE SEAT


Vantage point: wheelchair occupant eye height = 43" AFF

The low figure in the range common among guidance materials



TYPICAL LUXURY SUITE SIGHTLINE FROM WHEELCHAIR ACCESSIBLE SEAT

Vantage point: wheelchair occupant eye height = 47.45" AFF, the height prescribed in USA v Ellerbe Becket Consent Order – represents the mean




TYPICAL LUXURY SUITE SIGHTLINE FROM WHEELCHAIR ACCESSIBLE SEAT

Vantage point: wheelchair occupant eye height = 52" AFF

The high figure in the range common among guidance materials

EXHIBIT P



FAVORABLE VIEW LUXURY SUITE SIGHTLINE FROM WHEELCHAIR ACCESSIBLE SEAT

Vantage point: eye height of a standing spectator = 63.45" AFF



Shoulder
height of
standing
spectator in
front =
55.65" AFF

FAVORABLE VIEW LUXURY SUITE SIGHTLINE FROM WHEELCHAIR ACCESSIBLE SEAT


Vantage point: wheelchair occupant eye height = 43" AFF

The low figure in the range common among guidance materials



FAVORABLE VIEW LUXURY SUITE SIGHTLINE FROM WHEELCHAIR ACCESSIBLE SEAT

Vantage point: wheelchair occupant eye height = 47.45" AFF, the height prescribed in USA v Ellerbe Becket Consent Order – represents the mean



FAVORABLE VIEW LUXURY SUITE SIGHTLINE FROM WHEELCHAIR ACCESSIBLE SEAT

Vantage point: wheelchair occupant eye height = 52" AFF

The high figure in the range common among guidance materials

EXHIBIT Q



LUXURY SUITE - VIEW FROM WINDOW DINING COUNTER – WINDOWS IN PLACE
Vantage point: eye height of a standing spectator = 63.45" AFF



LUXURY SUITE - VIEW FROM WINDOW DINING COUNTER – WINDOWS IN PLACE

Vantage point: wheelchair occupant eye height = 43" AFF

The low figure in the range common among guidance materials



LUXURY SUITE - VIEW FROM WINDOW DINING COUNTER – WINDOWS IN PLACE

Vantage point: wheelchair occupant eye height = 47.45" AFF, the height prescribed in USA v Ellerbe Becket Consent Order – represents the mean



LUXURY SUITE - VIEW FROM WINDOW DINING COUNTER – WINDOWS IN PLACE

Vantage point: wheelchair occupant eye height = 52" AFF

The high figure in the range common among guidance materials

EXHIBIT R



LUXURY SUITE - VIEW FROM WINDOW DINING COUNTER – WINDOWS RETRACTED
Vantage point: eye height of a standing spectator = 63.45" AFF



LUXURY SUITE - VIEW FROM WINDOW DINING COUNTER – WINDOWS RETRACTED

Vantage point: wheelchair occupant eye height = 43" AFF

The low figure in the range common among guidance materials



LUXURY SUITE - VIEW FROM WINDOW DINING COUNTER – WINDOWS RETRACTED

Vantage point: wheelchair occupant eye height = 47.45" AFF, the height prescribed in USA v Ellerbe Becket Consent Order – represents the mean



LUXURY SUITE - VIEW FROM WINDOW DINING COUNTER – WINDOWS RETRACTED

Vantage point: wheelchair occupant eye height = 52" AFF

The high figure in the range common among guidance materials